



TREE CONSERVATION REPORT
ADDENDUM
71 Russell Ave

Tree Conservation Report Addendum submitted as
Partial Requirements for a Site Plan Control
Application, April 10, 2026

Dendron Forestry Services



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca

Tree Conservation Report Addendum

Address: 71 Russell Ave

Date of Report: April 10th 2026

Date of Site Visit: April 9, 2026

Prepared by: Astrid Nielsen, RPF, ISA Certified Arborist®
101- 45 Spencer Ave, K1Y 2P5
Astrid.nielsen@dendronforestry.ca

Client: Colin Miller, Colin@pinehillbuilders.ca

This Report must be read in its entirety, including the Assumptions and Limiting Conditions.

Introduction

This Tree Conservation Report Addendum has been prepared to provide additional information regarding the potential for tree retention in the Tree Conservation Report prepared by James B. Lennox & Associates Inc dated Jan 30, 2026. Specifically, this Addendum addresses the following comments by the City in the first submission on February 11, 2026:

Comment# 107: There are significant tree implications associated with this proposed development. An updated Tree Conservation Report must be prepared by a Registered Professional Forester. The report must address:

- 1. The retention plan for trees 1, 10 and 11 raises concern. Please provide more detail on the current growing condition of these trees, how much of the CRZs will be impacted by the proposed excavation and how far excavation is from the trunk of each tree. Address how the existing retaining wall beside trees 10 and 11 has influenced root growth and ensure the CRZs of these trees are accurately depicted. For tree 1, the proximity of the pavement and retaining wall is particularly concerning as it appears to be within the trees static root zone. There is concern over trees 1, 10 and 11 being made unstable by the extent of excavation/construction proposed in their proximity.
- 2. The Official Plan directs development to protect healthy trees outside of the building footprint. There are over 20 trees on the subject site and none are proposed for retention. Please have the Forester and Engineering consultant address why construction on this site leaves no potential for tree retention. The tree removal must be justified by these experts. In this response by these experts, also address the tree retention possibilities if the 11.27m rear yard setback was implemented opposed to the 7.52m setback proposed.
- 3. The feedback form directed the TCR author to discuss construction methods (including shoring), extent of excavation and engineering requirements in the TCR. This was not addressed.



This is critical to justify the extent of tree removal proposed. Please incorporate this information in the TCR.

- 4. The tree protection fencing for trees 10 and 11 overlaps with the proposed stairs and with a future talkway and curb for tree 1. This is unrealistic. Please address in the TCR and provide more details on the plan and how it can be executed as planned.

Methodology

A site visit was conducted on April 9th to assess any changes in tree health since the last site visit completed by Dendron in September 2024. A more thorough assessment on tree impacts was also completed based on the most recent grading plan prepared by TL Mak dated January 22, 2026.

Findings

Tree 1: This tree is identified for retention; however, its proximity to the proposed walkway requires specific mitigation measures. Following consultations with Barry Westby from Pinehill, the project will utilize a low-impact installation method to ensure that no stabilizing roots are severed. To guarantee the tree's long-term health, a certified arborist must be present to supervise all work within this area. Furthermore, pre-construction root exploration using an airspade is recommended to help finalize the walkway alignment and minimize root impact. The Tree Protection Zone (TPZ) fencing must remain in place throughout all site works and should only be removed once walkway installation is ready to proceed.

Tree 10: This tree is located directly on the property line and will be severely impacted by the proposed development. While the building excavation will utilize shoring to limit root disturbance, the construction of the retaining wall requires a grade change exceeding 4 meters. This excavation will effectively eliminate the tree's entire Critical Root Zone (CRZ) on the subject property. Furthermore, the building footprint creates a significant crown conflict, necessitating the removal of approximately 30% of the canopy, including two larger branches. Given the severity of both root and crown impacts, retention is not a safe or viable option. As this tree is situated on the adjacent property, written consent from the owner is required to proceed with a removal permit application.



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca



Photo 1: Existing retaining wall by Tree 10, American elm on adjacent property. The new retaining wall will be over 4 m in depth and flush against the property line which is close to the existing fence

Tree 11: This tree is located on the adjacent property and exhibits a severe structural defect, growing at a nearly horizontal lean. Given its poor condition, the tree may be susceptible to failure triggered by construction-related vibrations. While its removal is not mandatory for the project, it is recommended that the applicant consult with the neighbor to explore this option. At a minimum, any large branches encroaching over the subject property that pose a risk of failure should be pruned.



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca



Photo 2: Tree 11, Manitoba maple with very heavy lean on adjacent property

Tree 27: This tree is situated on an adjacent property on a steep slope experiencing active soil creep. Evidence of this movement is visible in the accumulation of soil and organic debris against the boundary fence, which has mostly collapsed under the pressure towards the base of the slope. The tree exhibits a significant lean toward the subject property, presenting a potential safety hazard. While a full assessment was limited by property access, a visual inspection from the property line suggests potential girdling roots on the upslope side of the root flare. Furthermore, the proposed building footprint presents a direct conflict with the tree's crown. Due to these combined factors, removal is recommended; however, this is contingent upon obtaining written permission from the neighboring property owner.



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca



Photo 3: Tree 27, Manitoba maple on adjacent property that should be removed due to the potential for failure on subject property

Additional two small Manitoba maple along the fence line: There are two small Manitoba maple along the fence line, intertwined with the existing metal fence, that will also require removal. These trees measure 11 cm in diameter and are in poor health due to their weak bases.



Photo 4: Small Manitoba maples along the fence long, intertwined with the fence

Trees in the rear yard:

Due to the significant grading requirements in the rear yard, tree retention is not feasible. There is already a steep slope, and grading will be required along with a retaining wall along the northern, and mostly eastern side.

Tree Retention possibilities with 11.27m rear yard setback vs proposed 7.52m setback:

It is unlikely that an increase in setbacks would result in an increase of tree retention as the reason for removal is based on grading requirements and not excavation for the new building. The rear yard is very steep making any tree retention very challenging.



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca

Tree Protection

Prior to any site works, protective fencing should be installed around the Tree Protection Area for tree 1 as indicated in the Tree Conservation Report map and maintained until all construction on site has been completed as per the City of Ottawa Tree Protection Specifications (March 2021).

Failure to install and maintain fencing as shown on the attached map may result in fines from the city.

Within the fenced area, the following tree protection guidelines should be applied:

- Do not change the grade
- Do not store construction material
- Do not operate machinery
- Do not convert to hard surface or change the landscaping
- Do not excavate unless it is a method that has been pre-approved by the City
- Do not place signs, notices or posters to any tree
- Do not damage the root system, trunk, or branches of any tree
- Direct the exhaust away from the tree

The tree protection fencing must be 1.2 m in height and constructed of a rigid or framed material (e.g. modulus – steel, plywood hoarding, or snow fence on a 2"X4" wood frame) with posts 2.4 m apart such that the fence location cannot be altered. All supports must be placed outside of the CRZ and installation must minimize damage to existing roots.

If the fenced tree protection area must be reduced to facilitate construction, *one* of the following mitigation measures should be applied:

- Place a layer of 6-12 inches (15 to 30 cm) of woodchip mulch to the area
- Apply ¾ (2 cm) inch plywood, or road mats over a 4+ inch (10 cm) thick layer of the wood chip mulch
- Apply 4-6 inches (10 to 15 cm) of gravel over a taut, staked, geotextile fabric

The undersigned personally inspected the property and issues associated with this report on April 9, 2026. On Behalf of Dendron Forestry Services,



Astrid Nielsen, MFC, RPF (Registered Professional Forester)

ISA Certified Arborist®, ON-1976

ISA Tree Risk Assessment Qualified

Principal, Dendron Forestry Services

Astrid.nielsen@dendronforestry.ca



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca

Assumptions and Limiting Conditions

Intended Use of the Report

This Report was prepared by Dendron Forestry Services (hereafter “Dendron”) at the request of the Client. The results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report are to be used solely for the purposes outlined within this Report. All other uses are impermissible and unintended, unless specifically stated in writing in the Report.

Intended User of the Report

This Report was prepared by Dendron for the exclusive use of the Client and may not be used or relied upon by any other party. All other users are unintended and unauthorized, unless specifically stated in writing in the Report.

Limitations of this Report

This Report is based on the circumstances and on-site conditions as they existed at the time of the site inspection and the information provided by the Client and/or third parties to Dendron. On-site conditions may limit the extent of the on-site inspection(s) conducted by Dendron, including weather events such as rain, flooding, storms, winds, tornados, snowfall, snow cover, hail; obstructions including fencing, dwellings, buildings, sheds, plants, and animals; lack of access to the entire perimeter of the tree due to adjacent properties; the shape of the tree; and accessibility of the tree crown, branches, trunk, or roots for examination.

In the event that information provided by the Client or any third parties, including but not limited to documents, records, site and grading plans, permits, or representations or any site conditions are updated or change following the completion of this Report, this Report is no longer current and valid and cannot be relied upon for the purpose for which it was prepared. Dendron and its agents, assessors, and/or employees are not liable for any damages, injuries, or losses arising from amendments, revisions, or changes to the documents, records, site and grading plans, permits, representations, or other information upon which Dendron relied in preparing this Report.

No assessment of any other trees or plants has been undertaken by Dendron. Dendron and its agents, assessors, and/or employees are not liable for any other trees or plants on or around the subject Property except those expressly identified herein. The results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report apply only to the trees identified herein.

Trees and plants are living organisms and subject to change, damage, and disease, and the results, observations, interpretations, analysis, recommendations, and conclusions as set out in this Report are valid only as at the date any inspections, observations, tests, and analysis took place. No guarantee, warranty, representation, or opinion is offered or made by Dendron as to the length of the validity of the results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report. As a result the Client shall only rely upon this Report as representing the results, observations, interpretations, analysis, recommendations, and conclusions that were made as at the date of such inspections, observations, tests, and analysis. The trees discussed in this Report should be re-assessed periodically and at least within one year of the date of this Report.

No Opinion regarding ownership of the Tree

This Report was not prepared to make a determination as to ownership of the subject tree(s). Where ownership of the subject tree(s) is identified within this Report, said identification is based on the information provided by the Client and third parties, including surveys, permits, and site and grading plans and may not be relied upon as a guarantee, warranty, or representation of ownership.

Assumptions

This Report is based on the circumstances and conditions as they existed at the time of the site inspection and the information provided by the Client and/or third parties to Dendron. Where documents, records, site and grading plans, permits, representations, and any other information was provided to Dendron for the purpose of preparing this Report, Dendron assumed that said information was correct and up-to-date and prepared this Report in reliance on that information. Dendron and its agents, assessors, and/or employees, are not responsible for the veracity or accuracy of such information. Dendron and its agents, assessors, or employees are not liable for any damages, injuries, or losses arising from inaccuracies, errors, and/or omissions in the documents, records, site and grading plans, permits, representations, or other information upon which Dendron relied in preparing this Report.

For the purpose of preparing this Report, Dendron and its agents, assessors, and/or employees assumed that the property which is the subject of this Report is in full compliance with all applicable federal, provincial, municipal, and local statutes, regulations, by-laws, guidelines, and other related laws. Dendron and its agents, assessors, and/or employees are not liable for any issues with respect to non-compliance with any of the above-referenced statutes, regulations, bylaws, guidelines, and laws as it may pertain to or affect the property to which this Report applies.

For the purpose of preparing this Report, Dendron and its agents, assessors, and/or employee assumed that there are no hidden or unapparent conditions affecting the results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report.



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca

No Publication

The Client acknowledges and agrees that all intellectual property rights and title, including without limitation, all copyright in this Report shall remain solely with Dendron Forestry. Possession of this Report, or a copy thereof, does not entitle the Client or any third party to the right of publication or reproduction of the Report for any purpose save and except where Dendron has given its prior written consent.

Neither all nor any part of the contents of this Report shall be disseminated to the public through advertising, public relations, news, sales, the internet or other media (including, without limitation, television, radio, print or electronic media) without the prior written consent of Dendron Forestry.

Implementing the Report Recommendations

Dendron and its agents, assessors, and/or employees accept no responsibility for the implementation of any part of this Report unless specifically requested to provide oversight on the implementation of the recommendations. In the event that inspection or supervision of all or part of the implementation of the within recommendations is requested, that request shall be in writing and the details agreed to in writing by both parties.

Dendron and its agents, assessors, and/or employees are not liable for any damages or injuries arising from the manner in which the recommendations in this Report are implemented, including failure to, incorrect, or negligent implementation of the recommendations.

Further Services

Neither Dendron nor any assessor employed or retained by Dendron for the purpose of preparing or assisting in the preparation of this Report shall be required to provide any further consultation or services to the Client, save and except as already carried out in the preparation of this Report and including, without limitation, to act as an expert witness or witness in any court in any jurisdiction unless the Client has first made specific arrangements with respect to such further services, including, without limitation, providing the payment of the Report's regular hourly billing fees.

Limits of Liability

In carrying out this Report, Dendron and its agents, assessors, and/or employees have exercised a reasonable standard of care, skill, and diligence as would be customarily and normally provided in carrying out this Report. While reasonable efforts have been made to ensure that the trees recommended for retention are healthy, no guarantees are offered, or implied, that these trees, or all parts of them will remain standing. It is professionally impossible to predict with absolute certainty the behaviour of any single tree or group of trees, or all their component parts, in all given circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential to fall, lean, or otherwise pose a danger to property and persons in the event of adverse weather conditions, and this risk can only be eliminated if the tree is removed.

Without limiting the foregoing, no liability is assumed by Dendron for:

- a) any legal description provided with respect to the Property;
- b) issues of title and or ownership respect to the Property;
- c) the accuracy of the Property line locations or boundaries with respect to the Property; and
- d) the accuracy of any other information provided to Dendron by the Client or third parties;
- e) any consequential loss, injury or damages suffered by the Client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and
- f) the unauthorized distribution of the Report.

The total monetary amount of all claims or causes of action the Client may have as against Dendron Forestry, including but not limited to claims for negligence, negligent misrepresentation, and breach of contract, shall be strictly limited solely to the total amount of fees paid by the Client to Dendron Forestry pursuant to the Contract for Services dated April 5, 2026, for which this Assessment was carried out.

Further, under no circumstance may any claims be initiated or commenced by the Client against Dendron or any of its directors, officers, employees, contractors, agents, assessors, or Assessors, in contract or in tort, more than 12 months after the date of this Report.

No Third Party Liability

This Report was prepared by Dendron exclusively for the Client for the purpose set out in the Report. Any use which a third party makes of this Report, or any reliance on or decisions a third party may make based upon this Report, are made at the sole risk of any such third parties. Dendron Forestry accepts no responsibility for any damages or loss suffered by any third party or by the Client as a result of decisions made or actions based upon the unauthorized use or reliance of this Report by any such party.

General

Any plans and/or illustrations in this Report are included only to help the Client visualize the issues in this Report and shall not be relied upon for any other purpose. This report is best viewed in colour. Any copies printed in black and white may make some details difficult to properly understand. Dendron accepts no liability for misunderstandings due to a black and white copy of the report.

Notwithstanding any of the above, nothing in this Report is taken to absolve the Client of the responsibility of obtaining a new Report in the event that the circumstances of the tree change.