PATERSON GROUP

Phase I – Environmental Site Assessment

75 Breezehill Avenue

Ottawa, Ontario

Prepared for 2729685 Ontario Inc. c/o Fotenn

Report: PE6049-1
August 8, 2023

EXECUTIVE SUMMARY

Assessment

Paterson Group was retained by Mr. Thomas Freeman to conduct a Phase I – Environmental Site Assessment (Phase I ESA) for 75 Breezehill Avenue , Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site (Phase I Property) and 250 m study area (Phase I Study Area) and to identify any environmental concerns with the potential to have impacted the Phase I property.

According to the historical research, the Phase I Property was utilized for commercial purposes as early as 1928 with a single commercial structure. Historical records indicated a commercial business in the 1930's utilized onsite gasoline storage of an unknown quantity. The commercial structure had undergone construction of two additions in approximately the 1940's and 1960's. respectively. The Phase I Property continues to be used for commercial purposes at this present time. Based on the construction of these additions in addition to the construction of the parking lot, fill material of unknown quality is expected to be present on the western portion of the Phase I Property. These potentially contaminating activity (PCA) are considered to represent an area of potential environmental concern (APEC) on the Phase I Property.

The historical use of the surrounding properties within the Phase I Study Area were developed for industrial, commercial, and residential purposes. Several historical off-site potentially contaminating activities (PCAs) were identified within the Phase I Study Area. Historical records identified the presence of a former coal fuel/lumber storage yard and various automotive businesses/motor vehicle repair shops adjacent to the north of the Phase I Property and a printing facility to the south of the Phase I Property at 975 Gladstone Avenue. Based on orientation and/or separation distances, all other off-site PCAs are not considered to represent APECs on the Phase I ESA Property.

Presently, the Phase I Property is occupied with a two-storey mixed-use building, located in the eastern portion of the site, adjacent to the former railway line. The building is occupied by various tenants that consist of commercial offices, commercial warehousing, and storage. A U-Haul rental fleet occupies a majority of the western parking lot. This paved parking lot is use by tenants and customers of the occupied units. It is expected that the use of road salt as a deicing agent was identified as PCA resulting in an APEC. Otherwise, no PCAs were identified on the Phase I ESA Property.

Neighbouring land use in the Phase I Study Area consists primarily of industrial commercial with some residential. An active automotive garage is located adjacent to

the Phase I Property located at 111 Breezehill Avenue. This off-site PCA is considered to represent and APEC to the Phase I Property.

Recommendations

Phase II – Environmental Site Assessment

Based on the findings of this assessment, it is our opinion that **a Phase II – Environmental Site Assessment will be required for the Phase I Property.**

Designated Substance Survey

Based on the age of the subject building and its additions (c.1940's – 1960's), asbestos containing building materials, lead-based paints, and other hazardous building materials may be potentially present within the structure. It is recommended that a designated substance survey (DSS) be completed for the subject building prior to any proposed demolition activities.

TABLE OF CONTENTS

EXECUTIVE SUMMARY ii
1.0 INTRODUCTION 1
2.0 PHASE I PROPERTY INFORMATION 2
3.0 SCOPE OF INVESTIGATION 3
4.0 RECORDS REVIEW 4
4.1 General 4
4.2 Environmental Source Information 7
4.3 Physical Setting Sources 15
5.0 INTERVIEWS 19
6.0 SITE RECONNAISSANCE 20
6.1 General Requirements 20
6.2 Specific Observations at the Phase I Property 20
7.0 REVIEW AND EVALUATION OF INFORMATION 25
7.1 Land Use History 25
7.2 Conceptual Site Model 27
8.0 CONCLUSIONS 31
8.1 Assessment 31
8.2 Recommendations 32
9.0 STATEMENT OF LIMITATIONS 33
10.0 REFERENCES 34

List of Figures

Figure 1 – Key Plan
Figure 2 – Topographic Map
Drawing PE6049-1 – Site Plan
Drawing PE6049-2 – Surrounding Land Use Plan

List of Appendices

Appendix 1 Aerial Photographs
Site Photographs

Appendix 2 MECP Freedom of Information Response
MECP Water Well Records
TSSA Correspondence
City of Ottawa HLUI Search Response
ERIS Database Report

Appendix 3 Qualifications of Assessors

1.0 INTRODUCTION

At the request of Mr. Thomas Freeman, Paterson Group (Paterson) conducted a Phase I – Environmental Site Assessment (Phase I ESA) for 75 Breezehill Avenue , in the City of Ottawa, Ontario, (Phase I Property). The purpose of this Phase I ESA has been to research the past and current use of the Phase I Property, as well as the neighbouring properties within a 250 m study area (Phase I Study Area), to identify any potentially contaminating activities (PCAs) that would result in areas of potential environmental concern (APECs) on the Phase I Property.

Paterson was engaged to conduct this Phase I ESA by Mr. Thomas Freeman, who can be reached by telephone at 613-730-5709.

This report has been prepared specifically and solely for the above noted project which is described herein. It contains all of our findings and results of the environmental conditions at this site.

This Phase I ESA report has been prepared under the supervision of a Qualified Person, in general accordance with Ontario Regulation (O. Reg.) 153/04, as amended under the Environmental Protection Act, and the requirements of CSA Z768-01 (reaffirmed 2022). The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I ESA are based on a review of readily available geological, historical, and regulatory information, as well as a cursory review made at the time of the field assessment. The historical research relies upon information supplied by others, such as local, provincial, and federal agencies, and was limited within the scope-of-work, time, and budget of the project herein.

2.0 PHASE I PROPERTY INFORMATION

Address:	75 Breezehill Avenue, Ottawa, Ontario.
Legal Description:	Part of Lots 10, 11, 12, 13 and 14 and all of lots D, E and 9, and Loretta Avenue of Registered Plan 73, in the City of Ottawa, Ontario.
Location:	The Phase I Property is located on the east side of Breezehill Avenue and on the north side of Laurel Avenue, in the City of Ottawa, Ontario. Refer to Figure 1 – Key Plan, appended to this report.
PIN:	04107-0004
Latitude and Longitude:	45° 24’ 20" N, 75° 43' 3.3" W

Site Description:

Configuration:	Irregular
Area:	6,170.4 m^2 (approximately)
Zoning:	IG1 – General Industrial Zone.
Current Use:	The Phase I Property is currently occupied by a two-storey mixed-use industrial building, consisting of commercial office space, warehouses, light manufacturing.
Services:	The Phase I Property is located within a municipally serviced area.

3.0 SCOPE OF INVESTIGATION

The scope of work for this Phase I ESA is described as follows:

- Determine the historical activities occurring on the Phase I Property and in the Phase I Study Area by conducting a review of readily available records, reports, photographs, plans, mapping information, databases, and regulatory agencies;
- Investigate the existing conditions present on the Phase I Property and in the Phase I Study Area by conducting site reconnaissance;
- Conduct interviews with persons knowledgeable of current and historic operations on the Phase I Property and, if warranted, the neighbouring properties;
- Present the results of our findings in a comprehensive report in general accordance with the requirements O. Reg. 153/04, as amended under the Environmental Protection Act, and in compliance with the requirements of CSA Z768-01 (reaffirmed 2022);
- Provide a preliminary environmental site evaluation based on our findings;
- Provide preliminary remediation recommendations and further investigative work if contamination is suspected or encountered.

4.0 RECORDS REVIEW

4.1 General

Phase I ESA Study Area Determination

A radius of approximately 250 m was deemed appropriate for defining the study area for this assignment, herein referred to as the Phase I Study Area. Properties located outside of the Phase I Study Area are not considered to have had the potential to impact the Phase I Property, based on their significant separation distances.

First Developed Use Determination

Based on a review of available historical information, the Phase I Property was first developed with a two-storey warehouse building prior to 1928.

Fire Insurance Plans

Fire insurance plans (FIPs), dated from 1912, 1948 and 1957, were reviewed for the general area of the Phase I Property as part of this assessment.

The 1912 FIPs depict the Phase I property as vacant undeveloped land. Adjacent to the east is the Canadian Pacific Railway. To the west, across Breezehill Avenue, a two-storey public school is present. Residential development is also present further to the west.

The 1948 FIPs depict the Phase I property developed with a large two-storey warehouse with an attached wood frame shed/garage. Two tenants occupy the building, one a furniture warehouse and the second a moving company warehouse. The Canadian Nation Railways line is adjacent to the east. Adjacent to the north is a is a coal supplier, chemical supplier and automotive repair shop. Further to the east is a lumber pile and further to the south is printing facility. Devonshire public school and residential development is present to west.

The 1957 FIPs depict the Phase I property developed with little changes from the previous 1948 FIP. The wood framed shed/garage has been relocated to the center of the parking area. Further to the south is a fuel supplier with an underground storage tank (UST).

The PCAs identified in the Phase I Study Area are summarized below in Table 1:

Table 1
Fire Insurance Plans
PCAs Identified in Phase I Study Area

Address	Potentially Contaminating Activity	Distance / Orientation from Site	Area of Potential Environmental Concern (Y / N)
1948 FIPs			
No Municipal Address	Railway Line	Adjacent to the east	N
63 Breezehill Ave N	Automotive repair shop	38 m North	N
73 Breezehill Ave N	Bruce Coal Co., Limited	Adjacent to the north	**Y**
73 Breezehill Ave N	Standard Chemical Co., Limited	Adjacent to the north	**Y**
1030 Somerset Street West	W.C. Edwards & Co., Limited	40m to the northeast	N
1030 Somerset Street West	No. 26 Central Ordnance Depot	95 m to the northeast	N
975 Gladstone Avenue	British American Bank Note Co., Limited	120m to the south	N
1957 FIPs			
No Municipal Address	Railway Line	Adjacent to the east	N
63 Breezehill Ave N	Automotive repair shop	38 m North	N
73 Breezehill Ave N	Bruce Coal Co. Limited	Adjacent to the north	**Y**
131 Loretta Avenue	Hall Fuel Ltd.	70 m south	N
1030 Somerset Street West	No. 26 Central Ordnance Depot	95 m to the northeast	N
975 Gladstone Avenue	British American Bank Note Co., Limited	120m to the south	N

Due to its proximity, the coal supplier (Bruce Coal Co. Limited) and Standard Chemical Co., Limited identified at 73 Breezehill Avenue are considered to represent APECs with respect to the Phase I Property.

Based on their separation distances, as well as their down-gradient or cross-gradient orientations with respect to anticipated groundwater flow to the east, none of the other remaining PCAs identified in the FIP review are considered to pose an environmental concern to the Phase I Property.

City of Ottawa Street Directories

City of Ottawa street directories were reviewed in approximate ten year intervals between 1900 and 2011 for the general area of the Phase I Property as part of this assessment. The Phase I Property was first listed in 1935 under Slater Brea co. and was subsequently listed until 2011 with various commercial, office and warehousing businesses. No environmental concerns were associated with the records of the Phase I Property with respect to the City of Ottawa street directories.

Adjacent properties within the Phase I study area were listed as private commercial businesses from 1935 to 2011. The commercial businesses identified are indicative of office space, warehousing storage, moving companies, and industrial activities. The PCAs identified in the Phase I Study Area are summarized below in Table 2:

Table 2
City Directories
PCAs Identified in Phase I Study Area

Address	Potentially Contaminating Activity (Years Listed)	Distance / Orientation from Site	Area of Potential Environmental Concern (Y / N)
Breezehill Avenue			
1 Breezehill Avenue North	Slacks (1959)	240 m north	N
1 Breezehill Avenue North	Grant's Body Shop (1974)	90 m north	N
3 Breezehill Avenue North	Ruddy Paint Shop auto painting (1959)	230m north	N
45 Breezehill Avenue North	Canadian Oil Company (1937, 1948)	25 m north	N
47 Breezehill Avenue North	Takaki Automotive (2009, 1998, 1988)	140 m to the north	N
50 Breezehill Avenue North	Wheelan Motors Ltd.	100 m to the north	N
53 Breezehill Avenue North	Bruce Fuels / Bruce Coal (1977, 1968, 1959, 1948)	Adjacent to the north	**Y**
55 Breezehill Avenue North	Japan Auto Service Inc, Ming Auto Service (2008)	70 m to the north	N
55 Breezehill Avenue North	A&T Auto Parts, Breezehill Auto body, Kingsway Automotive (1998, 1988)	70 m to the north	N
55 Breezehill Avenue North	Elmer's Auto Electric (1978)	70 m to the north	N
73 Breezehill Avenue	Standard Chemical Co. (1948)	Adjacent to the north	**Y**
73 Breezehill Avenue	Charcoal Supply Co. (1927)	Adjacent to the north	**Y**
109 Breezehill Avenue North	Alaska Steel & Welding (1984, 1974)	Adjacent to the west	N

Table 2 (Continued)
City Directories
PCAs Identified in Phase I Study Area

Address	Potentially Contaminating Activity (Years Listed)	Distance / Orientation from Site	Area of Potential Environmental Concern (Y / N)
Gladstone			
951Gladstone Avenue	Love Printing Service (1971, 1981, 1987)	165 m to the south	N
975 Gladstone Avenue	British American Bank Note Co.(1951, 1961, 1971, 1981, 2001)	90 m to the south	Y

Due to their close proximities, the coal and chemical supplier identified at 53 and 73 Breezehill Avenue and historical printing activities the British American Bank Note Co. at 975 Gladstone Avenue are considered to represent APECs with respect to the Phase I Property.

Based on its down-gradient orientation with respect to anticipated groundwater flow to the East, the railway line and train station is not considered to pose an environmental concern to the Phase I Property.

Plan of Survey

A survey plan of the Phase I Property completed by Stantec dated May 12, 2021 was provided for review as part of this assessment. The survey plan is attached to the appendix of this report.

4.2 Environmental Source Information

National Pollutant Release Inventory

A search of the National Pollutant Release Inventory (NPRI) database was conducted as part of this assessment. This federally managed database provides various reports and tracking information relating to the release of solid, liquid, or gaseous pollutants from industrial facilities into the natural environment.

A search of the National Pollutant Release Inventory (NPRI) was conducted electronically on April 18, 2023. The Phase I property and adjacent properties were not listed in the NPRI database for the years 1993 to 2021, with the exception of the property at 975 Gladstone Avenue, approximately 90 m south of the Phase I property. According to this listing the site has generated hexavalent chromium for off-site disposal from years 2003-2011 and volatile organic

compounds (VOCs) for off-site disposal from years 2003-2004. These records indicate the release of these chemicals was to the air. Based on the review, these releases are not expected to have impacted the Phase I property.

Ontario PCB Waste Storage Site Inventory

The Ontario Ministry of Environment, Conservation and Parks document entitled, *"Ontario Inventory of PCB Storage Sites, April 1995"* was reviewed as part of this assessment. This document identifies all recorded active and closed PCB waste storage sites situated in the Province of Ontario.

No PCB waste storage sites are located within the Phase I study area.

MECP Brownfields Environmental Site Registry

A search of the MECP Brownfields Environmental Site Registry was conducted as part of this assessment. This database contains publicly available information on all Records of Site Condition (RSCs) filed in the Province of Ontario.

A review of the registry did not identify any RSCs in the database as having been filed for the Phase I Property, however, two were identified for an off-site property situated within the Phase I Study Area:

- RSC# 236233 – 933 Gladstone Avenue (70 m East of Phase I Property)

According to the RSC, filed in 2022 by Golder Associates Ltd., all soil and groundwater test results complied with the applicable MECP standards and no remedial action was required to be undertaken.

- RSC# 226204 – 933 Gladstone Avenue (90 m East of Phase I Property)

According to the RSC, filed in 2019 by Golder Associates Ltd., all soil and groundwater test results complied with the applicable MECP standards with the exception of multiple Vanadium exceedances within the soil. It was determined that the vanadium exceedances were naturally occurring. As a result, no remedial action was required to be undertaken.

MECP Incident Reports

A request was submitted to the MECP Freedom of Information office for information with respect to records concerning environmental incidents, orders, offences, spills, discharges of contaminants, or inspections maintained by the MECP for the Phase I Property or any of the neighbouring properties.

A response from the MECP was received by our firm on March 31, 2023. No records were identified by the MECP.

MECP Submissions

A request was submitted to the MECP Freedom of Information office for information with respect to reports related to environmental conditions for the Phase I Property.

A response from the MECP was received by our firm on March 31, 2023. No records were identified by the MECP.

MECP Waste Management Records

A request was submitted to the MECP Freedom of Information office for information with respect to waste management records for the Phase I Property.

A response from the MECP was received by our firm on March 31, 2023. No records were identified by the MECP.

MECP Instruments

A request was submitted to the MECP Freedom of Information office for information with respect to certificates of approval, permits to take water, certificates of property use, or any other similar MECP issued instruments for the Phase I Property.

A response from the MECP was received by our firm on March 31, 2023. No records were identified by the MECP.

MECP Waste Disposal Site Inventory

The Ontario Ministry of Environment, Conservation and Parks document entitled, *"Waste Disposal Site Inventory in Ontario, 1991"* was reviewed as part of this assessment. This document includes all recorded active and closed waste disposal sites, industrial manufactured gas plants, and coal tar distillation plants situated in the Province of Ontario.

A review of this document did not identify any active waste disposal sites situated on the Phase I Property or within the Phase I Study Area. One (1) closed landfill site (Baywater Avenue and Wellington Street) located approximately 225m northwest of the Phase I Property. Based on the separation distance, this former landfill site is not considered to have impacted the Phase I Property.

MECP Coal Gasification Plant Inventory

The Ontario Ministry of Environment, Conservation and Parks document entitled, *"Municipal Coal Gasification Plant Site Inventory, 1991"* was reviewed as part of this assessment. This document provides a reference to the locations of former plants with respect to the Phase I Property.

A review of this document did not identify any former coal gasification plants located on the Phase I Property or within the Phase I Study Area.

OMNRF Areas of Natural and Scientific Interest (ANSI)

A search for ANSI sites situated within the Phase I Study Area was conducted electronically via the Ontario Ministry of Natural Resources and Forestry (OMNRF) website as part of this assessment.

A review of the available mapping information did not identify any ANSI sites situated on the Phase I Property or within the Phase I Study Area.

Technical Standards and Safety Authority (TSSA)

The TSSA Fuels Safety Branch in Toronto was contacted electronically on April 21, 2023, as part of this assessment, to inquire about current and former fuel storage tanks, spills, and historical incidents for the Phase I Property as well as the neighbouring properties within the Phase I Study Area.

The response from the TSSA indicated that no records were identified associated with the Phase I Property.

A copy of the correspondence with the TSSA is included in Appendix 2.

City of Ottawa Former Industrial Sites

The document prepared by Intera Technologies Limited entitled, *"Mapping and Assessment of Former Industrial Sites, City of Ottawa"*, was reviewed as part of this assessment. This document identifies the details and locations of all former industrial sites situated in the City of Ottawa.

A review of this document identified one former industrial site situated within the Phase I Study Area, which is summarized as follows:

- Site #61 – Somerset Street West and Breezehill Avenue North, Ottawa, Ontario (120 m North of Phase I Property)

According to the document, this site was under the occupation of "Canadian Oil Co.; Limited", a non-industrial site for bulk storage of oil and gas. Based on its separation distance and cross gradient location from the Phase I Property, this site does not represent an environmental concern to the Phase I Property.

City of Ottawa Historical Land Use Inventory (HLUI) Database

As part of this assessment, a requisition form was submitted to the City of Ottawa to request information from the City's Historical Land Use Inventory (HLUI) database for any environmental records pertaining to the Phase I Property as well as any properties situated within the Phase I Study Area.

A response from the City of Ottawa was received by our firm dated April 17, 2023. The received document identified a total two-hundred and fourteen (214) records of various industrial, light industrial and commercial activities within the Phase I Study area. A review of these activities concluded that a large majority consisted of light industrial and commercial activities were situated 130 m down gradient of the Phase I Property and are not considered to pose a risk to the Phase I Property. A total of one (1) on-site location and fifteen (15) off-site locations within 250 m of the Phase I Property were identified to be potentially contaminating activity. These activities are listed in Table 3 below. The distances/orientations with respect to the Phase I Property listed in Table 3 are based on depicted locations in the overview map provided by the City.

A copy of the City's response has been included in Appendix 2.

Table 3
HLUI Identified Activities

Address	Name / Activity	Distance / Orientation from site	Potential Environmental Concern (Y / N)
35 Laurel	Slater Bread Co – Gasoline (fuel storage tank)	On-Site	Y
53 Breezehill Avenue	Joseph Barrie, Bruce Coal Co, Bruce Fuels Ltd. / Lumber yard, underground storage tank - Gasoline and fuel oil	Adjacent to the north	**Y**
55 Breezehill Avenue	Various automotive businesses / Motor vehicle repair shops	37 m To the north	Y
73 Breezehill	Charcoal Supply Co./ Petroleum products	Adjacent to the north	**Y**
100 Breezehill Avenue	Devonshire Public School / Underground storage tank – Fuel oil	52 m To the west	N
111 Breezehill Avenue	907462 Ontario Ltd, Grandtech Auto / Motor vehicle repair shops	Adjacent to the west	**Y**
933 Gladstone Avenue	Multiple federal and commercial businesses / Commercial printing and manufacturing	70 m To the east	N
951 Gladstone Avenue	Various commercial and light industrial businesses / Gasoline, diesel and fuel oil storage tanks, manufacturing, commercial printing industries, chemical products and textiles product industries	150 m To the south	N
971 Gladstone Avenue	Mr. Gas Limited / Retail fuel outlet – gasoline	200 m To the south	N
975 Gladstone Avenue	British American Bank Note / Linseed oil, varsol, fuel oil storage tanks and commercial printing industries	81 m To the south	**Y**
Laurel and Loretta	Hall Fuel Co. / Fuel supply	50 m to the south	N

Table 3 (Continued)
HLUI Identified Activities

Address	Name / Activity	Distance / Orientation from site	Potential Environmental Concern (Y / N)
131 Loretta	Hall Fuel – Mccoll Frontenac Oil Co. / Underground storage tank - fuel oil	50 m to the south	N
145 Loretta	Bell Telephone Co. of Canada, Hall Fuel / Garage and underground storage tank - fuel oil	80 m To the south	N
1040 Somerset Street	Various automotive businesses / Motor vehicles repair shops	75 m To the north	N
1050 Somerset Street	Various automotive businesses / Underground storage tank and motor vehicles repair shops	80 m To the north west	N
1066 Somerset Street West	L. J. Corkery - Globe Oil Co / Gasoline storage tank	130 m To the north west	N

The former fuel storage located at 35 Laurel Street was associated with Slater Bread Co. This business was also identified in the 1935 City of Ottawa Directories, addressed 75 Breezehill Avenue. Based on a review of the HLUI records in conjunction with the City of Ottawa Directories, this former fuel storage was located on-site and is considered to represent an APEC with respect to the Phase I Property.

Due to its close proximity and the nature of the activity, the automotive garage located at 111 Breezehill Avenue is considered to represent an APEC with respect to the Phase I Property.

Due to its close proximity and the nature of the activity, the various automotive businesses/motor vehicle repair shops located at 55 Breezehill Avenue is considered to represent an APEC with respect to the Phase I Property

As previously noted in reviewed records identified in this investigation, the coal and chemical supplier identified at 53 and 73 Breezehill Avenue and historical printing activities the British American Bank Note Co. at 975 Gladstone Avenue are considered to represent APECs with respect to the Phase I Property.

City of Ottawa Old Landfill Sites

The document prepared by Golder Associates entitled, *"Old Landfill Management Strategy, Phase I - Identification of Sites, City of Ottawa"*, was reviewed as part of this assessment. This document identifies the details and locations of all recorded active and closed landfill sites situated in the City of Ottawa.

One (1) former landfill site was identified within 500 m of the Phase I Property. Site id UR-41 was a privately operated landfill with an approximated operation date prior to 1928. This landfill site is located approximately 200 m northwest of the Phase I Property. Based on the separation distance, this landfill site is not considered to have had the potential to impact to the Phase I Property.

ERIS Database Report

A database report, prepared by ERIS (Environmental Risk Information Services Ltd.), dated March 17, 2023, was acquired and reviewed as part of this assessment. This report provides a compilation of various provincial and federal environmental related records pertaining to any properties situated within the Phase I Study Area.

The complete ERIS report has been included in Appendix 2.

❑ On-Site Records:

The ERIS report identified ten (10) records associated with current and past activities on the Phase I Property. Five (5) waste generator records and five (5) manufacturing records were identified. A review of these records did not identify any waste products or manufacturing activities that are considered to have impacted the Phase I Property.

❑ Off-Site Records:

The ERIS report identified three-hundred and fifteen (315) records associated with the properties situated within the Phase I Study Area.

A large majority of the records identified in the report are composed of waste generator and manufacturing records from light industrial, manufacturing and commercial activities. A review of these records determined that the waste generators that pose a risk to the Phase I Property have already been identified from other previous historical record searches completed in this report. All other identified waste generator and manufacturing records are not considered to have

impacted the Phase I Property based on separation distance and down/cross gradient locations.

One (1) spill record of transformer oil was identified at 99 Breezehill Avenue. A total of five (5) litres of transformer oil were discharged to the soil and grass and were noted to be cleaned up following the equipment failure. Based on the limited quantity and clean up of the transformer oil, this record is not considered to have impacted the Phase I Property.

Various remaining records were also noted to be associated with activities identified in previous historical record searches completed in this report. Based on the nature of the activity, the significant separation distance, and/or the down-gradient or cross-gradient orientation with respect to anticipated groundwater flow to the northeast, the remaining off-site records are not considered to pose an environmental concern to the Phase I Property.

Previous Engineering Reports

No historical reports associated with the Phase I Property were available for review. Paterson has utilized in house assessments completed within the study area to reaffirm our findings of historical records and any potentially contaminating activities.

4.3 Physical Setting Sources

Historical aerial photographs of the Phase I Study Area were obtained from the National Air Photo Library and reviewed in approximate ten year intervals, beginning with the earliest available photograph.

Based on a review of these photographs, the following observations have been made:

1928 The Phase I Property, appears to be used as a storage yard and is occupied by a small commercial structure in the northeast corner of the property. The property to the north is occupied by a several commercial/industrial structures and the yard appears to be used for storage. The property to the south appears to be used as a storage yard. Property to the west is occupied by the Devonshire public school and to a railway line and spur line are present to the east.

1946 The Phase I Property appears to have been developed with an addition to the on-site commercial structure that extends further to the south from the original footprint. The property to the south appears to have been developed with a large industrial building and parking lot in addition to smaller industrial/commercial buildings. A large warehouse structure has been constructed to the east just beyond the railway line.

1958 No significant changes are apparent with respect to the Phase I Property. The adjacent properties to the west have been developed with residential structures.

1971 The Phase I Property appears to have been further developed with a second addition to the on-site commercial structure extending to the southern property line at Laurel Street. The industrial building to the south has been developed with an addition and larger parking lot.

1995 No significant changes are apparent with respect to the Phase I Property. The north adjacent property has been redeveloped with a commercial warehouse building. Some of the west adjacent residential properties have been redeveloped into commercial structures.

2007 No significant changes are apparent with respect to the Phase I Property or the surrounding lands since the time of the previous photograph.

2015 No significant changes are apparent with respect to the Phase I Property since the time of the previous photograph. The large warehouse structure to the east beyond the railway line has been demolished.

2021 No significant changes are apparent with respect to the Phase I Property since the time of the previous photograph. The railway line to the east has been removed and is under redevelopment of a new light rail line.

Copies of the aerial photographs selected for review are included in Appendix 1.

Water Bodies

No water bodies are present on the Phase I Property.

The nearest named water body with respect to the Phase I Property is the Ottawa River, located approximately 750 m to the North.

Geological Maps

Geological mapping information for the Phase I Property was obtained from The Geological Survey of Canada – Urban Geology of the National Capital Area and reviewed as part of this assessment.

Based on the available mapping information, the bedrock beneath the Phase I Property generally consists of interbedded limestone and shale of the Verulam Formation, while the surficial geology consists largely of Paleozoic rocks with an overburden ranging in thickness from approximately 2 m to 3 m.

Topographic Maps

A topographic map of the Phase I Property was obtained from the Natural Resources Canada – The Atlas of Canada website and reviewed as part of this assessment.

The topographic map indicates that the general elevation of the Phase I Property is approximately 70 m above sea level, while the regional topography within the greater area is depicted as sloping downwards to the north, in the general direction of the Ottawa River.

An illustration of the referenced topographic map is presented on Figure 2 – Topographic Map, appended to this report.

Physiographic Maps

A physiographic map was obtained from the Natural Resources Canada – The Atlas of Canada website and reviewed as a part of this assessment.

According to the publication and available mapping information, the Phase I Property is situated within the St. Lawrence Lowlands. According to the description provided: *"…the lowlands are plain-like areas that were affected by the Pleistocene glaciations and are therefore covered by surficial deposits and other features associated with the ice sheets."* The Phase I Property is specifically located within the Central St. Lawrence Lowland area, which is rarely more than 150 m above sea level.

MECP Water Well Records

A search of the MECPs website for all drilled well records within a 250 m radius of the Phase I Property was conducted as part of this assessment. The search identified fifty-nine (59) well records within the Phase I Study Area. These records pertain to wells installed between 2005 and 2021 and used for groundwater monitoring purposes. Based on the availability of municipal services, no drinking water wells are expected to be in use within the Phase I Study Area.

According to the well records, the overburden stratigraphy in the vicinity of the Phase I Property generally consists of fill material over silty clay. Bedrock was generally encountered at depths ranging from approximately 6 m below ground surface.

The identified well records have been included in Appendix 2.

5.0 INTERVIEWS

Property Owner Representative

Mr. Vince Della Penna, a representative of the property owner, was available at the time of the site inspection to respond to questioning about the environmental history of the Phase I Property.

According to Mr. Della Penna, the Phase I Property was purchased in approximately 1985 The property was previously and has continued to be used for commercial warehousing, commercial office space, storage, and light manufacturing purposes. Mr. Della Penna did not know the original date of construction of the building.

Since purchasing the property in approximately 1985, Mr. Della Penna stated that the subject building was heated via a natural gas fired system that was recently upgraded to a newer natural gas fired system in 2020. Mr. Della Penna was unaware of any environmental concerns pertaining to the current use of the Phase I Property. No previous environmental investigations or reports have been completed on the Phase I Property.

6.0 SITE RECONNAISSANCE

6.1 General Requirements

A site inspection was conducted for the Phase I Property on March 23, 2023, between 9:00 AM and 11:00 AM. Weather conditions were cloudy with rain, and a temperature of approximately -1°C. Mr. Mark St Pierre, from the Environmental Department of Paterson Group, conducted the inspection.

In addition to the Phase I Property, the uses of neighbouring properties within the Phase I Study Area were also assessed from publicly accessible locations at the time of the site inspection.

6.2 Specific Observations at the Phase I Property

Site Description

The Phase I Property is currently occupied with a two-storey mixed-use building, located in the eastern portion of the property, backing to the former railway line. A single sea can shipping container was located on the parking areas fronting Laurel Street. A large portion of the western parking lot is used for storage of a U-Haul rental vehicle fleet. The subject building consists of eight tenant spaces, while only one of them was vacant at the time of this assessment. The tenants consist of a mix of commercial retail, warehousing and storage.

The site topography is relatively flat, while the regional topography appears to slope down towards the north, in the general direction of the Rideau River. A railway line to the east of the property is situated at a deep depression within the regional area. The Phase I Property is considered to be at grade with respect to the adjacent streets and the neighbouring properties with the exception of the eastern railway line.

Water drainage on the Phase I Property occurs primarily via surface runoff towards catch basins located on the Phase I Property and neighbouring street. No ponded water, stressed vegetation, surficial staining, or any other indications of potential sub-surface contamination were observed on the Phase I Property at time of the site inspection.

A depiction of the Phase I Property is illustrated on Drawing PE6049-1 – Site Plan, in the Figures section of this report.

Buildings and Structures

At the time of the site inspection, the Phase I Property was occupied with a two-storey mixed-use building. The original building was built prior to 1928 with a single basement level mechanical room and has received two additions to the south of the original building. The subject building is constructed with a poured concrete foundation, and is finished on the exterior with stucco siding, in addition to a flat tar and gravel roof. The subject building is currently heated via natural gas-fired equipment, within each tenant unit.

Potential Environmental Concerns

- **Fuels and Chemical Storage**

  At the time of the site inspection, no chemical storage areas, vent and fill pipes, above ground fuel storage tanks (ASTs), or evidence indicating the presence of any underground fuel storage tanks (USTs) were observed on the Phase I Property.

- **Hazardous Materials and Unidentified Substances**

  At the time of the site inspection, no hazardous materials, unidentified substances, spills, surficial staining, abnormal odours, stressed vegetation, or any other indications of potential sub-surface contamination were observed on the Phase I Property.

- **Polychlorinated Biphenyls (PCBs) and Transformer Oil**

  At the time of the site inspection, only dry-cell electrical transformers were identified on the Phase I Property. With the exception of fluorescent light ballasts that were observed throughout the building no other potential sources of PCBs or transformer oil were identified on the Phase I Property.

- **Waste Management**

  At the time of the site inspection, solid, non-hazardous domestic waste and recyclable products were observed to be stored in plastic and metals bins on the south east side of the subject building. No environmental concerns were noted with respect to waste management practices on the Phase I Property.

Interior Assessment

A general description of the interior of the subject building is as follows:

- ❑ The floors consist of poured concrete and vinyl floor tiles;
- ❑ The walls consist of drywall and concrete block walls;
- ❑ The ceilings consist of drywall and open steel joist framing;
- ❑ Lighting throughout the building is provided by incandescent, and fluorescent light fixtures.

Potentially Hazardous Building Products

❑ **Asbestos-Containing Materials (ACMs)**

Based on the age of the subject building, asbestos containing building materials may be potentially present within the structure. Potential ACMs observed inside the subject building include the drywall joint compound, pipe fitting and pipe run insulation, and the vinyl floor tiles.

These potential ACMs were observed to be in good condition at the time of the site inspection and do not represent an immediate concern to the building's occupants.

❑ **Lead-Based Paints**

Based on the age of the subject building, lead-based paints may be present inside the structure, on any original or older painted surfaces. Painted surfaces were generally observed to be in good condition at the time of the site inspection and do not represent an immediate concern to the occupants.

❑ **Polychlorinated Biphenyls (PCBs) and Transformer Oil**

At the time of the site inspection, no potential sources of PCBs were identified inside the subject building.

❑ **Urea Formaldehyde Foam Insulation (UFFI)**

At the time of the site inspection, UFFI was not observed inside the subject building, however, wall cavities were not exposed to allow for the inspection of insulation type.

Other Potential Environmental Concerns

❑ Interior Fuel and Chemical Storage

At the time of the site inspection, no aboveground fuel storage tanks or signs of underground fuel storage tanks were observed within the subject building.

Chemical products identified in the subject building were observed to be predominantly limited to domestically available cleaning products, stored properly in their original containers.

❑ Ozone Depleting Substances (ODSs)

Potential sources of ODSs observed on-site include fire extinguishers, air conditioners, freezers and refrigerators. These appliances appeared to be in good condition at the time of the site inspection and should be regularly serviced by a licensed contractor.

❑ Wastewater Discharges

Wastewater from the subject building (wash water and sewage) is discharged into the City of Ottawa sanitary sewer system, and stormwater runoff is discharged via catch basins located in the parking lot areas and the adjacent streets, which drain into the City of Ottawa storm water sewer system.

A floor drain was observed on the floor slabs of all subject building, in which no water was observed at the time of the site inspection.

A sump pump and pit were observed in the basement of the original building structure. Water present in the sump pit was noted to be clear with no olfactory observations.

No potential environmental concerns were identified with respect to the wastewater discharges of the Phase I Property.

Neighbouring Properties

At the time of the site inspection, a survey of the neighbouring properties was conducted from publicly accessible roadways.

Land use adjacent to the Phase I Property was observed as follows:

North: A commercial structure with parking lot, followed by an automotive service garage.

South: Laurel Street, followed by the Canadian Bank Noted limited printing facility.

East: The O-Train LRT line (under construction), followed by a vacant parking lot and grass land area.

West: Residential, commercial, and an automotive garage followed by Breezehill Avenue.

As previously noted in reviewed records identified in this investigation, the automotive garage located at 111 Breezehill Avenue is considered to represent APECs with respect to the Phase I Property.

The neighbouring land use within the Phase I Study Area is depicted on Drawing PE6049-2 – Surrounding Land Use Plan, in the Figures section of this report.

7.0 REVIEW AND EVALUATION OF INFORMATION

7.1 Land Use History

Based on a review of available historical information, the land use history of the Phase I Property is summarized below in Table 4.

Table 4
Land Use History – 75 Breezehill Avenue, Ottawa, Ontario

Time Period	Land Use	Description	Other Observations from Aerial Photos, FIPs, etc
Prior to 1928	Unknown	Vacant	1912 FIP depict the Phase I Property as vacant.
1928 – Present	Commercial	Slater Bread Co., Sparks and Son Warehouse, Breezehill heating, Capital self storage & Uhaul,	1928 aerial photograph depicts the first development on the Phase I Property. FIPs and city directories indicated the presence of various commercial businesses, retail business, warehousing and office space.

Potentially Contaminating Activities (PCAs) and Areas of Potential Environmental Concern

Based on the findings of the Phase I ESA, six potentially contaminating activities (PCAs), resulting in areas of potential environmental concern (APECs), were identified on the Phase I Property.

As per Table 2 – Column A of O. Reg. 153/04, as amended, the PCAs resulting in APECs on the Phase I Property are described as follows:

- PCA 28: Gasoline and associated products storage in fixed tanks, associated with a former fuel storage located on the original two-storey commercial building located at the northeast corner of the Phase I Property. (APEC #1).
- PCA Other: "Use of Road Salt for Deicing," across the Phase I ESA Property (APEC #2)
- PCA 30: Importation of Fill Material of Unknown Quality; associated with the possible presence of poor quality fill material located associated with the multiple additions and regrading of the parking lot located in the western portion of the Phase I Property. (APEC #3)

- ❒ Item 52: Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems; associated with the presence of an existing off-site auto service garage at 111 Breezehill Avenue L, located adjacent to the west of the Phase I Property. (APEC #4)

- ❒ Item 31: Ink manufacturing, processing and bulk storage; associated with the presence of the Canadian Bank Note Limited (formerly British American Bank Note Co.), located 80 m to the south of the Phase I Property. (APEC #5)

- ❒ Item N/A: Former fuel/coal company located north of the Phase I Property. Transfer and storage of coal fuel, possible leakage of storage tanks/containers and discharge of coal petroleum hydrocarbons (APEC#6).

- ❒ Item 52: Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems; associated with various automotive businesses/motor vehicle repair shops located at 55 Breezehill Avenue. (APEC#7)

Although not identified as a specific PCA in Table 2, the application of deicing salts for vehicular and pedestrian safety is also considered to represent an APEC (APEC #2) on the Phase I ESA Property. Based on the findings of the Phase I ESA, it is considered likely that road salt was applied to the surface of the walkways, paved access lane and parking lot across the Phase I ESA Property for the safety of vehicular and pedestrian traffic under conditions of ice and/or snow.

According to Section 49.1 of O.Reg. 153/04, if an applicable site condition standard is exceeded at a property solely because of the following reason, the applicable site condition standard is deemed not to be exceeded for the purpose of Part XV.1 of the Act: “The qualified person has determined, based on a phase one environmental site assessment or a phase two environmental site assessment, that a substance has been applied to surfaces for the safety of vehicular or pedestrian traffic under conditions of snow or ice or both.”

In accordance with Section 49.1 of O.Reg. 153/04, any EC and SAR concentrations on the Phase I ESA Property that may exceed the MECP Table 3 standards for a residential/institutional land use are deemed not to be exceeded for the purpose of Part XV.1 of the Act.

The APECs are shown on Drawing PE6049-1 – Site Plan, while the corresponding PCAs are shown in red on Drawing PE6049-2 – Surrounding Land Use Plan.

The remaining off-site PCAs identified within the Phase I Study Area were not considered to result in APECs based on their separation distances and/or orientations (down or cross-gradient) with respect to the Phase I ESA Property. These PCAs are identified in green on Drawing PE6049-2– Surrounding Land Use Plan.

Contaminants of Potential Concern (CPCs)

The contaminants of potential concern (CPCs) associated with the aforementioned APECs are considered to be:

- ❒ Benzene, Ethylbenzene, Toluene, and Xylenes (BTEX);
- ❒ Volatile Organic Compounds (VOCs);
- ❒ Petroleum Hydrocarbons, fractions 1 – 4 (PHCs F_1-F_4);
- ❒ Polycyclic Aromatic Hydrocarbons (PAHs);
- ❒ Mercury (Hg^+)
- ❒ Hexavalent Chromium (Cr^{VI})

These CPCs have the potential to be present in the soil matrix and/or the groundwater situated beneath the Phase I Property.

7.2 Conceptual Site Model

Geological and Hydrogeological Setting

Based on the available mapping information, the bedrock beneath the Phase I Property generally consists of interbedded limestone and shale of the Verulam Formation, while the surficial geology consists largely of paleozoic rocks with an overburden ranging in thickness from approximately 2 m to 3 m.

Groundwater is anticipated to be encountered within the overburden and flow in a north easterly direction towards the Rideau River.

Water Bodies and Areas of Natural and Scientific Interest

No water bodies or areas of natural and scientific interest were identified within the Phase I Study Area. The nearest named water body with respect to the Phase I Property is the Ottawa River, located approximately 750m to the north.

Drinking Water Wells

Based on the availability of municipal services, no drinking water wells are expected to be present within the Phase I Study Area.

Existing Buildings and Structures

The Phase I Property is currently occupied with a two-storey commercial warehouse building, that is composed of two additions to the original building. A single basement level is present in the footprint of the original building to the north.

Current and Future Property Use

The Phase I Property is currently being used for commercial office space, commercial warehousing purposes and storage.

It is our understanding that the Phase I Property is to be redeveloped with two multi-storey residential apartment buildings.

Neighbouring Land Use

The surrounding lands within the Phase I Study Area consist largely of commercial and industrial properties, with the exception of some residential land to the east, across Breezehill Avenue.

Current land use is depicted on Drawing PE6049-2 – Surrounding Land Use Plan, in the Figures section of this report.

Potentially Contaminating Activities and Areas of Potential Environmental Concern

As per Section 7.1 of the Phase I ESA report, five potentially contaminating activities (PCAs), resulting in areas of potential environmental concern (APECs), are summarized in Table 5, along with their respective locations and contaminants of potential concern (CPCs):

Table 5
Areas of Potential Environmental Concern

Area of Potential Environmental Concern	Location of APEC on Phase I Property	Potentially Contaminating Activity (Table 2 – O. Reg. 153/04)	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern	Media Potentially Impacted (Groundwater, Soil, and/or Sediment)
APEC #1 Former Fuel Storage Tank	Northeastern portion/original two-storey commercial building	*"Gasoline and Associated Products Storage and Fixed Tanks"*	On-Site	VOCs BTEX PHCs(F_1-F_4)	Soil and Groundwater
APEC #2 Possible Use of Road Salt for De-Icing Purposes	Parking lot	*"Item N/A: Use of de-icing salt for safety purposes during snow and ice conditions"*	On-Site	EC SAR	Soil
APEC #3 Fill Material of Unknown Quality	Parking lot	*"Item 30: Importation of Fill Material of Unknown Quality"*	On-Site	PAHs Metals	Soil
APEC #4 Existing Automotive Garage	Western portion of parking lot area of Phase I Property	*"Item 52: Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems"*	Off-Site	VOCs BTEX PHCs (F_1-F_4)	Soil and Groundwater
APEC #5 Existing printing facility	Southern portion of Phase I Property	*"Item 31: Ink Manufacturing Processing and Bulk Storage""*	Off-Site	VOCs	Groundwater
APEC #6 Former Coal Fuel Storage and Supplier	Northern portion of Phase I Property	*"Item Other: Former fuel/coal company located north of the Phase I Property. Transfer and storage of coal fuel, possible leakage of storage tanks/containers and discharge of coal petroleum hydrocarbons"*	Off-Site	VOCs BTEX PHCs (F_1-F_4) PAHs Metals Hg CrVI	Soil and Groundwater
APEC #7 Various automotive businesses / motor vehicle repair shops	Northern portion of Phase I Property	*"Item 52: Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems"*	Off-Site	VOCs BTEX PHCs (F1-F4)	Soil and Groundwater

Based on the findings of this assessment, it is understood a substance has been applied to surfaces of the Phase I ESA Property for the safety of vehicular or pedestrian traffic under conditions of snow or ice or both.

In accordance with Section 49.1 of O.Reg. 153/04, any EC and SAR concentrations on the RSC Property that exceed the MECP Table 3 standards for a residential/institutional land use are deemed not to be exceeded for the purpose of Part XV.1 of the Act. This exemption is being relied on for APEC 1.

Other off-site PCAs were identified within the Phase I Study Area but were deemed not to be of any environmental concern to the Phase I Property based on their separation distances as well as their inferred down-gradient or cross-gradient orientation with respect to anticipated groundwater flow to the west.

Contaminants of Potential Concern

The contaminants of potential concern (CPCs) associated with the aforementioned APECs are considered to be:

- Benzene, Ethylbenzene, Toluene, and Xylenes (BTEX);
- Volatile Organic Compounds (VOCs);
- Petroleum Hydrocarbons, fractions 1 – 4 (PHCs F_1-F_4);
- Polycyclic Aromatic Hydrocarbons (PAHs);
- Mercury (Hg^+)
- Hexavalent Chromium (Cr^{VI})

These CPCs have the potential to be present in the soil matrix and/or the groundwater situated beneath the Phase I Property.

Assessment of Uncertainty and/or Absence of Information

The information available for review as part of the preparation of this Phase I ESA is considered to be sufficient to conclude that there are PCAs and APECs associated with the Phase I Property.

The presence of any PCAs was confirmed by a variety of independent sources, and as such, the conclusions of this report are not affected by uncertainty which may be present with respect to the individual sources.

8.0 CONCLUSIONS

8.1 Assessment

Paterson Group was retained by Mr. Thomas Freeman to conduct a Phase I – Environmental Site Assessment (Phase I ESA) for 75 Breezehill Avenue , Ottawa, Ontario. The purpose of this Phase I ESA was to research the past and current use of the site (Phase I Property) and 250 m study area (Phase I Study Area) and to identify any environmental concerns with the potential to have impacted the Phase I property.

According to the historical research, the Phase I Property was utilized for commercial purposes as early as 1928 with a single commercial structure. Historical records indicated a commercial business in the 1930's utilized onsite gasoline storage of an unknown quantity. The commercial structure had undergone construction of two additions in approximately the 1940's and 1960's. respectively. The Phase I Property continues to be used for commercial purposes at this present time. Based on the construction of these additions in addition to the construction of the parking lot, fill material of unknown quality is expected to be present on the western portion of the Phase I Property. These potentially contaminating activity (PCA) are considered to represent an area of potential environmental concern (APEC) on the Phase I Property.

The historical use of the surrounding properties within the Phase I Study Area were developed for industrial, commercial, and residential purposes. Several historical off-site potentially contaminating activities (PCAs) were identified within the Phase I Study Area. Historical records identified the presence of a former coal fuel/lumber storage yard and various automotive businesses/motor vehicle repair shops adjacent to the north of the Phase I Property and a printing facility to the south of the Phase I Property at 975 Gladstone Avenue. Based on orientation and/or separation distances, all other off-site PCAs are not considered to represent APECs on the Phase I ESA Property.

Presently, the Phase I Property is occupied with a two-storey mixed-use building, located in the eastern portion of the site, adjacent to the former railway line. The building is occupied by various tenants that consist of commercial offices, commercial warehousing, and storage. A U-Haul rental fleet occupies a majority of the western parking lot. This paved parking lot is use by tenants and customers of the occupied units. It is expected that the use of road salt as a

deicing agent was identified as PCA resulting in an APEC. Otherwise, no PCAs were identified on the Phase I ESA Property.

Neighbouring land use in the Phase I Study Area consists primarily of industrial commercial with some residential. An active automotive garage is located adjacent to the Phase I Property located at 111 Breezehill Avenue. This off-site PCA is considered to represent and APEC to the Phase I Property.

8.2 Recommendations

Phase II – Environmental Site Assessment

Based on the findings of this assessment, it is our opinion that **a Phase II – Environmental Site Assessment will be required for the Phase I Property.**

Designated Substance Survey

Based on the age of the subject building (c.1950's), asbestos containing building materials, lead-based paints, and other hazardous building materials may be potentially present within the structure. It is recommended that a designated substance survey (DSS) be completed for the subject building prior to any proposed demolition activities.

9.0 STATEMENT OF LIMITATIONS

This Phase I – Environmental Site Assessment report has been prepared in general accordance with O.Reg. 153/04, as amended, and meets the requirements of CSA Z768-01 (reaffirmed 2016). The conclusions presented herein are based on information gathered from a limited historical review and field inspection program. The findings of the Phase I ESA are based on a review of readily available geological, historical, and regulatory information as well as a cursory review made at the time of the field assessment. The historical research relies on information supplied by others, such as local, provincial, and federal agencies and was limited within the scope-of-work, time, and budget of the project herein.

Should any conditions be encountered at the Phase I Property and/or historical information that differ from our findings, we request that we be notified immediately in order to allow for a reassessment.

This report was prepared for the sole use of 2729685 Ontario Inc. c/o Fotenn. Permission and notification from 2729685 Ontario Inc. c/o Fotenn and Paterson Group will be required prior to the release of this report to any other party.

Paterson Group Inc.



Mark St Pierre, P.Eng.



Michael Beaudoin, P.Eng., QP_{ESA}

Report Distribution:

- ❑ 2729685 Ontario Inc. c/o Fotenn
- ❑ Paterson Group Inc.

10.0 REFERENCES

Federal Records

- ❒ Natural Resources Canada: Air Photo Library.
- ❒ Natural Resources Canada: The Atlas of Canada.
- ❒ Geological Survey of Canada: Surficial and Subsurface Mapping.
- ❒ Environment Canada: National Pollutant Release Inventory.
- ❒ National Archives of Canada.

Provincial Records

- ❒ MECP: Freedom of Information and Privacy Office.
- ❒ MECP: Municipal Coal Gasification Plant Site Inventory, 1991.
- ❒ MECP: Waste Disposal Site Inventory, 1991.
- ❒ MECP: Brownfields Environmental Site Registry.
- ❒ MECP: Water Well Inventory.
- ❒ MECP: Ontario PCB Waste Storage Site Inventory, 1995.
- ❒ Office of Technical Standards and Safety Authority, Fuels Safety Branch.
- ❒ Ministry of Natural Resources and Forestry Areas of Natural Significance.
- ❒ Chapman, L.J., and Putnam, D.F., 1984: 'The Physiography of Southern Ontario, Third Edition', Ontario Geological Survey Special Volume 2.

Municipal Records

- ❒ City of Ottawa: GeoOttawa
- ❒ City of Ottawa: Historical Land Use Inventory Database
- ❒ City of Ottawa: document entitled, "Old Landfill Management Strategy, Phase I – Identification of Sites", prepared by Golder Associates, 2004.

Local Information Sources

- ❒ Personal Interviews.
- ❒ Previous Engineering Reports.

Public Information Sources

- ❒ ERIS Database Report.
- ❒ Google Earth.
- ❒ Google Maps/Street View.

FIGURES

FIGURE 1 – KEY PLAN

FIGURE 2 – TOPOGRAPHIC MAP

DRAWING PE6049-1 – SITE PLAN

DRAWING PE6049-2 – SURROUNDING LAND USE PLAN




FIGURE 1

KEY PLAN

PATERSON GROUP





FIGURE 2

TOPOGRAPHIC MAP



AREAS OF POTENTIAL ENVIRONMENTAL CONCERN :

ID#	PCA ID	DESCRIPTION
1)	28	FORMER FUEL STORAGE (SLATER BREAD CO)
2)	OTHER	ESC / SAR IMPACTED FILL MATERIAL
3)	30	FILL MATERIAL OF UNKNOWN QUALITY
4)	52	AUTOMOTIVE SERVICE GARAGE (GRANDTECH AUTO)
5)	31	PRINTING FACILITY (CANADIAN BANK NOTES)
6)	OTHER	FORMER COAL FUEL SUPPLIERS
7)	52	AUTOMOTIVE SERVICE GARAGE (VARIOUS AUTOMTOIVE BUSINESS / MOTOR VEHICLE REPAIR SHOPS)

SCALE: 1:750

0 10 20 30 50m

PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

NO.	REVISIONS	DATE	INITIAL

2729685 ONTARIO INC.

PHASE I - ENVIRONMENTAL SITE ASSESSMENT
75 BREEZEHILL AVENUE NORTH

OTTAWA, ONTARIO


Title:

SITE PLAN

Scale: 1:750	Date: 05/2023
Drawn by: YA	Report No.: PE6049-1
Checked by: MSP	Dwg. No.: PE6049-1
Approved by: MSD	Revision No.:

11x17

p:\autocad drawings\environmental\pe60xx\pe6049\pe6049-1-site plan.dwg



POTENTIALLY CONTAMINATING ACTIVITES :

ID#	PCA ID	DESCRIPTION
1)	28	FORMER FUEL STORAGE (SLATER BREAD CO)
2)	OTHER	ESC / SAR IMPACTED FILL MATERIAL
3)	30	FILL MATERIAL OF UNKNOWN QUALITY
4)	52	AUTOMOTIVE SERVICE GARAGE (GRANDTECH AUTO)
5)	31	PRINTING FACILITY (CANADIAN BANK NOTES)
6)	OTHER	FORMER COAL FUEL SUPPLIERS
7)	52	VARIOUS AUTOMTOIVE BUSINESS / MOTOR VEHICLE REPAIR SHOPS
8)	46	FORMER RAIL WAY LINE
9)	28	FORMER FUEL SUPPLIER
10)	28	FURNACE FUEL UNDERGROUND STORAGE TANK
11)	52	FORMER AUTOMOTIVE GARAGE
12)	28	UNDERGROUND STORAGE TANK
13)	20	FORMER ORDINANCE DEPOT
14)	OTHER	FORMER COAL STORAGE
15)	OTHER	FORMER COAL STORAGE
16)	52	FORMER AUTOMOTIVE GARAGE
17)	52	FORMER AUTOMOTIVE GARAGE
18)	52	FORMER AUTOMOTIVE GARAGE
19)	37	FORMER DRY CLEANERS
20)	59	FORMER LUMBER STORAGE YARD
21)	37	FORMER DRY CLEANERS
22)	31	FORMER PRINTING FACILITY
23)	28	FORMER RETAIL FUEL OUTLET
24)	OTHER	FORMER LANDFILL
25)	18	ELECTRICAL TRANSFORMER STATION

SCALE: 1:3000

0 25 50 75 100 125 150 200m

PATERSON GROUP
9 AURIGA DRIVE
OTTAWA, ON
K2E 7T9
TEL: (613) 226-7381

NO.	REVISIONS	DATE	INITIAL

2729685 ONTARIO INC.

PHASE I - ENVIRONMENTAL SITE ASSESSMENT
75 BREEZEHILL AVENUE NORTH
OTTAWA, ONTARIO

Title:

SURROUNDING LAND USE PLAN

Scale: 1:3000	Date: 05/2023
Drawn by: YA	Report No.: PE6049-1
Checked by: MSP	Dwg. No.: PE6049-2
Approved by: MSD	Revision No.:


11x17

p:\autocad drawings\environmental\pe60xx\pe6049\pe6049-2-surrounding land use plan.dwg

APPENDIX 1


AERIAL PHOTOGRAPHS

SITE PHOTOGRAPHS




AERIAL PHOTOGRAPH
1928

PATERSON GROUP



AERIAL PHOTOGRAPH
1946

PATERSON GROUP




AERIAL PHOTOGRAPH
1958

PATERSON GROUP



AERIAL PHOTOGRAPH
1971

PATERSON GROUP



AERIAL PHOTOGRAPH
1995

PATERSON GROUP



AERIAL PHOTOGRAPH
2007

PATERSON GROUP



AERIAL PHOTOGRAPH
2015

PATERSON GROUP



AERIAL PHOTOGRAPH
2021

PATERSON GROUP

Site Photographs

PE6049 | 75 Breezehill Avenue, Ottawa, Ontario | March 23, 2023



Photograph 1: View of the Phase I Property, facing northwest from McGee Side Road



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.

Site Photographs

PE6049 | 75 Breezehill Avenue, Ottawa, Ontario | March 23, 2023



Photograph 1: View of the Phase I Property, facing northwest from McGee Side Road



Photograph 1: View of the Phase I Property, facing northwest from McGee Side Road

Site Photographs


PE6049 | 75 Breezehill Avenue, Ottawa, Ontario | March 23, 2023



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.




Photograph 1: View of the Phase I Property, facing northwest from McGee Side Road




Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.




Photograph 1: View of the Phase I Property, facing northwest from McGee Side Road



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.

Site Photographs

PE6049 | 75 Breezehill Avenue, Ottawa, Ontario | March 23, 2023



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.



Photograph 2: View of the Phase I Property and west adjacent property, facing South West from John Cavanaugh Drive.

APPENDIX 2

MECP FREEDOM OF INFORMATION RESPONSE

MECP WATER WELL RECORDS

TSSA CORRESPONDENCE

CITY OF OTTAWA HLUI RESPONSE

ERIS DATBASE REPORT

Ministry of the Environment, Conservation and Parks

Access and Privacy Office

12th Floor
40 St. Clair Avenue West
Toronto ON M4V 1M2
Tel: (416) 314-4075

Ministère de l'Environnement, de la Protection de la nature et des Parcs

Bureau de l'accès à l'information et de la protection de la vie privée

12e étage
40, avenue St. Clair ouest
Toronto ON M4V 1M2
Tél. : (416) 314-4075

Ontario

March 31, 2023

Mark ST PIERRE
Paterson Group
9 Auriga Drive
Ottawa, Ontario K2E 7T9
mstpierre@patersongroup.ca

Dear Mark ST PIERRE:

RE: **MECP FOI A-2023-01868, Your Reference PE6049 – Decision Letter**

This letter is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to 75 Breezehill Avenue, Ottawa.

After a thorough search through the files of the ministry's Ottawa District Office, Environmental Assessment and Permissions Division (EAPD), Environmental Monitoring and Reporting Branch (EMRB), Environmental Investigations and Enforcement Branch (EIEB), and Safe Drinking Water Branch (SDW) no records were located responsive to your request. **This file is now closed.**

You may request a review of my decision within 30 days from the date of this letter by contacting the Information and Privacy Commissioner/Ontario at http://www.ipc.on.ca. Please note there may be a fee associated with submitting the appeal.

If you have any questions, please contact Dany Briollais at 416-319-7739 or Dany.Briollais@ontario.ca.

Yours truly,

ORIGINAL SIGNED BY

Ryan Gunn
Manager (A), Access and Privacy Office

Ontario | Ministry of the Environment

Well Tag Number (Pl) A011954

A011954

Well Record

Regulation 903 Ontario Water Resources Act

page 1 of 7

Instructions for Completing Form

- For use in the **Province of Ontario** only. This document is a permanent **legal** document. Please retain for future reference.
- All Sections **must** be completed in full to avoid delays in processing. Further instructions and explanations are available on the back of this form.
- Questions regarding completing this application can be directed to the Water Well Management Coordinator at 416-235-6203.
- **All metre measurements shall be reported to 1/10th of a metre.**
- Please print clearly in blue or black ink only.

Ministry Use Only

MUN | CON | LOT

Well Owner's Information and Location of Well Information

First Name: Public Works Government Services | Last Name: Canada | Mailing Address (Street Number/Name, RR, Lot, Concession): 1451 Coldrey Street.

County/District/Municipality | Township/City/Town/Village: Ottawa | Province: Ontario | Postal Code: K1A 0S5 | Telephone Number (include area code): 1-[illegible]-[illegible]-6099

Address of Well Location (County/District/Municipality): Ottawa | Township: Ottawa - Carleton | Lot | Concession

RR#/Street Number/Name: 1010 Somerset Street West. | City/Town/Village: Ottawa | Site/Compartment/Block/Tract etc.

GPS Reading: NAD 83 | Zone 18 | Easting 443960 | Northing 5028100 | Unit Make/Model | Mode of Operation: ☐ Undifferentiated ☐ Averaged ☐ Differentiated, specify

Log of Overburden and Bedrock Materials (see instructions)

General Colour	Most common material	Other Materials	General Description	Depth From	Depth To (Metres)
	5 Monitoring wells as a Cluster - See Attached B.H. Logs.				

Hole Diameter

Depth From	Metres To	Diameter Centimetres
See Attached B.H. Logs		

Water Record

Water found at ___ Metres / Kind of Water

- ___ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals ☐ Other:
- ___ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals ☐ Other:
- ___ m ☐ Fresh ☐ Sulphur ☐ Gas ☐ Salty ☐ Minerals ☐ Other:

After test of well yield, water was ☐ Clear and sediment free ☐ Other, specify

Chlorinated ☐ Yes ☑ No

Construction Record

Inside diam centimetres	Material	Wall thickness centimetres	Depth From	Depth To (Metres)
Casing				
5" Cas.	☐ Steel ☐ Fibreglass ☑ Plastic ☐ Concrete ☐ Galvanized	Schedule 40	See Attached Drawings	
	☐ Steel ☐ Fibreglass ☐ Plastic ☐ Concrete ☐ Galvanized			
	☐ Steel ☐ Fibreglass ☐ Plastic ☐ Concrete ☐ Galvanized			
Screen				
Outside diam 6.5 cm	☐ Steel ☐ Fibreglass ☑ Plastic ☐ Concrete ☐ Galvanized	Slot No. #10	See Attached Drawings	
No Casing or Screen				
	☐ Open hole			

Test of Well Yield

Pumping test method

	Draw Down Time min	Draw Down Water Level Metres	Recovery Time min	Recovery Water Level Metres
Pump intake set at - (metres)	Static Level			
Pumping rate - (litres/min)	1		1	
Duration of pumping ___ hrs + ___ min	2		2	
Final water level end of pumping ___ metres	3		3	
Recommended pump type. ☐ Shallow ☐ Deep	4		4	
Recommended pump depth. ___ metres	5		5	
Recommended pump rate. (litres/min)	10		10	
If flowing give rate - (litres/min)	15		15	
If pumping discontinued, give reason.	20		20	
	25		25	
	30		30	
	40		40	
	50		50	
	60		60	

Plugging and Sealing Record

☐ Annular space ☐ Abandonment

Depth set at - Metres From	To	Material and type (bentonite slurry, neat cement slurry) etc.	Volume Placed (cubic metres)
		See Attached Installation Drawings	

Method of Construction

☐ Cable Tool ☐ Rotary (air) ☐ Diamond ☐ Digging
☐ Rotary (conventional) ☑ Air percussion ☐ Jetting ☑ Other Auger
☐ Rotary (reverse) ☐ Boring ☑ Driving

Water Use

☐ Domestic ☐ Industrial ☐ Public Supply ☑ Other Sample wells
☐ Stock ☐ Commercial ☐ Not used
☐ Irrigation ☐ Municipal ☐ Cooling & air conditioning

Final Status of Well

☐ Water Supply ☐ Recharge well ☐ Unfinished ☐ Abandoned, (Other)
☑ Observation well ☐ Abandoned, insufficient supply ☐ Dewatering
☐ Test Hole ☐ Abandoned, poor quality ☐ Replacement well

Well Contractor/Technician Information

Name of Well Contractor: George Downing Estate Drilling Ltd | Well Contractor's Licence No.: 1844.

Business Address (street name, number, city etc.): 410 Main St, Granville Sur La Rouge

Name of Well Technician (last name, first name): Downing Bruce | Well Technician's Licence No.: T2173

Signature of Technician/Contractor: X Bruce Downing | Date Submitted YYYY MM DD: 05 02 03

Location of Well

In diagram below show distances of well from road, lot line, and building. Indicate north by arrow.

See Attached Site Plan.

Audit No. Z 20840 | Date Well Completed YYYY MM DD: 04 08 18

Was the well owner's information package delivered? ☐ Yes ☑ No | Date Delivered YYYY MM DD

Ministry Use Only


Data Source | Contractor: 1844

Date Received YYYY MM DD: MAR 22 2005 | Date of Inspection YYYY MM DD

Remarks | Well Record Number

0506E (09/03) Contractor's Copy ☐ Ministry's Copy ☑ Well Owner's Copy ☐

Cette formule est disponible en français



Trow Associates Inc.
154 Colonnade Road South, Ottawa, Ontario K2E 7J5
Tel: (613) 225-9640
Fax: (613) 225-7337

SCALE 1:2,000	PUBLIC WORKS AND GOVERNMENT SERVICES CANADA PLOUFFE PARK (DFRP#08830)	JOB NO OTEN00015305 V
DATE: JAN 2005	TITLE: CURRENT/HISTORIC DRILLING PROGRAM	FIG 5
DRAWN RG		

Z 20840 1844

MAR 2 2 2005

Ontario Ministry of the Environment

Well Tag No. for Master Well *(Place Sticker and/or Print Below)*
A 074574 BH#10

Master Well Record for Cluster Well Construction

Regulation 903 Ontario Water Resources Act

Page 1 of 2

Master Well Owner's and Land Owner's Information

First Name	Last Name	E-mail Address
Freedman Holdings		

Mailing Address (Street Number/Name, RR)	Municipality	Province	Postal Code	Telephone No. *(inc. area code)*
1 Nicholas Street Suite 1516	Ottawa	ON	K1N7B7	6137598383

Location and Construction of the Master Well in the Cluster

Address of Well Location (Street Number/Name, RR)	Township	Lot	Concession
250, 270, 290 City Centre Ave			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	GPS Unit Make	Model	Mode of Operation
NAD 83	18	443756	5028682	Garmin	Map 76Am	☐ Undifferentiated ☑ Averaged ☐ Differentiated, specify

Overburden and Bedrock Materials *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (Metres) From	Depth (Metres) To
Grey	Asphaltic concrete	crushed stone		0	0.2
Brown	Fill	sand + gravel		0.2	1.67
DK Brown	Peat	organic matter		1.67	2.29
Grey/Brown	Silty clay			2.29	3.20
Grey	glacial till	silty sand & gravel		3.20	5.18

Hole Details

Depth (Metres) From	Depth (Metres) To	Diameter (Centimetres)
0	5.18	20

Water Use

☐ Public ☐ Industrial ☐ Not used ☐ Other, *specify*
☐ Domestic ☐ Commercial ☐ Dewatering
☐ Livestock ☐ Municipal ☑ Monitoring
☐ Irrigation ☐ Test Hole ☐ Cooling & Air Conditioning

Method of Construction

☐ Cable Tool ☐ Air Percussion ☐ Digging
☐ Rotary (Conventional) ☐ Diamond ☐ Boring
☐ Rotary (Reverse) ☐ Jetting ☑ Other, *specify* HSA
☐ Rotary (Air) ☐ Driving

Status of Well

☑ Test Hole ☐ Abandoned, Insufficient Supply
☐ Replacement Well ☐ Abandoned, Poor Water Quality
☐ Dewatering Well ☐ Other, *specify*
☐ Alteration (Construction) ☐ Abandoned, other, *specify*

Construction Details

Inside Diameter (Centimetres)	Material (steel, plastic, fibreglass, concrete, galvanized)	Wall Thickness	Depth (Metres) From	Depth (Metres) To
5.1	PVC	sched 40	0	2.0

No Casing and Screen Used

Open Hole ☐ Yes ☑ No

Static Water Level Test

2.5 Metres

Screen

☐ Galvanized ☐ Steel ☐ Fibreglass ☐ Concrete ☑ Plastic

Outside Diameter (Centimetres)	Slot No.
5.8	10

Annular Space/Abandonment Sealing Record

Depth Set at (Metres) From	Depth Set at (Metres) To	Type of Sealant Used (Material and Type)	Volume Used (Cubic Metres)
1.3	1.8	Bentonite	22 Kgs

Water Details

Water found at Depth		Kind of Water
Metres	☐ Gas	☐ Fresh ☐ Salty ☐ Sulphur ☐ Minerals
Metres	☐ Gas	☐ Fresh ☐ Salty ☐ Sulphur ☐ Minerals
Metres	☐ Gas	☐ Fresh ☐ Salty ☐ Sulphur ☐ Minerals

Disinfected ☐ Yes ☑ No If no, provide reason: Monitoring wells

Date Master Well Completed *(yyyy/mm/dd)* 2009/01/19

Cluster Information *(Please also fill out the additional Cluster Well Information for Well Construction for each parcel of land and cluster.)*

Total Wells in Cluster	Please indicate Number of Cluster Well Information Log Sheets Submitted
11	
Total Wells on this Property: unknown	1

Location of Well Cluster

Detailed Map must be provided as an attachment no larger than legal size (8.5" x 14"). Sketches are not allowed.
☑ Check box to confirm detailed map is provided as per Section 11.1 (3)

Consent to release additional information concerning the cluster to the Director upon request

Signature of Technician/Contractor [redacted] Date *(yyyy/mm/dd)*

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
George Downing Estate Drilling	1814

Business Address (Street No./Name, number, RR)	Municipality
410 Rue Principale	Grenville Sur-La-Rouge

Province	Postal Code	Business E-mail Address
QC	J0V1B0	downing@hawk.igs.net

Bus. Telephone No. *(inc. area code)*	Name of Well Technician (Last Name, First Name)
8192426469	Downing, Bruce

Well Technician's Licence No.	Signature of Technician	Date Submitted *(yyyy/mm/dd)*
2173	Bruce Downing	09/03/05

Audit No. M 04546

Date Received *(yyyy/mm/dd)* MAR 30 2009

Date of Inspection *(yyyy/mm/dd)*

Remarks

1992 (11/2006)

© Queen's Printer for Ontario, 2006

Ministry's Copy

Ontario Ministry of the Environment

Well Tag No. for Master Well (Print Well Tag No.)
A 074574 A074574

Cluster Well Information for Cluster Well Construction

Regulation 903 Ontario Water Resources Act

Page _____ of _____

[redacted]

Consent

Address of Well Location (Street Number/Name, RR): 250, 270, 290 City Centre Ave | Lot | Concession | Township | County/District/Municipality

City/Town/Village: Ottawa | Province: Ontario | Postal Code | GPS Unit Make: Garmin | Model: Map 76Csx | Unit Mode of Operation: ☐ Differentiated, specify: ☐ Undifferentiated ☑ Averaged

Signature of Technician/Contractor: Bruce Downing | Date (yyyy/mm/dd): 2009/03/05

Well # on Sketch	UTM Coordinates Zone	Easting	Northing	Full Depth of Hole (metres)	Hole Diameter (cm)	Method of Construction	Casing Material	Casing Length (metres)	Screen Interval (metres) From	To	Annular Space Sealant Used	Static Water Level (metres)	Abandonment Sealant Used	Comments	Date of Completion (yyyy/mm/dd)
BH #1	18	443813	5028612	4.57	20	HSA	PVC	1.5	1.5	4.5	Bentonite	2.3			2009/01/16
BH #2	18	443811	5028542	4.62				1.5	1.5	4.6		2.5			2009/01/16
BH #3	18	443793	5028529	5.11				2.1	2.1	5.1		3.5			2009/01/16
BH #5	18	443709	5028515	3.58				2.0	2.0	3.5					2009/01/19
BH #12	18	443817	5028499	4.86				1.8	1.8	4.8		3.6			2009/01/20
BH #14	18	443810	5028570	4.95				1.5	1.5	4.5		2.1			2009/02/02
BH #15	18	443838	5028541	4.57				1.5	1.5	4.5		3.0			2009/02/02
BH #16	18	443784	5028531	4.57				1.5	1.5	4.5		2.7			2009/02/02
BH #17	18	443791	5028498	4.57				3.0	3.0	4.5		3.3			2009/02/02
BH #18	18	443826	5028505	4.57				3.0	3.0	4.5					2009/02/02

Well Contractor and Well Technician Information

Business Name of Well Contractor: George Downing Estate Drilling Ltd | Business Address (Street Number/Name, RR): 410 Rue Principale | Municipality: Grenville Sur-la-Rouge | Province: QC

Postal Code: J0V 1B0 | Business Telephone No. (inc. area code): 819 242 6419 | Well Contractor's Licence No.: 1814 | Business E-mail Address: downing@hawk.igs.net

Name of Well Technician (First Name, Last Name): Bruce Downing | Well Technician's Licence No.: 2173 | Date Submitted (yyyy/mm/dd): 2009/03/05 | Signature of Technician: Bruce Downing

Date 1st Well in Cluster Constructed (yyyy/mm/dd): 2009/01/16 | Date Last Well in Cluster Constructed (yyyy/mm/dd): 2009/02/02

Ministry Use Only

Date Received (yyyy/mm/dd): MAR 30 2009 | Date Inspected (yyyy/mm/dd):

Audit No.: c 05151 | Remarks: m04546

1991 (11/2006)

Ministry's Copy

© Queen's Printer for Ontario, 2006



C1844 M04546 C05751

MAR 3 0 2009

Ontario — Ministry of the Environment

Measurements recorded in: ☑ Metric ☐ Im

Well Tag No. (Sticker and/or Print Below): **A 094120** A 094120

Well Record

Regulation 903 Ontario Water Resources Act

9242 Page 1 of 3

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
Equity	Realty Group Inc		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. (inc. area code)
50 Baywater Ave	Ottawa	ON	K1J2E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
270 City Center Ave			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443839	5028526		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Sand	Cobbles	Soft, dry	0	2.44
Brn	Sand	Gravel	Hard, saturated	2.44	3.35

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	Concrete / flushmount	
.31	.91	Benseal	
.91	3.35	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☑ Other, specify Direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	To
5.20	PVC	.390	0	1.22

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	To
6.03	PVC	10	1.22	3.35

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☐ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

Water Details

Water found at Depth (m/ft)	Kind of Water	Gas	Other, specify
	☐ Fresh ☐ Untested	☐	
	☐ Fresh ☐ Untested	☐	
	☐ Fresh ☐ Untested	☐	

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	3.35	10.92

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Soil Sampling	7241

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver Creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	w.records@strata soil.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9057649304	Beatty Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2011 11 06

Well owner's information package delivered: ☐ Yes ☐ No

Date Package Delivered: Y Y Y Y M M D D

Date Work Completed: 2011 11 06

Ministry Use Only

Audit No. Z140244

Received DEC 09 2011

 © Queen's Printer for Ontario, 2007

Ministry's Copy

Ontario — Ministry of the Environment

Tag#: A123877

Well Tag No. (Place Sticker and/or Print Below) A123877

Well Record

Regulation 903 Ontario Water Resources Act

9242 Page 2 of 3

Measurements recorded in: ☑ Metric ☐ Imperial

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
Equity	Realty Group Inc		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. (inc. area code)
50 Bays water Ave	Ottawa	ON	K1Y2E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
270 City Center Ave			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443839	5028528		

Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Sand	Cobbles	Soft, dry	0	2.44
Brn	Sand	Gravel	Hard saturated	2.44	3.35

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	Concrete / flushmount	
.31	.91	Benseal	
.91	3.35	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond ☐ Rotary (Conventional) ☐ Jetting ☐ Rotary (Reverse) ☐ Driving ☐ Boring ☐ Digging ☐ Air percussion ☑ Other, specify Direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used ☐ Domestic ☐ Municipal ☐ Dewatering ☐ Livestock ☐ Test Hole ☑ Monitoring ☐ Irrigation ☐ Cooling & Air Conditioning ☐ Industrial ☐ Other, specify

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	To
5.20	PVC	.390	0	1.22

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	To
6.03	PVC	10	1.22	3.35

Status of Well

☐ Water Supply ☐ Replacement Well ☐ Test Hole ☐ Recharge Well ☐ Dewatering Well ☑ Observation and/or Monitoring Hole ☐ Alteration (Construction) ☐ Abandoned, Insufficient Supply ☐ Abandoned, Poor Water Quality ☐ Abandoned, other, specify ☐ Other, specify

Water Details

Water found at Depth (m/ft)	Kind of Water	Gas	Other, specify
	☐ Fresh ☐ Untested	☐	
	☐ Fresh ☐ Untested	☐	
	☐ Fresh ☐ Untested	☐	

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	3.35	10.92

Results of Well Yield Testing

After test of well yield, water was: ☐ Clear and sand free ☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Soil Sampling	7241

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver Creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9057649304	Beatty Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3161		2011/11/06

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: YYYY MM DD

Date Work Completed: 2011/11/16

Ministry Use Only

Audit No. Z140245

DEC 09 2011 Received

0506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

Ontario — Ministry of the Environment

Tag No. (Place Sticker and/or Print Below): Tag#: A123878 A123878

Well Record

Regulation 903 Ontario Water Resources Act

9242 Page 3 of 3

Measurements recorded in: ☑ Metric ☐ Imperial

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
Equity	Realty Group Inc.		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. (inc. area code)
50 Baywater Ave	Ottawa	On	K1Y2E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
270 City Center Ave			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443858	5028529		

Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Sand	fill	Soft, dry	0	3.1
Brn	Sand	Gravel	Hard, Saturated	3.1	4.27

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	Concrete / flushmount	
.31	.91	Benseal	
.91	4.27	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☑ Other, specify: Direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
5.20	PVC	.380	0	1.22

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
6.03	PVC	10	1.22	4.27

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

Water Details

Water found at Depth (m/ft)	Gas	Kind of Water: Fresh	Untested	Other, specify

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	4.27	10.92

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Soil Sampling	7241

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver Creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9057649304	Beatty Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2011/11/06

Well owner's information package delivered: ☐ Yes ☐ No

Date Package Delivered: YYYY MM DD

Date Work Completed: 2011 11 01

Ministry Use Only

Audit No. Z140246

DEC 09 2011 Received

0506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

Well ID

Well ID Number: 7231311
Well Audit Number: *C07437*
Well Tag Number: *A108227*
This table contains information from the original well record and any subsequent updates.

This well is part of a well cluster.
The information below is extracted from the cluster well record.
More information on the cluster well record (related to other wells in the cluster)
is also available.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443890.00 Northing: 5028521.00

Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 6964

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	

Pumping Rate	
Duration of Pumping	
Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	**Draw Down Water level**	**Recovery Time(min)**	**Recovery Water level**
SWL			
1		1	
2		2	
3		3	

4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C07437

Date Well Completed: October 14, 2011

Date Well Record Received by MOE: December 14, 2011

Ontario — Ministry of the Environment

Measurements recorded in: ☑ Metric ☐ Imperia

Well Tag No. *(Place Sticker and/or Print Below)*: **Tag#: A123760** A123760

Well Record

Regulation 903 Ontario Water Resources Act

9287 Page 4 of 4

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
City of	Ottawa		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. *(inc. area code)*
175 Loretta St N	Ottawa	ON	K1Y4L8	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
175 Loretta Ave N.			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	445403	5028050		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Cobbles	fill	Hard, dry	0	3.66
Brn	Sand	Silt	soft, Saturated	3.66	4.27
Grey	Silt	fine Sand	soft, Saturated	4.27	4.88

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	Concrete / flushmount	
.31	1.5	Benseal	
1.5	4.88	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify* Direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
4.03	PVC	.368	0	1.83

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
4.82	PVC	10	1.83	4.88

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, *specify*
Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, *specify*
Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	4.88	8.25

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Soil Sampling	7214

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. *(inc. area code)*	Name of Well Technician (Last Name, First Name)
9057649304	Beath, Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2011/11/16

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: YYYY/MM/DD

Date Work Completed: 2011/11/16

Ministry Use Only

Audit No. Z134418

Received JAN 09 2012

 © Queen's Printer for Ontario, 2007 Ministry's Copy

Ontario — Ministry of the Environment

Well Tag No. *(Place Sticker and/or Print Below)* **Tag#: A141858** A141858

S-13358

Well Record

Regulation 903 Ontario Water Resources Act

Measurements recorded in: ☑ Metric ☐ Imperial

Page _____ of _____

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
Equity Realty	Group Inc.		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. *(inc. area code)*
50 Bayswater Ave	Ottawa	ON	K1Y2E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
270 City Centre st.			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443306	5028520		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Cobbles	Course Sand	Hard, dry	0	3.35
Brn	Cobbles	Course sand	Hard Saturcated	3.35	5.49

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used *(Material and Type)*	Volume Placed (m^3/ft^3)
0	.31	Concrete / flushmount	
.31	2.13	Benseal	
2.13	5.49	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☑ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify* _____

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify* _____

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
5.20	PVC	.390	0	2.44

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
6.03	PVC	10	2.44	5.49

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☐ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	5.49	10.92

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*

Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.

See map

MW 1202

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Drilling Group	7141

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver Creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. *(inc. area code)*	Name of Well Technician (Last Name, First Name)
9057649304	Beath, Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2012/12/13

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☐ No		2012/12/12

Ministry Use Only


Audit No. Z152964

Received DEC 18 2012

Go to refusal + 10' screen

S-13358

TCLP on all wells



LEGEND

- PREVIOUS INJECTION POINT
- MONITORING POINT
- INJECTION AND MONITORING POINT
- NEW WELL LOCATION
- DAMAGED WELL
- RETAINING WALL
- FIRE HYDRANT
- TRAIN TRACKS
- BUILDING
- ROAD/PAVED AREA
- GRASS AREA

Title: PROPOSED WELL LOCATIONS

FRANZ ENVIRONMENTAL INC.
CONSULTING ENGINEERING TECHNOLOGIES

Project: UPDATE ON REMEDIAL PROGRESS 250, 270 AND 290 CITY CENTRE AVE

Date: OCTOBER 2012

Client: WILLMS & SHIER ENVIRONMENTAL LAWYERS LLP

Scale 1:500 (10 8 6 4 2 0 5 10 15 20 metres)

FIGURE 1

z:\projects\2012\1673-1202 city centre stage 4 remediation\proposal\cc_3.dwg

S-13358, 2152964,

RECEIVED 2013

Ontario — Ministry of the Environment

Measurements recorded in: ☑ Metric ☐ Imperial

Well Tag No. *(Place Sticker and/or Print Below)*

Tag#: A141857 A141857

S-13358

Well Record

Regulation 903 Ontario Water Resources Act

Page _____ of _____

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
	Equity Realty Group Inc.		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. *(inc. area code)*
50 Bayswater Ave.	Ottawa	ON	K1Y 2E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
270 City Centre			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443305	5026524		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brown	Cobbles and Sand		dry	0	2.74
Brown	Cobbles and Sand		Saturated	2.74	5.49

Annular Space

Depth Set at (m/ft) From	Depth Set at (m/ft) To	Type of Sealant Used *(Material and Type)*	Volume Placed (m^3/ft^3)
0	.31	Concrete / flushmount	
.31		Benseal	
		Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☑ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify* _____

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☐ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify* _____

Construction Record - Casing

Inside Diameter *(cm/in)*	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness *(cm/in)*	Depth (m/ft) From	Depth (m/ft) To
5.20	PVC	.390	0	2.44

Construction Record - Screen

Outside Diameter *(cm/in)*	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
6.03	PVC	10	2.44	5.49

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter *(cm/in)*
0	5.49	10.92

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

	Draw Down Time *(min)*	Draw Down Water Level *(m/ft)*	Recovery Time *(min)*	Recovery Water Level *(m/ft)*
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Drilling Group	7241

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver creek	Richmondhill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. *(inc. area code)*	Name of Well Technician (Last Name, First Name)
9057649304	Beath, Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2012/11/23

Well owner's information package delivered	Date Package Delivered	Ministry Use Only
☐ Yes ☐ No	Y Y Y Y M M D D	Audit No. Z 152963
	Date Work Completed 2012/11/21	Received DEC 06 2012


0506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

Go to refusal + 10' screen

S-13358

TCLP on all wells



No samples

Injection wells at road

wells

E-mail 2012-08-23

Ontario — Ministry of the Environment

Well Tag No. (Place Sticker and/or Print Below) **Tag#: A141856** A141856

5-13358

Well Record

Regulation 903 Ontario Water Resources Act

Measurements recorded in: ☑ Metric ☐ Imperial

Page _____ of _____

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
	Equity realty Group Inc.		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. (inc. area code)
50 Bayswater Ave	Ottawa	ON	K1 Y2 E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
270 City Centre Ottawa			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 8 3	18	443347	5028541		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Blk	Muck	clay	soft, dry	0	2.74
Brn	Cobbles	Course Sand	hard, Saturated	2.74	3.35

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
0	.31	Concrete/flushmount	
.31	.91	Benseal	
.91	3.35	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☑ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify* _____

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify* _____

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
5.20	PVC	.390	0	.91

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
6.03	PVC	10	.91	3.35

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☐ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify* _____
☐ Other, *specify* _____

Water Details

Water found at Depth (m/ft)	☐ Gas	Kind of Water: ☐ Fresh ☐ Untested ☐ Other, *specify*
Water found at Depth (m/ft)	☐ Gas	Kind of Water: ☐ Fresh ☐ Untested ☐ Other, *specify*
Water found at Depth (m/ft)	☐ Gas	Kind of Water: ☐ Fresh ☐ Untested ☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0	3.35	11.43

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping _____ hrs + _____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)

Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.

See map MW1203

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Drilling Group	7241

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver Creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9057649304	Beatty, Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2012/11/23

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☐ No		2012/12/12

Ministry Use Only

Audit No. Z154423

DEC 06 2012

Received


 © Queen's Printer for Ontario, 2007

Ministry's Copy

Go to refusal + 10' screen

S-13358

TCLP on all wells



No samples

wells

Injection wells at road

C7941 215403

Aug 31 2012

Ontario | Ministry of the Environment

Well Tag No. (Place Sticker and/or Print Below) **Tag#: A141855** A141855

3S-13358 **Well Record**

Regulation 903 Ontario Water Resources Act

Measurements recorded in: ☑ Metric ☐ Imperial

Page _____ of _____

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
Equity realty	Group Inc		

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. (inc. area code)
50 Bayswater Ave	Ottawa	ON	K1Y2E9	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
220 City Centre Ave			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443848	5028545		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Blk	Muck	Clay	Soft, dry	0	2.74
Brn	Cobbles	Course Sand	Hard, saturated	2.74	3.66

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
0	.31	Concrete / flushmount	
.31	.91	Benseal	
.91	3.66	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☑ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, specify _____

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify _____

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
5.20	PVC	.390	0	1.22

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
6.03	PVC	10	1.22	3.66

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

Water Details

Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, specify
Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, specify
Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested ☐ Gas ☐ Other, specify

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0		

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify _____

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping _____ hrs + _____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)

Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.

See map

MW 204

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Drilling Group	7124

Business Address (Street Number/Name)	Municipality
147-2 W. Beaver creek	Richmond Hill

Province	Postal Code	Business E-mail Address
ON	L4B1C6	wrecords@stratasoil.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9057649304	Beatty Brian

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3616		2012/11/23

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☐ No		2012/11/21

Ministry Use Only

Audit No. z154422

Received DEC 06 2012


 © Queen's Printer for Ontario, 2007

Ministry's Copy

Go to refusal + 10' screen

S-13358

TCLP on all wells



LEGEND

- PREVIOUS INJECTION POINT
- MONITORING POINT
- INJECTION AND MONITORING POINT
- NEW WELL LOCATION
- DAMAGED WELL
- RETAINING WALL
- FIRE HYDRANT
- TRAIN TRACKS
- BUILDING
- ROAD/PAVED AREA
- GRASS AREA

Title: PROPOSED WELL LOCATIONS

FRANZ ENVIRONMENTAL INC.
CONSULTING ENGINEERING TECHNOLOGIES

Project: UPDATE ON REMEDIAL PROGRESS 250, 270 AND 290 CITY CENTRE AVE

Date: OCTOBER 2012

Client: WILLMS & SHIER ENVIRONMENTAL LAWYERS LLP

Scale 1:500

10 8 6 4 2 0 5 10 15 20 metres

FIGURE 1

z:\projects\2012\1673-1202 city centre stage 4 remediation\proposal\cc_3.dwg

c-3411 12Mar12

Rev 1 Jan 13

7202037

Ontario — Ministry of the Environment

S-13938

Well Record

Regulation 903 Ontario Water Resources Act

Well Tag No. *(Place Sticker and/or Print Below)* A145365

Tag#: A145365

Page ____ of ____

Measurements recorded in: ☑ Metric ☐ Imperial

[redacted]

CITY OF OTTAWA

Address of Well Location (Street Number/Name)	Township	Lot	Concession
E 250 City Centre Ave			
County/District/Municipality	**City/Town/Village**	**Province**	**Postal Code**
	Ottawa	Ontario	
UTM Coordinates NAD 83 — Zone 18 — Easting 443793 — Northing 5028563	**Municipal Plan and Sublot Number**	**Other**	

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
BLK	asphalt	gravel		0	.31
BRN	sand	stones, brick		.31	1.83
BRN	sand	stones		1.83	4.57

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	concrete/flushmount	
.31	1.22	bentonite	
1.22	4.57	filter sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☑ Other, specify Direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
~~5.20~~ 4.03	PVC	.368	0	1.52

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
~~6.03~~ 4.82	PVC	10	1.52	4.57

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☐ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, specify
☐ Gas	☐ Fresh ☐ Untested	☐ Other, specify
☐ Gas	☐ Fresh ☐ Untested	☐ Other, specify

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0	4.57	8.25

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)

Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.

See Map

40

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor: Strata Drilling Group — Well Contractor's Licence No.: 7241

Business Address (Street Number/Name): 147 West Beaver Creek — Municipality: Richmond Hill

Province: ON — Postal Code: L4B 1G6 — Business E-mail Address: wrecords@stratasoil.com

Bus. Telephone No. (inc. area code): 905 764-9380 — Name of Well Technician (Last Name, First Name): Coy, James

Well Technician's Licence No.: 3656 — Signature of Technician and/or Contractor — Date Submitted: 2013/05/31

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered

Date Work Completed: 2013/04/23

Ministry Use Only


Audit No. Z 168676

Received

0506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

S-1398



LEGEND

- PROPERTY LINE
- PROPOSED PHASE II ESA STUDY AREA
- DELINEATED PLUME
- PROPOSED BOREHOLE (LOWEST INTEREST)
- PROPOSED BOREHOLE (MODERATE INTEREST)
- PROPOSED BOREHOLE (HIGHEST INTEREST)

NOTE(S):
1. SCALE AND SITE INFRASTRUCTURE LOCATIONS ARE APPROXIMATE
2. INFORMATION ON THIS FIGURE MAY BE LOST IF IT IS PHOTOCOPIED, FAXED OR PRINTED IN OTHER THAN ITS ORIGINAL SIZE AND COLOURS
3. 'm' : METRES

SOURCE(S):
1. HISTORICAL AIR PHOTOGRAPH, 2011

SCALE 1:750

0 10 20 40m

SNC·LAVALIN Environment

Client/Location: CITY OF OTTAWA, 250 CITY CENTRE AVENUE, OTTAWA, ONTARIO		Title: PROPOSED BOREHOLE LOCATIONS	
Project No: 07103	Filename: 07103-250CC-PMW-1	Date: MARCH 2013	Dwg No: FIGURE 2
Drawn: EM	Verified: EV	Project Manager: RPT	

C-7241216876

7205660

Ontario — Ministry of the Environment

Measurements recorded in: [x] Metric [ ] Imperial

Well Tag No. *(Place Sticker and/or Print Below)* **A111219**

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

[redacted]

CITY OF OTTAWA

Address of Well Location (Street Number/Name)	Township	Lot	Concession
O-Train Rail Corridor Brookfield + Gladstone	Ottawa		

County/District/Municipality	City/Town/Village	Province	Postal Code
Ottawa	Ottawa	Ontario	K1V 6L5 1

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 8 3	18	443981	5028199		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)

Method of Construction

[ ] Cable Tool [ ] Diamond
[ ] Rotary (Conventional) [ ] Jetting
[ ] Rotary (Reverse) [ ] Driving
[ ] Boring [ ] Digging
[ ] Air percussion
[ ] Other, *specify*

Well Use

[ ] Public [ ] Commercial [ ] Not used
[ ] Domestic [ ] Municipal [ ] Dewatering
[ ] Livestock [ ] Test Hole [ ] Monitoring
[ ] Irrigation [ ] Cooling & Air Conditioning
[ ] Industrial
[ ] Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
	Abandon			

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
3.2	PLASTIC			

Status of Well

[ ] Water Supply
[ ] Replacement Well
[ ] Test Hole
[ ] Recharge Well
[ ] Dewatering Well
[ ] Observation and/or Monitoring Hole
[ ] Alteration (Construction)
[ ] Abandoned, Insufficient Supply
[ ] Abandoned, Poor Water Quality
[x] Abandoned, other, *specify* CONSTRUCTION
[ ] Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	Hole Diameter Depth (m/ft) From	To	Diameter (cm/in)
[ ] Gas	[ ] Fresh [ ] Untested [ ] Other, *specify*			
[ ] Gas	[ ] Fresh [ ] Untested [ ] Other, *specify*			
[ ] Gas	[ ] Fresh [ ] Untested [ ] Other, *specify*			

Results of Well Yield Testing

After test of well yield, water was:
[ ] Clear and sand free
[ ] Other, *specify*

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping ____ hrs + ____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? [ ] Yes [ ] No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Marathon Drilling Co Ltd.	6894

Business Address (Street Number/Name)	Municipality
6847 Hiram Dr	OTT

Province	Postal Code	Business E-mail Address
ON	K4P1A2	

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
6138205711	Wright Terry

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
0715		20130724

Well owner's information package delivered	Date Package Delivered	Date Work Completed
[ ] Yes [ ] No	Y Y Y Y M M D D	Y Y Y Y M M D D

Ministry Use Only

Audit No. Z096874

Received JUL 31 2013

0506E (12/2007)

Ministry's Copy

© Queen's Printer for Ontario, 2007

Well ID

Well ID Number: 7216640
Well Audit Number: *C21873*
Well Tag Number: *A137238*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443739.00 Northing: 5028276.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 6964

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C21873

Date Well Completed: January 04, 2013

Date Well Record Received by MOE: February 20, 2014

7245907

15-0039-00

Ontario — Ministry of the Environment

Measurements recorded in: ☐ Metric ☒ Imperial

Well Tag No. *(Place Sticker and/or Print Below)*
Tag#: A175221

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

CANADIAN BANK NOTE COMPANY

Address of Well Location (Street Number/Name)	Township	Lot	Concession
975 Gladstone Ave	Nepean		
County/District/Municipality	**City/Town/Village**	**Province**	**Postal Code**
Carleton	Ottawa.	Ontario	
UTM Coordinates Zone / Easting / Northing	**Municipal Plan and Sublot Number**	**Other**	
NAD 83 18 443936 5028115			

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
brown	Top Soil			0'	6"
brown	Clay	Cobble	fill	6"	10'
Grey	Clay	Silt	wet.	10'	20'9"

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
20'9"	7'	Sand	
7'	0'	Holeplug	

Method of Construction

☐ Cable Tool ☐ Diamond
☒ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify*

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	Sched 40	10'9"	0'

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	10	20'9"	10'9"

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0'	20'9"	6"

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Aardvark Drilling Inc.	7238
Business Address (Street Number/Name)	**Municipality**
25-C Lewis Road	Guelph
Province	**Postal Code**	**Business E-mail Address**
ON	N1H1E9	www.aardvarkdrillinginc.com
Bus. Telephone No. *(inc. area code)*	**Name of Well Technician (Last Name, First Name)**
5198269340	Smith, Kyle
Well Technician's Licence No.	**Signature of Technician and/or Contractor**	**Date Submitted**
3591		20150729

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: Y Y Y Y M M D D

Date Work Completed: 20150703

Ministry Use Only

Audit No. Z 199796

Received AUG 05 2015

506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

7245908

Ontario — Ministry of the Environment

Measurements recorded in: ☐ Metric ☒ Imperial

Well Tag No. *(Place Sticker and/or Print Below)*
Tag#: A175222

15-0039-00

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

CANADIAN BANK NOTE COMPANY

Address of Well Location (Street Number/Name)	Township	Lot	Concession
975 Gladstone, Ave	Nepean		
County/District/Municipality	**City/Town/Village**	**Province**	**Postal Code**
Carleton	Ottawa	Ontario	
UTM Coordinates Zone / Easting / Northing	**Municipal Plan and Sublot Number**	**Other**	
NAD 83 18 445393 5028129			

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brown	Topsoil			0'	4"
Brow	clay	silt	gravel.	4"	10'
grey	clay	silt	gvel.	10'	22'

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
22'	8'	Sand	
8'	0'	Holeplug	

Method of Construction

☐ Cable Tool ☐ Diamond
☒ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify*

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☐ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	sched 40	12'	0'

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	10	22'	12'

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0'	22'	8"

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
50		50	
60		60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Aardvark Drilling Inc.	7238
Business Address (Street Number/Name)	**Municipality**
25-C Lewis Road	Guelph
Province	**Postal Code** / **Business E-mail Address**
ON	N1H1B9 www.aardvarkdrillinginc.com
Bus. Telephone No. (inc. area code)	**Name of Well Technician (Last Name, First Name)**
5198259340	Smith, Kyle
Well Technician's Licence No.	**Signature of Technician and/or Contractor** / **Date Submitted**
3591		2015/07/29

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered

Date Work Completed 2015/07/03

Ministry Use Only

Audit No. Z 199795

Received AUG 05 2015

506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

7245909

Ontario — Ministry of the Environment

Measurements recorded in: ☐ Metric ☒ Imperial

Well Tag No. *(Place Sticker and/or Print Below)*
Tag#: A175220

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

CANADIAN BANK NOTE COMPANY

Address of Well Location (Street Number/Name)	Township	Lot	Concession
975 Gladstone Ave	Nepean		
County/District/Municipality	**City/Town/Village**	**Province**	**Postal Code**
Carleton	Ottawa	Ontario	
UTM Coordinates Zone / Easting / Northing	**Municipal Plan and Sublot Number**	**Other**	
NAD 83 18 445940 5028103			

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
brown	Topsoil			0'	8"
brown	clay	silt/cobbles	~~moist~~ ~~wet~~	8"	10'
Grey	clay	silt	wet.	10'	18'
	bedrock			18'	18'2"

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
18'	6'	Sand	
6'	0'	Bentonite.	

Method of Construction

☐ Cable Tool ☐ Diamond
☒ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify*

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	Sch 40	8'	0'

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	10	18'	8'

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
	☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*
	☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*
	☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0'	18'	8"

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping ____ hrs + ____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Aardvark Drilling Inc.	7236
Business Address (Street Number/Name)	**Municipality**
25-C Lewis Road	Guelph
Province	**Postal Code** / **Business E-mail Address**
ON	N1H1E9 www.aardvarkdrillinginc.com
Bus. Telephone No. (inc. area code)	**Name of Well Technician (Last Name, First Name)**
5198269340	Smith, Kyle
Well Technician's Licence No.	**Signature of Technician and/or Contractor** / **Date Submitted**
3591	20150729

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered

Date Work Completed 20150702

Ministry Use Only

Audit No. Z199797

Received AUG 05 2015

0506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

7245910

15-0007-00

Ontario Ministry of the Environment

Measurements recorded in: ☐ Metric ☒ Imperial

Well Tag No. *(Place Sticker and/or Print Below)* **Tag#: A175219**

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

CANADIAN BANK NOTE COMPANY

Address of Well Location (Street Number/Name)	Township	Lot	Concession
9755 Gladstone Ave,	Nepean		
County/District/Municipality	**City/Town/Village**	**Province**	**Postal Code**
Carleton	Ottawa	Ontario	
UTM Coordinates Zone 18 Easting 443948 Northing 5028086 (NAD 83)	**Municipal Plan and Sublot Number**	**Other**	

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brown	Top Soil			0'	6"
Brown	Silty Clay		Cobbles	6"	10'
Grey	Clay	Silt	mucky, wet	10'	18'
	bedrock			18'	18'1"

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
18'	6'	Sand	
6'	0'	Holeplug	

Method of Construction

☐ Cable Tool ☐ Diamond
☒ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify*

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	sch 40	0'	8'

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	10	8'	18'

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0'	18'	8"

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at (m/ft)

Pumping rate (l/min / GPM)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.


N
Gladstone
60 yards
Iona Ct
Iona Ct
Iona Ct

7245911

15-0039-00

Ontario — Ministry of the Environment

Well Tag No. *(Place Sticker and/or Print Below)* **Tag#: A175223**

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

Measurements recorded in: ☐ Metric ☒ Imperial

[redacted]

Address of Well Location (Street Number/Name)	Township	Lot	Concession
975 Gladstone ave.	Nepean		
County/District/Municipality	**City/Town/Village**	**Province**	**Postal Code**
Carleton	Ottawa	Ontario	
UTM Coordinates Zone / Easting / Northing	**Municipal Plan and Sublot Number**	**Other**	
NAD 8 3 1 8 4 4 3 9 2 6 5 0 2 8 1 4 2			

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brown	Top Soil			0'	6"
Brow	Clay	Silt	damp	6"	10'
Grey	Clay	Silt	wet	10'	23'

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
23'	11'	Sand	
11'	0'	Hole plug	

Method of Construction

☐ Cable Tool ☐ Diamond
☒ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify*

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☐ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	Sched 10	13'	0'

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
2"	PVC	10	23'	13'

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify*

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping _____ hrs + _____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*


Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level				
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15			15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Water Details

Water found at Depth (m/ft)	Kind of Water	Gas	Other, specify
	☐ Fresh ☐ Untested	☐	
	☐ Fresh ☐ Untested	☐	
	☐ Fresh ☐ Untested	☐	

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0'	23'	8"

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Aardvark Drilling Inc.	7236
Business Address (Street Number/Name)	**Municipality**
25-C Lewis Road	Guelph
Province	**Postal Code**	**Business E-mail Address**
ON	N1H1E9	www.aardvarkdrillinginc.com
Bus. Telephone No. (inc. area code)	**Name of Well Technician (Last Name, First Name)**
5198269340	Smith, Kyle
Well Technician's Licence No.	**Signature of Technician and/or Contractor**	**Date Submitted**
3591		20150729

Comments:

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☐ No		20150706

Ministry Use Only

Audit No. Z199820

Received AUG 05 2015

0506E (2007/12) © Queen's Printer for Ontario, 2007

Ministry's Copy

Well ID

Well ID Number: 7292789
Well Audit Number: *C36226*
Well Tag Number: *A198420*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	039
Concession	01
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443968.00 Northing: 5028136.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7543

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C36226

Date Well Completed:

Date Well Record Received by MOE: August 17, 2017

Ontario — Ministry of the Environment and Climate Change

Measurements recorded in: ☒ Metric ☐ Imperial

Well Tag No. *(Place Sticker and/or Print Below)* Tag#:A253878

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
—	Canadian Bank Note LTD.	—	

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. *(inc. area code)*
145 Richmond RD.	Ottawa	ON	K1R1A1	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
975 Gladstone Ave	Centretown West	—	—

County/District/Municipality	City/Town/Village	Province	Postal Code
City of Ottawa	Ottawa	Ontario	K1Y4W5

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443918	5025110	—	—

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Grey	Gravel	Asphalt		0	0.3m
Brown	Sand	Cobbles, Gravel		0.3	2.13m
Grey	clay			2.13	4.57m
Grey	silt	Sand, gravel		4.57	5.33m

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
0	0.3m	Cement	0.014m^3
0.3	1.98m	Bentonite	0.040m^3
1.98	5.33m	#3 Sand	0.028m^3

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☒ Boring ☐ Digging
☐ Air percussion
☐ Other, *specify* _____

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☒ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify* _____

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	To
17.78	Aluminum	0.32	0	0.3m
5.08	Plastic	0.47	0	2.29

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	To
6.03	Plastic	0.10	2.29	5.33m

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at (m/ft): Not Tested

Pumping rate (l/min / GPM)

Duration of pumping: _____ hrs + _____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)

Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No


	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level	5.03m			
1			1	
2			2	
3			3	
4			4	
5			5	
10			10	
15	monitoring well installed		15	
20			20	
25			25	
30			30	
40			40	
50			50	
60			60	

Water Details

Water found at Depth	Kind of Water	Hole Diameter Depth From	Depth To	Diameter (cm/in)
5.33 (m/ft) ☐ Gas	☐ Fresh ☒ Untested ☐ Other, *specify*	0	0.3m	30.48
(m/ft) ☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*	0.3	5.33	16.51
(m/ft) ☐ Gas	☐ Fresh ☐ Untested ☐ Other, *specify*			

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
GET Drilling LTD	7058

Business Address (Street Number/Name)	Municipality
229 Drive-in RD	Napanee

Province	Postal Code	Business E-mail Address
ON	K7R3L1	getdrilling@mycando.ca

Bus. Telephone No. *(inc. area code)*	Name of Well Technician (Last Name, First Name)
6133541767	Harrison, Jim

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
2251		2018/11/20

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☒ No		2018/11/20

Ministry Use Only

Audit No. Z298740

NOV 16 2018

Received

0506E (2014/11)

Ministry's Copy

© Queen's Printer for Ontario, 2014

Ontario — Ministry of the Environment and Climate Change

Measurements recorded in: ☒ Metric ☐ Imperial

Well Tag No. *(Place Sticker and/or Print Below)* Tag#:A253877

Well Record

Regulation 903 Ontario Water Resources Act

Page 1 of 1

Well Owner's Information

First Name	Last Name / Organization	E-mail Address	☐ Well Constructed by Well Owner
—	Canadian Bank Note LTD.	—	

Mailing Address (Street Number/Name)	Municipality	Province	Postal Code	Telephone No. (inc. area code)
145 Richmond RD.	Ottawa	ON	K1R1A1	

Well Location

Address of Well Location (Street Number/Name)	Township	Lot	Concession
975 Gladstone Ave	Centretown West	—	—

County/District/Municipality	City/Town/Village	Province	Postal Code
City of Ottawa	Ottawa	Ontario	K1Y4W5

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	445930	5028111B	—	—

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Grey	Gravel	Asphalt		0	0.3m
Brown	Sand	Gravel		0.3	1.52m
Grey	clay			1.52	4.88m
Grey	silt	Sand, gravel		4.88	5.79m

Annular Space

Depth Set at (m/ft) From	Depth Set at (m/ft) To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	0.3m	Cement	0.014m³
0.3	2.13m	Bentonite	0.040m³
2.13	5.79m	#3 Sand	0.228m³

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☒ Boring ☐ Digging
☐ Air percussion
☐ Other, specify

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☒ Test Hole ☒ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, specify

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
17.78	Aluminum	0.32	0	0.3m
5.08	Plastic	0.47	0	2.74m

Status of Well

☐ Water Supply
☐ Replacement Well
☐ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, specify
☐ Other, specify

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
6.03	Plastic	0.10	2.74	5.79m

Water Details

Water found at Depth	Kind of Water	Other, specify
5.18 (m/ft) ☐ Gas	☐ Fresh ☒ Untested	
(m/ft) ☐ Gas	☐ Fresh ☐ Untested	
(m/ft) ☐ Gas	☐ Fresh ☐ Untested	

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0	0.3	30.48
0.3	5.79	16.51

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, specify

If pumping discontinued, give reason:

Pump intake set at (m/ft): NOT

Pumping rate (l/min / GPM): TESTED

Duration of pumping: ____ hrs + ____ min

Final water level end of pumping (m/ft)

If flowing give rate (l/min / GPM)

Recommended pump depth (m/ft)

Recommended pump rate (l/min / GPM)


Well production (l/min / GPM)

Disinfected? ☐ Yes ☐ No

	Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level	5.18m			
1			1	
2			2	
3			3	
4			4	
5			5	
10	monitoring		10	
15	well		15	
20	Installed		20	
25			25	
30			30	
40			40	
50			50	
60			60	

Map of Well Location

Please provide a map below following instructions on the back.



Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
G.E.T. Drilling LTD	7085

Business Address (Street Number/Name)	Municipality
278 Drive-in RD	Napanee

Province	Postal Code	Business E-mail Address
on	K7R3L1	getdrilling@mycable.ca

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
6133541760	Harrison, Jim

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
2251		2016/11/22

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☒ No		2016/11/22

Ministry Use Only

Audit No. Z298739

Received NOV 16 2018

0506E (2014/11)

Ministry's Copy

© Queen's Printer for Ontario, 2014

9-23328

Ontario — Ministry of the Environment and Climate Change

Well Tag No. *(Place Sticker and/or Print Below)* A261253 Tag#:A261253

Well Record

Regulation 903 Ontario Water Resources Act

Page ____ of ____

Measurements recorded in: ☑ Metric ☐ Imperial

[redacted]

Address of Well Location (Street Number/Name)	Township	Lot	Concession
73 Breezehill Ave N			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Markham	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443799	5028315		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (*m/ft*) From	Depth (*m/ft*) To
BLK	Sandy Silt	gravel	damp	0	.31
BRN	sand	silt, gravel	damp	.31	2.74
GRY	clay	silt	soft	2.74	6.1

Annular Space

Depth Set at (*m/ft*) From	To	Type of Sealant Used (*Material and Type*)	Volume Placed (*m³/ft³*)
0	.31	Concrete/Cuttings	
.31	2.83	Bentonite	
2.83	6.1	Filter sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☑ Other, *specify* Direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☑ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify* _____

Construction Record - Casing

Inside Diameter (*cm/in*)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (*cm/in*)	Depth (*m/ft*) From	To
4.03	PVC	.368	0	3.1

Construction Record - Screen

Outside Diameter (*cm/in*)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (*m/ft*) From	To
4.81	PVC	10	3.1	6.1

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify* _____
☐ Other, *specify* _____

Water Details

Water found at Depth (*m/ft*)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*

Hole Diameter

Depth (*m/ft*) From	To	Diameter (*cm/in*)
0	6.1	8.25

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at (*m/ft*)

Pumping rate (*l/min / GPM*)

Duration of pumping ____ hrs + ____ min

Final water level end of pumping (*m/ft*)

If flowing give rate (*l/min / GPM*)

Recommended pump depth (*m/ft*)

Recommended pump rate (*l/min / GPM*)

Well production (*l/min / GPM*)

Disinfected? ☐ Yes ☐ No

Draw Down Time (*min*)	Draw Down Water Level (*m/ft*)	Recovery Time (*min*)	Recovery Water Level (*m/ft*)
Static Level			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
50		50	
60		60	

Map of Well Location

Please provide a map below following instructions on the back.

See Map (MW)

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Drilling Group	7241

Business Address (Street Number/Name)	Municipality
165 Shelbourne Court	Markham

Province	Postal Code	Business E-mail Address
ON	L3R8V2	wreed45@stratasoil.com

Bus. Telephone No. (*inc. area code*)	Name of Well Technician (Last Name, First Name)
905 940 7911	

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
		Y Y Y Y M M D D

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: Y Y Y Y M M D D

Date Work Completed: 2019 03 06

Ministry Use Only

Audit No. Z302759

Received Apr 15 2019

0506E (2014/11) Ministry's Copy

© Queen's Printer for Ontario, 2014

C-7241
2302759



PINCHIN

LEGEND

	SITE BOUNDARY
	SITE BUILDING
RES	RESIDENTIAL
COM	COMMERCIAL
LI	LIGHT INDUSTRIAL
(P)	PARKING
	RAILWAY LINE

PROJECT NAME: PHASE I ENVIRONMENTAL SITE ASSESSMENT			
CLIENT NAME: VIV NUTT			
PROJECT LOCATION: 73 BREEZEHILL AVENUE NORTH, OTTAWA, ONTARIO			
FIGURE NAME: SITE AND SURROUNDING LAND USE PLAN			FIGURE NO.: 2
APPROXIMATE SCALE: AS SHOWN	PROJECT NO.: 235945	DATE: FEBRUARY 2019	

ENRB-RECEIVED
APR 15 2019

Ontario

Ministry of the Environment and Climate Change

Measurements recorded in: ☒ Metric ☐ Imperial

Well Tag#:A261092 (Label Below)

A261092

Well Record

Regulation 903 Ontario Water Resources Act

S-23250 Page ____ of ____

[redacted]

Address of Well Location (Street Number/Name)	Township	Lot	Concession
73 Breezehill Ave N			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443782	5028310		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
BRN	Fill		Packed	0	1.83
BRN	Clay	Silt	Soft	1.83	4.57
GRY	Clay	Silt	Soft	4.57	6.1

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	Concrete/Flushmount	
.31	2.74	Bentonite	
2.74	6.1	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☒ Other, *specify* direct Push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☒ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	To
4.03	PVC	365	0	3.1

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	To
4.82	PVC	10	3.1	6.1

Status of Well

☐ Water Supply
☐ Replacement Well
☒ Test Hole
☐ Recharge Well
☐ Dewatering Well
☒ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	6.1	8.25

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping ____ hrs + ____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*

Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
50		50	
60		60	

Map of Well Location

Please provide a map below following instructions on the back.

See map

MW1

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata drilling Group	7241

Business Address (Street Number/Name)	Municipality
145 Shields Court	Markham

Province	Postal Code	Business E-mail Address
ON	L3R8U2	Lrecords@Stratas0il.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9054902919	Halladay Phil

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3833		2019 02 22

Comments:

Well owner's information package delivered ☐ Yes ☐ No

Date Package Delivered: YYYY MM DD

Date Work Completed: 2019 02 05

Ministry Use Only

Audit No. Z302772

Received APR 15 2019

0506E (2014/11) Ministry's Copy

© Queen's Printer for Ontario, 2014

C-1341
2303734



PINCHIN

LEGEND

[ ]	SITE BOUNDARY
▨	SITE BUILDING
RES	RESIDENTIAL
COM	COMMERCIAL
LI	LIGHT INDUSTRIAL
Ⓟ	PARKING
++++++	RAILWAY LINE

PROJECT NAME: PHASE I ENVIRONMENTAL SITE ASSESSMENT			
CLIENT NAME: VIV NUTT			
PROJECT LOCATION: 73 BREEZEHILL AVENUE NORTH, OTTAWA, ONTARIO			
FIGURE NAME: SITE AND SURROUNDING LAND USE PLAN			FIGURE NO.: 2
APPROXIMATE SCALE: AS SHOWN	PROJECT NO.: 235945.001	DATE: FEBRUARY 2019	

EMR - RECEIVED
APR 15 2019

Ontario

Ministry of the Environment and Climate Change

Measurements recorded in: [X] Metric [ ] Imperial

Well Ta Tag#:A261093 elow)

A261093

Well Record

Regulation 903 Ontario Water Resources Act

S3258 Page ____ of ____

[redacted]

Address of Well Location (Street Number/Name)	Township	Lot	Concession
23 ~~Bluebell~~ Breezehill Ave N			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Ottawa	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	443750	5028316		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Fill		Packed	0	1.83
Brn	Clay	Silt	Soft	1.83	9.57
Grey	Clay	Silt	Soft	9.57	6.1

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m³/ft³)
0	.31	Concrete Flushmount	
.31	2.74	Bentonite	
2.74	6.1	Sand	

Method of Construction

- [ ] Cable Tool
- [ ] Rotary (Conventional)
- [ ] Rotary (Reverse)
- [ ] Boring
- [ ] Air percussion
- [X] Other, *specify* direct Push
- [ ] Diamond
- [ ] Jetting
- [ ] Driving
- [ ] Digging

Well Use

- [ ] Public
- [ ] Domestic
- [ ] Livestock
- [ ] Irrigation
- [ ] Industrial
- [ ] Other, *specify* ____
- [ ] Commercial
- [ ] Municipal
- [X] Test Hole
- [ ] Cooling & Air Conditioning
- [ ] Not used
- [ ] Dewatering
- [X] Monitoring

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	To
4.03	PVC	365	0	3.1

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	To
4.82	PVC	10	3.1	6.1

Status of Well

- [ ] Water Supply
- [ ] Replacement Well
- [X] Test Hole
- [ ] Recharge Well
- [ ] Dewatering Well
- [X] Observation and/or Monitoring Hole
- [ ] Alteration (Construction)
- [ ] Abandoned, Insufficient Supply
- [ ] Abandoned, Poor Water Quality
- [ ] Abandoned, other, *specify* ____
- [ ] Other, *specify* ____

Water Details

Water found at Depth (m/ft)	Kind of Water	
[ ] Gas	[ ] Fresh [ ] Untested	[ ] Other, *specify* ____
Water found at Depth (m/ft) [ ] Gas	[ ] Fresh [ ] Untested	[ ] Other, *specify* ____
Water found at Depth (m/ft) [ ] Gas	[ ] Fresh [ ] Untested	[ ] Other, *specify* ____

Hole Diameter

Depth (m/ft) From	To	Diameter (cm/in)
0	6.1	8.25

Results of Well Yield Testing

After test of well yield, water was:
- [ ] Clear and sand free
- [ ] Other, *specify* ____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping ____ hrs + ____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*

Well production *(l/min / GPM)*

Disinfected?
- [ ] Yes
- [ ] No

Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
50		50	
60		60	

Map of Well Location

Please provide a map below following instructions on the back.

See MAP

MW 2

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata drilling Group	7241

Business Address (Street Number/Name)	Municipality
105 Shields Court	Markham

Province	Postal Code	Business E-mail Address
ON	L3R8V2	Wrecords@Stratase.ca.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9053940719	Holladay Phil

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3532		2019/04/22

Well owner's information package delivered
- [ ] Yes
- [ ] No

Date Package Delivered: ____

Date Work Completed: 2019/03/25

Ministry Use Only

Audit No. Z302771

Received APR 15 2019

0506E (2014/11)

Ministry's Copy

© Queen's Printer for Ontario, 2014



PINCHIN

LEGEND

	SITE BOUNDARY
	SITE BUILDING
RES	RESIDENTIAL
COM	COMMERCIAL
LI	LIGHT INDUSTRIAL
(P)	PARKING
	RAILWAY LINE

PROJECT NAME: PHASE I ENVIRONMENTAL SITE ASSESSMENT			
CLIENT NAME: VIV NUTT			
PROJECT LOCATION: 73 BREEZEHILL AVENUE NORTH, OTTAWA, ONTARIO			
FIGURE NAME: SITE AND SURROUNDING LAND USE PLAN			FIGURE NO.: 2
APPROXIMATE SCALE: AS SHOWN	PROJECT NO.: 235945, 001	DATE: FEBRUARY 2019	

EMRB - RECEIVED
APR 15 2019

Ontario — Ministry of the Environment and Climate Change

Measurements recorded in: ☒ Metric ☐ Imperial

Well Tag#:A261094 (See Below)

A261094

Well Record

Regulation 903 Ontario Water Resources Act

5-23250 Page ____ of ____

[redacted]

Address of Well Location (Street Number/Name)	Township	Lot	Concession
73 Breezehill Ave N			

County/District/Municipality	City/Town/Village	Province	Postal Code
	Uxbridge	Ontario	

UTM Coordinates	Zone	Easting	Northing	Municipal Plan and Sublot Number	Other
NAD 83	18	644799	4852637		

Overburden and Bedrock Materials/Abandonment Sealing Record *(see instructions on the back of this form)*

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	Depth (m/ft) To
Brn	Fill		Packed	0	1.83
Brn	Clay	Silt	Soft	1.83	3.1
Grey	Clay	Silt	Soft	3.1	6.1

Annular Space

Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)	Volume Placed (m^3/ft^3)
0	.31	Cement Flushmount	
.31	2.74	Bentonite	
2.74	6.1	Sand	

Method of Construction

☐ Cable Tool ☐ Diamond
☐ Rotary (Conventional) ☐ Jetting
☐ Rotary (Reverse) ☐ Driving
☐ Boring ☐ Digging
☐ Air percussion
☒ Other, *specify* direct push

Well Use

☐ Public ☐ Commercial ☐ Not used
☐ Domestic ☐ Municipal ☐ Dewatering
☐ Livestock ☒ Test Hole ☑ Monitoring
☐ Irrigation ☐ Cooling & Air Conditioning
☐ Industrial
☐ Other, *specify*

Construction Record - Casing

Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	Depth (m/ft) To
4.03	PVC	368	0	3.1

Construction Record - Screen

Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From	Depth (m/ft) To
4.83	PVC	10	3.1	6.1

Status of Well

☐ Water Supply
☐ Replacement Well
☑ Test Hole
☐ Recharge Well
☐ Dewatering Well
☑ Observation and/or Monitoring Hole
☐ Alteration (Construction)
☐ Abandoned, Insufficient Supply
☐ Abandoned, Poor Water Quality
☐ Abandoned, other, *specify*
☐ Other, *specify*

Water Details

Water found at Depth (m/ft)	Kind of Water	
☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*
Water found at Depth (m/ft) ☐ Gas	☐ Fresh ☐ Untested	☐ Other, *specify*

Hole Diameter

Depth (m/ft) From	Depth (m/ft) To	Diameter (cm/in)
0	6.1	8.25

Results of Well Yield Testing

After test of well yield, water was:
☐ Clear and sand free
☐ Other, *specify* _____

If pumping discontinued, give reason:

Pump intake set at *(m/ft)*

Pumping rate *(l/min / GPM)*

Duration of pumping ____ hrs + ____ min

Final water level end of pumping *(m/ft)*

If flowing give rate *(l/min / GPM)*

Recommended pump depth *(m/ft)*

Recommended pump rate *(l/min / GPM)*

Well production *(l/min / GPM)*

Disinfected? ☐ Yes ☐ No

Draw Down Time (min)	Draw Down Water Level (m/ft)	Recovery Time (min)	Recovery Water Level (m/ft)
Static Level			
1		1	
2		2	
3		3	
4		4	
5		5	
10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
50		50	
60		60	

Map of Well Location

Please provide a map below following instructions on the back.

See MAP

MW 3

Comments:

Well Contractor and Well Technician Information

Business Name of Well Contractor	Well Contractor's Licence No.
Strata Drilling Group	7241

Business Address (Street Number/Name)	Municipality
165 Shields Court	Markham

Province	Postal Code	Business E-mail Address
ON	L3R8V2	Wrecords@Stratasoil.com

Bus. Telephone No. (inc. area code)	Name of Well Technician (Last Name, First Name)
9054907919	Halladay Phil

Well Technician's Licence No.	Signature of Technician and/or Contractor	Date Submitted
3832		2019 09 22

Well owner's information package delivered	Date Package Delivered	Date Work Completed
☐ Yes ☐ No	Y Y Y Y M M D D	2019 09 05

Ministry Use Only

Audit No. Z302773

APR 15 2019

Received

0506E (2014/11)

Ministry's Copy

© Queen's Printer for Ontario, 2014



PINCHIN

LEGEND

	SITE BOUNDARY
	SITE BUILDING
RES	RESIDENTIAL
COM	COMMERCIAL
LI	LIGHT INDUSTRIAL
(P)	PARKING
	RAILWAY LINE

PROJECT NAME: PHASE I ENVIRONMENTAL SITE ASSESSMENT			
CLIENT NAME: VIV NUTT			
PROJECT LOCATION: 73 BREEZEHILL AVENUE NORTH, OTTAWA, ONTARIO			
FIGURE NAME: SITE AND SURROUNDING LAND USE PLAN			FIGURE NO.: 2
APPROXIMATE SCALE: AS SHOWN	PROJECT NO.: 235945.001	DATE: FEBRUARY 2019	

EMRB-RECEIVED
APR 15 2019

Well ID

Well ID Number: 7346904
Well Audit Number: *C45377*
Well Tag Number: *A268556*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443870.00 Northing: 5028132.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To	

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To	

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7085

Results of Well Yield Testing

After test of well yield, water was		
If pumping discontinued, give reason		
Pump intake set at		
Pumping Rate		
Duration of Pumping		

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C45377

Date Well Completed: September 30, 2019

Date Well Record Received by MOE: November 12, 2019

Well ID

Well ID Number: 7359833
Well Audit Number: *C40444*
Well Tag Number: *A278961*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443877.00 Northing: 5028530.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7328

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C40444

Date Well Completed: December 05, 2019

Date Well Record Received by MOE: June 03, 2020

Well ID

Well ID Number: 7357891
Well Audit Number: *C48494*
Well Tag Number: *A279017*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443839.00 Northing: 5028551.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7328

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C48494

Date Well Completed: January 16, 2020

Date Well Record Received by MOE: May 07, 2020

Well ID

Well ID Number: 7399141
Well Audit Number: *Z349217*
Well Tag Number: *A299972*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443739.00 Northing: 5028387.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7328

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z349217

Date Well Completed: November 17, 2020

Date Well Record Received by MOE: September 28, 2021

Well ID

Well ID Number: 7387934
Well Audit Number: *Z359395*
Well Tag Number: *A318162*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443987.00 Northing: 5028143.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359395

Date Well Completed: April 30, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388043
Well Audit Number: *Z359451*
Well Tag Number: *A318228*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444020.00 Northing: 5028043.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359451

Date Well Completed: April 30, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388044
Well Audit Number: *Z359467*
Well Tag Number: *A318227*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444029.00 Northing: 5028099.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359467

Date Well Completed: April 29, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388045
Well Audit Number: *Z359465*
Well Tag Number: *A318243*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444017.00 Northing: 5028101.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359465

Date Well Completed: April 29, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388046
Well Audit Number: *Z359448*
Well Tag Number: *A318232*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444022.00 Northing: 5028048.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359448

Date Well Completed: April 27, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388048
Well Audit Number: *Z359450*
Well Tag Number: *A318225*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443999.00 Northing: 5028023.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359450

Date Well Completed: April 27, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388049
Well Audit Number: *Z359446*
Well Tag Number: *A318224*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443989.00 Northing: 5028037.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359446

Date Well Completed: April 26, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7388050
Well Audit Number: *Z359466*
Well Tag Number: *A318241*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444007.00 Northing: 5028091.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z359466

Date Well Completed: April 27, 2021

Date Well Record Received by MOE: March 31, 2021

Well ID

Well ID Number: 7391242
Well Audit Number: *Z364090*
Well Tag Number: *A303023*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443982.00 Northing: 5028150.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z364090

Date Well Completed: May 25, 2021

Date Well Record Received by MOE: June 29, 2021

Well ID

Well ID Number: 7391243
Well Audit Number: *Z364091*
Well Tag Number: *A303024*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443969.00 Northing: 5028115.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z364091

Date Well Completed: May 25, 2021

Date Well Record Received by MOE: June 29, 2021

Well ID

Well ID Number: 7391244
Well Audit Number: *Z364088*
Well Tag Number: *A303025*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443964.00 Northing: 5028112.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z364088

Date Well Completed: May 25, 2021

Date Well Record Received by MOE: June 29, 2021

Well ID

Well ID Number: 7392848
Well Audit Number: *Z361150*
Well Tag Number:
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443878.00 Northing: 5028540.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z361150

Date Well Completed: January 21, 2021

Date Well Record Received by MOE: July 26, 2021

Well ID

Well ID Number: 7399142
Well Audit Number: *C50176*
Well Tag Number: *A215028*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443753.00 Northing: 5028376.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7328

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C50176

Date Well Completed: July 29, 2021

Date Well Record Received by MOE: September 28, 2021

Well ID

Well ID Number: 7402449
Well Audit Number: *C50367*
Well Tag Number: *A311090*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444013.00 Northing: 5028455.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To	

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To	

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7675

Results of Well Yield Testing

After test of well yield, water was		
If pumping discontinued, give reason		
Pump intake set at		
Pumping Rate		
Duration of Pumping		

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C50367

Date Well Completed: September 30, 2021

Date Well Record Received by MOE: November 08, 2021

Well ID

Well ID Number: 7402478
Well Audit Number: *Z366821*
Well Tag Number: *A328474*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443832.00 Northing: 5028529.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z366821

Date Well Completed: September 02, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402479
Well Audit Number: *Z366820*
Well Tag Number: *A328472*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443826.00 Northing: 5028541.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z366820

Date Well Completed: September 02, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402480
Well Audit Number: *Z366822*
Well Tag Number: *A328473*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443828.00 Northing: 5028523.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z366822

Date Well Completed: September 02, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402481
Well Audit Number: *Z368537*
Well Tag Number: *A328471*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443837.00 Northing: 5028518.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368537

Date Well Completed: September 02, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402482
Well Audit Number: *Z368412*
Well Tag Number: *A328478*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443818.00 Northing: 5028519.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368412

Date Well Completed: September 03, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402483
Well Audit Number: *Z368408*
Well Tag Number: *A328477*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443819.00 Northing: 5028529.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368408

Date Well Completed: September 03, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402484
Well Audit Number: *Z368413*
Well Tag Number: *A328479*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443809.00 Northing: 5028534.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368413

Date Well Completed: September 03, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402499
Well Audit Number: *Z368406*
Well Tag Number: *A328476*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443798.00 Northing: 5028525.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368406

Date Well Completed: September 03, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7402500
Well Audit Number: *Z368407*
Well Tag Number: *A328475*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443783.00 Northing: 5028531.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed	

Method of Construction & Well Use

Method of Construction	Well Use	

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368407

Date Well Completed: September 03, 2021

Date Well Record Received by MOE: October 27, 2021

Well ID

Well ID Number: 7404497
Well Audit Number: *C41274*
Well Tag Number: *A331358*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443707.00 Northing: 5028271.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 6964

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: C41274

Date Well Completed: November 23, 2021

Date Well Record Received by MOE: December 03, 2021

Well ID

Well ID Number: 7404785
Well Audit Number: *Z368456*
Well Tag Number: *A287699*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 443964.00 Northing: 5028097.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368456

Date Well Completed: October 06, 2021

Date Well Record Received by MOE: December 07, 2021

Well ID

Well ID Number: 7404786
Well Audit Number: *Z368455*
Well Tag Number: *A287700*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444033.00 Northing: 5028093.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368455

Date Well Completed: October 06, 2021

Date Well Record Received by MOE: December 07, 2021

Well ID

Well ID Number: 7406958
Well Audit Number: *Z364126*
Well Tag Number: *A287710*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444068.00 Northing: 5028459.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z364126

Date Well Completed: November 05, 2021

Date Well Record Received by MOE: December 29, 2021

Well ID

Well ID Number: 7406960
Well Audit Number: *Z364124*
Well Tag Number: *A330905*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	NEPEAN TOWNSHIP
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444073.00 Northing: 5028377.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z364124

Date Well Completed: November 04, 2021

Date Well Record Received by MOE: December 29, 2021

Well ID

Well ID Number: 7406963
Well Audit Number: *Z368306*
Well Tag Number: *A330903*
This table contains information from the original well record and any subsequent updates.

Well Location

Address of Well Location	
Township	OTTAWA CITY
Lot	
Concession	
County/District/Municipality	OTTAWA-CARLETON
City/Town/Village	
Province	ON
Postal Code	n/a
UTM Coordinates	NAD83 — Zone 18 Easting: 444043.00 Northing: 5028473.00
Municipal Plan and Sublot Number	
Other	

Overburden and Bedrock Materials Interval

General Colour	Most Common Material	Other Materials	General Description	Depth From	Depth To

Annular Space/Abandonment Sealing Record

Depth From	Depth To	Type of Sealant Used (Material and Type)	Volume Placed

Method of Construction & Well Use

Method of Construction	Well Use

Status of Well

Construction Record - Casing

Inside Diameter	Open Hole or material	Depth From	Depth To

Construction Record - Screen

Outside Diameter	Material	Depth From	Depth To

Well Contractor and Well Technician Information

Well Contractor's Licence Number: 7241

Results of Well Yield Testing

After test of well yield, water was	
If pumping discontinued, give reason	
Pump intake set at	
Pumping Rate	
Duration of Pumping	

Final water level	
If flowing give rate	
Recommended pump depth	
Recommended pump rate	
Well Production	
Disinfected?	

Draw Down & Recovery

Draw Down Time(min)	Draw Down Water level	Recovery Time(min)	Recovery Water level
SWL			
1		1	
2		2	
3		3	
4		4	
5		5	

10		10	
15		15	
20		20	
25		25	
30		30	
40		40	
45		45	
50		50	
60		60	

Water Details

Water Found at Depth	Kind	

Hole Diameter

Depth From	Depth To	Diameter

Audit Number: Z368306

Date Well Completed: November 03, 2021

Date Well Record Received by MOE: December 29, 2021

Mark St. Pierre

From: Public Information Services <publicinformationservices@tssa.org>
Sent: April 21, 2023 1:36 PM
To: Mark St. Pierre
Subject: RE: Records search request for 75 Breezehill Avenue North in Ottawa, Ontario

Hello,

NO RECORD FOUND IN CURRENT DATABASE

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are no records in our database of any **fuel storage tanks** at the subject address(es).

This is not a confirmation that there are no records in the archives. For a further search in our archives, please submit an application for release of public information (PI Form) through TSSA's new Service Prepayment Portal. The associated fee must be paid via credit card (Visa or MasterCard) through a secure site.
Please follow the steps below to access the new application(s) and Service Prepayment Portal:

1. Click Release of Public Information - TSSA - TSSA and click "need a copy of a document";
2. Select the appropriate application, download it and complete it in full; and
3. Proceed to page 3 of the application and click the link TSSA Service Prepayment Portal under payment options (the link will take you the secure site to pay for the release via credit card).

Accessing the Service Prepayment Portal:

1. Select new or existing customer (*if you are an existing customer, you will need your account # & postal code to access your account);
2. Select the program area: AD (Amusement Devices), BPV (Boilers and Pressure Vessels), ED (Elevating Devices), FS (Fuels Services), OE (Operating Engineers) or SKI (Ski Lifts) and click continue;
3. Enter the application form number (obtained from bottom left corner of application form) and click continue;
    a. When selecting the application form number from the drop-down menu, please make sure you select the application that begins with "PI" (i.e. PI-FS, PI-BPV etc.);
4. Complete the primary contact information section;
5. Complete the fees section;
6. Upload your completed application; and
7. Upload supporting documents (if required) and click continue.

Once all steps have been successfully completed, you will receive your receipt via email.
Questions? Please contact TSSA's Public Information Release team at publicinformationservices@tssa.org.
Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Kind regards,

Kimberly Gage | Public Information Agent
Legal
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3348 | Fax: +1 416-734-3568 | E-Mail: kgage@tssa.org
www.tssa.org

Winner of 2022 5-Star Safety Cultures Award

From: Mark St. Pierre <MStPierre@patersongroup.ca>
Sent: Friday, April 21, 2023 9:52 AM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: Records search request for 75 Breezehill Avenue North in Ottawa, Ontario

[CAUTION]: This email originated outside the organisation.
Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Good morning,

Could you please complete a search of your records for underground/aboveground storage tanks, historical spills or other incidents/infractions for the following addresses for properties located in the Ottawa, ON:

75 Breezehill Avenue North
111 Breezehill Avenue North
100 Breezehill Avenue North
103 Breezehill Avenue North
73 Breezehill Avenue North
53 Breezehill Avenue North
131 Loretta Avenue North
127 Loretta Avenue North
975 Gladstone
145 Loretta Avenue North

Regards,

MARK ST PIERRE, P.ENG.
Intermediate Environmental Engineer

TEL: (613) 226-7381 ext. 126
DIRECT: (613) 229-9822

9 AURIGA DRIVE
OTTAWA ON K2E 7T9

patersongroup.ca

TEMPORARY SHORING DESIGN SERVICES ARE NOW AVAILABLE, PLEASE CONTACT US TO SEE HOW WE CAN HELP!

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

Office Use Only			
Application Number:	Ward Number:	Application Received: (dd/mm/yyyy):	
Client Service Centre Staff:		Fee Received:	$

Historic Land Use Inventory

Application Form

Notice of Public Record

All information and materials required in support of your application shall be made available to the public, as indicated by Section 1.0.1 of *The Planning Act*, R.S.O. 1990, C.P.13.

Municipal Freedom of Information and Protection Act

Personal information on this form is collected under the authority the *Planning Act*, RSO 1990, c. P. 13 and will be used to process this application. Questions about this collection may be directed by mail to Manager, Business Support Services, Planning, Real Estate and Economic Development Department, 110 Laurier Avenue West, Ottawa, K1P 1J1, or by phone at (613) 580-2424, ext. 24075

Background Information

***Site Address or Location:** *75 Breezehill Avenue / 35 Laurel Street*

** Mandatory Field*

Applicant/Agent Information:

Name: *Paterson Group*

Mailing Address: *9 Auriga Drive*

Telephone: *613-226-7381* Email Address: *mstpierre@patersongroup.ca*

Registered Property Owner Information: ☐ Same as above

Name: *2729685 Ontario Inc.*

Mailing Address:

Telephone: Email Address:

Site Details

Legal Description and PIN: *Part of Lot 38, Concession 1*

What is the land currently used for? *Commercial*

Lot frontage: _____ m Lot depth: _____ m Lot area: _____ m²

OR Lot area: (irregular lot) 6174.62 m²

Does the site have Full Municipal Services: (•) Yes ( ) No

Required Fees

Please don't hesitate to visit the Historic Land Use Inventory website more information. Fees must be paid in full at the time of application submission.

Planning Fee $136.00

Submittal Requirements

The following are required to be submitted with this application:

1. **Consent to Disclose Information:** Consultants and other third parties may make requests for information on behalf of an individual or corporation. However, if the requester is not the owner of the property, **the requester must provide the City of Ottawa with a 'consent to disclose information' letter, signed by the property owner.** This will authorize the City of Ottawa to release any relevant information about the property or its owner(s) to the requester. Consent for disclosure is required in the event that personal information or proprietary company information is found concerning the property and its owner. All consents must clearly indicate the name of the property owner as well as the name of the requester, and must be signed and dated.
2. **Disclaimer:** Requesters must read and understand the conditions included in the attached disclaimer and submit a signed disclaimer to the City of Ottawa's Planning, Real Estate and Economic Development Department. This disclaimer is related to the Historic Land Use Inventory and must be received by the City of Ottawa, signed and dated by the requestor, before the process can begin.
3. **A site plan or key plan of the property, its location and particular features.**
4. **Any significant dates or time frames that you would like researched.**

Disclaimer
For use with HLUI Database

CITY OF OTTAWA ("the City") is the owner of the Historical Land Use Inventory ("HLUI"), a database of information on the type and location of land uses within the geographic area of Ottawa, which had or have the potential to cause contamination in soil, groundwater or surface water.

The City, in providing information from the HLUI, to Paterson Group ("the Requester") does so only under the following conditions and understanding:

1. The HLUI may contain erroneous information given that such records and sources of information may be flawed. Changes in municipal addresses over time may have introduced error in such records and sources of information. The City is not responsible for any errors or omissions in the HLUI and reserves the right to change and update the HLUI without further notice. The City does not, however, make any commitment to update the HLUI. Accordingly, all information from the HLUI is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.

2. City staff will perform a search of the HLUI based on the information given by the Requester. City staff will make every effort to be accurate, however, the City does not provide an assurance, guarantee, warranty, representation (express or implied), as to the availability, accuracy, completeness or currency of information which will be provided to the Requester. The HLUI in no way confirms the presence or absence of contamination or pollution of any kind. The information provided by the City to the Requester is provided on the assumption that it will not be relied upon by any person whatsoever. The City denies all liability to any such persons attempting to rely on any information provided from the HLUI database.

3. The City, its employees, servants, agents, boards, officials or contractors take no responsibility for any actions, claims, losses, liability, judgments, demands, expenses, costs, damages or harm suffered by any person whatsoever including negligence in compiling or disseminating information in the HLUI.

4. Copyright is reserved to the City.

5. Any use of the information provided from the HLUI which a third party makes, or any reliance on or decisions to be based on it, are the responsibilities of such third parties. The City, its employees, servants, agents, boards, officials or contractors accept no responsibility for any damages, if any, suffered by a third party as a result of decisions made as a result of an information search of the HLUI.

6. Any use of this service by the Requestor indicates an acknowledgement, acceptance and limits of this disclaimer.

7. All information collected under this request and all records provided in response to this request are subject to the provisions of the Municipal Freedom of Information and Protection of Privacy Act, R.S.O. 1990, c. M.56, as amended.

Signed: 

Dated (dd/mm/yyyy): 04/04/2023

Per: Mark St Pierre
(Please print name)

Title: Engineer

Company: Paterson Group

HLUI SUMMARY REPORT
AREA FEATURES

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	ST_DIR	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	ST_DIR2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	STORAGE_TANK	Shape_Length	Shape_Area
2243	AARKDALE DESIGN AND OFFSE	Commercial Printing Industries	1998-SC	1	1998		880	WELLINGTON	ST		OTTAWA	900	ALBERT	ST			40980005	Old Ottawa					769.5458882	32613.86415
4685	CAMPBELL PRINTING CO	Commercial Printing Industries	1970-M	1	1970		880	WELLINGTON	ST		OTTAWA	900	ALBERT	ST			40980005	Old Ottawa					769.5458882	32613.86415
4686	FAIRBURN STUDIOS LTD	Commercial Printing Industries	1970/71-S	1	1970-1971		880	WELLINGTON	ST		OTTAWA	900	ALBERT	ST			40980005	Old Ottawa					769.5458882	32613.86415
4687	KG CAMPBELL CORPORATION	Commercial Printing Industries	1994-PID	1	1994		880	WELLINGTON	ST		OTTAWA	900	ALBERT	ST			40980005	Old Ottawa					769.5458882	32613.86415
4688	PRINTING CENTER	Commercial Printing Industries	2005-SelectPhone	1	2005		880	WELLINGTON	ST		OTTAWA	900	ALBERT	ST			40980005	Old Ottawa					769.5458882	32613.86415
4689	RAPID GRIP AND BATTEN LTD	Commercial Printing Industries	1958-1965-S; 1970-M	1	1958-1965-1970		880	WELLINGTON	ST		OTTAWA	900	ALBERT	ST			40980005	Old Ottawa					769.5458882	32613.86415
7280	INTERPROVINCIAL PAVING CO	Site Work	1960-M; 1970-M; 1980-M; 1998-S	1	1960-1980	c. 1960; c.	98	BAYSWATER	AVE		OTTAWA	98	BAYSWATER	AVE		K1Y2G1	40990373	OLD OTTAWA	238390; 238910	369; 412; 421			68.74899931	278.7347792
7281	MISTER SEALER CORP	Industrial Construction (Other Than Buildings)	2005-SelectPhone	1	2005	c. 2005	98	BAYSWATER	AVE			98	BAYSWATER	AVE		K1Y2G1	40990373	OLD OTTAWA	237310				68.74899931	278.7347792
7380	OTTAWA LITHO PLATEMAKERS	Platemaking, Typesetting and Bindery Industry	1970-M; 1980-M	1	1960-1980	c. 1970-19	14	BAYSWATER	AVE		OTTAWA	10	BAYSWATER	AVE		K1Y2E4	40980026	OLD OTTAWA	323120; 812921	282			158.9967149	1169.662937
7382	D KEMP EDWARDS	Lumber and Building Materials, Wholesale	1930-M; 1940-M; 1948-FIP-320-8	1	1900-1980	c. 1900-19	25	BAYSWATER	AVE		OTTAWA	25	BAYSWATER	AVE		K1Y2E5	40980169	OLD OTTAWA	321111; 321112	251; 254; 9	listed In M.1900 at #8-16 I		389.4280939	9025.886899
8101	DESOURDY 1949 PAVING INC	Site Work	1998-SC	1	1998		98	BAYSWATER	AVE		OTTAWA	98	BAYSWATER	AVE			40990373	OTTAWA					68.74899931	278.7347792
4801	D & E MCEWAN	Other Chemical Products Industries	1920-M	2	1920			WELLINGTON	ST		OTTAWA	141	BAYVIEW	RD		K1Y4M3	40980008	Old Ottawa					769.5458882	32613.86415
1202	CANADIAN OIL CO LIMITED	Petroleum Products, Wholesale	1912-FIP-112-821; 1920-M; 1922	1	1912-1956	c. 1912-19	45	BREEZEHILL	AVE		OTTAWA	47	BREEZEHILL	AVE	N	K1Y2H4	40980140	OLD OTTAWA	412110; 419120	479; 511	45 - 47; FIP1901 - vacant	2 UST-coal tar(1912,1922	158.6278982	1384.319589
5545	SUPERIOR EQUIPMENT	Retail trade	2012-ES	1			73	BREEZEHILL	AVE	N		73	BREEZEHILL	AVE	N	K1Y2H6	41070003	OLD OTTAWA	443110				188.8020984	1911.654799
7145	BRUCE COAL CO (YARD)	Lumber and Building Materials, Wholesale	1920-M; 1922-FIP-118-820; 193	1	1920-1970	c. 1920-19	53	BREEZEHILL	AVE		OTTAWA	53	BREEZEHILL	AVE	N	K1Y2H6	41070002	OLD OTTAWA	412110; 416310	453; 511; 563			304.6721262	4430.841504
7148	ALASKA STEEL AND IRON WOR	Other Repair Services	1980-M	1	1980	c. 1980	109	BREEZEHILL	AVE		OTTAWA	103	BREEZEHILL	AVE	N	K1Y2H6	41070278	OLD OTTAWA	331511; 332810	294; 994			89.96541279	442.0633765
7274	TAKAKI AUTOMOTIVE	Automobile Repairing & Service	1960-M; 1970-M; 1980-M; 1990-(	1	1960-2017	SalesGeni	47	BREEZEHILL	AVE		OTTAWA	47	BREEZEHILL	AVE	N	K1Y2H4	40980013	OLD OTTAWA	81111104	Jan-38	3 and 47		199.4265338	1275.540475
7734	ELMER'S AUTO ELECTRIC	Motor Vehicle Repair Shops	1980-M	1	1980		55	BREEZEHILL	AVE	NORTH		55	BREEZEHILL	AVE	NORTH		41070002						190.0960841	2174.925655
7735	KINGSWAY AUTOMOTIVE	Motor Vehicle Repair Shops	1998-SC	1	1998		55	BREEZEHILL	AVE	NORTH		55	BREEZEHILL	AVE	NORTH		41070002						190.0960841	2174.925655
7736	PONAK AUTO REPAIR	Motor Vehicle Repair Shops	1998-SC	1	1998		55	BREEZEHILL	AVE	NORTH		55	BREEZEHILL	AVE	NORTH		41070002						190.0960841	2174.925655
8079	BRUCE FUELS LTD	Lumber and Building Materials, Wholesale	1960-1970-M	1	1960-1970		53	BREEZEHILL	AVE		OTTAWA	53	BREEZEHILL	AVE			41070002	OTTAWA					304.6720644	4430.841395
8080	JOSEPH BARRIE (COAL & WOO	Lumber and Building Materials, Wholesale	1920-1922-M	1	1920-1922		53	BREEZEHILL	AVE		OTTAWA	53	BREEZEHILL	AVE			41070002	OTTAWA					304.6720644	4430.841395
8785	GERVAIS MOTORS LTD	Motors	1990-CD	1	1990	CD 1990	3	BREEZEHILL	AVE	NORTH		3	BREEZEHILL	AVE	N	K1Y2H4	40980182	OLD OTTAWA					73.71147672	308.4360518
8801	JAPAN AUTO SERVICE	Other-Garage	2001-ES; 2005-SelectPhone; 200	1	2001-2017	ES 2001; E	55	BREEZEHILL	AVE			53	BREEZEHILL	AVE	N	K1Y2H6	41070002	OLD OTTAWA	811111; 811121				190.0960841	2174.925655
8802	MING AUTO SERVICE	Other-Garage	2001-ES; 2006-ES; 2012-ES; 20	1	2001-2017	ES 2001; E	55	BREEZEHILL	AVE			53	BREEZEHILL	AVE	N	K1Y2H6	41070002	OLD OTTAWA	811111; 811121				190.0960841	2174.925655
8803	BREEZEHILL AUTO BODY	Motor Vehicle Repair Shops	1980-M; 1990-CD; 1998-SC; 200	1	1960-2012	c. 1980; c.	55	BREEZEHILL	AVE	NORTH		53	BREEZEHILL	AVE	N	K1Y2H6	41070002	OLD OTTAWA	811112; 811119	635			190.0960841	2174.925655
8814	907462 ONTARIO LIMITED	Motor Vehicle Repair Shops	2005-PropertyAssessment	1	2005	c. 2005	111	BREEZEHILL	AVE	NORTH	OTTAWA	111	BREEZEHILL	AVE	N	K1Y2H6	41070007	OLD OTTAWA	811111; 811112; 811119; 811121; 811199				107.833499	714.3645739
8815	GRANDTECH AUTO	Motor Vehicles, Wholesale, Automobile Repairing	2001-ES; 2005-SelectPhone; 200	1	2001-2017	c. 2001; c.	111	BREEZEHILL	AVE	NORTH		111	BREEZEHILL	AVE	N	K1Y2H6	41070007	OLD OTTAWA	811111				107.833499	714.3645739
8824	MURRAY LEN SUPPLY INC	Other Machinery, Equipment and Supplies, Whole	2001-ES	1	2001	c. 2001	103	BREEZEHILL	AVE		OTTAWA	103	BREEZEHILL	AVE	N	K1Y2H6	41070278	OLD OTTAWA	417990				117.2869886	858.4252144
8843	J SAINT GERMAIN AND SON	Exterior Close In Work	1970-M; 1980-M	1	1970-1980	c. 1970-19	99	BREEZEHILL	AVE		OTTAWA	99	BREEZEHILL	AVE	N	K1Y2H6	41070279	OLD OTTAWA	238140; 238150	423			86.91470833	395.3758632
10718	ARO INDUSTRIES	Souvenirs	2004-GWStudy	1	1973	GW Study	73	BREEZEHILL	AVE	NORTH	OTTAWA	73	BREEZEHILL	AVE	N	K1Y2H6	41070003	OLD OTTAWA	339990	3999	73 Breezehill Ave N		188.8020984	1911.654799
10719	CHARCOAL SUPPLY CO	Petroleum Products, Wholesale	1920-M; 1930-M; 1940-M	1	1900-1950	c. 1920-19	73	BREEZEHILL	AVE		OTTAWA	73	BREEZEHILL	AVE	N	K1Y2H6	41070003	OLD OTTAWA	412110; 419120	511			188.8020984	1911.654799
43	CCB 2000	Manufacturing	2012-ES	1	2012		250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	336320				769.5458882	32613.86415
44	QUALITY SIGNS	Signs (Mfrs)	2006-ES; 2017-SalesGenie	1	2006-2017		250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	339990				769.5458882	32613.86415
45	TORBRAM ELECTRIC SUPPLY	Manufacturing	2006-ES	1	2006		250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	333416				769.5458882	32613.86415
46	VISION 2000 GLASS	Manufacturing	2012-ES	1	2012		250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	327214				769.5458882	32613.86415
509	W C EDWARDS AND COMPANY	Sawmill, Planing Mill and Shingle Mill Products In	1912-FIP-112-825; 1920-M; 1930	1	1900-1956	c. 1912-19	991	SOMERSET	ST	WEST	OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	321111; 321112	251; 254; 9	Shavings press, planing m		692.2199138	18152.31663
2221	BOOTH STREET AUTO BODY	Auto Shop	1990-CD	1	1990	CD 1990	348	BOOTH	ST	NORTH		250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA					769.5458882	32613.86415
2222	PERFORMANCE MOTORS OTTA	Garage Repairs	1990-CD	1	1990	CD 1990	959	CUMMINGS	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA					769.5458882	32613.86415
2223	CIELO PRINT INC	Printers (Mfrs)	2006-ES; 2012-ES; 2017-SalesG	1	2006-2017	ES 2006; E	250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323114; 323115; 323119; 326121; 339950; 541690; 561430; 812320				769.5458882	32613.86415
2224	FED-PUBLIC WORKS	Professional, scientific and technical services	2001-ES; 2012-ES	1	2001-2012	ES 2001; E	880	WELLINGTON	ST			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	541690; 812320; 911910				769.5458882	32613.86415
2225	MARQUARDT PRINTING	Printers (Mfrs)	2001-ES; 2004-GWStudy; 2006-I	1	1948-2017	ES 2001; E	880	WELLINGTON	ST			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	541690; 812320; 911910				769.5458882	32613.86415
2226	OTTAWA PRINT FINISHING INC	Manufacturing	2006-ES; 2012-ES	1	2006-2016	ES 2006; E	250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323114; 323115; 323119; 326121; 339950; 541690; 561430; 812320				769.5458882	32613.86415
2227	ELDON DRAPERY & VERTICAL (	Drapery & Curtain Cleaners	2006-ES; 2012-ES; 2017-SalesG	1	2006-2017	ES 2006; E	270	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	232490; 551114; 812320				769.5458882	32613.86415
2228	MICRON PLASTICS	Manufacturing	2006-ES; 2012-ES	1	2006-2012	ES 2006; E	250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323114; 323115; 323119; 326121; 339950; 541690; 561430; 812320				769.5458882	32613.86415
2229	PSI MECHANICAL SERVICES IN(	Controls Control Systems/Regulators-Mfrs	1998-SC; 2006-ES; 2012-ES; 20	1	1998-2017	ES 2006; E	250	CITY CENTRE	AVE			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323114; 323115; 323119; 326121; 339950; 541690; 561430; 812320				769.5458882	32613.86415
2230	PEAK SPORTSWEAR	Sporting Goods and Toy Industries	2001-ES	2	2001	c. 2001	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	339920				769.5458882	32613.86415
2231	ALLEGRA PRINT & IMAGING	Men'S and Boys' Clothing Industries	2003-PID	2	2003	c. 2003	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323113	BAY 142			769.5458882	32613.86415
2232	PRIMOSE CARTAGE LIMITED	Highway and Heavy Construction	2001-ES	2	2001	c. 2001	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	238910; 238990				769.5458882	32613.86415
2233	ULTRALUX	Lumber and Building Materials, Wholesale	2005-SelectPhone	1	2005	c. 2001; c.	160	SPRUCE	ST			250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	416340; 444120				769.5458882	32613.86415
2234	BLM TRADE PRINTERS LIMITED	Platemaking, Typesetting and Bindery Industry	1998-SC; 2000-PID; 2006-ES	2	1998-2006	c. 1998; c.	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323114; 323115	281	BAY 226		769.5458882	32613.86415
2235	BROWNS CLEANERS & TAILORS	Laundries and Cleaners	1994-PID; 1998-SC; 2000-PID; 2	1	1998-2017	c. 1994-19	6	CHAMPAGNE	AVE	NORTH	OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	561740; 812310	972			769.5458882	32613.86415
2236	JULES PATRY LIMITED	Other Chemical Products Industries	1920-M; 1998-SC; 2004-GWStuc	2	1900-1998	c. 1920; c.	0	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	325520; 325910	379			769.5458882	32613.86415
2237	DIPLOMA PRODUCTIONS	Other Textile Products Industries	2001-ES	2	2001	c. 2001	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	313320				769.5458882	32613.86415
2238	DISPLAY LAMINATING	Other Textile Products Industries	2001-ES; 2004-GWStudy; 2006-I	1	1998-2017	c. 1998; c.	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	313320; 321114	259; 279; 397			769.5458882	32613.86415
2239	HORNBLOWER BOOKS	Combined Publishing and Printing Industries	2001-ES	2	2001	c. 2001	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	511130				769.5458882	32613.86415
2240	HORTICULTURAL PLANT MAINT	Recreational Vehicle Dealers (Where Servicing Is	2001-ES	2	2001	c. 2001	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	811490				769.5458882	32613.86415
2241	J R BOOTH LUMBER YARD - SP/	Lumber and Building Materials, Wholesale	1901-FIP-113-826; 1912-FIP-113	1	1912-1953	c. 1912	161	SPRUCE	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	321111; 321112	251; 479; 9	M. 1956, M. 1963 Located		1199.075207	55570.58033
2242	LALONDE APPLIANCE CARE INC	Hardware, Tool and Cutlery Industries	2000-PID	2	2000	c. 2000	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	332510		UNIT 118		769.5458882	32613.86415
2245	NEW SUN TECHNOLGIES LIMITE	Other Machinery and Equipment Industries	2003-PID	2	2003	c. 2003	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	335990		UNIT 138		769.5458882	32613.86415
2246	OTTAWA STAIRWORKS LIMITEC	Other Wood Industries	1900-M; 1901-FIP-119-8281912-	1	1910-1930	c. 1910-19	989	SOMERSET	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	321114; 321215	254; 259			769.5458882	32613.86415
2247	VISION FORM	Signs (Mfrs)	2016-PID; 2017-SalesGenie	1	2016-2017	PID2016	244	CITY CENTRE	AVE		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	<Null>			244	769.5458882	32613.86415
2248	FURNITURE AFFAIRS	Manufacturing	2012-ES; 2016-PID	1	2016	PID2016	250	CITY CENTRE	AVE		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	337121; 337123; 337126				769.5458882	32613.86415
2249	EQUITY REALTY GROUP INC	Real estate and rental and leasing	2016-PID	1	2016	PID2016	250	CITY CENTRE	AVE		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	531310				769.5458882	32613.86415
2250	LOMOR PRINTING 7168926	Printers (Mfrs)	2017-SalesGenie	1	2017	SalesGeni	250	CITY CENTRE	AVE		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	32311109	Feb-52		134	769.5458882	32613.86415
2251	PATRY JULES LTD	Fireworks-Manufacturers	2017-SalesGenie	1	2017	SalesGenie 2017					OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	32599812	Sep-99		202	769.5458882	32613.86415
2252	STUDIO X OTTAWA INC	Die Cutting (Mfrs)	2017-SalesGenie	1	2017	SalesGenie 2017					OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	33351401	Mar-44		122	769.5458882	32613.86415
4690	TRAVERS 1910 LIMITED	Commercial Printing Industries	1970/71-S; 1970-M; 1971-M; 198	1	1970-2000	c. 1970; c.	880	WELLINGTON	ST		OTTAWA	250	CITY CENTRE	AVE		K1R6K7	40980009	OLD OTTAWA	323114; 323115	281; 282; 9	UNIT 224		769.5458882	32613.86415
218	FED-PUBLIC WORKS	Public administration	2001-ES; 2006-ES; 2012-ES	1	2001-2012		933	GLADSTONE	AVE			933	GLADSTONE	AVE		K1A0T4	41070029	OLD OTTAWA	911910				25.25572272	21.45779422
1894	R C O C	Commercial Printing Industries	1956-M	1	1956		1010	SOMERSET	ST	WEST	OTTAWA	933	GLADSTONE	AVE		K1A0T4	41070039	Old Ottawa					1052.663511	44662.91048
3765	PUBLIC WORKS AND GOVERNM	General Administrative Services	2000-PID; 2001-ES; 2006-ES; 20	1	2000-2016	ES 2001; E	933	GLADSTONE	AVE			933	GLADSTONE	AVE		K1A0T4	41070039	OLD OTTAWA	911910				1052.663511	44662.91048
3766	GOV'T OF CANADA - DEPT OF S	Commercial Printing Industries	1912-FIP-118-832; 1922-FIP-119	1	1949-1980	c. 1956; c.	1010	SOMERSET	ST	WEST	OTTAWA	933	GLADSTONE	AVE		K1A0T4	41070039	OLD OTTAWA	323114; 323115	281; 815	R. C. O. C. - central ordna		1052.663511	44662.91048
5212	SILKWEAR	Manufacturing	2001-ES	1			951	GLADSTONE	AVE			951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	315231				309.3166816	5747.459862
7147	BRITISH AMERICAN BANK NOTE	Commercial Printing Industries, Printing (Specialty	1948-M; 1949-M; 1950-M; 1957-I	1	1948-2016	c. 1948-19	975	GLADSTONE	AVE		OTTAWA	975	GLADSTONE	AVE		K1Y4W5	41070009	OLD OTTAWA	323114; 323115	281; 282			503.2220305	14188.78579
8081	SECURITY PRINT	Commercial Printing Industries	1980-M	1	1980		975	GLADSTONE	AVE		OTTAWA	975	GLADSTONE	AVE			41070009	OTTAWA					503.2220765	14188.78617
8150	CANADA PRINTING INK	Other Chemical Products Industries	1970-M; 1980-1994-M	2	1970-1994		155	LORETTA	AVE	NORTH	OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	Old Ottawa					309.3166816	5747.459862
8826	DAVE'S GAS BAR	Gas Station	1990-CD	2	1990	CD 1990	971	GLADSTONE	AVE			951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA					309.3166816	5747.459862
8827	POPULAR PRINTING	Other Chemical Products Industries	1970-M; 1980-M	2	1960-1980	c. 1970; c.	155	LORETTA	AVE	NORTH	OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	323114; 323115	281; 379	Unit B		309.3166816	5747.459862
8828	REGIONAL TEXTILES	Other Textile Products Industries	1980-M	2	1960-1980	c. 1980	155	LORETTA	AVE	NORTH	OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	313220; 313320	199			309.3166816	5747.459862
8829	STANDARD BREAD DIVISION OF	Bakery Products Industries	1930-M; 1940-M; 1948-FIP-319-8	1	1900-1956	c. 1930-19	155	LORETTA	AVE		OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	311814; 311821	107		1 UST - fuel oil (1948)	309.3166816	5747.459862
8830	SPORTIVE SPORTSWEAR	Men'S and Boys' Clothing Industries	2001-ES; 2004-GWStudy	2	1984-2004	c. 2001	155	LORETTA	AVE		OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	315299				309.3166816	5747.459862
8831	VESUVIO IRON WORKS	Iron Foundries	1998-SC	2	1998	c. 1998	949	GLADSTONE	AVE		OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	331511; 332810	294			309.3166816	5747.459862
8832	HOCO BRANDS LIMITED	Sugar and Sugar Confectionery Industries	1998-SC; 2004-GWStudy	2	1971-1998	c. 1998	155	LORETTA	AVE	NORTH	OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	311310; 311320	108			309.3166816	5747.459862
8833	LAWCOM MANUFACTURING LIM	Electric Lighting Industries	1970/71-S; 1970-M; 1971-M	2	1970-1971	c. 1970-19	155	LORETTA	AVE			951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	327215; 332321	303; 333	Unit B; Products include- (		309.3166816	5747.459862
8834	LOVE PRINTING SERVICE LIMIT	Combined Publishing and Printing Industries	1970/71-S; 1970-M; 1971-M; 198	1	1970-1994	c. 1970-19	951	GLADSTONE	AVE			951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	323114; 323115	281; 284	Love Printing Service Ltd.		309.3166816	5747.459862
8835	NORTHERN ART GLASS	Lumber and Building Materials, Wholesale	2005-SelectPhone	2	2005	c. 2005	955	GLADSTONE	AVE			951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	444120				309.3166816	5747.459862
8836	ORVILLE'S ELECTRIC SERVICE	Electrical and Electronic Machinery, Equipment A	1998-SC; 2001-ES; 2017-SalesG	2	1998-2017	c. 1998; c.	949	GLADSTONE	AVE		OTTAWA	951	GLADSTONE	AVE		K1Y3E5	41070276	OLD OTTAWA	811112; 811119	635			309.3166816	5747.459862
3772	VENICE IRON WORKS	Other Repair Services, Manufacturers	1998-SC; 2001-ES; 2006-ES; 20	1	1998-2017	c. 1998	17	LARCH	ST		OTTAWA	15	LARCH	ST		K1R6W4	41070066	OLD OTTAWA	331511; 332810	294; 994			156.3084869	914.8534472
8805	PAPER SIGN MAN THE	Signs (Mfrs)	2012-ES; 2017-SalesGenie	1	2012-2017	ES 2012	35	LAUREL	ST			35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	339950				377.1582166	6174.607221
8806	BREEZEHILL HEATING LIMITED	Heating Equipment Industry; Sheet Metal Specialt	1990-CD; 2004-GWStudy; 2005-	1	1990-2005	c. 2001; c.	75	BREEZEHILL	AVE	NORTH		35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	333416; 416210				377.1582166	6174.607221
8807	CARQUEST OF OTTAWA CENTR	Machine Shop Industry	2003-PID; 2004-GWStudy	1	2003	c. 2003	35	LAUREL	ST		OTTAWA	35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	336350		UNIT A		377.1582166	6174.607221
8808	CROLLA CONSTRUCTION CORF	Non Residential Building and Development	2001-ES	1	2001	c. 2001	35	LAUREL	ST		OTTAWA	35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	236210; 236220				377.1582166	6174.607221
8809	EMERITUS ENGRAVING	Recreational Vehicle Dealers (Where Servicing Is	2001-ES	1	2001	c. 2001	75	BREEZEHILL	AVE		OTTAWA	35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	811490				377.1582166	6174.607221
8810	GRANT TRADING-COAL AND W(	Lumber and Building Materials, Wholesale	1940-M	1	1940	c. 1940	75	BREEZEHILL	AVE		OTTAWA	35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	412110; 416310	511; 563			377.1582166	6174.607221
8811	IDS INTL DUPLICATION SVC	Other Manufactured Products Industries	2005-SelectPhone	1	2005	c. 2005	35	LAUREL	ST			35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	334610				377.1582166	6174.607221
8812	LEBRUN BUILDING SERVICES	Services to Buildings and Dwellings	2003-PID	1	2003	c. 2001; c.	75	BREEZEHILL	AVE	NORTH	OTTAWA	35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	236110; 561799		UNIT G		377.1582166	6174.607221
8813	SIGNS IN 23 HOURS	Signs (Mfrs)	2017-SalesGenie	1	2017	SalesGenie 2017					OTTAWA	35	LAUREL	ST		K1Y4M4	41070004	OLD OTTAWA	33995008	Feb-93	B		377.1582166	6174.607221
7286	BELL TELEPHONE CO OF CANA	Communication	1956-FIP-319-4-857; 1956-M	1	1956	c. 1956	145	LORETTA	AVE	NORTH	OTTAWA	145	LORETTA	AVE	N	K1Y2J7	41070013	OLD OTTAWA	334210; 334220	335; 551; 9	FIP1912 - vacant lot FIP19	1 UST - gasoline	272.6671464	4249.258046
8816	BUCHANAN LIGHTING	Lamp Bulbs-Manufacturers, Retail	2001-ES; 2004-GWStudy; 2005-S	2	2001-2017	ES 2001; E	129	LORETTA	AVE	NORTH		127	LORETTA	AVE	N		41070015	OLD OTT

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	SOURCE_UPDATE_SORTED	QAQC	YEAR	YEAR_1	ST_NUM	ST_NAME	ST_SUFFIX	ST_DIR	MUNICIPALITY	ST_NUM2017	ST_NAME2017	ST_SUFFIX2017	ST_DIR2017	POSTAL_CODE2017	PIN2017	MUNICIPALITY2017	NAICS	SIC	COMMENTS	STORAGE_TANK	Shape_Length	Shape_Area
2265	PRESTON HARDWARE	Interior and Finishing Work; Hardware, Tools (Pov	2001-ES; 2004-GWStudy; 2005-S	1	2005	c. 2001; c.	248	PRESTON	ST			232	PRESTON	ST		K1R7R4	41070041	OLD OTTAWA	238340; 444130		#234		354.5827406	5847.169689
1093	VALLEY CHEMICALS	Paint and Varnish Industry	1950-M; 1958-M; 1958-S; 1960-M	1	1900-1965	c. 1950-19	963	SOMERSET	ST	WEST	OTTAWA	961	SOMERSET	ST	W	K1R6R8	41070121	OLD OTTAWA	325510; 334110	336; 375	963-965; Chemical factor		64.02577649	254.6589596
1320	DEPARTMENT OF VETERANS AI	Platemaking, Typesetting and Bindery Industry	1949-1950-M	1	1949-1950		989	SOMERSET	ST	WEST	WEST	989	SOMERSET	ST	WEST		41070124	OTTAWA					182.1236568	1847.109066
1815	ROBT TAPE LIMITED	Machine Shop Industry	2000-PID; 2003-PID	1	2000-2003		989	SOMERSET	ST	WEST	OTTAWA	989	SOMERSET	ST	W	K1R6R8	41070124	Old Ottawa					182.1236568	1847.109066
2326	BREADNER CO LIMITED	Jewellery and Precious Metal Industries	1910-M; 1912-FIP-119-712; 192(	1	1900-1957	c. 1910-19	1002	SOMERSET	ST	WEST	OTTAWA	1002	SOMERSET	ST	W	K1R6R9	41070113	OLD OTTAWA	331490	392			84.38064841	329.8618132
2327	G K DENTAL LAB INC	Medical and Other Health Laboratories	2001-ES	1	2001	c. 2001	1002	SOMERSET	ST	WEST	OTTAWA	1002	SOMERSET	ST	W	K1R6R9	41070113	OLD OTTAWA	621510				84.38064841	329.8618132
2348	RL CRAIN LIMITED	Platemaking, Typesetting and Bindery Industry	1948-FIP-116-828; 1949-M; 195(	1	1921-1964	c. 1948-19	989	SOMERSET	ST	WEST	OTTAWA	989	SOMERSET	ST	W	K1R6R8	41070124	OLD OTTAWA	323114; 323115	281; 282; 479			182.1236568	1847.109066
2349	ROBERT TAPE LIMITED	Machine Shop Industry	1970/71-S; 1970-M; 1971-M; 198	1	1960-2005	c. 1970-19	989	SOMERSET	ST	WEST		989	SOMERSET	ST	W	K1R6R8	41070124	OLD OTTAWA	332710; 332991	336; 319			182.1236568	1847.109066
2350	BAKER BROTHERS SASH AND D	Sash, Door and Other Millwork Industries	1940-M; 1950-M	1	1900-1950	c. 1940-19	989	SOMERSET	ST	WEST	OTTAWA	989	SOMERSET	ST	W	K1R6R8	41070124	OLD OTTAWA	321215; 321911	254			182.1236568	1847.109066
2351	INTERNATIONAL PAINTS (CANA	Paint and Varnish Industry	1970-M; 1980-M	1	1970-1980	c. 1970-19	160	SPRUCE	ST		OTTAWA	989	SOMERSET	ST	W	K1R6R8	41070124	OLD OTTAWA	325510	375			182.1236568	1847.109066
3692	GENESOVE PRESS LIMITED	Combined Publishing and Printing Industries	1901-FIP-119-828; 1912-FIP-119	1	1960-1963	c. 1960-19	969	SOMERSET	ST	WEST	OTTAWA	969	SOMERSET	ST	W	K1R6R8	41070122	OLD OTTAWA	323114; 323115	281; 282; 284			105.9022756	687.2419827
3693	MUSCA-WINE PRESSING &	Distillery Products Industry	2001-ES; 2006-ES	1	2001-2006	c. 2001	969	SOMERSET	ST		OTTAWA	969	SOMERSET	ST	W	K1R6R8	41070122	OLD OTTAWA	312130				105.9022756	687.2419827
3782	CORPORATION CITY OF OTTAW	Public administration	2016-PID	1	2016	PID2016	930	SOMERSET	ST	WEST	OTTAWA	930	SOMERSET	ST	W	K1R6R9	41070111	OLD OTTAWA	913150		<Null>		525.9745321	16417.95709
5200	CAS-TECH	Retail trade	2006-ES	1			1066	SOMERSET	ST	W		1066	SOMERSET	ST	W	K1Y3C5	40990367	OLD OTTAWA	443120				155.4377189	1509.478431
5201	EVOLUTEL INC	Manufacturing	2006-ES	1			1066	SOMERSET	ST	W		1066	SOMERSET	ST	W	K1Y3C5	40990367	OLD OTTAWA	334210				155.4377189	1509.478431
5202	GRAFIK VISUALS	Signs (Mfrs)	2012-ES; 2017-SalesGenie	1			1066	SOMERSET	ST	W		1066	SOMERSET	ST	W	K1Y3C5	40990367	OLD OTTAWA	339950				155.4377189	1509.478431
5210	APPLIANCE HEAVEN	Appliance, Television, Radio and Stereo Stores	2006-ES	1			1089	SOMERSET	ST	W		1089	SOMERSET	ST	W	K1Y3C6	40980029	OLD OTTAWA	443110				83.88940209	350.2152408
5538	APPLIANCE HEAVEN	Appliance, Television, Radio and Stereo Stores	2001-ES	1			1092	SOMERSET	ST			1092	SOMERSET	ST	W	K1Y3C7	40990250	OLD OTTAWA	442110				64.47214342	246.1514094
7134	WHELAN MOTORS LIMITED	Motor Vehicle Repair Shops	1980-M	1	1980	c. 1980	50	BREEZEHILL	AVE		OTTAWA	1050	SOMERSET	ST	W	K1Y3C5	40990348	OLD OTTAWA	811112; 811119	635			201.1543767	2415.154695
7135	ACTECK AUTOMOTIVE	Motor Vehicles, Wholesale, Automobile Machine S	2001-ES; 2005-SelectPhone; 200	1	2001-2017	c. 2001; c.	1050	SOMERSET	ST	WEST		1050	SOMERSET	ST	W	K1Y3C5	40990348	OLD OTTAWA	811111				201.1543767	2415.154695
7136	NATIONAL BRAKE AND CLUTCH	Motor Vehicle Repair Shops	1970-M; 1980-M; 1994-PID; 199	1	1970	c. 1970	1050	SOMERSET	ST	WEST	OTTAWA	1050	SOMERSET	ST	W	K1Y3C5	40990348	OLD OTTAWA	811112; 811119	635	Acklands Auto Paint, Auto		201.1543767	2415.154695
7739	NVN AUTO COLLISION LTD/ AM(	Motor Vehicle Repair Shops	1998-SC	1	1998		1040	SOMERSET	ST	WEST	OTTAWA	1040	SOMERSET	ST	WEST		41070001	OTTAWA					153.7236155	1344.141419
8077	ACKLANDS AUTO PAINT, AUTO	Motor Vehicle Repair Shops	na	1			1050	SOMERSET	ST	WEST	OTTAWA	1050	SOMERSET	ST	WEST		40990348	OTTAWA					201.1543767	2415.154695
8149	PRESTIGE CLEANING SERVICE!	Service Industries Incidental to Air Transport	2001-ES; 2005-SelectPhone; 200	1	2001-2005		1089	SOMERSET	ST	WEST		1089	SOMERSET	ST	W	K1Y3C6	40980029	Old Ottawa					83.88940209	350.2152408
8771	ESPRIT DE CORPS	Combined Publishing and Printing Industries	2001-ES; 2004-GWStudy; 2005-S	1	2004-2017	c. 2001; c.	1066	SOMERSET	ST	WEST		1066	SOMERSET	ST	W	K1Y3C5	40990367	OLD OTTAWA	511120		#204		155.4377189	1509.478431
8837	PARADISE AUTO REPAIR	Other-Garage	2001-ES; 2005-SelectPhone; 200	1	2001-2012	ES 2001; E	1040	SOMERSET	ST			1040	SOMERSET	ST	W	K1Y4L3	41070001	OLD OTTAWA	811111				153.7236155	1344.141419
8838	A-SANDOR INC	Machine Shop Industry	2001-ES; 2005-SelectPhone	1	2005	c. 2001; c.	1040	SOMERSET	ST	WEST		1040	SOMERSET	ST	W	K1Y4L3	41070001	OLD OTTAWA	332710; 334110				153.7236155	1344.141419
8839	AERO MECHTRONICS LIMITED	Stamped, Pressed and Coated Metal Products Inc	1994-PID	1	1994	c. 1994	1040	SOMERSET	ST	WEST	OTTAWA	1040	SOMERSET	ST	W	K1Y4L3	41070001	OLD OTTAWA	332118; 332210	304	GEN# = ON0507400		153.7236155	1344.141419
8840	AL'S BODY SHOP	Motor Vehicle Repair Shops	1980-M; 1998-SC	1	1980-1998	c. 1980; c.	1040	SOMERSET	ST	WEST	OTTAWA	1040	SOMERSET	ST	W	K1Y4L3	41070001	OLD OTTAWA	811112; 811119	635			153.7236155	1344.141419
7275	GEORGE M MASON CO	Sawmill, Planing Mill and Shingle Mill Products Inc	1912-FIP-111-815; 1920-M	1	1900-1963	c. 1912-19	2	BREEZEHILL	AVE		OTTAWA	1	SPADINA	AVE		K1Y2B7	40980030	OLD OTTAWA	321111; 321112	251	FIP1901 - vacant lot FIP1!		307.2222179	5097.733705
7947	UNAMED GASOLINE SERVICE	Motor Vehicle Repair Shops	1948-1956-M	1	1948-1956		1	SPADINA	AVE		OTTAWA	1	SPADINA	AVE			40980030	OTTAWA					178.3329063	1418.044017
7948	CECIL'S SERVICE STATION	Motor Vehicle Repair Shops	1948-M; 1950-M	1	1948-1950		1	SPADINA	AVE		OTTAWA	1	SPADINA	AVE			40980030	OTTAWA					178.3329063	1418.044017
7949	DEACON'S SERVICE STATION	Motor Vehicle Repair Shops	1940-M	1	1940		1	SPADINA	AVE		OTTAWA	1	SPADINA	AVE			40980030	OTTAWA					178.3329063	1418.044017
7950	SHELL CO SERVICE STATION	Motor Vehicle Repair Shops	1930-M	1	1930		1	SPADINA	AVE		OTTAWA	1	SPADINA	AVE			40980030	OTTAWA					178.3329063	1418.044017
10679	131680 CANADA INC	Gasoline Service Stations	2005-PropertyAssessment	1	2005	c. 2005	1	SPADINA	AVE		OTTAWA	1	SPADINA	AVE		K1Y2B7	40980030	OLD OTTAWA	811111; 811112; 811119;	633; 635	811121; 811199		178.3329063	1418.044017
10680	DIRIENZO & SAIKALEY AUTOMC	Motor Vehicles, Wholesale, Garage	2001-ES; 2005-SelectPhone; 200	1	2005-2017	c. 2001; c.	1	SPADINA	AVE			1	SPADINA	AVE		K1Y2B7	40980030	OLD OTTAWA	811111				178.3329063	1418.044017
10681	GORDIE PANTALONE SERVICE	Motor Vehicle Repair Shops	1900-1980-M; 1912-FIP-111-815	1	1930-1998	c. 1930; c.	1	SPADINA	AVE		OTTAWA	1	SPADINA	AVE		K1Y2B7	40980030	OLD OTTAWA	447110; 447190	633; 635	Site is located on the corn	Three (3), gasoline, under	178.3329063	1418.044017
10682	SERVICE STATION, BRITISH AM	Gasoline Service Station	1934-CityofOttawa	1	1934	c. 1934		WELLINGTON	ST			1	SPADINA	AVE		K1Y2B7	40980030	OLD OTTAWA			Wellington & Spadina		178.3329063	1418.044017
3747	UNIVERSAL CONFECTIONARY L	Sugar and Sugar Confectionery Industries	1958-M; 1958-S; 1961-S; 1964/1	1	1958-1964	c. 1958-19	158	SPRUCE	ST		OTTAWA	158	SPRUCE	ST		K1R6P2	41070274	OLD OTTAWA	311310; 311320	108			168.4812679	1435.938816
3748	NATIONAL DRUG AND CHEMICA	Drug and Chemical Co.	1970-M	1	1960-1980	c. 1970	158	SPRUCE	ST		OTTAWA	158	SPRUCE	ST		K1R6P2	41070274	OLD OTTAWA		374			168.4811975	1437.123789
4743	SPARK'S ESTATE NORTH YARD	Petroleum Products, Wholesale	1901-1912-M	1	1901-1912		128	CHAMPAGNE	AVE		OTTAWA	161	SPRUCE	ST			41070154	Old Ottawa					769.5458882	32613.86415
7379	UNNAMED WASTE DISPOSAL SI	Other Utility Industries n.e.c.	1988-Intera; 2017-CityofOttawa-L	1	<1988	c. 1988	0	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST	W	K1Y2X6	40980189	OLD OTTAWA	221320; 221330	499	Listed as a former landfill,		264.2127957	2767.146866
7713	B & R IMPORTS INC	Motor Vehicles, Wholesale	2005-SelectPhone	1	2005		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7714	MOORHOUSE SERVICE STATIO	Gasoline Service Stations	1960-M	1	1960		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7715	SHELL OIL CO LTD	Gasoline Service Stations	1956-M; 1960-1970-M	1	1956-1970		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7716	FRANCIS J GLADWIN	Gasoline Service Stations	1940-M	1	1940		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7717	DON'S SHELL SERVICE STATIO	Gasoline Service Stations	1960-1970-M	1	1960-1970		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7718	DEACON'S SERVICE STATION	Gasoline Service Stations	1940-M	1	1940		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7719	CLIFFORD MOFFETT	Gasoline Service Stations	1950-M	1	1950		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
7720	CECIL'S SERVICE STATION	Gasoline Service Stations	1948-M; 1950-M	1	1948-1950		930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST			40980189	OTTAWA					114.7161974	745.73797
8749	TK AUTOMOTIVE SERVICE	Garage	2006-ES; 2012-ES	1	2006-2012	ES 2006; E	930	WELLINGTON	ST			930	WELLINGTON	ST	W	K1Y2X6	40980189	OLD OTTAWA	811111				114.7161974	745.73797
8750	CAR COUNTRY CANADA INC	Motor Vehicles, Wholesale	2001-ES	1	2001	c. 2001; c.	930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST	W	K1Y2X6	40980189	OLD OTTAWA	811111				114.7161974	745.73797
8751	SPEEDY AUTO GLASS LIMITED	Gasoline Service Stations	1940-M; 1948-M; 1950-M; 1954-I	1	1900-1998	c. 1940; c.	930	WELLINGTON	ST		OTTAWA	930	WELLINGTON	ST	W	K1Y2X6	40980189	OLD OTTAWA	447110; 447190	633; 635	Two(2) Underground Stora		114.7161974	745.73797
8752	SERVICE STATION, SHELL GAS	Gasoline Service Station	1934-CityofOttawa	1	1934	c. 1934		WELLINGTON	ST			930	WELLINGTON	ST	W	K1Y2X6	40980189	OLD OTTAWA			S. Cor. Wellington & Bayswater		114.7161974	745.73797
8753	AUTO REBEX SVC CTR	Automobile Repairing & Service	2017-SalesGenie	1	2017	SalesGenie 2017					OTTAWA	930	WELLINGTON	ST	W	K1Y2X6	40980189	OLD OTTAWA	81111104	Jan-38			114.7161974	745.73797
1227	EXTENT OF FIRE APRIL 1990	Extent of Fire April 1990	2017-CityofOttawa	1	1990																		8663.714733	1358086.523
17749	J R BOOTH LUMBER YARD - SP/	Lumber Yard	1901-FIP-121; 1912-FIP-118	1																			1584.060943	81334.86809

March 28, 2023
File: PE6049 -HLUI

Consulting Engineers
9 Auriga Drive
Ottawa, Ontario
K2E 7T9
Tel: (613) 226-7381

Geotechnical Engineering
Environmental Engineering
Hydrogeology
Materials Testing
Building Science
Rural Development Design
Retaining Wall Design
Noise and Vibration Studies

patersongroup.ca

City of Ottawa
110 Laurier Avenue W
Ottawa, Ontario
K1P 1J1

Subject: **Authorization Letter, HLUI Search**
Phase I-Environmental Site Assessment
75 Breezehill Avenue
Ottawa, ON

Dear Sir/Madame

Please consider this letter as confirmation that Paterson Group has been retained to conduct a Phase I-Environmental Site Assessment at the aforementioned property.

With this letter, the property owner authorizes the City of Ottawa and other regulatory bodies to release, to Paterson Group, information requested for the purpose of completing an environmental assessment of the property.

Name of Company/Property Owner: 2729685 ONTARIO INC.

Name of Representative: VINCE DELLAPENNA

Signature:

Date: APRIL 4/2023

March 28, 2023
File: PE6049 -HLUI

Consulting Engineers
9 Auriga Drive
Ottawa, Ontario
K2E 7T9
Tel: (613) 226-7381

Geotechnical Engineering
Environmental Engineering
Hydrogeology
Materials Testing
Building Science
Rural Development Design
Retaining Wall Design
Noise and Vibration Studies

patersongroup.ca

City of Ottawa
110 Laurier Avenue W
Ottawa, Ontario
K1P 1J1

Subject: **Authorization Letter, HLUI Search**
Phase I-Environmental Site Assessment
75 Breezehill Avenue
Ottawa, ON

Dear Sir/Madame

Please consider this letter as confirmation that Paterson Group has been retained to conduct a Phase I-Environmental Site Assessment at the aforementioned property.

With this letter, the property owner authorizes the City of Ottawa and other regulatory bodies to release, to Paterson Group, information requested for the purpose of completing an environmental assessment of the property.

Name of Company/Property Owner: _____

Name of Representative: _____

Signature: _____

Date: _____

HLUI SUMMARY REPORT
AREA FEATURES

HISTORIC LANDFILL FEATURE	The historic landfills identified within the HLUI are referenced from the City's Old Landfill Management Strategy report (OLMS, 2004). Contact the City's Environmental Remediation Unit (ERU-UAE@ottawa.ca) if you would like more information about the old landfill sites identified in the OLMS report.
ACTIVITY2	7075
ACTIVITYID	7075
ADJACENT_INDUSTRY	Canadian Oil Co. Ltd. (bulk storage of oil and gas), 1920s-1930s, east side of Breezhill, north of Somerset [Intera #62]; CP Railway Roadhouse (railway workshops and roundhouses), 1920s-1950s, NE corner of Bayview and O'Mera Ave. [Intera #62]; CPR Roundh
ADJACENT_LANDUSE	residential on east side, commercial all elsewhere; the zoning is partially L2[317] (leisure linkage) and R5A[160] H(24) (low rise apartment) in the general area of the site.
ADJACENT_OWNER	24 Spadina Ave. and 1073 Somerset St. on southeast side, 2 Spadina Ave. on southwest side, properties northwest of Wellington St. and south of Somerset St.
ANDERSONSWASTEDISPOSALSITES_ID	-
COMMONNAME	Bayswater & Wellington
COMMONNAME_FR	Bayswater et Wellington
CONCENTRTN	no known monitoring
DEPTH_TO_BEDROCK	bedrock at surface
DEPTH_TO_GROUNDWATER	water table encountered 1.2 m below ground level during GLL survey conducted in 1988
DISTANCE_TO_SURFACE_WATER	Ottawa River 550 m NNW
ECOLOGICAL	none expected since most of the area is paved and no water body located close-by
FORMER_MUN	OTTAWA
G_GENERATION	<null>
G_NEXT_VERSION	<null>
G_VERSION	0
GLOBALID	{D7CB863D-068E-4D64-B91A-DB2C25B4A4C8}
GROUNDWATER_FLOW_DIRECTION	assumed north towards the Ottawa River
INFORMATION_SOURCE	Intera-1988a
LANDFILL_1998_ID	__6O044Q
LOCATION	between Wellington St., Bayswater Ave., Somerset St. and Spadina Ave.
LOCTN_REF	Corner of Bayswater Ave. and Wellington St.
MAGNITUDE	no known monitoring
METHANE	no methane detected during GLL survey conducted in 1988
MOE_ID	-
OBJECTID	109
OPERATIONAL_PERIOD	unknown, but likely prior to 1928
OPERATOR	City of Ottawa
OTHER_INFO	none
OTHERREF	Gartner Lee, 1988 (Site #41); Intera, 1988 (Lf #41); Bayswater/Somerset / Closed Landfill Site folder
OVERBURDEN	generally bedrock is at the surface
OWNER	businesses/industries located at 1079, 1085, 1089 Somerset St., 1 Spadina Ave, 10 Bayswater Ave. and 930 Wellington St. (Car Country Canada Ltd.)
OWNERCATEGORY	Private
PARAMETERS	no known monitoring
PARENT_ID	<null>
PHYSICAL	area is developed with commercial buildings and is paved on most of its surface
ROAD_NAME	WELLINGTON
ROAD_TYPE	ST
SERVICE_AREA	presumably City of Ottawa
SHAPE	Polygon
SHAPE_AREA	2767.146866
SHAPE_LEN	264.212796
SITE_ACCES	Avenue Baywater et rue Wellington
SITE_ALIAS	Ur-41
SITE_COORD	old landfill site mostly located on private property
SITE_ID_FR	Bayswater and Wellington
SITE_IDENTIFICATION	Listed as a former landfill, the years of operation and closure are unknown.
SITE_NAME	Ur-41

Prepared By: *D.Kiar*
City of Ottawa
Environmental Remediation Unit
2023-05-23

HLUI SUMMARY REPORT
AREA FEATURES

HISTORIC LANDFILL FEATURE	The historic landfills identified within the HLUI are referenced from the City's Old Landfill Management Strategy report (OLMS, 2004). Contact the City's Environmental Remediation Unit (ERU-UAE@ottawa.ca) if you would like more information about the old landfill sites identified in the OLMS report.
SITE_NAME_FR	Baywater Avenue and Wellington Street
SITE_STATUS	Confirmed
SIZE_HA	approx. 0.3 ha
SOIL_COVER	wastes covered in one area by a thin cover (0.05m) of asphalt and crushed stone fill
TOPOGRAPHY	general area has a slight slope to the north and northeast
UNIQUEID	Baywater Avenue and Wellington StreetUr-41
UTM_NAD27_E_NOTE	<null>
UTM_NAD27_EASTING	443500
UTM_NAD27_N_NOTE	<null>
UTM_NAD27_NORTHING	5028150
WASTEDEPTH	approx. 1 m [GLL, 1988]
WASTETYPE	unknown; glass, crushed stone, brick fragments and other construction rubble encountered in probe holes
WATER_SUPPLY	municipally supplied water

HLUI SUMMARY REPORT
LINEAR FEATURES

OBJECTID	SOURCE	FEATURE	YEAR	COMMENT	NAME	Shape_Length
21	1979-Topographic Map	Abandoned Railway				587.574
22	1979-Topographic Map	Abandoned Railway				1309.943
69	1909-City Map	Abandoned Railway				516.4625
70	1909-City Map	Abandoned Railway				1170.108
110	1909-City Map	Electric Railway	1895, 1929, 1950, 1954	Ottawa Electric Railv		2244.643
534	City of Ottawa	Railway				277.609
535	City of Ottawa	Railway				279.522
536	City of Ottawa	Railway				292.5479
537	City of Ottawa	Railway				15.55684
538	City of Ottawa	Railway				25.61331
539	City of Ottawa	Railway				10.39671
540	City of Ottawa	Railway				0.037513
541	City of Ottawa	Railway				10.29595
542	City of Ottawa	Railway				483.0299

Prepared By: *D.Kiar*
City of Ottawa
Environmental Remediation Unit
2023-05-23

HLUI SUMMARY REPORT
POINT FEATURES

OBJECTID	ACTIVITY_NAME	FACILITY_TYPE	TANK_LOCATION	TANK_CONTENT	TANK_SIZE	TANK_TYPE	TANK_STATUS	SOURCE	INSTALLED_ST_NUM	INSTALLED_ST_NAME	INSTALLED_ST_ABR	INSTALLED_ST_DIR	COMMENT	MTM_X	MTM_Y	IMAGE_MAP	IMAGE_CERTAINTY	IMAGE_MAP_2	TANK_MATERIAL	TANK_ID	TANK_LEAKING	TANK_REMOVED	REMOVED_DATE	DATE_INSTALLED	NATURE_OF_BUSINESS	SCANNED_DRAWING	TEMPREcordID	CAPACITY_UOM	MUNICIPALITY	POSTCODE
514	SHELL OIL CO. GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1948; FIP1956	930	WELLINGTON			historical address - 930 Wellington	365769.4557	5029969.889	Volume3_317.jp	1	317.jpg												
515	SHELL OIL CO. GASOLINE SERVICE STATION	Gasoline Service Station	UST					FIP1948; FIP1956	930	WELLINGTON			historical address - 930 Wellington	365771.7708	5029973.527	Volume3_317.jp	1	317.jpg												
524	HALL FUEL CO		UST					FIP1956		LAUREL			historical address - SE corner Laurel and Lor	366146.157	5029723.496	Volume3_319_1	1													
525	BELL TELEPHONE CO OF CANADA GARAGE		UST					FIP1956	145	LORETTA			historical address - 145 Loretta	366175.9227	5029653.712	Volume3_319_4	1													
528	W. C. EDWARDS & CO. LTD		UST					FIP1948; FIP1956	991	SOMERSET	WEST		historical address - 991 Somerset West	366016.7424	5030039.078	Volume3_320.jp	1	320.jpg												
948	CANADIAN OIL CO. LTD		AST	naptha	45400			FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365892.0488	5030026.538	320.jpg	1													
949	CANADIAN OIL CO. LTD		AST	naptha				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365889.9851	5030028.046	320.jpg	1													
950	CANADIAN OIL CO. LTD		AST	naptha				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365888.0007	5030029.951	320.jpg	1													
951	CANADIAN OIL CO. LTD		AST	coal Oil				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365886.6513	5030031.3	320.jpg	1													
952	CANADIAN OIL CO. LTD		AST	coal Oil				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365885.6194	5030032.491	320.jpg	1													
953	CANADIAN OIL CO. LTD		AST	coal Oil				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365884.7463	5030033.602	320.jpg	1													
954	CANADIAN OIL CO. LTD		AST	gasoline				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365883.0794	5030036.936	320.jpg	1													
955	CANADIAN OIL CO. LTD		AST	gasoline				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365881.8888	5030035.904	320.jpg	1													
956	CANADIAN OIL CO. LTD		AST	gasoline				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365881.0951	5030035.19	320.jpg	1													
957	CANADIAN OIL CO. LTD		AST	gasoline				FIP1948	30	BREEZEHILL	AVE		historical address - 30 Breezehill Ave	365880.2219	5030034.555	320.jpg	1													
1940			UST	fuel oil				ROW	131	LORETTA	AVE			366150.6956	5029735.253					ST7472					1 tank					
1941			UST	fuel oil				ROW	145	LORETTA	AVE			366184.6568	5029686.361					ST7473					1 tank					
3965	L J CORKERY - GLOBE OIL CO		not specified	gasoline	4540	Permit		Bylaw No. 8022 - P994	1066	SOMERSET	ST	W		365854.7759	5029896.542					ST0730			04/06/1956		1 - 1000 gal gas tank					
4004	SLATER BREAD CO - SHELL		not specified	gasoline	2270	Permit		Bylaw No. 8022	35	LAUREL	ST			366045.4404	5029813.512					ST0814			05/01/1931							
4005	HALL FUEL		UST	fuel oil	4540	Permit		Bylaw No. 8022 - P876	145	LORETTA	AVE		address verified from dwg & geoottawa, Lore	366184.6568	5029686.361		1			ST0176			18/07/1955		1 - 1000 gal t	Yes				
4006	HALL FUEL - MCCOLL FRONTENAC OIL CO		not specified	gasoline	9080	Permit		Bylaw No. 8022 - P1025	131	LORETTA	AVE			366150.6956	5029735.253					ST0815			01/10/1956		1 - 2000 gas tank					
4008	BROOKSHIRE CLEANERS		not specified	gasoline	2270	Permit		Bylaw No. 8022 - P483	158	SPRUCE	ST			366123.5088	5030082.7					ST0823			18/12/1950		one 500 gal gas tank					
5734	LEGERE ENGINEERING SUPPLIES		not specified	fuel oil	4540	Permit		Bylaw No. 8022 - P312	10	BAYSWATER	AVE		between somerset st w & wellington rd addre	365757.9599	5029945.191					ST0160			06/10/1947		1000 fuel oil tank					
5735	LEGERE ENGINEERING SUPPLIES LTD		UST	gasoline	9080	Permit		Bylaw No. 304-60 VAH600	10	BAYSWATER	AVE		and pump, 10 Bayswater Ave	365757.9599	5029945.191	FR300-VAH600	1			ST4188			03/10/1969		Yes					
5759	CANADIAN OIL CO		not specified	gasoline	2270	Permit		Bylaw No. 8022 - P216	3 & 47	BREEZEHILL	AVE			365887.2379	5030022.874					ST0717			01/12/1941		install gasoline tank 500 gal					
5760	CANADIAN OIL CO					Existing		Bylaw No. 8022 - P274	3 & 47	BREEZEHILL	AVE			365887.2379	5030022.874					ST3189			07/10/1946		1 pumping unit					
5772	NATIONAL BRAKE & CLUTCH SERVICE		UST	not specifie	9080	Permit		Bylaw No. 304-60 VAH600	1050	SOMERSET	ST	W		365910.3876	5029883.415	FR300-VAH600	1			ST4747			26/08/1963		Yes					
5773	NAT BRAKE & CLUTCH LTD		UST	gasoline	13620	Permit		Bylaw No. 304-60 VAH600	1050	SOMERSET	ST	W	and pump, 1050 Somerset St W	365910.3876	5029883.415	FR300-VAH600	1			ST4192			28/04/1969		Yes					
5774	DEVONSHIRE PUBLIC SCHOOL		UST	fuel oil	22700	Permit		Bylaw No. 304-60 VAH600	100	BREEZEHILL	AVE		devonshire public school also includes pins (	365934.772	5029827.549	FR300-VAH600	2			ST3709			29/08/1972		Yes					
5775	DEVONSHIRE PUBLIC SCHOOL		UST	fuel oil	22700	Existing	Not active	Bylaw No. 304-60 VAH600	100	BREEZEHILL	AVE		devonshire public school also includes pins (	365934.772	5029827.549	FR300-VAH600	2			ST0162	Y	Y	1972-008-29	21/07/1958		Yes					
6037	BRUCE COAL CO		UST	gasoline	45400	Permit		Bylaw No. 8022 - P174	53	BREEZEHILL	AVE			365975.7354	5029893.748		3			ST0813			06/11/1939		install gasoline & fuel oil tanks					
6038	BRUCE COAL CO		UST	fuel oil	45400	Permit		Bylaw No. 8022 - P174	53	BREEZEHILL	AVE			365975.7354	5029893.748		3			ST1830			06/11/1939		install gasoline & fuel oil tanks					
6039	BRUCE FUELS LTD		UST	no 6 fuel oi	90800	Permit		Bylaw No. 304-60 VAH61	53	BREEZEHILL	AVE		tanks located on 1040 somerset st w, Yard o	365975.7354	5029893.748		3			ST4612			17/09/1965		Yes					
6040	BRUCE FUELS LTD		UST	no 6 fuel oi	45400	Existing	Active	Bylaw No. 304-60 VAH61	53	BREEZEHILL	AVE		tanks located on 1040 somerset st w, Yard o	365975.7354	5029893.748		3			ST0011	N	N		17/12/1951		Yes					
6041	BRUCE FUELS LTD		UST	no 6 fuel oi	45400	Existing	Active	Bylaw No. 304-60 VAH61	53	BREEZEHILL	AVE		tanks located on 1040 somerset st w, Yard o	365975.7354	5029893.748		3			ST0173	N	N		21/07/1947		Yes					
6042	BRUCE FUELS LTD		UST	no 6 fuel oi	45400	Existing	Active	Bylaw No. 304-60 VAH61	53	BREEZEHILL	AVE		tanks located on 1040 somerset st w, Yard o	365975.7354	5029893.748		3			ST1783	N	N		21/07/1947		Yes					
6043	BRUCE FUELS LTD		UST	no 5 fuel oi	45400	Existing	Active	Bylaw No. 304-60 VAH61	53	BREEZEHILL	AVE		tanks located on 1040 somerset st w, Yard o	365975.7354	5029893.748		3			ST0174	N	N		21/12/1953		Yes					
6044	BRUCE FUELS LTD		UST	no 5 fuel oi	45400	Existing	Active	Bylaw No. 304-60 VAH61	53	BREEZEHILL	AVE		tanks located on 1040 somerset st w, Yard o	365975.7354	5029893.748		3			ST1784	N	N		21/12/1953		Yes					
6045	BRITISH AMERICAN BANK NOTE		not specified	raw linseed	2270	Permit		Bylaw No. 8022 - P284	975	GLADSTONE	AVE			366123.4875	5029658.68					ST1732			03/02/1947		4 - 500 gal linseed oil & 1 - 500 gal varsol					
6046	BRITISH AMERICAN BANK NOTE		not specified	raw linseed	2270	Permit		Bylaw No. 8022 - P284	975	GLADSTONE	AVE			366123.4875	5029658.68					ST2356			03/02/1947		4 - 500 gal linseed oil & 1 - 500 gal varsol					
6047	BRITISH AMERICAN BANK NOTE		not specified	raw linseed	2270	Permit		Bylaw No. 8022 - P284	975	GLADSTONE	AVE			366123.4875	5029658.68					ST2663			03/02/1947		4 - 500 gal linseed oil & 1 - 500 gal varsol					
6048	BRITISH AMERICAN BANK NOTE		not specified	raw linseed	2270	Permit		Bylaw No. 8022 - P284	975	GLADSTONE	AVE			366123.4875	5029658.68					ST2806			03/02/1947		4 - 500 gal linseed oil & 1 - 500 gal varsol					
6049	BRITISH AMERICAN BANK NOTE		not specified	industrial b	908	Permit		Bylaw No. 8022 - P284	975	GLADSTONE	AVE			366123.4875	5029658.68					ST2903			03/02/1947		4 - 500 gal linseed oil & 1 - 500 gal varsol					
6050	BRITISH AMERICAN BANK NOTE		not specified	varsol	2270	Permit		Bylaw No. 8022 - P284	975	GLADSTONE	AVE			366123.4875	5029658.68					ST2948			03/02/1947		4 - 500 gal linseed oil & 1 - 500 gal varsol					
6051	BRITISH AMERICAN BANK NOTE		not specified	fuel oil	22700	Permit		Bylaw No. 8022 - P390	975	GLADSTONE	AVE			366123.4875	5029658.68					ST0175			04/07/1949		one 5000 gal fuel oil tk					
6076	STANDARD BREAD CO		not specified	gasoline	2270	Permit		Bylaw No. 8022 - P377	951	GLADSTONE	AVE			366226.6454	5029625.073					ST0825			21/02/1949		one 500 gal gas tank					
6077	STANDARD BREAD CO		not specified	gasoline	2270	Existing	Not active	Bylaw No. 8022 - P377	951	GLADSTONE	AVE			366226.6454	5029625.073					ST0824	Y (defective	Y	1949-002-21	04/11/1940	one 500 gal gas tank					
6078	STANDARD BREAD CO		not specified	fuel oil	22700	Permit		Bylaw No. 8022 - P622	951	GLADSTONE	AVE			366226.6454	5029625.073					ST0178			19/05/1953		1 - 5000 fuel oil					
6079	STANDARD BREAD		UST	diesel	9080	Permit		Bylaw No. 304-60 VAH600	951	GLADSTONE	AVE		and pump address verified from dwg & geoo	366226.6454	5029625.073	FR300-VAH600	1			ST3576			21/09/1965		Yes					
6080	STANDARD BREAD		UST	gasoline	9080	Existing	Active	Bylaw No. 304-60 VAH600	951	GLADSTONE	AVE		and pump address verified from dwg & geoo	366226.6454	5029625.073	FR300-VAH600	1			ST0826	N	N		01/02/1954		Yes					
6082	STAR DELIVERY		UST	gasoline	9080	Permit		Bylaw No. 304-60 VAH600	951	GLADSTONE	AVE		and pumps, 155 Loretta Ave	366226.6454	5029625.073	FR300-VAH600	1			ST4945			11/09/1967		Yes					
6081	STAR DELIVERY		UST	gasoline	13620	Permit		Bylaw No. 304-60 VAH600	951	GLADSTONE	AVE		and pumps, 155 Loretta Ave	366226.6454	5029625.073	FR300-VAH600	1			ST4221			11/09/1967		Yes					
8930	THEILE DIETER ELECTRICAL CONTRACTORS	Private Fuel Outlet		gasoline	9092	Pending Ac	Current	GW Study 2004	10	BAYSWATER	AV	<Null>	10-14 BAYSWATER AV	365778.5168	5029954.699								19830401	Private		1062	L	OTTAWA	K1Y 2E4
9044	MR GAS LIMITED	Gasoline Station-FS		gasoline	22700	Cancelled	Current	GW Study 2004	971	GLADSTONE	AV	<Null>	971 GLADSTONE AV	366211.9589	5029596.375								19830401	Retail		1181	L	OTTAWA	K1Y 3E5
9045	MR GAS LIMITED	Gasoline Station-FS		gasoline	22700	Cancelled	Current	GW Study 2004	971	GLADSTONE	AV	<Null>	971 GLADSTONE AV	366211.9589	5029596.375								19830401	Retail		1182	L	OTTAWA	K1Y 3E5

Prepared By: *D.Kiar*
City of Ottawa
Environmental Remediation Unit
2023-05-23

File Number: D06-03-23-0062

April 17, 2023

Mark St. Pierre
Paterson Group

Sent via email Mstpierre@patersongroup.ca

Dear Mark St Pierre,

Re: Information Request
75 Breezehill Avenue **Ottawa, Ontario ("Subject Property")**

Internal Department Circulation:

The Planning, Infrastructure and Economic Development Department has the following information in response to your request for information regarding the Subject Property:

- **Ottawa Public Health - Environmental Health:** all public inspection results are publicly available on the Ottawa Public Health website: https://www.ottawapublichealth.ca/en/public-health-services/public-health-inspections.aspx

Documents Provided:

HLUI Summary Report and HLUI Map

The HLUI Summary Report Excel spreadsheet identifies HLUI area, point and line features within 250 metres of the Subject Property, as shown on the provided HLUI Map PDF. Within 500 metres of the Subject Property, landfills and Environmental Risk Management Area (ERMA) are also identified if applicable.

For more information on how to interpret the HLUI data identified in the attached excel sheet ('ADDRESS – HLUI Summary report.xlsx'), please refer to the Overview and User Guide."

Additional information may be obtained by contacting:

Ontario's Environmental Registry

The Environmental Registry found at https://ero.ontario.ca/ contains "public notices" about environmental matters being proposed by all government ministries covered by the Environmental Bill of Rights. The public notices may contain information about proposed new laws, regulations, policies and programs or about proposals to change or eliminate existing ones. By using keys words i.e. name of proponent/owner and the address one

can ascertain if there is any information on the proponent and address under the following categories: Ministry, keywords, notice types, Notice Status, Acts, Instruments and published date (all years).

The Ontario Land Registry Office

Registration of real property is recorded in the Ontario Land Registry Office through the Land Titles Act or the Registry Act. Documents relating to title and other agreements that may affect your property are available to the public for a fee. It is recommended that a property search at the Land Registry Office be included in any investigation as to the historic use of your property. The City of Ottawa cannot comment on any documents to which it is not a party.

Court House
161 Elgin Street 4th Floor
Ottawa ON K2P 2K1
Tel: (613) 239-1230
Fax: (613) 239-1422

Ottawa Public Health

Ottawa Public Health inspects many different types of establishments. To view inspection results, please visit the Ottawa Public Health website: Public Health Inspections - Ottawa Public Health

Please note that Ottawa Public Health is not the lead agency on land use contamination in the City of Ottawa – contact the Ministry of Environment Conservation and Parks (MECP) for further information.

Please note, as per the HLUI Disclaimer, that the information contained in the HLUI database has been compiled from publicly available records and other sources of information. The HLUI may contain erroneous information given that the records used as sources of information may be flawed. For instance, changes in municipal addresses over time may introduce error. Accordingly, all information from the HLUI database is provided on an "as is" basis with no representation or warranty by the City with respect to the information's accuracy or exhaustiveness in responding to the request.

Furthermore, the HLUI database and the results of this search in no way confirm the presence or absence of contamination or pollution of any kind. This information is provided on the assumption that it will not be relied upon by any person for any purpose whatsoever. The City of Ottawa denies all liability to any persons attempting to rely on any information provided from the HLUI database.

Please note that in responding to your request, the City of Ottawa does not guarantee or comment on the environmental condition of the Subject Property. You

may wish to contact the Ontario Ministry of Environment and Climate Change for additional information.

If you have any further questions or comments, please contact HLUI@ottawa.ca.

Sincerely,

Samuel Farkas
Student Planner | Étudiante en Urbanism
Development Review | Examen des projects d'amenagement
City of Ottawa | Ville d'Ottawa
613-580-2424 Ext. 25791

Per:


Michael Boughton, MCIP, RPP
Senior Planner
Development Review East
Planning Services
Planning, Infrastructure and Economic Development Department

MB / **SF**

Enclosures: (2)
1. HLUI Map
2. HLUI Summary Report

cc: File no. D06-03-23-0062

HISTORIC LAND USE INVENTORY (HLUI) - REPORT REFERENCE MAP



DATABASE REPORT

Project Property:	*75 Breezehill Avenue* *75 Breezehill Avenue* *Ottawa ON*
Project No:	*PE6049*
Report Type:	*Standard Report*
Order No:	*23031600150*
Requested by:	*Paterson Group Inc.*
Date Completed:	*March 17, 2023*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....7
Executive Summary: Summary By Data Source.....33
Map.....64
Aerial.....65
Topographic Map.....66
Detail Report.....67
Unplottable Summary.....300
Unplottable Report.....303
Appendix: Database Descriptions.....321
Definitions.....330

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*75 Breezehill Avenue* *75 Breezehill Avenue Ottawa ON*
Project No:	*PE6049*

Coordinates:

Latitude:	*45.4055973*
Longitude:	*-75.7173832*
UTM Northing:	*5,028,259.00*
UTM Easting:	*443,859.58*
UTM Zone:	*18T*

Elevation:	*212 FT* *64.57 M*

Order Information:

Order No:	*23031600150*
Date Requested:	*March 16, 2023*
Requested by:	*Paterson Group Inc.*
Report Type:	*Standard Report*

Historical/Products:

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Within 0.25 km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	1	1
BORE	Borehole	Y	0	11	11
CA	Certificates of Approval	Y	0	11	11
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	5	5
EASR	Environmental Activity and Sector Registry	Y	0	2	2
EBR	Environmental Registry	Y	0	7	7
ECA	Environmental Compliance Approval	Y	0	12	12
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	39	39
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	2	2
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	1	129	130
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	1	1
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0

Database	Name	Searched	Project Property	Within 0.25 km	Total
INC	Fuel Oil Spills and Leaks	Y	0	1	1
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory	Y	0	10	10
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	5	5
PINC	Pipeline Incidents	Y	0	3	3
PRT	Private and Retail Fuel Storage Tanks	Y	0	1	1
PTTW	Permit to Take Water	Y	0	1	1
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	2	2
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directory	Y	1	34	35
SPL	Ontario Spills	Y	0	19	19
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	0	27	27
	Total:		2	323	325

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	GEN	LEBRUN BUILDING SERVICES	75 G Breezehill North Ottawa ON K1Y 2H7	-/0.0	0.00	67
1	SCT	Breezehill Heating Ltd.	75 Breezehill Ave N Unit D Ottawa ON K1Y 2H6	-/0.0	0.00	67

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
2	GEN	MCKERLIE-MILLEN INC.	35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE/18.3	0.31	67
2	GEN	MCKERLIE MILLEN (SEE & USE ON2231907)	35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE/18.3	0.31	68
2	GEN	CARQUEST CANADA LTD.	35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE/18.3	0.31	68
2	GEN	CARQUEST CANADA LTD.	AUTO PAINT SUPPLY 35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE/18.3	0.31	68
2	SCT	Wake Cup Coffee Roasters	35 Laurel St Ottawa ON K1Y 4M4	SSE/18.3	0.31	69
2	SCT	Paper Sign Man	35B Laurel St Ottawa ON K1Y 4M4	SSE/18.3	0.31	69
2	SCT	Signs in 23 hours.com	35B Laurel St Ottawa ON K1Y 4M4	SSE/18.3	0.31	69
2	SCT	merge design, print & promo	35B Laurel St Ottawa ON K1Y 4M4	SSE/18.3	0.31	70
3	SPL	OTTAWA HYDRO	99 BREEZE HILL AVENUE TRANSFORMER OTTAWA CITY ON	W/60.4	0.31	70
4	CA	907462 ONTARIO LIMITED	111-113 BREEZEHILL AVE.N., SWM OTTAWA CITY ON K1Y 2H6	WSW/61.0	1.36	70
4	EBR	Grandtech Auto Inc.	111 Breezehill Avenue North Suite 3-4 Ottawa Ontario K1Y 2H6 Ottawa ON	WSW/61.0	1.36	71
4	CA	Grandtech Auto Inc.	111 Breezehill Avenue North Ottawa ON K1Y 2H6	WSW/61.0	1.36	71

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
4	ECA	Grandtech Auto Inc.	111 Breezehill Avenue North Ottawa ON K1Y 2H6	WSW/61.0	1.36	71
5	BORE		ON	ESE/69.3	0.63	72
6	WWIS		73 Breezehill Ave N Ottawa ON ***Well ID:*** 7333875	WNW/82.5	-0.64	72
7	SCT	Buchanan Lighting Ltd.	129 Loretta Ave N Ottawa ON K1Y 2J7	ESE/85.9	0.36	76
8	SCT	ARC Industries	73 Breezehill Ave N Ottawa ON K1Y 2H6	WNW/86.0	-0.64	76
8	SCT	A R C INDUSTRIES	73 BREEZEHILL AVE N OTTAWA ON K1Y 2H6	WNW/86.0	-0.64	76
8	SCT	Arc Industries - Div. of OCAPDD	73 Breezehill Ave N Ottawa ON K1Y 2H6	WNW/86.0	-0.64	77
8	EHS		73 Breezehill Avenue North Ottawa ON K1Y 2H6	WNW/86.0	-0.64	77
8	EHS		73 Breezehill Ave North Ottawa Ontario Ottawa ON K1Y 2H6	WNW/86.0	-0.64	77
8	SPL	Enbridge Gas Inc.	73 Breezehill Ave N. Ottawa ON	WNW/86.0	-0.64	77
8	PINC	ENBRIDGE GAS INC	73 BREEZEHILL AVE N,,OTTAWA,ON, K1Y 2H6,CA ON	WNW/86.0	-0.64	78
9	WWIS		73 Breezehill Ave N Ottawa ON ***Well ID:*** 7333913	NW/91.1	-1.69	78
10	BORE		ON	N/92.5	-2.00	82

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	WWIS		73 Breezehill Ave N Ottawa ON ***Well ID:*** 7333911	WNW/92.8	-0.64	83
12	BORE		ON	E/95.8	-1.24	86
13	WWIS		23 Breezehill Ave N Ottawa ON ***Well ID:*** 7333912	WNW/97.9	-0.64	87
14	EHS		933 Gladstone Ave Ottawa ON K1Y 2G4	ENE/99.4	-1.63	91
14	EHS		933 Gladstone Ave Ottawa ON K1Y 2G4	ENE/99.4	-1.63	91
14	EHS		933 Gladstone Ave Ottawa ON K1Y 2G4	ENE/99.4	-1.63	91
15	EHS		Breezehill Avenue North Ottawa ON K1Y	SW/99.8	1.22	91
16	EHS		131 Loretta Avenue Ottawa ON	ESE/114.7	0.77	92
17	SPL	SHELL CANADA PRODUCTS LTD.	DEPT OF PUBLIC WORKS 1010 SUMMERSET TANK TRUCK (CARGO) OTTAWA CITY ON	NNE/115.6	-2.24	92
17	EHS		1010 Somerset St W Ottawa ON	NNE/115.6	-2.24	92
17	GEN	GVT. OF CAN.-PUBLIC WORKS CANADA	MAINTENANCE SUPPORT SERV. PLOUFFE PARK 1010 SOMERSET ST.W. C/O140 PROMENADE DU PORTAGE-OTTAWA ON K1A 0M3	NNE/115.6	-2.24	93
17	GEN	GVT. OF CAN.-PUBLIC WORKS CANADA 18-285	MAINTENANCE SUPPORT SERVICES PLOUFFE PARK, 1010 SOMERSET STREET W. OTTAWA ON	NNE/115.6	-2.24	93

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	GEN	PUBLIC WORKS CANADA	MAINTENANCE SUPPORT SERVICES PLOUFFE PARK- 1010 SOMERSET STREET WEST OTTAWA ON	NNE/115.6	-2.24	95
17	GEN	BROOKFIELD LEPAGE JOHNSON CONTROLS	1010 SOMERSET STREET PLOUFFE PARK OTTAWA ON	NNE/115.6	-2.24	96
17	EHS		1010 Somerset Street West Ottawa ON	NNE/115.6	-2.24	96
17	GEN	Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE/115.6	-2.24	96
17	GEN	PUBLIC WORK & GOV`T SER CANADA	1010 SOMERSET st OTTAWA ON	NNE/115.6	-2.24	98
17	GEN	Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE/115.6	-2.24	98
17	GEN	Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE/115.6	-2.24	99
17	GEN	public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON	NNE/115.6	-2.24	100
17	GEN	Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE/115.6	-2.24	101
17	GEN	SNC Lavalin O&M	1010 Somerset St. W Ottawa ON K1A 0K9	NNE/115.6	-2.24	102
17	GEN	Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE/115.6	-2.24	103
17	GEN	public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON	NNE/115.6	-2.24	104
17	GEN	Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE/115.6	-2.24	104

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	PINC	GUANGZHOU TRISTATE INDUSTRIAL CO LTD	1010 SOMERSET ST W,,OTTAWA,ON, K1A 0J9,CA ON	NNE/115.6	-2.24	105
17	GEN	public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	NNE/115.6	-2.24	106
17	GEN	public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	NNE/115.6	-2.24	106
17	GEN	public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	NNE/115.6	-2.24	107
17	GEN	Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE/115.6	-2.24	108
17	GEN	Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE/115.6	-2.24	109
17	GEN	Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE/115.6	-2.24	109
17	GEN	Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE/115.6	-2.24	110
18	SCT	Beacon Lite Ltd.	131 Loretta Ave N Ottawa ON K1Y 2J7	ESE/117.2	0.77	111
19	AUWR	A & T AUTO PARTS	55 BREEZEHILL AVE N OTTAWA ON K1Y 2H6	WNW/119.2	-1.69	112
20	WWIS		ON ***Well ID:*** 7216640	W/121.8	0.00	112
21	WWIS		ON ***Well ID:*** 7346904	S/127.4	2.31	113
22	BORE		ON	SSE/127.5	2.39	114

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
23	WWIS		975 GLADESTONE AVE OTTAWA ON ***Well ID:*** 7245911	SE/134.5	1.31	116
24	WWIS		O-TRAIN RAIL CORRIDOR Ottawa ON ***Well ID:*** 7205660	ESE/135.4	-0.73	119
25	BORE		ON	NE/136.7	-3.39	121
26	BORE		ON	SSE/138.4	2.52	122
27	WWIS		975 GLADSTONE AVE. OTTAWA ON ***Well ID:*** 7245908	SE/147.9	2.36	124
28	GEN	OTTAWA BOARD OF EDUCATION	100 BREEZEHILL AVENUE OTTAWA ON K1Y 2H5	WNW/153.9	-0.62	127
28	GEN	Ottawa-Carleton District School Board	Devonshire Community PS 100 Breezehill Avenue Ottawa ON K1Y 2H5	WNW/153.9	-0.62	128
28	GEN	Ottawa-Carleton District School Board	Devonshire PS 100 Breezehill Avenue Ottawa ON	WNW/153.9	-0.62	128
28	GEN	SEACOR Environmental Inc.	100 Breezehill Ave Ottawa ON	WNW/153.9	-0.62	128
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	129
28	GEN	SLR Consulting (Canada) Ltd.	100 Breezehill Ave Ottawa ON K1Y 2H5	WNW/153.9	-0.62	129
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW/153.9	-0.62	129
28	GEN	SLR Consulting (Canada) Ltd.	100 Breezehill Ave Ottawa ON	WNW/153.9	-0.62	130

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW/153.9	-0.62	130
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW/153.9	-0.62	131
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	131
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW/153.9	-0.62	132
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	133
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	133
28	GEN	Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	134
28	GEN	Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	135
28	GEN	Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	135
28	GEN	Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	136
28	GEN	Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW/153.9	-0.62	137
29	WWIS		975 GLADSTONE AVE Ottawa ON ***Well ID:*** 7322626	SSE/160.0	2.36	138
30	SPL	PRIVATE RESIDENCE	69 BAYSWATER AVE. FURNACE OIL TANK OTTAWA CITY ON K1Y 2E7	W/161.9	0.31	142

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
31	WWIS		975 GLADSTONE AVE Ottawa ON ***Well ID:*** 7322627	SE/162.1	2.36	142
32	EHS		1010 Somerset Street West Ottawa ON K1R 6R9	NE/162.5	-3.39	146
33	GEN	AERO MECHTRONICS LIMITED	1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3	NW/162.9	-2.49	146
33	GEN	AERO MECHTRONICS LIMITED 01-084	1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3	NW/162.9	-2.49	147
33	GEN	AERO MECHTRONICS LIMITED	1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3	NW/162.9	-2.49	147
33	EHS		1040 Somerset St. W Ottawa ON	NW/162.9	-2.49	147
33	WWIS		1040 SOMERSET ST W OTTAWA ON ***Well ID:*** 7184358	NW/162.9	-2.49	148
33	GEN	Claridge Homes (Hintonburg Yards) LP	1040 Somerset Street West Ottawa ON K1L 4Y3	NW/162.9	-2.49	151
33	EHS		1040 Somerset Street West Ottawa ON K1Y 2H6	NW/162.9	-2.49	151
33	PTTW	Claridge Homes (Hintonburg Yards) Inc.	1040 Somerset Street West Ottawa, ON Canada ON	NW/162.9	-2.49	152
33	EHS		1040 Somerset Street West Ottawa ON K1Y 2H6	NW/162.9	-2.49	152
33	EHS		1040 Somerset Street West Ottawa ON K1Y 2H6	NW/162.9	-2.49	152
34	WWIS		975 GLADSTON AVE OTTAWA ON	SE/163.0	2.36	153

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7245907			
35	WWIS		ON ***Well ID:*** 7391242	ESE/163.9	0.31	156
36	WWIS		lot 39 con 1 ON ***Well ID:*** 7292789	SE/164.0	1.39	157
37	EHS		975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/167.8	3.31	158
38	EHS		1010 Somerset Street West Ottawa ON	NE/171.3	-3.41	158
38	EHS		1010 Somerset Street West Ottawa ON	NE/171.3	-3.41	158
38	EHS		1010 Somerset Street West Ottawa ON	NE/171.3	-3.41	158
39	WWIS		ON ***Well ID:*** 7387934	ESE/172.3	0.31	158
40	WWIS		ON ***Well ID:*** 7387898	SE/175.1	1.39	159
41	WWIS		975 GLADSTON AVE OTTAWA ON ***Well ID:*** 7245909	SE/175.5	2.15	160
42	SCT	The Original Maple Bat Company	93 Bayswater Ave Unit A Ottawa ON K1Y 2G2	SW/177.1	1.31	163
42	SCT	The Original Maple Bat Company	93 Bayswater Ave Ottawa ON K1Y 2G2	SW/177.1	1.31	164
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON K1Y 2J7	SE/177.6	1.61	164
43	PES	TERRA PRO CORPORATION	145 LORETTA AVE N OTTAWA ON K1Y 2J7	SE/177.6	1.61	164

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
43	PES	TERRAPRO CORPORATION	145 LORETTA AVENUE NORTH OTTAWA ON K1Y 2J7	SE/177.6	1.61	165
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE/177.6	1.61	165
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE/177.6	1.61	165
43	EHS		145 Loretta Avenue North Ottawa ON	SE/177.6	1.61	166
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE/177.6	1.61	166
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE/177.6	1.61	166
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON K1Y 2J7	SE/177.6	1.61	167
43	GEN	TerraPro Corporation	145 Loretta Ave. North Ottawa ON K1Y 2J7	SE/177.6	1.61	167
43	GEN	DST Group Inc	145 Loretta Ave Ottawa ON K1Y 4W5	SE/177.6	1.61	168
43	PES	TERRA PRO CORPORATION	145 LORETTA AVE N OTTAWA ON K1Y2J7	SE/177.6	1.61	168
43	PES	TERRAPRO CORPORATION	145 LORETTA AVENUE NORTH OTTAWA ON K1Y2J7	SE/177.6	1.61	168
43	PES	TERRA PRO CORPORATION	145 LORETTA AVE N OTTAWA ON K1Y2J7	SE/177.6	1.61	169
43	SPL		145 Loretta Ave North Ottawa ON	SE/177.6	1.61	169

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
43	SPL	Private Pickup Truck<UNOFFICIAL>	145 Loretta Avenue, North Ottawa ON K1Y 2J7	SE/177.6	1.61	170
44	EHS		57 Bayswater Avenue Ottawa ON K1Y 3C4	W/178.4	0.22	170
44	EHS		57 Bayswater Avenue Ottawa ON K1Y 3C4	W/178.4	0.22	170
44	EHS		57 Bayswater Avenue Ottawa ON K1Y 3C4	W/178.4	0.22	170
45	SPL	UNKNOWN	933 GLADSTONE OTTAWA CITY ON K1A 0T4	E/179.0	-1.69	171
45	GEN	GVT. OF CAN.- PUBLIC WORKS CANADA	CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II OTTAWA ON K1A 0T4	E/179.0	-1.69	171
45	GEN	GVT. OF CAN.- PUBLIC WORKS CANADA 18-375	CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II HULL OTTAWA ON K1A 0T4	E/179.0	-1.69	172
45	GEN	GVT. OF CAN.- PUBLIC WORKS CANADA 18-375	CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II ON K1A 0T4	E/179.0	-1.69	172
45	GEN	DSS CAPITAL REGION SUPPLY CENTRE	933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	E/179.0	-1.69	172
45	GEN	PUBLIC WORKS AND GOVT SERVICES CANADA	CAPITAL REGION SUPPLY CENTRE (CRSC) 933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	E/179.0	-1.69	173
45	GEN	DSS CAPITAL REGION SUPPLY CENTRE 13-297	933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	E/179.0	-1.69	173
45	EHS		933 Gladstone Ave Ottawa ON K1A0T4	E/179.0	-1.69	174

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
45	RSC	OTTAWA COMMUNITY HOUSING CORPORATION	933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4 Ottawa ON	E/179.0	-1.69	174
45	RSC	OTTAWA COMMUNITY HOUSING CORPORATION	933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4 Ottawa ON	E/179.0	-1.69	175
45	EHS		933 Gladstone Ave Ottawa ON K1Y 3E5	E/179.0	-1.69	176
46	WWIS		ON ***Well ID:*** 7391244	SE/180.3	1.61	177
47	WWIS		ON ***Well ID:*** 7391243	SE/180.9	1.61	177
48	BORE		ON	ESE/181.5	-0.24	178
49	EHS		57 Bayswater Ave Ottawa ON K1Y 2E8	W/187.6	0.22	179
49	EHS		57 Bayswater Ave Ottawa ON K1Y2E8	W/187.6	0.22	179
50	WWIS		1010 SOMERSET ET W OTTAWA ON ***Well ID:*** 1535405	SE/188.1	1.61	179
51	SPL	City of Ottawa	Breezehill Ave N between Laurel and Gladstone Ottawa ON	S/188.5	4.02	181
52	BORE		ON	NNW/188.5	-2.69	182
53	SPL	Broadband Maintenance Inc. <UNOFFICIAL>	49 Bayswater Ave Ottawa ON K1Y 2E7	W/193.8	0.39	183
53	INC		49 Bayswater Avenue, Ottawa ON K1Y 2E7	W/193.8	0.39	183

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
54	WWIS		975 GLADSTONE AVE. OTTAWA ON ***Well ID:*** 7245910	SE/194.3	2.16	184
55	EHS		933 Gladstone Ave Ottawa ON K1A0T4	E/196.8	-1.69	187
56	CA	B.A. BANKNOTE INC.	975 GLADSTONE AVE. OTTAWA CITY ON K1Y 4W5	SSE/209.3	3.61	187
56	SCT	B A BANKNOTE	975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	188
56	CA		975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	188
56	CA		975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	188
56	EBR	BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA ON	SSE/209.3	3.61	188
56	EBR	BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA ON	SSE/209.3	3.61	189
56	SCT	B.A. Banknote	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	189
56	GEN	BRITISH AMERICAN BANK NOTE INC.	975 GLADSTONE AVENUE C/O P.O. BOX 399, STATION A OTTAWA ON K1Y 4W5	SSE/209.3	3.61	190
56	GEN	BA BANKNOTE	OTTAWA DIV., DIV OF QUEBECOR PUBLITECH INC./975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	190
56	GEN	BA BANKNOTE 05-931	OTTAWA DIV., DIV OF QUEBECOR PUBLITECH INC./975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	191

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	GEN	BA BANKNOTE	975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	SSE/209.3	3.61	193
56	GEN	BA BANKNOTE INC.	975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	SSE/209.3	3.61	194
56	NPRI	BA BANKNOTE INC.	975 GLADSTONE AVE. NOT AVAILABLE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	195
56	SCT	B.A. Banknote Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	196
56	NPRI	BA BANKNOTE INC.	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	196
56	EHS		975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	197
56	GEN	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	SSE/209.3	3.61	197
56	SCT	BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	199
56	NPRI	BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	199
56	GEN	Pinchin Environmental	975 Gladstone Ottawa ON K1Y 4W5	SSE/209.3	3.61	201
56	NPRI	BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	202
56	EHS		975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	203
56	NPRI	BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	203

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	EBR	BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario Ottawa ON	SSE/209.3	3.61	205
56	EBR	BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario Ottawa ON	SSE/209.3	3.61	205
56	EBR	BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario Ottawa ON	SSE/209.3	3.61	205
56	SPL	BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	206
56	SPL	BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	206
56	EHS		975 Gladstone Avenue n/a ON K1Y 4W5	SSE/209.3	3.61	207
56	NPRI	BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	207
56	SPL	Drain-All Ltd.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	208
56	SCT	BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	208
56	NPRI	BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	209
56	SPL	349977 Ontario Ltd.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	210
56	CA	BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	210

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	CA	BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	210
56	CA	BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	211
56	CA	BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	211
56	CA	BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	211
56	NPRI	BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	212
56	NPRI	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	213
56	GEN	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	213
56	NPRI	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE/209.3	3.61	215
56	GEN	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	215
56	GEN	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	217
56	EASR	CANADIAN BANK NOTE COMPANY, LIMITED	975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	218
56	EASR	CANADIAN BANK NOTE COMPANY, LIMITED	975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	218
56	GEN	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE/209.3	3.61	219

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	EBR	Canadian Bank Note Company, Limited	975 Gladstone Avenue Ottawa K1Y 4W5 CITY OF OTTAWA ON	SSE/209.3	3.61	220
56	GEN	BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON	SSE/209.3	3.61	221
56	ECA	Canadian Bank Note Company, Limited	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE/209.3	3.61	222
56	ECA	BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	222
56	ECA	BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	223
56	ECA	BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	223
56	ECA	BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	223
56	ECA	BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	223
56	ECA	BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	224
56	ECA	BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	224
56	GEN	Canadian Bank Note Company, limited	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	224
56	GEN	Canadian Bank Note Company, limited	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	226
56	GEN	Canadian Bank Note Company, limited	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	227

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	GEN	Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	227
56	GEN	Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	229
56	SPL	Canadian Bank Note Company, Limited	975 Gladstone Road Ottawa ON	SSE/209.3	3.61	231
56	GEN	Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	231
56	GEN	Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE/209.3	3.61	232
57	GEN	ACKLANDS LIMITED	1050 SOMERSET ST. WEST OTTAWA ON K1Y 3C5	WNW/213.1	-0.98	234
57	GEN	ACKLANDS LIMITED 02-414	1050 SOMERSET ST. WEST OTTAWA ON K1Y 3C5	WNW/213.1	-0.98	234
57	GEN	ACKLANDS LIMITED	1050 SOMERSET STREET WEST OTTAWA ON K1Y 3C5	WNW/213.1	-0.98	234
58	SPL	OLRT Constructors	1035 somerset street Ottawa ON	NW/214.1	-2.73	235
58	ECA	SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc. and EllisDon	Corporation Bayview (1035 Somerset Street W, 801 Albert Street) Ottawa ON K1Z 1G3	NW/214.1	-2.73	235
58	GEN	CITY OF OTTAWA CITY OF OTTAWA	1035 Somerset Street West Ottawa ON K2P 0H9	NW/214.1	-2.73	235
59	HINC		150 BREEZEHILL AVENUE NORTH OTTAWA ON K1Y 2H8	S/216.0	4.31	236
60	WWIS		ON ***Well ID:*** 7387933	ESE/216.2	1.13	236

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
61	EHS		86 Bayswater Ave Ottawa ON K1Y 2E9	WSW/217.2	2.31	237
62	EHS		951 Gladestone Avenue & 145 Loretta Avenue North Ottawa ON	SE/217.6	1.77	237
63	SCT	ESPRIT DE CORPS	1066 SOMERSET ST W SUITE 204 OTTAWA ON K1Y 4T3	WNW/220.6	-0.69	238
63	SCT	Esprit de Corps Inc.	1066 Somerset St W Unit 204 Ottawa ON K1Y 4T3	WNW/220.6	-0.69	238
63	SCT	Grafik Visuals	A-1066 Somerset St W Ottawa ON K1Y 4T3	WNW/220.6	-0.69	238
64	EHS		155 Loretta Ave N Ottawa ON K1Y 3E5	SE/221.4	1.77	238
64	EHS		155 Loretta Ave N Ottawa ON K1Y 3E5	SE/221.4	1.77	238
64	EHS		155 Loretta Ave N Ottawa ON K1Y 3E5	SE/221.4	1.77	239
65	SCT	SPORTIVE SPORTSWEAR MFG INC.	155A LORETTA AVE N OTTAWA ON K1Y 2J7	SE/222.1	2.00	239
65	SCT	SPORTIVE SPORTSWEAR MFG INC.	155 A LORETTA AVE N OTTAWA ON K1Y 2J7	SE/222.1	2.00	239
65	SCT	Sportive Sportswear Manufacturers Inc.	155A Loretta Ave N Ottawa ON K1Y 2J7	SE/222.1	2.00	240
66	WWIS		ON ***Well ID:*** 7388045	SE/223.0	1.13	240
67	WWIS		ON ***Well ID:*** 7388050	SE/223.5	1.77	241

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
68	EHS		PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	W/228.9	1.00	242
68	EHS		PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	W/228.9	1.00	242
68	EHS		PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	W/228.9	1.00	242
69	BORE		ON	SSE/231.5	3.34	242
70	BORE		ON	W/231.9	2.15	244
71	WWIS		ON ***Well ID:*** 7388044	ESE/233.0	0.62	246
72	BORE		ON	N/233.2	-4.39	246
73	GEN	Hydro OTTAWA LIMITED	59 LAUREL AVE OTTAWA ON K2C3G2	WSW/235.8	2.31	247
73	ECA	Hydro Ottawa Limited	59 Laurel St Ottawa ON K1G 3S4	WSW/235.8	2.31	247
74	PRT	MR GAS LIMITED ATTN LILIANNE LEVAC	971 GLADSTONE AV OTTAWA ON K1Y 3E5	SE/237.7	2.31	248
74	DTNK	MR GAS LIMITED **	971 GLADSTONE AV OTTAWA ON K1Y 3E5	SE/237.7	2.31	248
74	DTNK	MR GAS LIMITED **	971 GLADSTONE AV OTTAWA ON	SE/237.7	2.31	249
74	DTNK	MR GAS LIMITED **	971 GLADSTONE AV OTTAWA ON	SE/237.7	2.31	249

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
74	DTNK	MR GAS LIMITED**	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE/237.7	2.31	250
74	DTNK	MR GAS LIMITED**	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE/237.7	2.31	250
74	FST	MGL PROPERTIES LTD.	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE/237.7	2.31	251
74	FST	MGL PROPERTIES LTD.	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE/237.7	2.31	252
75	GEN	Primrose Printing Inc	250 City Centre Avenue, BAY 142 Ottawa ON K1R 6K7	NNW/239.4	-4.15	252
75	SCT	Display Laminating	250 City Centre Ave Suite 128 Ottawa ON K1R 6K7	NNW/239.4	-4.15	252
75	SCT	Artext Electronic Publishing	250 City Centre Ave Suite 140 Ottawa ON K1R 6K7	NNW/239.4	-4.15	253
75	SCT	Ottawa Print Finishing	250 City Centre Ave Suite 226 Ottawa ON K1R 6K7	NNW/239.4	-4.15	253
75	SCT	Marquardt Printing Ltd.	250 City Centre Ave Bay 240 Ottawa ON K1R 6K7	NNW/239.4	-4.15	253
75	SCT	Quality Signs Ltd.	250 City Centre Ave Suite 128 Ottawa ON K1R 6K7	NNW/239.4	-4.15	254
75	SCT	C.N. Embroidery Inc.	250 City Centre Ave Unit 100 Ottawa ON K1R 6K7	NNW/239.4	-4.15	254
75	EHS		250 City Centre Avenue (formerly Champagne Avenue N) Ottawa ON	NNW/239.4	-4.15	254
75	GEN	Cielo Print Inc.	250 City Centre Avenue, BAY 136 Ottawa ON	NNW/239.4	-4.15	254

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	GEN	Equity Management International Limited	250 City Centre Avenue Ottawa ON	NNW/239.4	-4.15	255
75	SCT	Cdn Parks & Wilderness Society	250 City Centre Ave Suite 506 Ottawa ON K1R 6K7	NNW/239.4	-4.15	255
75	SCT	Christie Lites Ltd. - Ottawa	250 City Centre Ave Suite 102-104 Ottawa ON K1R 6K7	NNW/239.4	-4.15	256
75	SCT	Cielo Print Inc.	250 City Centre Ave Unit 136 Ottawa ON K1R 6K7	NNW/239.4	-4.15	256
75	GEN	MARQUARDT PRINTING LTD.	250 CITY CENTRE AVENUE, UNIT 236 OTTAWA ON K1R 6K7	NNW/239.4	-4.15	256
75	GEN	PUBLIC WORKS AND GOVERNMENT SERVICES CANADA	250 City Centre Av Ottawa ON K1R 6K7	NNW/239.4	-4.15	257
75	GEN	City of Ottawa	250 City Centre Avenue Ottawa ON	NNW/239.4	-4.15	257
75	GEN	VISION FORM	BAY 244-250 CITY CENTRE AVE OTTAWA ON	NNW/239.4	-4.15	257
75	SPL	Cascades Recovery Inc.	250 City Centre Ave. Ottawa ON	NNW/239.4	-4.15	258
75	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON	NNW/239.4	-4.15	258
75	GEN	FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON	NNW/239.4	-4.15	259
75	GEN	FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	NNW/239.4	-4.15	259
75	GEN	VISION FORM	BAY 244-250 CITY CENTRE AVE OTTAWA ON K1R 6K7	NNW/239.4	-4.15	260

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	GEN	FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	NNW/239.4	-4.15	260
75	GEN	FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	NNW/239.4	-4.15	260
75	GEN	Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW/239.4	-4.15	261
75	GEN	VISION FORM	BAY 244-250 CITY CENTRE AVE OTTAWA ON K1R 6K7	NNW/239.4	-4.15	261
75	GEN	Public Services & Procurement Canada ESD/Trades	250 City Centre Av Ottawa ON K1R 6K7	NNW/239.4	-4.15	262
75	GEN	Public Services and Procurement Canada	250 City Centre Avenue Ottawa ON K1R 6K7	NNW/239.4	-4.15	262
75	GEN	Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW/239.4	-4.15	263
75	GEN	Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW/239.4	-4.15	263
75	SPL	District Realty <UNOFFICIAL>	250 City Centre Ave Ottawa ON	NNW/239.4	-4.15	264
75	GEN	Marquardt Printing Ltd.	208-250 City Centre Avenue Ottawa ON K1R6K7	NNW/239.4	-4.15	264
75	GEN	Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW/239.4	-4.15	265
76	GEN	LOVE PRINTING SERVICE LTD.	951 GLADSTONE AVENUE OTTAWA ON K1Y 3E5	SE/241.8	1.77	265
76	GEN	LOVE PRINTING (OUT OF BUS) 24-265	951 GLADSTONE AVENUE OTTAWA ON K1Y 3E5	SE/241.8	1.77	265

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
76	GEN	DST Group Inc	951 Gladstone Ave Ottawa ON K1Y 3E5	SE/241.8	1.77	266
77	SCT	VESUVIO IRON LOGIC CUSTOM	949 GLADSTONE AVE OTTAWA ON K1Y 3E5	ESE/246.3	1.25	266
77	SCT	VESUVIO IRON WORKS	949 GLADSTONE AVE OTTAWA ON K1Y 3E5	ESE/246.3	1.25	266
77	SPL	SNC-Lavalin Inc.	949 B Gladstone Ave, Ottawa ON	ESE/246.3	1.25	266
77	SPL	SNC- Lavalin Trillium Partner 1 Inc. and SNC- Lavalin Trillium Partner 2 Inc.	949-B Gladstone Avenue Ottawa ON	ESE/246.3	1.25	267
77	ECA	SNC- Lavalin Trillium Partner 1 Inc. and SNC- Lavalin Trillium Partner 2 Inc.,	as general partners for and on behalf of Transitnext General Partnership 949 Gladstone Ave Ottawa ON M5H 3T9	ESE/246.3	1.25	267
78	SCT	ROBERT TAPE LIMITED	989 SOMERSET ST W OTTAWA ON K1R 6R8	N/247.1	-4.69	268
78	GEN	ROBT TAPE LIMITED	989 SOMERSET ST. W. OTTAWA ON K1R 6R8	N/247.1	-4.69	268
78	GEN	ROBT TAPE LIMITED 33-483	989 SOMERSET ST. W. OTTAWA ON K1R 6R8	N/247.1	-4.69	268
78	GEN	ROBT TAPE LIMITED	989 SOMERSET STREET WEST OTTAWA ON K1R 6R8	N/247.1	-4.69	269
78	GEN	ROBT. TAPE LTD.	989 Somerset St. West Ottawa ON K1R 6R8	N/247.1	-4.69	269
79	PINC	ST LAWRENCE PLACE C/O HARBOUR PLANT RETIREMENT LODGES	114 BAYSWATER AVE,,OTTAWA,ON,K1Y 2G1,CA ON	SW/247.3	3.31	270

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	270
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	270
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	271
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	271
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	272
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	272
80	GEN	Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N/247.6	-4.69	273
81	CA	HARAMBEE CENTRES CANADA	29 BAYWATER AVE. (SWM) OTTAWA CITY ON	WNW/247.7	-1.70	273
81	GEN	Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	273
81	GEN	Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	274
81	GEN	Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON	WNW/247.7	-1.70	274
81	GEN	Ottawa Integrative Cancer Centre	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	274
81	GEN	Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	275

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
81	GEN	Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	275
81	GEN	Ottawa Integrative Cancer Centre	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	276
81	GEN	Ottawa Integrative Cancer Centre	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW/247.7	-1.70	276
82	WWIS		250 CITY CENTRE AVE. Ottawa ON ***Well ID:*** 7121083	NNW/248.3	-4.69	276

Executive Summary: Summary By Data Source

AUWR - Automobile Wrecking & Supplies

A search of the AUWR database, dated 1999-May 31, 2022 has found that there are 1 AUWR site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
A & T AUTO PARTS	55 BREEZEHILL AVE N OTTAWA ON K1Y 2H6	WNW	119.21	19

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 11 BORE site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON	ESE	69.30	5
	ON	SSE	127.50	22
	ON	SSE	138.39	26
	ON	SSE	231.53	69
	ON	W	231.85	70

Lower Elevation	Address	Direction	Distance (m)	Map Key
	ON	N	92.47	10

	ON	E	95.84	12
	ON	NE	136.71	25
	ON	ESE	181.54	48
	ON	NNW	188.54	52
	ON	N	233.24	72

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 11 CA site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
907462 ONTARIO LIMITED	111-113 BREEZEHILL AVE.N., SWM OTTAWA CITY ON K1Y 2H6	WSW	61.04	4
Grandtech Auto Inc.	111 Breezehill Avenue North Ottawa ON K1Y 2H6	WSW	61.04	4
B.A. BANKNOTE INC.	975 GLADSTONE AVE. OTTAWA CITY ON K1Y 4W5	SSE	209.32	56
	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56

Lower Elevation	Address	Direction	Distance (m)	Map Key
HARAMBEE CENTRES CANADA	29 BAYWATER AVE. (SWM) OTTAWA CITY ON	WNW	247.69	81

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Feb 28, 2022 has found that there are 5 DTNK site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
MR GAS LIMITED **	971 GLADSTONE AV OTTAWA ON K1Y 3E5	SE	237.67	74
MR GAS LIMITED **	971 GLADSTONE AV OTTAWA ON	SE	237.67	74
MR GAS LIMITED**	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE	237.67	74
MR GAS LIMITED**	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE	237.67	74

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
MR GAS LIMITED **	971 GLADSTONE AV OTTAWA ON	SE	237.67	74

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011- Jan 31, 2023 has found that there are 2 EASR site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
CANADIAN BANK NOTE COMPANY, LIMITED	975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SSE	209.32	56
CANADIAN BANK NOTE COMPANY, LIMITED	975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SSE	209.32	56

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Jan 31, 2023 has found that there are 7 EBR site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Grandtech Auto Inc.	111 Breezehill Avenue North Suite 3-4 Ottawa Ontario K1Y 2H6 Ottawa ON	WSW	61.04	4
Canadian Bank Note Company, Limited	975 Gladstone Avenue Ottawa K1Y 4W5 CITY OF OTTAWA ON	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA ON	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario Ottawa ON	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario Ottawa ON	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario Ottawa ON	SSE	209.32	56

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
BA Banknote Inc.	975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA ON	SSE	209.32	56

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Jan 31, 2023 has found that there are 12 ECA site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Grandtech Auto Inc.	111 Breezehill Avenue North Ottawa ON K1Y 2H6	WSW	61.04	4
Canadian Bank Note Company, Limited	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA Banknote Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Hydro Ottawa Limited	59 Laurel St Ottawa ON K1G 3S4	WSW	235.78	73
SNC- Lavalin Trillium Partner 1 Inc. and SNC- Lavalin Trillium Partner 2 Inc.,	as general partners for and on behalf of Transitnext General Partnership 949 Gladstone Ave Ottawa ON M5H 3T9	ESE	246.29	77

Lower Elevation	Address	Direction	Distance (m)	Map Key
SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc. and EllisDon	Corporation Bayview (1035 Somerset Street W, 801 Albert Street) Ottawa ON K1Z 1G3	NW	214.14	58

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Dec 31, 2022 has found that there are 39 EHS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	Breezehill Avenue North Ottawa ON K1Y	SW	99.82	15
	131 Loretta Avenue Ottawa ON	ESE	114.72	16
	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	167.78	37
	145 Loretta Avenue North Ottawa ON	SE	177.64	43
	57 Bayswater Avenue Ottawa ON K1Y 3C4	W	178.44	44
	57 Bayswater Avenue Ottawa ON K1Y 3C4	W	178.44	44

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	57 Bayswater Avenue Ottawa ON K1Y 3C4	W	178.44	44
	57 Bayswater Ave Ottawa ON K1Y 2E8	W	187.57	49
	57 Bayswater Ave Ottawa ON K1Y2E8	W	187.57	49
	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
	975 Gladstone Avenue Ottawa ON K1Y 4W5	SSE	209.32	56
	975 Gladstone Avenue n/a ON K1Y 4W5	SSE	209.32	56
	86 Bayswater Ave Ottawa ON K1Y 2E9	WSW	217.16	61
	951 Gladestone Avenue & 145 Loretta Avenue North Ottawa ON	SE	217.63	62
	155 Loretta Ave N Ottawa ON K1Y 3E5	SE	221.36	64
	155 Loretta Ave N Ottawa ON K1Y 3E5	SE	221.36	64
	155 Loretta Ave N Ottawa ON K1Y 3E5	SE	221.36	64

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	W	228.94	68
	PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	W	228.94	68
	PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	W	228.94	68

Lower Elevation	Address	Direction	Distance (m)	Map Key
	73 Breezehill Ave North Ottawa Ontario Ottawa ON K1Y 2H6	WNW	86.04	8
	73 Breezehill Avenue North Ottawa ON K1Y 2H6	WNW	86.04	8
	933 Gladstone Ave Ottawa ON K1Y 2G4	ENE	99.38	14
	933 Gladstone Ave Ottawa ON K1Y 2G4	ENE	99.38	14
	933 Gladstone Ave Ottawa ON K1Y 2G4	ENE	99.38	14
	1010 Somerset Street West Ottawa ON	NNE	115.58	17
	1010 Somerset St W Ottawa ON	NNE	115.58	17
	1010 Somerset Street West Ottawa ON K1R 6R9	NE	162.48	32

1040 Somerset Street West Ottawa ON K1Y 2H6	NW	162.94	33
1040 Somerset Street West Ottawa ON K1Y 2H6	NW	162.94	33
1040 Somerset Street West Ottawa ON K1Y 2H6	NW	162.94	33
1040 Somerset St. W Ottawa ON	NW	162.94	33
1010 Somerset Street West Ottawa ON	NE	171.34	38
1010 Somerset Street West Ottawa ON	NE	171.34	38
1010 Somerset Street West Ottawa ON	NE	171.34	38
933 Gladstone Ave Ottawa ON K1A0T4	E	179.03	45
933 Gladstone Ave Ottawa ON K1Y 3E5	E	179.03	45
933 Gladstone Ave Ottawa ON K1A0T4	E	196.82	55
250 City Centre Avenue (formerly Champagne Avenue N) Ottawa ON	NNW	239.44	75

FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2022 has found that there are 2 FST site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
MGL PROPERTIES LTD.	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE	237.67	74
MGL PROPERTIES LTD.	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	SE	237.67	74

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 130 GEN site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
LEBRUN BUILDING SERVICES	75 G Breezehill North Ottawa ON K1Y 2H7	-	0.00	1
MCKERLIE-MILLEN INC.	35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE	18.33	2
MCKERLIE MILLEN (SEE & USE ON2231907)	35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE	18.33	2
CARQUEST CANADA LTD.	35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE	18.33	2
CARQUEST CANADA LTD.	AUTO PAINT SUPPLY 35A LAUREL STREET OTTAWA ON K1Y 4M4	SSE	18.33	2
TerraPro Corporation	145 Loretta Ave. North Ottawa ON K1Y 2J7	SE	177.64	43
TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE	177.64	43
TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE	177.64	43

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE	177.64	43
TerraPro Corporation	145 Loretta Ave. North Ottawa ON	SE	177.64	43
TerraPro Corporation	145 Loretta Ave. North Ottawa ON K1Y 2J7	SE	177.64	43
TerraPro Corporation	145 Loretta Ave. North Ottawa ON K1Y 2J7	SE	177.64	43
DST Group Inc	145 Loretta Ave Ottawa ON K1Y 4W5	SE	177.64	43
BRITISH AMERICAN BANK NOTE INC.	975 GLADSTONE AVENUE C/O P.O. BOX 399, STATION A OTTAWA ON K1Y 4W5	SSE	209.32	56
BA BANKNOTE	OTTAWA DIV., DIV OF QUEBECOR PUBLITECH INC./975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE	209.32	56
BA BANKNOTE 05-931	OTTAWA DIV., DIV OF QUEBECOR PUBLITECH INC./975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE	209.32	56
BA BANKNOTE	975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	SSE	209.32	56
BA BANKNOTE INC.	975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE	209.32	56

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	SSE	209.32	56
Pinchin Environmental	975 Gladstone Ottawa ON K1Y 4W5	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE OTTAWA ON	SSE	209.32	56
Canadian Bank Note Company, limited	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56
Canadian Bank Note Company, limited	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56
Canadian Bank Note Company, limited	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56
Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56
Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56
Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Canadian Bank Note Company, limited Gladstone	975 Gladstone avenue Ottawa ON K1Y 4W5	SSE	209.32	56
Hydro OTTAWA LIMITED	59 LAUREL AVE OTTAWA ON K2C3G2	WSW	235.78	73
LOVE PRINTING SERVICE LTD.	951 GLADSTONE AVENUE OTTAWA ON K1Y 3E5	SE	241.77	76
LOVE PRINTING (OUT OF BUS) 24-265	951 GLADSTONE AVENUE OTTAWA ON K1Y 3E5	SE	241.77	76
DST Group Inc	951 Gladstone Ave Ottawa ON K1Y 3E5	SE	241.77	76

Lower Elevation	Address	Direction	Distance (m)	Map Key
GVT. OF CAN.-PUBLIC WORKS CANADA	MAINTENANCE SUPPORT SERV. PLOUFFE PARK 1010 SOMERSET ST.W.C/O140 PROMENADE DU PORTAGE-OTTAWA ON K1A 0M3	NNE	115.58	17
GVT. OF CAN.-PUBLIC WORKS CANADA 18-285	MAINTENANCE SUPPORT SERVICES PLOUFFE PARK, 1010 SOMERSET STREET W. OTTAWA ON	NNE	115.58	17
PUBLIC WORKS CANADA	MAINTENANCE SUPPORT SERVICES PLOUFFE PARK- 1010 SOMERSET STREET WEST OTTAWA ON	NNE	115.58	17
BROOKFIELD LEPAGE JOHNSON CONTROLS	1010 SOMERSET STREET PLOUFFE PARK OTTAWA ON	NNE	115.58	17
Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE	115.58	17
PUBLIC WORK & GOV`T SER CANADA	1010 SOMERSET st OTTAWA ON	NNE	115.58	17

Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE	115.58	17
Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE	115.58	17
public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON	NNE	115.58	17
Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE	115.58	17
SNC Lavalin O&M	1010 Somerset St. W Ottawa ON K1A 0K9	NNE	115.58	17
Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE	115.58	17
public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON	NNE	115.58	17
Public Works and Government Services Canada	1010 Somerset Street Plouffe Park Shop Ottawa ON	NNE	115.58	17
public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	NNE	115.58	17
public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	NNE	115.58	17
public works government services canada	1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	NNE	115.58	17
Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE	115.58	17

Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE	115.58	17
Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE	115.58	17
Public Services & Procurement Canada ESD/AFD	1010 Somerset ST W OTTAWA ON K1R 6R9	NNE	115.58	17
OTTAWA BOARD OF EDUCATION	100 BREEZEHILL AVENUE OTTAWA ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board	Devonshire Community PS 100 Breezehill Avenue Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board	Devonshire PS 100 Breezehill Avenue Ottawa ON	WNW	153.91	28
SEACOR Environmental Inc.	100 Breezehill Ave Ottawa ON	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
SLR Consulting (Canada) Ltd.	100 Breezehill Ave Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW	153.91	28
SLR Consulting (Canada) Ltd.	100 Breezehill Ave Ottawa ON	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW	153.91	28

Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
Ottawa-Carleton District School Board Health & Safety	100 Breezehille Ave. Ottawa ON K1Y 2H5	WNW	153.91	28
AERO MECHTRONICS LIMITED	1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3	NW	162.94	33
AERO MECHTRONICS LIMITED 01-084	1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3	NW	162.94	33
AERO MECHTRONICS LIMITED	1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3	NW	162.94	33

Claridge Homes (Hintonburg Yards) LP	1040 Somerset Street West Ottawa ON K1L 4Y3	NW	162.94	33
GVT. OF CAN.- PUBLIC WORKS CANADA	CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II OTTAWA ON K1A 0T4	E	179.03	45
GVT. OF CAN.- PUBLIC WORKS CANADA 18-375	CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II HULL OTTAWA ON K1A 0T4	E	179.03	45
GVT. OF CAN.- PUBLIC WORKS CANADA 18-375	CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II ON K1A 0T4	E	179.03	45
DSS CAPITAL REGION SUPPLY CENTRE	933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	E	179.03	45
PUBLIC WORKS AND GOVT SERVICES CANADA	CAPITAL REGION SUPPLY CENTRE (CRSC) 933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	E	179.03	45
DSS CAPITAL REGION SUPPLY CENTRE 13-297	933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	E	179.03	45
ACKLANDS LIMITED	1050 SOMERSET ST. WEST OTTAWA ON K1Y 3C5	WNW	213.10	57
ACKLANDS LIMITED 02-414	1050 SOMERSET ST. WEST OTTAWA ON K1Y 3C5	WNW	213.10	57
ACKLANDS LIMITED	1050 SOMERSET STREET WEST OTTAWA ON K1Y 3C5	WNW	213.10	57
CITY OF OTTAWA CITY OF OTTAWA	1035 Somerset Street West Ottawa ON K2P 0H9	NW	214.14	58

Primrose Printing Inc	250 City Centre Avenue, BAY 142 Ottawa ON K1R 6K7	NNW	239.44	75
Cielo Print Inc.	250 City Centre Avenue, BAY 136 Ottawa ON	NNW	239.44	75
Equity Management International Limited	250 City Centre Avenue Ottawa ON	NNW	239.44	75
MARQUARDT PRINTING LTD.	250 CITY CENTRE AVENUE, UNIT 236 OTTAWA ON K1R 6K7	NNW	239.44	75
PUBLIC WORKS AND GOVERNMENT SERVICES CANADA	250 City Centre Av Ottawa ON K1R 6K7	NNW	239.44	75
City of Ottawa	250 City Centre Avenue Ottawa ON	NNW	239.44	75
VISION FORM	BAY 244-250 CITY CENTRE AVE OTTAWA ON	NNW	239.44	75
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON	NNW	239.44	75
FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON	NNW	239.44	75
FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	NNW	239.44	75
VISION FORM	BAY 244-250 CITY CENTRE AVE OTTAWA ON K1R 6K7	NNW	239.44	75
FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	NNW	239.44	75
FURNITURE AFFAIRS	250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	NNW	239.44	75

Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW	239.44	75
VISION FORM	BAY 244-250 CITY CENTRE AVE OTTAWA ON K1R 6K7	NNW	239.44	75
Public Services & Procurement Canada ESD/Trades	250 City Centre Av Ottawa ON K1R 6K7	NNW	239.44	75
Public Services and Procurement Canada	250 City Centre Avenue Ottawa ON K1R 6K7	NNW	239.44	75
Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW	239.44	75
Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW	239.44	75
Marquardt Printing Ltd.	208-250 City Centre Avenue Ottawa ON K1R6K7	NNW	239.44	75
Visionform Inc	BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	NNW	239.44	75
ROBT TAPE LIMITED	989 SOMERSET ST. W. OTTAWA ON K1R 6R8	N	247.07	78
ROBT TAPE LIMITED 33-483	989 SOMERSET ST. W. OTTAWA ON K1R 6R8	N	247.07	78
ROBT TAPE LIMITED	989 SOMERSET STREET WEST OTTAWA ON K1R 6R8	N	247.07	78
ROBT. TAPE LTD.	989 Somerset St. West Ottawa ON K1R 6R8	N	247.07	78

Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Equity Realty Group Inc.	250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	N	247.57	80
Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81
Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81
Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON	WNW	247.69	81
Ottawa Integrative Cancer Centre	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81
Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81
Institute of Naturopathic Education and Research	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81

Ottawa Integrative Cancer Centre	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81
Ottawa Integrative Cancer Centre	29 Bayswater Ave. Ottawa ON K1Y 2E5	WNW	247.69	81

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 1 HINC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	150 BREEZEHILL AVENUE NORTH OTTAWA ON K1Y 2H8	S	216.01	59

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated Feb 28, 2022 has found that there are 1 INC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	49 Bayswater Avenue, Ottawa ON K1Y 2E7	W	193.79	53

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 10 NPRI site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
BA BANKNOTE INC.	975 GLADSTONE AVE. NOT AVAILABLE OTTAWA ON K1Y 4W5	SSE	209.32	56
BA BANKNOTE INC.	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL INC.	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56
BA INTERNATIONAL	975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	SSE	209.32	56

PES - Pesticide Register

A search of the PES database, dated Oct 2011- Jan 31, 2023 has found that there are 5 PES site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
TERRA PRO CORPORATION	145 LORETTA AVE N OTTAWA ON K1Y2J7	SE	177.64	43
TERRA PRO CORPORATION	145 LORETTA AVE N OTTAWA ON K1Y2J7	SE	177.64	43
TERRAPRO CORPORATION	145 LORETTA AVENUE NORTH OTTAWA ON K1Y 2J7	SE	177.64	43

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
TERRA PRO CORPORATION	145 LORETTA AVE N OTTAWA ON K1Y 2J7	SE	177.64	43
TERRAPRO CORPORATION	145 LORETTA AVENUE NORTH OTTAWA ON K1Y2J7	SE	177.64	43

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 3 PINC site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
ST LAWRENCE PLACE C/O HARBOUR PLANT RETIREMENT LODGES	114 BAYSWATER AVE,,OTTAWA,ON, K1Y 2G1,CA ON	SW	247.32	79

Lower Elevation	Address	Direction	Distance (m)	Map Key
ENBRIDGE GAS INC	73 BREEZEHILL AVE N,,OTTAWA, ON,K1Y 2H6,CA ON	WNW	86.04	8
GUANGZHOU TRISTATE INDUSTRIAL CO LTD	1010 SOMERSET ST W,,OTTAWA, ON,K1A 0J9,CA ON	NNE	115.58	17

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 1 PRT site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
MR GAS LIMITED ATTN LILIANNE LEVAC	971 GLADSTONE AV OTTAWA ON K1Y 3E5	SE	237.67	74

PTTW - Permit to Take Water

A search of the PTTW database, dated 1994 - Jan 31, 2023 has found that there are 1 PTTW site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
Claridge Homes (Hintonburg Yards) Inc.	1040 Somerset Street West Ottawa, ON Canada ON	NW	162.94	33

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Jan 2023 has found that there are 2 RSC site(s) within approximately 0.25 kilometers of the project property.

Lower Elevation	Address	Direction	Distance (m)	Map Key
OTTAWA COMMUNITY HOUSING CORPORATION	933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4 Ottawa ON	E	179.03	45
OTTAWA COMMUNITY HOUSING CORPORATION	933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4 Ottawa ON	E	179.03	45

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 35 SCT site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Breezehill Heating Ltd.	75 Breezehill Ave N Unit D Ottawa ON K1Y 2H6	-	0.00	1
merge design, print & promo	35B Laurel St Ottawa ON K1Y 4M4	SSE	18.33	2
Signs in 23 hours.com	35B Laurel St Ottawa ON K1Y 4M4	SSE	18.33	2
Paper Sign Man	35B Laurel St Ottawa ON K1Y 4M4	SSE	18.33	2
Wake Cup Coffee Roasters	35 Laurel St Ottawa ON K1Y 4M4	SSE	18.33	2
Buchanan Lighting Ltd.	129 Loretta Ave N Ottawa ON K1Y 2J7	ESE	85.87	7

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
Beacon Lite Ltd.	131 Loretta Ave N Ottawa ON K1Y 2J7	ESE	117.20	18
The Original Maple Bat Company	93 Bayswater Ave Ottawa ON K1Y 2G2	SW	177.06	42
The Original Maple Bat Company	93 Bayswater Ave Unit A Ottawa ON K1Y 2G2	SW	177.06	42
BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
B.A. Banknote Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
B.A. Banknote	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
B A BANKNOTE	975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SSE	209.32	56
SPORTIVE SPORTSWEAR MFG INC.	155A LORETTA AVE N OTTAWA ON K1Y 2J7	SE	222.10	65
SPORTIVE SPORTSWEAR MFG INC.	155 A LORETTA AVE N OTTAWA ON K1Y 2J7	SE	222.10	65
Sportive Sportswear Manufacturers Inc.	155A Loretta Ave N Ottawa ON K1Y 2J7	SE	222.10	65

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
VESUVIO IRON LOGIC CUSTOM	949 GLADSTONE AVE OTTAWA ON K1Y 3E5	ESE	246.29	77
VESUVIO IRON WORKS	949 GLADSTONE AVE OTTAWA ON K1Y 3E5	ESE	246.29	77

Lower Elevation	Address	Direction	Distance (m)	Map Key
ARC Industries	73 Breezehill Ave N Ottawa ON K1Y 2H6	WNW	86.04	8
A R C INDUSTRIES	73 BREEZEHILL AVE N OTTAWA ON K1Y 2H6	WNW	86.04	8
Arc Industries - Div. of OCAPDD	73 Breezehill Ave N Ottawa ON K1Y 2H6	WNW	86.04	8
Esprit de Corps Inc.	1066 Somerset St W Unit 204 Ottawa ON K1Y 4T3	WNW	220.65	63
Grafik Visuals	A-1066 Somerset St W Ottawa ON K1Y 4T3	WNW	220.65	63
ESPRIT DE CORPS	1066 SOMERSET ST W SUITE 204 OTTAWA ON K1Y 4T3	WNW	220.65	63
Artext Electronic Publishing	250 City Centre Ave Suite 140 Ottawa ON K1R 6K7	NNW	239.44	75
Quality Signs Ltd.	250 City Centre Ave Suite 128 Ottawa ON K1R 6K7	NNW	239.44	75
Marquardt Printing Ltd.	250 City Centre Ave Bay 240 Ottawa ON K1R 6K7	NNW	239.44	75

Ottawa Print Finishing	250 City Centre Ave Suite 226 Ottawa ON K1R 6K7	NNW	239.44	75
C.N. Embroidery Inc.	250 City Centre Ave Unit 100 Ottawa ON K1R 6K7	NNW	239.44	75
Cdn Parks & Wilderness Society	250 City Centre Ave Suite 506 Ottawa ON K1R 6K7	NNW	239.44	75
Christie Lites Ltd. - Ottawa	250 City Centre Ave Suite 102-104 Ottawa ON K1R 6K7	NNW	239.44	75
Cielo Print Inc.	250 City Centre Ave Unit 136 Ottawa ON K1R 6K7	NNW	239.44	75
Display Laminating	250 City Centre Ave Suite 128 Ottawa ON K1R 6K7	NNW	239.44	75
ROBERT TAPE LIMITED	989 SOMERSET ST W OTTAWA ON K1R 6R8	N	247.07	78

SPL - Ontario Spills

A search of the SPL database, dated 1988-Sep 2020; Dec 2020-Mar 2021 has found that there are 19 SPL site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
OTTAWA HYDRO	99 BREEZE HILL AVENUE TRANSFORMER OTTAWA CITY ON	W	60.38	3
PRIVATE RESIDENCE	69 BAYSWATER AVE. FURNACE OIL TANK OTTAWA CITY ON K1Y 2E7	W	161.95	30
Private Pickup Truck<UNOFFICIAL>	145 Loretta Avenue, North Ottawa ON K1Y 2J7	SE	177.64	43
	145 Loretta Ave North Ottawa ON	SE	177.64	43

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
City of Ottawa	Breezehill Ave N between Laurel and Gladstone Ottawa ON	S	188.48	51
Broadband Maintenance Inc. <UNOFFICIAL>	49 Bayswater Ave Ottawa ON K1Y 2E7	W	193.79	53
Canadian Bank Note Company, Limited	975 Gladstone Road Ottawa ON	SSE	209.32	56
349977 Ontario Ltd.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
Drain-All Ltd.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
BA International Inc.	975 Gladstone Ave Ottawa ON K1Y 4W5	SSE	209.32	56
SNC- Lavalin Trillium Partner 1 Inc. and SNC- Lavalin Trillium Partner 2 Inc.	949-B Gladstone Avenue Ottawa ON	ESE	246.29	77
SNC-Lavalin Inc.	949 B Gladstone Ave, Ottawa ON	ESE	246.29	77

Lower Elevation	Address	Direction	Distance (m)	Map Key
Enbridge Gas Inc.	73 Breezehill Ave N. Ottawa ON	WNW	86.04	8

SHELL CANADA PRODUCTS LTD.	DEPT OF PUBLIC WORKS 1010 SUMMERSET TANK TRUCK (CARGO) OTTAWA CITY ON	NNE	115.58	17
UNKNOWN	933 GLADSTONE OTTAWA CITY ON K1A 0T4	E	179.03	45
OLRT Constructors	1035 somerset street Ottawa ON	NW	214.14	58
Cascades Recovery Inc.	250 City Centre Ave. Ottawa ON	NNW	239.44	75
District Realty <UNOFFICIAL>	250 City Centre Ave Ottawa ON	NNW	239.44	75

WWIS - Water Well Information System


A search of the WWIS database, dated Jun 30 2022 has found that there are 27 WWIS site(s) within approximately 0.25 kilometers of the project property.

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON ***Well ID:*** 7216640	W	121.77	20
	ON ***Well ID:*** 7346904	S	127.43	21
	975 GLADESTONE AVE OTTAWA ON ***Well ID:*** 7245911	SE	134.54	23
	975 GLADSTONE AVE. OTTAWA ON ***Well ID:*** 7245908	SE	147.85	27
	975 GLADSTONE AVE Ottawa ON ***Well ID:*** 7322626	SSE	160.05	29
	975 GLADSTONE AVE Ottawa ON	SE	162.10	31

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	Well ID: 7322627			
	975 GLADSTON AVE OTTAWA ON ***Well ID:*** 7245907	SE	163.02	34
	ON ***Well ID:*** 7391242	ESE	163.92	35
	lot 39 con 1 ON ***Well ID:*** 7292789	SE	163.97	36
	ON ***Well ID:*** 7387934	ESE	172.32	39
	ON ***Well ID:*** 7387898	SE	175.06	40
	975 GLADSTON AVE OTTAWA ON ***Well ID:*** 7245909	SE	175.51	41
	ON ***Well ID:*** 7391244	SE	180.32	46
	ON ***Well ID:*** 7391243	SE	180.86	47
	1010 SOMERSET ET W OTTAWA ON ***Well ID:*** 1535405	SE	188.06	50
	975 GLADSTONE AVE. OTTAWA ON ***Well ID:*** 7245910	SE	194.29	54
	ON ***Well ID:*** 7387933	ESE	216.24	60

Equal/Higher Elevation	Address	Direction	Distance (m)	Map Key
	ON ***Well ID:*** 7388045	SE	223.04	66
	ON ***Well ID:*** 7388050	SE	223.51	67
	ON ***Well ID:*** 7388044	ESE	233.03	71

Lower Elevation	Address	Direction	Distance (m)	Map Key
	73 Breezehill Ave N Ottawa ON ***Well ID:*** 7333875	WNW	82.50	6
	73 Breezehill Ave N Ottawa ON ***Well ID:*** 7333913	NW	91.07	9
	73 Breezehill Ave N Ottawa ON ***Well ID:*** 7333911	WNW	92.84	11
	23 Breezehill Ave N Ottawa ON ***Well ID:*** 7333912	WNW	97.89	13
	O-TRAIN RAIL CORRIDOR Ottawa ON ***Well ID:*** 7205660	ESE	135.44	24
	1040 SOMERSET ST W OTTAWA ON ***Well ID:*** 7184358	NW	162.94	33
	250 CITY CENTRE AVE. Ottawa ON ***Well ID:*** 7121083	NNW	248.28	82



Map: 0.25 Kilometer Radius

Order Number: 23031600150


Address: 75 Breezehill Avenue, Ottawa, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership

75°43'30"W



Aerial


Year: 2022

Order Number: 23031600150

Address: 75 Breezehill Avenue, Ottawa, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: 75 Breezehill Avenue, ON

Source: ESRI World Topographic Map

Order Number: 23031600150

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 2	-/0.0	64.6 / 0.00	LEBRUN BUILDING SERVICES 75 G Breezehill North Ottawa ON K1Y 2H7	GEN

Generator No: ON1423690
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	2 of 2	-/0.0	64.6 / 0.00	Breezehill Heating Ltd. 75 Breezehill Ave N Unit D Ottawa ON K1Y 2H6	SCT

Established: 01-JUL-82
Plant Size (ft²):
Employment:

--Details--
Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 8	SSE/18.3	64.9 / 0.31	MCKERLIE-MILLEN INC. 35A LAUREL STREET OTTAWA ON K1Y 4M4	GEN

Generator No: ON0212446
SIC Code: 3259
SIC Description: OTHER VEHICLE ACCES.
Approval Years: 96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

2 ***2 of 8*** ***SSE/18.3*** ***64.9 / 0.31*** ***MCKERLIE MILLEN (SEE & USE ON2231907)***
35A LAUREL STREET
OTTAWA ON K1Y 4M4 ***GEN***

Generator No: ON0212446
SIC Code: 3259
SIC Description: OTHER VEHICLE ACCES.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

2 ***3 of 8*** ***SSE/18.3*** ***64.9 / 0.31*** ***CARQUEST CANADA LTD.***
35A LAUREL STREET
OTTAWA ON K1Y 4M4 ***GEN***

Generator No: ON2231902
SIC Code: 3259
SIC Description: OTHER VEHICLE ACCES.
Approval Years: 97,98,02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

2 ***4 of 8*** ***SSE/18.3*** ***64.9 / 0.31*** ***CARQUEST CANADA LTD.***
AUTO PAINT SUPPLY 35A LAUREL STREET
OTTAWA ON K1Y 4M4 ***GEN***

Generator No: ON2231902
SIC Code: 3259
SIC Description: OTHER VEHICLE ACCES.
Approval Years: 99,00,01
PO Box No:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

2 ***5 of 8*** ***SSE/18.3*** ***64.9 / 0.31*** ***Wake Cup Coffee Roasters*** ***SCT***
35 Laurel St
Ottawa ON K1Y 4M4

Established: 01-AUG-08
Plant Size (ft²):
Employment:

--Details--
Description: Coffee and Tea Manufacturing
SIC/NAICS Code: 311920

---

2 ***6 of 8*** ***SSE/18.3*** ***64.9 / 0.31*** ***Paper Sign Man*** ***SCT***
35B Laurel St
Ottawa ON K1Y 4M4

Established: 01-AUG-96
Plant Size (ft²):
Employment:

--Details--
Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Sign Manufacturing
SIC/NAICS Code: 339950

---

2 ***7 of 8*** ***SSE/18.3*** ***64.9 / 0.31*** ***Signs in 23 hours.com*** ***SCT***
35B Laurel St
Ottawa ON K1Y 4M4

Established: 01-AUG-87
Plant Size (ft²):
Employment:

--Details--
Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	8 of 8	SSE/18.3	64.9 / 0.31	merge design, print & promo 35B Laurel St Ottawa ON K1Y 4M4	SCT

Established: 01-SEP-04
Plant Size (ft²): 1000
Employment:

--Details--
Description: Advertising Agencies
SIC/NAICS Code: 541810

Description: All Other Wholesaler-Distributors
SIC/NAICS Code: 418990

Description: Graphic Design Services
SIC/NAICS Code: 541430

Description: Business Service Centres
SIC/NAICS Code: 561430

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	1 of 1	W/60.4	64.9 / 0.31	OTTAWA HYDRO 99 BREEZE HILL AVENUE TRANSFORMER OTTAWA CITY ON	SPL

Ref No: 117044
Site No:
Incident Dt: 8/11/1995
Year:
Incident Cause: COOLING SYSTEM LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/11/1995
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:
Municipality No: 20101
Site Geo Ref Meth:
Incident Summary: OTTAWA HYDRO: 5 L OF TRANSFORMER OIL TO GRASS & SOIL: CLEANING UP
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	1 of 4	WSW/61.0	65.9 / 1.36	907462 ONTARIO LIMITED 111-113 BREEZEHILL AVE.N., SWM OTTAWA CITY ON K1Y 2H6	CA

Certificate #: 3-0953-97-
Application Year: 97
Issue Date: 9/9/1997
Approval Type: Municipal sewage

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

4 | ***2 of 4*** | ***WSW/61.0*** | ***65.9 / 1.36*** | ***Grandtech Auto Inc.*** ***111 Breezehill Avenue North Suite 3-4 Ottawa*** ***Ontario K1Y 2H6 Ottawa*** ***ON*** | ***EBR***

EBR Registry No: IA03E0588
Ministry Ref No: 8463-5M5SK5
Notice Type: Instrument Decision
Notice Stage:
Notice Date: December 03, 2003
Proposal Date: May 02, 2003
Year: 2003
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Grandtech Auto Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 111 Breezehill Avenue North , 3-4, Ottawa Ontario, K1Y 2H6
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

111 Breezehill Avenue North Suite 3-4 Ottawa Ontario K1Y 2H6 Ottawa

---

4 | ***3 of 4*** | ***WSW/61.0*** | ***65.9 / 1.36*** | ***Grandtech Auto Inc.*** ***111 Breezehill Avenue North*** ***Ottawa ON K1Y 2H6*** | ***CA***

Certificate #: 6533-5TGM3J
Application Year: 2003
Issue Date: 11/21/2003
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

4 | ***4 of 4*** | ***WSW/61.0*** | ***65.9 / 1.36*** | ***Grandtech Auto Inc.*** ***111 Breezehill Avenue North*** ***Ottawa ON K1Y 2H6*** | ***ECA***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	6533-5TGM3J	**MOE District:**	Ottawa
Approval Date:	2003-11-21	**City:**	
Status:	Approved	**Longitude:**	-75.718575
Record Type:	ECA	**Latitude:**	45.40595
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Grandtech Auto Inc.		
Address:	111 Breezehill Avenue North		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/8463-5M5SK5-14.pdf		
PDF Site Location:			

---

5 | ***1 of 1*** | ***ESE/69.3*** | ***65.2 / 0.63*** | ***ON*** | ***BORE***

Borehole ID:	613137	**Inclin FLG:**	No
OGF ID:	215514441	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:	-58.0	**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.40518
Total Depth m:	-999	**Longitude DD:**	-75.716725
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443911
Drill Method:		**Northing:**	5028212
Orig Ground Elev m:	0	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	62.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 056450 NTS_Sheet: 31G05G		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

6 | ***1 of 1*** | ***WNW/82.5*** | ***63.9 / -0.64*** | ***73 Breezehill Ave N Ottawa ON*** | ***WWIS***

Well ID:	7333875	**Flowing (Y/N):**	

Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	15-Apr-2019 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z302759	***Contractor:***	7241
Tag:	A261253	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2019/03/06
Year Completed:	2019
Depth (m):	1.85928
Latitude:	45.4060964287436
Longitude:	-75.7181636408839
Path:	

Bore Hole Information

Bore Hole ID:	1007435434	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443799.00
Code OB Desc:		***North83:***	5028315.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	06-Mar-2019 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007962885
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	12
Mat2 Desc:	STONES
Mat3:	11
Mat3 Desc:	GRAVEL

Formation Top Depth: 0.3100000023841858
Formation End Depth: 2.7899999618530273
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007962884
Layer: 1
Color: 8
General Color: BLACK
Mat1: 27
Most Common Material: OTHER
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007962886
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 2.7899999618530273
Formation End Depth: 6.099999904632568
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007964158
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007964160
Layer: 3
Plug From: 2.8299999237060547
Plug To: 6.099999904632568
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007964159
Layer: 2
Plug From: 0.3100000023841858

Plug To: 2.8299999237060547
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007965415
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: Direct Push

Pipe Information

Pipe ID: 1007961918
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007965893
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007966475
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 4.820000171661377

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007967090
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1007964867
Diameter: 8.25
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: ft
Hole Diameter UOM: Inch

Links

Bore Hole ID: 1007435434
Depth M: 1.85928
Year Completed: 2019
Well Completed Dt: 2019/03/06
Audit No: Z302759
Tag No: A261253
Contractor: 7241
Path: 733\7333875.pdf
Latitude: 45.4060964287436
Longitude: -75.7181636408839

---

7 ***1 of 1*** ***ESE/85.9*** ***64.9 / 0.36*** ***Buchanan Lighting Ltd.*** ***129 Loretta Ave N*** ***Ottawa ON K1Y 2J7*** ***SCT***

Established: 01-DEC-71
Plant Size (ft²): 6000
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

---

8 ***1 of 7*** ***WNW/86.0*** ***63.9 / -0.64*** ***ARC Industries*** ***73 Breezehill Ave N*** ***Ottawa ON K1Y 2H6*** ***SCT***

Established: 1973
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

8 ***2 of 7*** ***WNW/86.0*** ***63.9 / -0.64*** ***A R C INDUSTRIES*** ***73 BREEZEHILL AVE N*** ***OTTAWA ON K1Y 2H6*** ***SCT***

Established: 1974
Plant Size (ft²): 0
Employment: 15

--Details--
Description: MILLWORK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 2431

---

8 | **3 of 7** | **WNW/86.0** | **63.9 / -0.64** | **Arc Industries - Div. of OCAPDD**
73 Breezehill Ave N
Ottawa ON K1Y 2H6 | **SCT**

Established: 1973
Plant Size (ft²):
Employment: 6

---

8 | **4 of 7** | **WNW/86.0** | **63.9 / -0.64** | **73 Breezehill Avenue North**
Ottawa ON K1Y 2H6 | **EHS**

Order No: 20080924003
Status: C
Report Type: Standard Report
Report Date: 10/2/2008
Date Received: 9/24/2008
Previous Site Name:
Lot/Building Size: 10' x ~200'
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Search; City Directory

Nearest Intersection: Somerset
Municipality: Ottawa
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.718626
Y: 45.405893

---

8 | **5 of 7** | **WNW/86.0** | **63.9 / -0.64** | **73 Breezehill Ave North Ottawa Ontario**
Ottawa ON K1Y 2H6 | **EHS**

Order No: 20190129049
Status: C
Report Type: Standard Report
Report Date: 01-FEB-19
Date Received: 29-JAN-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.718268
Y: 45.406057

---

8 | **6 of 7** | **WNW/86.0** | **63.9 / -0.64** | **Enbridge Gas Inc.**
73 Breezehill Ave N.
Ottawa ON | **SPL**

Ref No: 4363-BGZR82
Site No: NA
Incident Dt: 10/16/2019
Year:
Incident Cause:
Incident Event: Leak/Break
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1075
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Air
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/16/2019
Dt Document Closed: 10/24/2019
Incident Reason: Operator/Human Error

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type: Corporation
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address: 73 Breezehill Ave N.
Site District Office: Ottawa
Site Postal Code:
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type: Pipeline/Components

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Name: Commercial<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: TSSA FSB: Enbridge Gas, 1" plastic IP service line damaged, made safe
Contaminant Qty: 0 other - see incident description

---

8 | **7 of 7** | **WNW/86.0** | **63.9 / -0.64** | **ENBRIDGE GAS INC**
73 BREEZEHILL AVE N,,OTTAWA,ON,K1Y 2H6, CA
ON | **PINC**

Incident Id:
Incident No: 2702886
Incident Reported Dt: 10/17/2019
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: ENBRIDGE GAS INC
Incident Address: 73 BREEZEHILL AVE N,,OTTAWA,ON,K1Y 2H6,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

---

9 | **1 of 1** | **NW/91.1** | **62.9 / -1.69** | **73 Breezehill Ave N**
Ottawa ON | **WWIS**

Well ID: 7333913
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z302773
Tag: A261094
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

PDF URL (Map):

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 15-Apr-2019 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Well Completed Date: 2019/02/15
Year Completed: 2019
Depth (m): 6.1
Latitude: 45.4062044356553
Longitude: -75.7181650095345
Path:

Bore Hole Information

Bore Hole ID: 1007435548
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 15-Feb-2019 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443799.00
North83: 5028327.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007811215
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 1.8300000429153442
Formation End Depth: 3.0999999046325684
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007811216
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 3.0999999046325684
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1007811214
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Mat2 Desc:	
Mat3:	79
Mat3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	1.8300000429153442
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812394
Layer:	3
Plug From:	2.740000009536743
Plug To:	6.099999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812392
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812393
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007813481
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	Direct Push

Pipe Information

Pipe ID:	1007810013
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007813872
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0999999046325684
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007814348
Layer:	1
Slot:	10
Screen Top Depth:	3.0999999046325684
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007814878
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007813189
Diameter:	8.25
Depth From:	0.0
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007435548	***Tag No:***	A261094
Depth M:	6.1	***Contractor:***	7241
Year Completed:	2019	***Path:***	733\7333913.pdf
Well Completed Dt:	2019/02/15	***Latitude:***	45.4062044356553
Audit No:	Z302773	***Longitude:***	-75.7181650095345

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	1 of 1	N/92.5	62.6 / -2.00	ON	BORE

Borehole ID:	847982	**Inclin FLG:**	No
OGF ID:	215589639	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	13-NOV-1962	**Municipality:**	
Static Water Level:		**Lot:**	LOT 38
Primary Water Use:		**Township:**	NEPEAN
Sec. Water Use:		**Latitude DD:**	45.406426
Total Depth m:	10.4	**Longitude DD:**	-75.717273
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443869
Drill Method:	Diamond Drill	**Northing:**	5028351
Orig Ground Elev m:	60.7	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 50 metres
DEM Ground Elev m:	59		
Concession:	CON 1 ON OTTAWA RIVER		
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6559468	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Topsoil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TOPSOIL **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559470	**Mat Consistency:**	Soft
Top Depth:	3.2	**Material Moisture:**	
Bottom Depth:	5.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOFT, GREY CLAY, TRACE OF SILT **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559472	**Mat Consistency:**	
Top Depth:	9.1	**Material Moisture:**	
Bottom Depth:	10.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559471	**Mat Consistency:**	
Top Depth:	5.9	**Material Moisture:**	
Bottom Depth:	9.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	

Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	CLAYEY, SILTY SAND AND GRAVEL (TILL) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559469	**Mat Consistency:**	Firm
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	3.2	**Material Texture:**	
Material Color:	Brown-Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	FIRM, BROWNISH-GREY, SILTY, SANDY CLAY **Note: Many records provided by the department have a truncated [Stratum Description] field.		

---

11 | **1 of 1** | **WNW/92.8** | **63.9 / -0.64** | **73 Breezehill Ave N Ottawa ON** | **WWIS**

Well ID:	7333911	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	15-Apr-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z302772	**Contractor:**	7241
Tag:	A261092	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2019/02/15
Year Completed:	2019
Depth (m):	6.1
Latitude:	45.4060500598675
Longitude:	-75.7183802875175
Path:	

Bore Hole Information

Bore Hole ID:	1007435542	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443782.00
Code OB Desc:		**North83:**	5028310.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4

Date Completed: 15-Feb-2019 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007811208
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3: 79
Mat3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 1.8300000429153442
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007811210
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 4.570000171661377
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007811209
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 1.8300000429153442
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Annular Space/Abandonment

Sealing Record

Plug ID:	1007812387
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812386
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812388
Layer:	3
Plug From:	2.740000009536743
Plug To:	6.099999904632568
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007813479
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	Direct Push

Pipe Information

Pipe ID:	1007810011
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007813870
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	31.0
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007814346
Layer:	1
Slot:	10
Screen Top Depth:	3.0999999046325684
Screen End Depth:	6.099999904632568
Screen Material:	5

Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1007814876
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1007813187
Diameter:	8.25
Depth From:	0.0
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007435542	**Tag No:**	A261092
Depth M:	6.1	**Contractor:**	7241
Year Completed:	2019	**Path:**	733\7333911.pdf
Well Completed Dt:	2019/02/15	**Latitude:**	45.4060500598675
Audit No:	Z302772	**Longitude:**	-75.7183802875175

---

12 ***1 of 1*** ***E/95.8*** ***63.3 / -1.24*** ***ON*** ***BORE***

Borehole ID:	847983	**Inclin FLG:**	No
OGF ID:	215589640	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	12-NOV-1962	**Municipality:**	
Static Water Level:		**Lot:**	LOT 38
Primary Water Use:		**Township:**	NEPEAN
Sec. Water Use:		**Latitude DD:**	45.405686
Total Depth m:	8.5	**Longitude DD:**	-75.716165
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443955
Drill Method:	Diamond Drill	**Northing:**	5028268
Orig Ground Elev m:	61.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 50 metres
DEM Ground Elev m:	58.5		
Concession:	CON 1 ON OTTAWA RIVER		
Location D:			

Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 6559474
Top Depth: .2
Bottom Depth: .8
Material Color:
Material 1: Fill
Material 2: Sand
Material 3: Silt
Material 4:
Gsc Material Description:
Stratum Description: FILL (SILTY SAND) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6559475
Top Depth: .8
Bottom Depth: 2.3
Material Color: Grey
Material 1: Clay
Material 2: Gravel
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: GREY CLAY, SOME GRAVEL **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6559476
Top Depth: 2.3
Bottom Depth: 6.9
Material Color: Grey
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOFT, GREY CLAY **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Soft
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6559477
Top Depth: 6.9
Bottom Depth: 8.5
Material Color:
Material 1: Bedrock
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SHALE BEDROCK **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6559473
Top Depth: 0
Bottom Depth: .2
Material Color:
Material 1: Asphalt
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: ASPHALT **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type: Asphalt
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

13	***1 of 1***	***WNW/97.9***	***63.9 / -0.64***	***23 Breezehill Ave N Ottawa ON***	***WWIS***

Well ID:	7333912	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	15-Apr-2019 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z302771	***Contractor:***	7241
Tag:	A261093	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2019/02/15
Year Completed:	2019
Depth (m):	6.1
Latitude:	45.4061039025887
Longitude:	-75.7184065270002
Path:	

Bore Hole Information

Bore Hole ID:	1007435545	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443780.00
Code OB Desc:		***North83:***	5028316.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	15-Feb-2019 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007811213
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	85

Mat3 Desc:	SOFT
Formation Top Depth:	4.570000171661377
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007811212
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	1.8300000429153442
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007811211
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Mat2 Desc:	
Mat3:	79
Mat3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	1.8300000429153442
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812389
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812390
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007812391
Layer:	3

Plug From: 2.740000009536743
Plug To: 6.099999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007813480
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: Direct Push

Pipe Information

Pipe ID: 1007810012
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007813871
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007814347
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007814877
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1007813188
Diameter:	8.25
Depth From:	0.0
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Links

Bore Hole ID:	1007435545	***Tag No:***	A261093
Depth M:	6.1	***Contractor:***	7241
Year Completed:	2019	***Path:***	733\7333912.pdf
Well Completed Dt:	2019/02/15	***Latitude:***	45.4061039025887
Audit No:	Z302771	***Longitude:***	-75.7184065270002

---

14 ***1 of 3*** ***ENE/99.4*** ***62.9 / -1.63*** ***933 Gladstone Ave Ottawa ON K1Y 2G4*** ***EHS***

Order No:	21082400094	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	RSC Report (Urban)	***Client Prov/State:***	ON
Report Date:	27-AUG-21	***Search Radius (km):***	.3
Date Received:	24-AUG-21	***X:***	-75.71616796
Previous Site Name:		***Y:***	45.40585683
Lot/Building Size:			
Additional Info Ordered:			

---

14 ***2 of 3*** ***ENE/99.4*** ***62.9 / -1.63*** ***933 Gladstone Ave Ottawa ON K1Y 2G4*** ***EHS***

Order No:	21082400094	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	RSC Report (Urban)	***Client Prov/State:***	ON
Report Date:	27-AUG-21	***Search Radius (km):***	.3
Date Received:	24-AUG-21	***X:***	-75.71616796
Previous Site Name:		***Y:***	45.40585683
Lot/Building Size:			
Additional Info Ordered:			

---

14 ***3 of 3*** ***ENE/99.4*** ***62.9 / -1.63*** ***933 Gladstone Ave Ottawa ON K1Y 2G4*** ***EHS***

Order No:	21082400094	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	RSC Report (Urban)	***Client Prov/State:***	ON
Report Date:	27-AUG-21	***Search Radius (km):***	.3
Date Received:	24-AUG-21	***X:***	-75.71616796
Previous Site Name:		***Y:***	45.40585683
Lot/Building Size:			
Additional Info Ordered:			

---

15 ***1 of 1*** ***SW/99.8*** ***65.8 / 1.22*** ***Breezehill Avenue North Ottawa ON K1Y*** ***EHS***

Order No:	23010300024	***Nearest Intersection:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	06-JAN-23	**Search Radius (km):**	.25
Date Received:	03-JAN-23	**X:**	-75.71813174
Previous Site Name:		**Y:**	45.40486981
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	1 of 1	ESE/114.7	65.3 / 0.77	131 Loretta Avenue Ottawa ON	EHS

Order No:	20130205035	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Select Report	**Client Prov/State:**	ON
Report Date:	14-FEB-13	**Search Radius (km):**	.25
Date Received:	05-FEB-13	**X:**	-75.716288
Previous Site Name:		**Y:**	45.404911
Lot/Building Size:	0.22 acre		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Title Searches; Topographic Maps; City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	1 of 25	NNE/115.6	62.3 / -2.24	SHELL CANADA PRODUCTS LTD. DEPT OF PUBLIC WORKS 1010 SUMMERSET TANK TRUCK (CARGO) OTTAWA CITY ON	SPL

Ref No:	66275	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	1/20/1992	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	CONTAINER OVERFLOW	**Sector Type:**	
Incident Event:		**Agency Involved:**	MOE
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	OTTAWA CITY
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	1/21/1992	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL - 0.5L FURNACE OIL OUTSIDE WALL & BESIDE TK VENT PIPE. CLEANED UP.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	2 of 25	NNE/115.6	62.3 / -2.24	1010 Somerset St W Ottawa ON	EHS

Order No:	20010316001	**Nearest Intersection:**	Loretta Av, Champagne Av, Oak St
Status:	C	**Municipality:**	
Report Type:	Complete Report	**Client Prov/State:**	ON
Report Date:	3/20/01	**Search Radius (km):**	0.35
Date Received:	3/16/01	**X:**	-75.714394

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Previous Site Name:			**Y:**	45.407494	
Lot/Building Size:					
Additional Info Ordered:					

17	3 of 25	NNE/115.6	62.3 / -2.24	**GVT. OF CAN.-PUBLIC WORKS CANADA MAINTENANCE SUPPORT SERV. PLOUFFE PARK 1010 SOMERSET ST.W.C/O140 PROMENADE DU PORTAGE-OTTAWA ON K1A 0M3**	GEN

Generator No: ON0144726
SIC Code: 8174
SIC Description: HOUSING ADMIN.
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

17	4 of 25	NNE/115.6	62.3 / -2.24	**GVT. OF CAN.-PUBLIC WORKS CANADA 18-285 MAINTENANCE SUPPORT SERVICES PLOUFFE PARK, 1010 SOMERSET STREET W. OTTAWA ON**	GEN

Generator No: ON0144726
SIC Code: 8174
SIC Description: HOUSING ADMIN.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	5 of 25	NNE/115.6	62.3 / -2.24	PUBLIC WORKS CANADA MAINTENANCE SUPPORT SERVICES PLOUFFE PARK- 1010 SOMERSET STREET WEST OTTAWA ON	GEN

Generator No: ON0144726
SIC Code: 8174
SIC Description: HOUSING ADMIN.
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

17 | **6 of 25** | **NNE/115.6** | **62.3 / -2.24** | **BROOKFIELD LEPAGE JOHNSON CONTROLS**
1010 SOMERSET STREET PLOUFFE PARK
OTTAWA ON | **GEN**

Generator No: ON0554822
SIC Code: 7512
SIC Description: NON-RES. BLDG. OPER.
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

17 | **7 of 25** | **NNE/115.6** | **62.3 / -2.24** | **1010 Somerset Street West**
Ottawa ON | **EHS**

Order No: 20040723005
Status: C
Report Type: Complete Report
Report Date: 8/3/04
Date Received: 7/23/04
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: Somerset & Champagne
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.716554
Y: 45.407406

---

17 | **8 of 25** | **NNE/115.6** | **62.3 / -2.24** | **Public Works and Government Services Canada**
1010 Somerset Street Plouffe Park Shop
Ottawa ON | **GEN**

Generator No: ON0144726
SIC Code: 913910
SIC Description: Other Municipal Public Administration

Approval Years: 03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	9 of 25	NNE/115.6	62.3 / -2.24	PUBLIC WORK & GOV`T SER CANADA 1010 SOMERSET st OTTAWA ON	GEN

Generator No: ON3451496
SIC Code:
SIC Description:
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	10 of 25	NNE/115.6	62.3 / -2.24	Public Works and Government Services Canada 1010 Somerset Street Plouffe Park Shop Ottawa ON	GEN

Generator No: ON0144726
SIC Code: 913910
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 145

Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	243
Waste Class Name:	PCBS
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

17	11 of 25	NNE/115.6	62.3 / -2.24	**Public Works and Government Services Canada** **1010 Somerset Street Plouffe Park Shop** **Ottawa ON**	GEN

Generator No:	ON0144726
SIC Code:	913910
SIC Description:	Other Local Municipal and Regional Public Administration
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	222
Waste Class Name:	HEAVY FUELS
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	243
Waste Class Name:	PCBS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	253

Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	12 of 25	NNE/115.6	62.3 / -2.24	public works government services canada 1010 SOMERSET STREET WEST OTTAWA ON	GEN

Generator No: ON8671552
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221

Waste Class Name: LIGHT FUELS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

17 | ***13 of 25*** | ***NNE/115.6*** | ***62.3 / -2.24*** | ***Public Works and Government Services Canada 1010 Somerset Street Plouffe Park Shop Ottawa ON*** | ***GEN***

Generator No: ON0144726
SIC Code: 913910
SIC Description: Other Local Municipal and Regional Public Administration
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265

Waste Class Name: GRAPHIC ART WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

17 | ***14 of 25*** | ***NNE/115.6*** | ***62.3 / -2.24*** | ***SNC Lavalin O&M***
1010 Somerset St. W
Ottawa ON K1A 0K9 | ***GEN***

Generator No: ON9617269
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	15 of 25	NNE/115.6	62.3 / -2.24	Public Works and Government Services Canada 1010 Somerset Street Plouffe Park Shop Ottawa ON	GEN

Generator No: ON0144726
SIC Code: 913910
SIC Description: Other Local Municipal and Regional Public Administration
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 112

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

17 | 16 of 25 | NNE/115.6 | 62.3 / -2.24 | public works government services canada
1010 SOMERSET STREET WEST
OTTAWA ON | GEN

Generator No: ON8671552
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

17 | 17 of 25 | NNE/115.6 | 62.3 / -2.24 | Public Works and Government Services Canada
1010 Somerset Street Plouffe Park Shop
Ottawa ON | GEN

Generator No: ON0144726
SIC Code: 913910
SIC Description: Other Local Municipal and Regional Public Administration
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148

Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 243
Waste Class Name: PCBS

17	18 of 25	NNE/115.6	62.3 / -2.24	GUAMGZHOU TRISTATE INDUSTRIAL CO LTD 1010 SOMERSET ST W,,OTTAWA,ON,K1A 0J9, CA ON	PINC

Incident Id:
Incident No: 1603296
Incident Reported Dt: 3/24/2015
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: GUANGZHOU TRISTATE INDUSTRIAL CO LTD
Incident Address: 1010 SOMERSET ST W,,OTTAWA,ON,K1A 0J9,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	19 of 25	NNE/115.6	62.3 / -2.24	public works government services canada 1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	GEN

Generator No: ON8671552
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Sarah Page
Choice of Contact: CO_OFFICIAL
Phone No Admin: 613-915-5668 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	20 of 25	NNE/115.6	62.3 / -2.24	public works government services canada 1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	GEN

Generator No: ON8671552
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Sarah Page
Choice of Contact: CO_OFFICIAL
Phone No Admin: 613-915-5668 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

17	21 of 25	NNE/115.6	62.3 / -2.24	public works government services canada 1010 SOMERSET STREET WEST OTTAWA ON K1R 6R9	GEN

Generator No: ON8671552
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	22 of 25	NNE/115.6	62.3 / -2.24	Public Services & Procurement Canada ESD/AFD 1010 Somerset ST W OTTAWA ON K1R 6R9	GEN

Generator No: ON8671552
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	23 of 25	NNE/115.6	62.3 / -2.24	Public Services & Procurement Canada ESD/AFD 1010 Somerset ST W OTTAWA ON K1R 6R9	GEN

Generator No: ON8671552
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	24 of 25	NNE/115.6	62.3 / -2.24	Public Services & Procurement Canada ESD/AFD	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				1010 Somerset ST W ***OTTAWA ON K1R 6R9***	

Generator No: ON8671552
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

17	***25 of 25***	***NNE/115.6***	***62.3 / -2.24***	***Public Services & Procurement Canada*** ***ESD/AFD*** ***1010 Somerset ST W*** ***OTTAWA ON K1R 6R9***	***GEN***

Generator No: ON8671552
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 121 C
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

18	***1 of 1***	***ESE/117.2***	***65.3 / 0.77***	***Beacon Lite Ltd.*** ***131 Loretta Ave N*** ***Ottawa ON K1Y 2J7***	***SCT***

Established: 01-JUL-64
Plant Size (ft²): 10000

Employment:

--Details--

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Other Commercial and Industrial Machinery and Equipment Rental and Leasing
SIC/NAICS Code: 532490

---

19 | ***1 of 1*** | ***WNW/119.2*** | ***62.9 / -1.69*** | ***A & T AUTO PARTS***
55 BREEZEHILL AVE N
OTTAWA ON K1Y 2H6 | ***AUWR***

Headcode: 96400
Headcode Desc: Automobile Parts & Supplies-Used & Rebuilt
Phone: 6137255309
List Name:
Description:

---

20 | ***1 of 1*** | ***W/121.8*** | ***64.6 / 0.00*** | ***ON*** | ***WWIS***

Well ID:	7216640	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	20-Feb-2014 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C21873	***Contractor:***	6964
Tag:	A137238	***Form Version:***	8
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2013/01/04
Year Completed: 2013
Depth (m):
Latitude: 45.4057405833126
Longitude: -75.7189258365056
Path:

Bore Hole Information

Bore Hole ID: 1004713335 ***Elevation:***

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443739.00
Code OB Desc:		**North83:**	5028276.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04-Jan-2013 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	gis
Loc Method Desc:	from gis		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1004713335	**Tag No:**	A137238
Depth M:		**Contractor:**	6964
Year Completed:	2013	**Path:**	
Well Completed Dt:	2013/01/04	**Latitude:**	45.4057405833126
Audit No:	C21873	**Longitude:**	-75.7189258365056

21 ***1 of 1*** ***S/127.4*** ***66.9 / 2.31*** ***ON*** ***WWIS***

Well ID:	7346904	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	12-Nov-2019 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C45377	**Contractor:**	7085
Tag:	A268556	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2019/09/30
Year Completed:	2019
Depth (m):	
Latitude:	45.4044550233403
Longitude:	-75.7172355953887
Path:	

Bore Hole Information

Bore Hole ID:	1007708703	**Elevation:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443870.00
Code OB Desc:		**North83:**	5028132.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	30-Sep-2019 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1007708703	**Tag No:**	A268556
Depth M:		**Contractor:**	7085
Year Completed:	2019	**Path:**	
Well Completed Dt:	2019/09/30	**Latitude:**	45.4044550233403
Audit No:	C45377	**Longitude:**	-75.7172355953887

---

22 ***1 of 1*** ***SSE/127.5*** ***67.0 / 2.39*** ***ON*** ***BORE***

Borehole ID:	613129	**Inclin FLG:**	No
OGF ID:	215514433	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:	7.4	**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.40455
Total Depth m:	-999	**Longitude DD:**	-75.716717
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443911
Drill Method:		**Northing:**	5028142
Orig Ground Elev m:	65.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	65.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218393824	**Mat Consistency:**	
Top Depth:	.6	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	GRAVEL.		

Geology Stratum ID:	218393823	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	

Bottom Depth:	.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SILT.		

Geology Stratum ID:	218393826	**Mat Consistency:**	
Top Depth:	4.7	**Material Moisture:**	
Bottom Depth:	4.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND.		

Geology Stratum ID:	218393827	**Mat Consistency:**	Hard
Top Depth:	4.9	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	GRAVEL. HARD.		

Geology Stratum ID:	218393825	**Mat Consistency:**	Compact
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	GRAVEL. COMPACT.		

Geology Stratum ID:	218393828	**Mat Consistency:**	Compact
Top Depth:	5	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK. BEDROCK. 013 00005 021 00050 081 000100670000500900050049COMPACT, W **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 056370 NTS_Sheet: 31G05G		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	SE/134.5	65.9 / 1.31	975 GLADESTONE AVE OTTAWA ON	WWIS

Well ID:	7245911	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	05-Aug-2015 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z199820	***Contractor:***	7238
Tag:	A175223	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2015/07/06
Year Completed:	2015
Depth (m):	7.0104
Latitude:	45.4045495200553
Longitude:	-75.7165212151218
Path:	

Bore Hole Information

Bore Hole ID:	1005538759	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443926.00
Code OB Desc:		***North83:***	5028142.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	06-Jul-2015 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005652469
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	6.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005652470
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	10.0
Formation End Depth:	23.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005652468
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005652477
Layer:	1
Plug From:	23.0
Plug To:	11.0
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1005652478
Layer:	2
Plug From:	11.0
Plug To:	0.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005652476
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005652467
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005652473
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	13.0
Depth To:	0.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005652474
Layer:	1
Slot:	10
Screen Top Depth:	23.0
Screen End Depth:	13.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1005652472
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005652471
Diameter:	8.0
Depth From:	0.0

Depth To:	23.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005538759	**Tag No:**	A175223
Depth M:	7.0104	**Contractor:**	7238
Year Completed:	2015	**Path:**	724\7245911.pdf
Well Completed Dt:	2015/07/06	**Latitude:**	45.4045495200553
Audit No:	Z199820	**Longitude:**	-75.7165212151218

---

24 | ***1 of 1*** | ***ESE/135.4*** | ***63.8 / -0.73*** | ***O-TRAIN RAIL CORRIDOR Ottawa ON*** | ***WWIS***

Well ID:	7205660	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	31-Jul-2013 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z096874	**Contractor:**	6894
Tag:	A111219	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	
Year Completed:	
Depth (m):	
Latitude:	45.4050669596233
Longitude:	-75.7158249524009
Path:	

Bore Hole Information

Bore Hole ID:	1004479434	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443981.00
Code OB Desc:		**North83:**	5028199.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Method of Construction & Well Use

Method Construction ID: 1004980781
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1004980775
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004980779
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004980780
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1004980778
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004980777
Diameter:
Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Links

Bore Hole ID:	1004479434	***Tag No:***	A111219
Depth M:		***Contractor:***	6894
Year Completed:		***Path:***	720\7205660.pdf
Well Completed Dt:		***Latitude:***	45.4050669596233
Audit No:	Z096874	***Longitude:***	-75.7158249524009

25 ***1 of 1*** ***NE/136.7*** ***61.2 / -3.39*** ***ON*** ***BORE***

Borehole ID:	847976	***Inclin FLG:***	No
OGF ID:	215589633	***SP Status:***	Initial Entry
Status:	Decommissioned	***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	04-DEC-1962	***Municipality:***	
Static Water Level:		***Lot:***	LOT 38
Primary Water Use:		***Township:***	NEPEAN
Sec. Water Use:		***Latitude DD:***	45.406683
Total Depth m:	7	***Longitude DD:***	-75.716561
Depth Ref:	Ground Surface	***UTM Zone:***	18
Depth Elev:		***Easting:***	443925
Drill Method:	Diamond Drill	***Northing:***	5028379
Orig Ground Elev m:	60.3	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Within 50 metres
DEM Ground Elev m:	61		
Concession:	CON 1 ON OTTAWA RIVER		
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6559449	***Mat Consistency:***	Stiff
Top Depth:	1.1	***Material Moisture:***	
Bottom Depth:	4.9	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BROWN, STIFF, CLAYEY SILT CHANGING TO STIFF TO SOFT GREY, SILTY CLAY **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559447	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.1	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	Asphalt
Material 1:	Asphalt	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	ASPHALT **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559448	***Mat Consistency:***	
Top Depth:	.1	***Material Moisture:***	
Bottom Depth:	1.1	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Granite	***Geologic Group:***	

Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	FILL (GRAVEL AND SAND) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559450	**Mat Consistency:**	
Top Depth:	4.9	**Material Moisture:**	
Bottom Depth:	5.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	2in. GRAVEL LAYER **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559451	**Mat Consistency:**	Dense
Top Depth:	5.9	**Material Moisture:**	
Bottom Depth:	7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Fine Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	DENSE, SILTY, FINE SAND, GRAVEL (GLACIAL TILL) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

26 **1 of 1** **SSE/138.4** **67.1 / 2.52** **ON** **BORE**

Borehole ID:	613126	**Inclin FLG:**	No
OGF ID:	215514430	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:	8.7	**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.404368
Total Depth m:	-999	**Longitude DD:**	-75.717098
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443881
Drill Method:		**Northing:**	5028122
Orig Ground Elev m:	66.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	66.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218393817	**Mat Consistency:**	
Top Depth:	3.6	**Material Moisture:**	
Bottom Depth:	8.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: GRAVEL.

Geology Stratum ID: 218393813
Top Depth: 1
Bottom Depth: 2.4
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY. FIRM.

Mat Consistency: Firm
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218393811
Top Depth: 0
Bottom Depth: .7
Material Color:
Material 1: Silt
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SILT.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218393812
Top Depth: .7
Bottom Depth: 1
Material Color:
Material 1: Gravel
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: GRAVEL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218393815
Top Depth: 2.7
Bottom Depth: 3
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218393816
Top Depth: 3
Bottom Depth: 3.6
Material Color:
Material 1: Gravel
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: GRAVEL. HARD.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218393818
Top Depth: 8.1
Bottom Depth:
Material Color:
Material 1: Bedrock
Material 2:
Material 3:
Material 4:

Mat Consistency: Compact
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Gsc Material Description:
Stratum Description: BEDROCK. 013 00005 021 00050 081 000100670000500900050049COMPACT, WATER STABLE AT **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218393814
Top Depth: 2.4
Bottom Depth: 2.7
Material Color:
Material 1: Gravel
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: GRAVEL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: OTTAWA2.txt RecordID: 056340 NTS_Sheet: 31G05G
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

27	1 of 1	SE/147.9	66.9 / 2.36	975 GLADSTONE AVE. OTTAWA ON	WWIS

Well ID: 7245908
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z199795
Tag: A175222
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05-Aug-2015 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7238
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2015/07/03
Year Completed: 2015
Depth (m): 6.7056
Latitude: 45.4044328330979
Longitude: -75.716468627476
Path:

Bore Hole Information

Bore Hole ID: 1005538750
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03-Jul-2015 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443930.00
North83: 5028129.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005652270
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005652272
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 10.0
Formation End Depth: 22.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID:	1005652271
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	11
Mat3 Desc:	GRAVEL
Formation Top Depth:	4.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005652279
Layer:	2
Plug From:	8.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005652278
Layer:	1
Plug From:	22.0
Plug To:	8.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005652277
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005652269
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005652275
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	12.0
Depth To:	0.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Screen

Screen ID:	1005652276
Layer:	1
Slot:	10
Screen Top Depth:	22.0
Screen End Depth:	12.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1005652274
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005652273
Diameter:	8.0
Depth From:	0.0
Depth To:	22.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Links

Bore Hole ID:	1005538750	***Tag No:***	A175222
Depth M:	6.7056	***Contractor:***	7238
Year Completed:	2015	***Path:***	724\7245908.pdf
Well Completed Dt:	2015/07/03	***Latitude:***	45.4044328330979
Audit No:	Z199795	***Longitude:***	-75.716468627476

---

28 ***1 of 19*** ***WNW/153.9*** ***63.9 / -0.62*** ***OTTAWA BOARD OF EDUCATION*** ***GEN***
100 BREEZEHILL AVENUE
OTTAWA ON K1Y 2H5

Generator No:	ON0375224
SIC Code:	8511
SIC Description:	ELEMT./SECON. EDUC.
Approval Years:	96,97,98,99,00,01
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	2 of 19	WNW/153.9	63.9 / -0.62	Ottawa-Carleton District School Board Devonshire Community PS 100 Breezehill Avenue Ottawa ON K1Y 2H5	GEN

Generator No:	ON7620039
SIC Code:	
SIC Description:	
Approval Years:	02,03,04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	243
Waste Class Name:	PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	3 of 19	WNW/153.9	63.9 / -0.62	Ottawa-Carleton District School Board Devonshire PS 100 Breezehill Avenue Ottawa ON	GEN

Generator No:	ON8413809
SIC Code:	
SIC Description:	
Approval Years:	03,04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	4 of 19	WNW/153.9	63.9 / -0.62	SEACOR Environmental Inc. 100 Breezehill Ave Ottawa ON	GEN

Generator No:	ON7477757
SIC Code:	611690
SIC Description:	All Other Schools and Instruction
Approval Years:	06
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	222
Waste Class Name:	HEAVY FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	5 of 19	WNW/153.9	63.9 / -0.62	Ottawa-Carleton District School Board 100 Breezehille Ave. Ottawa ON K1Y 2H5	GEN

Generator No: ON7473867
SIC Code: 611110
SIC Description: Elementary and Secondary Schools
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	6 of 19	WNW/153.9	63.9 / -0.62	SLR Consulting (Canada) Ltd. 100 Breezehill Ave Ottawa ON K1Y 2H5	GEN

Generator No: ON7477757
SIC Code: 611690
SIC Description: All Other Schools and Instruction
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	7 of 19	WNW/153.9	63.9 / -0.62	Ottawa-Carleton District School Board 100 Breezehille Ave. Ottawa ON	GEN

Generator No: ON7473867
SIC Code: 611110
SIC Description: Elementary and Secondary Schools
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

28	8 of 19	WNW/153.9	63.9 / -0.62	**SLR Consulting (Canada) Ltd.** **100 Breezehill Ave** **Ottawa ON**	GEN

Generator No: ON7477757
SIC Code: 611690
SIC Description: All Other Schools and Instruction
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 221
Waste Class Name: LIGHT FUELS

28	9 of 19	WNW/153.9	63.9 / -0.62	**Ottawa-Carleton District School Board** **100 Breezehille Ave.** **Ottawa ON**	GEN

Generator No: ON7473867
SIC Code: 611110
SIC Description: Elementary and Secondary Schools
Approval Years: 2010

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

28	***10 of 19***	***WNW/153.9***	***63.9 / -0.62***	***Ottawa-Carleton District School Board*** ***100 Breezehille Ave.*** ***Ottawa ON***	***GEN***

Generator No: ON7473867
SIC Code: 611110
SIC Description: Elementary and Secondary Schools
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

28	***11 of 19***	***WNW/153.9***	***63.9 / -0.62***	***Ottawa-Carleton District School Board*** ***100 Breezehille Ave.***	***GEN***

Ottawa ON K1Y 2H5

Generator No: ON7473867
SIC Code: 611110
SIC Description: Elementary and Secondary Schools
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

28 | ***12 of 19*** | ***WNW/153.9*** | ***63.9 / -0.62*** | ***Ottawa-Carleton District School Board***
100 Breezehille Ave.
Ottawa ON | ***GEN***

Generator No: ON7473867
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

28 | **13 of 19** | **WNW/153.9** | **63.9 / -0.62** | **Ottawa-Carleton District School Board**
100 Breezehille Ave.
Ottawa ON K1Y 2H5 | **GEN**

Generator No: ON7473867
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Greg Benson
Choice of Contact: CO_OFFICIAL
Phone No Admin: 613-596-8211 Ext.8549
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

28 | **14 of 19** | **WNW/153.9** | **63.9 / -0.62** | **Ottawa-Carleton District School Board**
100 Breezehille Ave.
Ottawa ON K1Y 2H5 | **GEN**

Generator No: ON7473867
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Greg Benson
Choice of Contact: CO_OFFICIAL
Phone No Admin: 613-596-8211 Ext.8549
Contaminated Facility: No
MHSW Facility: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

28 | ***15 of 19*** | ***WNW/153.9*** | ***63.9 / -0.62*** | ***Ottawa-Carleton District School Board***
100 Breezehille Ave.
Ottawa ON K1Y 2H5 | ***GEN***

Generator No: ON7473867
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Greg Benson
Choice of Contact: CO_OFFICIAL
Phone No Admin: 613-596-8211 Ext.8549
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 122

Waste Class Name: ALKALINE WASTES - OTHER METALS

---

28 | **16 of 19** | **WNW/153.9** | **63.9 / -0.62** | **Ottawa-Carleton District School Board Health & Safety**
100 Breezehille Ave.
Ottawa ON K1Y 2H5 | **GEN**

Generator No: ON7473867
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 T
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

28 | **17 of 19** | **WNW/153.9** | **63.9 / -0.62** | **Ottawa-Carleton District School Board Health & Safety**
100 Breezehille Ave.
Ottawa ON K1Y 2H5 | **GEN**

Generator No: ON7473867
SIC Code:
SIC Description:

Approval Years:	As of Jul 2020
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	148 I
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	148 C
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	213 I
Waste Class Name:	Petroleum distillates
Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	263 B
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	145 T
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	263 I
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)
Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders

28	***18 of 19***	***WNW/153.9***	***63.9 / -0.62***	***Ottawa-Carleton District School Board Health & Safety*** ***100 Breezehille Ave.*** ***Ottawa ON K1Y 2H5***	***GEN***

Generator No:	ON7473867
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 T
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 213 I
Waste Class Name: Petroleum distillates

28	19 of 19	WNW/153.9	63.9 / -0.62	**Ottawa-Carleton District School Board Health & Safety** **100 Breezehille Ave.** **Ottawa ON K1Y 2H5**	GEN

Generator No: ON7473867
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145 T
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263 B
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

---

29 | **1 of 1** | **SSE/160.0** | **66.9 / 2.36** | **975 GLADSTONE AVE Ottawa ON** | **WWIS**

Well ID: 7322626
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z298740
Tag: A253878
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 16-Nov-2018 00:00:00
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7085
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2018/10/22
Year Completed: 2018
Depth (m): 5.33
Latitude: 45.4042608601541
Longitude: -75.7166197904968
Path:

Bore Hole Information

Bore Hole ID: 1007314972
DP2BR:

Elevation:
Elevrc:

Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443918.00
Code OB Desc:		***North83:***	5028110.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	22-Oct-2018 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007593067
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.130000114440918
Formation End Depth:	4.570000171661377
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007593068
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	11
Mat3 Desc:	GRAVEL
Formation Top Depth:	4.570000171661377
Formation End Depth:	5.329999923706055
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007593065
Layer:	1
Color:	2
General Color:	GREY
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0

Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007593066
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 2.130000114440918
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007593080
Layer: 3
Plug From: 1.9800000190734863
Plug To: 5.329999923706055
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007593079
Layer: 2
Plug From: 0.30000001192092896
Plug To: 1.9800000190734863
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007593078
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007593077
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007593064
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1007593072
Layer:	1
Material:	
Open Hole or Material:	
Depth From:	0.0
Depth To:	0.30000001192092896
Casing Diameter:	17.780000686645508
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Casing

Casing ID:	1007593073
Layer:	2
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.2899999618530273
Casing Diameter:	5.079999923706055
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007593074
Layer:	1
Slot:	.10
Screen Top Depth:	2.2899999618530273
Screen End Depth:	5.329999923706055
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03000020980835

Water Details

Water ID:	1007593071
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	5.329999923706055
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1007593069
Diameter:	30.479999542236328
Depth From:	0.0
Depth To:	0.30000001192092896
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1007593070
Diameter:	16.510000228881836
Depth From:	0.30000001192092896
Depth To:	5.329999923706055

Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1007314972
Depth M: 5.33
Year Completed: 2018
Well Completed Dt: 2018/10/22
Audit No: Z298740
Tag No: A253878
Contractor: 7085
Path: 732\7322626.pdf
Latitude: 45.4042608601541
Longitude: -75.7166197904968

---

30 | ***1 of 1*** | ***W/161.9*** | ***64.9 / 0.31*** | ***PRIVATE RESIDENCE 69 BAYSWATER AVE. FURNACE OIL TANK OTTAWA CITY ON K1Y 2E7*** | ***SPL***

Ref No: 171718
Site No:
Incident Dt: 8/20/1999
Year:
Incident Cause: ABOVE-GROUND TANK LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: NOT ANTICIPATED
Nature of Impact: Other
Receiving Medium: WATER
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/20/1999
Dt Document Closed:
Incident Reason: CORROSION
Site Name:
Site County/District:
Municipality No: 20101
Site Geo Ref Meth:
Incident Summary: PRIVATE RESIDENCE-UNKNW AMOUNT FURNACE OIL TO BASEMENT AND DRAIN.
Contaminant Qty:
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved: WORKS
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: OTTAWA CITY
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

31 | ***1 of 1*** | ***SE/162.1*** | ***66.9 / 2.36*** | ***975 GLADSTONE AVE Ottawa ON*** | ***WWIS***

Well ID: 7322627
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z298739
Tag: A253877
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 16-Nov-2018 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7085
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:

Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date: 2018/10/22
Year Completed: 2018
Depth (m): 5.29
Latitude: 45.4042888237835
Longitude: -75.7164668070328
Path:

Bore Hole Information

Bore Hole ID: 1007314975
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 22-Oct-2018 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443930.00
North83: 5028113.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr
UTM Reliability:

Overburden and Bedrock Materials Interval

Formation ID: 1007593103
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 28
Mat2 Desc: SAND
Mat3: 11
Mat3 Desc: GRAVEL
Formation Top Depth: 4.880000114440918
Formation End Depth: 5.289999961853027
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007593101
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL

Mat3:
Mat3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 1.5199999809265137
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007593100
Layer: 1
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007593102
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.5199999809265137
Formation End Depth: 4.880000114440918
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007593113
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007593114
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.130000114440918
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007593115

Layer: 3
Plug From: 2.130000114440918
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007593112
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007593099
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007593107
Layer: 1
Material:
Open Hole or Material:
Depth From: 0.0
Depth To: 0.30000001192092896
Casing Diameter: 17.780000686645508
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1007593108
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.740000009536743
Casing Diameter: 5.079999923706055
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007593109
Layer: 1
Slot: .10
Screen Top Depth: 2.740000009536743
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Water Details

Water ID: 1007593106
Layer: 1
Kind Code: 8

Kind: Untested
Water Found Depth: 5.179999828338623
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007593105
Diameter: 16.510000228881836
Depth From: 0.30000001192092896
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1007593104
Diameter: 30.479999542236328
Depth From: 0.0
Depth To: 0.30000001192092896
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1007314975
Depth M: 5.29
Year Completed: 2018
Well Completed Dt: 2018/10/22
Audit No: Z298739
Tag No: A253877
Contractor: 7085
Path: 732\7322627.pdf
Latitude: 45.4042888237835
Longitude: -75.7164668070328

---

32 | **1 of 1** | **NE/162.5** | **61.2 / -3.39** | ***1010 Somerset Street West Ottawa ON K1R 6R9*** | **EHS**

Order No: 20190621309
Status: C
Report Type: Custom Report
Report Date: 26-JUN-19
Date Received: 21-JUN-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: NS
Search Radius (km): .3
X: -75.716434
Y: 45.406898

---

33 | **1 of 10** | **NW/162.9** | **62.1 / -2.49** | ***AERO MECHTRONICS LIMITED 1040 SOMERSET STREET WEST OTTAWA ON K1Y 4L3*** | **GEN**

Generator No: ON0507400
SIC Code: 3041
SIC Description: COATING OF METAL PR.
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

---

33 **2 of 10** **NW/162.9** **62.1 / -2.49** **AERO MECHTRONICS LIMITED 01-084**
1040 SOMERSET STREET WEST
OTTAWA ON K1Y 4L3 **GEN**

Generator No: ON0507400
SIC Code: 3041
SIC Description: COATING OF METAL PR.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

---

33 **3 of 10** **NW/162.9** **62.1 / -2.49** **AERO MECHTRONICS LIMITED**
1040 SOMERSET STREET WEST
OTTAWA ON K1Y 4L3 **GEN**

Generator No: ON0507400
SIC Code: 3041
SIC Description: COATING OF METAL PR.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

---

33 **4 of 10** **NW/162.9** **62.1 / -2.49** **1040 Somerset St. W**
Ottawa ON **EHS**

Order No: 20120516034
Status: C
Report Type: Standard Report
Report Date: 28-MAY-12
Date Received: 16-MAY-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.718876
Y: 45.406752

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	5 of 10	NW/162.9	62.1 / -2.49	1040 SOMERSET ST W OTTAWA ON	WWIS

Well ID: 7184358
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z140766
Tag: A133892
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality:
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 19-Jul-2012 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7417
Form Version: 7
Owner:
County:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004013583
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 18-Jun-2012 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone:
East83:
North83:
Org CS: UTM83
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004373869
Layer: 5
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3: 79
Mat3 Desc: PACKED
Formation Top Depth: 13.399999618530273
Formation End Depth: 14.300000190734863
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004373865
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 12
Mat3 Desc: STONES
Formation Top Depth: 0.0
Formation End Depth: 2.0999999046325684
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004373866
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 2.0999999046325684
Formation End Depth: 3.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004373870
Layer: 6
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3: 74
Mat3 Desc: LAYERED
Formation Top Depth: 14.300000190734863
Formation End Depth: 24.299999237060547
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004373868
Layer: 4
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 12
Mat2 Desc: STONES
Mat3: 28
Mat3 Desc: SAND
Formation Top Depth: 10.899999618530273
Formation End Depth: 13.399999618530273

Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004373867
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 3.0
Formation End Depth: 10.899999618530273
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004373878
Layer: 1
Plug From: 0.0
Plug To: 14.300000190734863
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004373877
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: AIR ROTARY

Pipe Information

Pipe ID: 1004373864
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004373874
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From: 14.300000190734863
Depth To: 24.299999237060547
Casing Diameter: 15.550000190734863
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1004373873
Layer: 1
Material: 1
Open Hole or Material: STEEL

Depth From: 0.0
Depth To: 14.300000190734863
Casing Diameter: 15.550000190734863
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004373875
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1004373872
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004373871
Diameter:
Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

33	***6 of 10***	***NW/162.9***	***62.1 / -2.49***	***Claridge Homes (Hintonburg Yards) LP*** ***1040 Somerset Street West*** ***Ottawa ON K1L 4Y3***	***GEN***

Generator No: ON3741725
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

33	***7 of 10***	***NW/162.9***	***62.1 / -2.49***	***1040 Somerset Street West*** ***Ottawa ON K1Y 2H6***	***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No:	20311700178	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	20-NOV-20	**Search Radius (km):**	.25
Date Received:	17-NOV-20	**X:**	-75.7187182
Previous Site Name:		**Y:**	45.4067228
Lot/Building Size:			
Additional Info Ordered:			

33	8 of 10	NW/162.9	62.1 / -2.49	**Claridge Homes (Hintonburg Yards) Inc.** **1040 Somerset Street West Ottawa, ON Canada** **ON**	PTTW

EBR Registry No:	019-4779	**Decision Posted:**	April 5, 2022
Ministry Ref No:	1747-C9SL95	**Exception Posted:**	
Notice Type:	Instrument	**Section:**	Section 34
Notice Stage:	Decision	**Act 1:**	Ontario Water Resources Act, R.S.O. 1990
Notice Date:		**Act 2:**	Ontario Water Resources Act
Proposal Date:	December 20, 2021	**Site Location Map:**	45.406723,-75.718718
Year:	2021		
Instrument Type:	Permit to take water		
Off Instrument Name:	Permit to Take Water (OWRA s. 34)		
Posted By:	Ministry of the Environment, Conservation and Parks		
Company Name:			
Site Address:	1040 Somerset Street West Ottawa, ON Canada		
Location Other:			
Proponent Name:	Claridge Homes (Hintonburg Yards) Inc.		
Proponent Address:	Claridge Homes (Hintonburg Yards) Inc. 210 Gladstone Avenue Suite 2001 Ottawa, ON K2P 0Y6 Canada		
Comment Period:	December 20, 2021 - January 19, 2022 (30 days) Closed		
URL:	https://ero.ontario.ca/notice/019-4779		

Site Location Details:

33	9 of 10	NW/162.9	62.1 / -2.49	**1040 Somerset Street West** **Ottawa ON K1Y 2H6**	EHS

Order No:	20311700178	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	20-NOV-20	**Search Radius (km):**	.25
Date Received:	17-NOV-20	**X:**	-75.7187182
Previous Site Name:		**Y:**	45.4067228
Lot/Building Size:			
Additional Info Ordered:			

33	10 of 10	NW/162.9	62.1 / -2.49	**1040 Somerset Street West** **Ottawa ON K1Y 2H6**	EHS

Order No:	20311700178	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	20-NOV-20	**Search Radius (km):**	.25
Date Received:	17-NOV-20	**X:**	-75.7187182
Previous Site Name:		**Y:**	45.4067228
Lot/Building Size:			
Additional Info Ordered:			

34 **1 of 1** **SE/163.0** **66.9 / 2.36** **975 GLADSTON AVE OTTAWA ON** **WWIS**

Well ID:	7245907	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05-Aug-2015 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z199796	**Contractor:**	7238
Tag:	A175221	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2015/07/03
Year Completed:	2015
Depth (m):	6.37032
Latitude:	45.4043073058128
Longitude:	-75.7163903721259
Path:	

Bore Hole Information

Bore Hole ID:	1005538747	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443936.00
Code OB Desc:		**North83:**	5028115.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03-Jul-2015 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1005652258
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005652259
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	01
Mat2 Desc:	FILL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	6.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005652260
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	91
Mat3 Desc:	WATER-BEARING
Formation Top Depth:	10.0
Formation End Depth:	20.899999618530273
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005652268
Layer:	2
Plug From:	7.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005652267
Layer: 1
Plug From: 20.75
Plug To: 7.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005652266
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005652257
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005652263
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 10.75
Depth To: 0.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005652264
Layer: 1
Slot: 10
Screen Top Depth: 20.75
Screen End Depth: 10.75
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1005652262
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005652261
Diameter: 8.0
Depth From: 0.0
Depth To: 20.75
Hole Depth UOM: ft

Hole Diameter UOM: inch

Links

Bore Hole ID:	1005538747	**Tag No:**	A175221
Depth M:	6.37032	**Contractor:**	7238
Year Completed:	2015	**Path:**	724\7245907.pdf
Well Completed Dt:	2015/07/03	**Latitude:**	45.4043073058128
Audit No:	Z199796	**Longitude:**	-75.7163903721259

---

35 **1 of 1** **ESE/163.9** **64.9 / 0.31** **ON** **WWIS**

Well ID:	7391242	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z364090	**Contractor:**	7241
Tag:	A303023	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008704736	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443982.00
Code OB Desc:		**North83:**	5028150.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	25-May-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008704736	**Tag No:**	A303023
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Path:**	
Well Completed Dt:	2021/05/25	**Latitude:**	45.404626011149
Audit No:	Z364090	**Longitude:**	-75.715806605072

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	1 of 1	SE/164.0	66.0 / 1.39	lot 39 con 1 ON	WWIS

Well ID: 7292789
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: C36226
Tag: A198420
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: NEPEAN TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 17-Aug-2017 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7543
Form Version: 8
Owner:
County: OTTAWA-CARLETON
Lot: 039
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:
Year Completed:
Depth (m):
Latitude: 45.4044988818001
Longitude: -75.7159838933495
Path:

Bore Hole Information

Bore Hole ID: 1006712664
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed:
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443968.00
North83: 5028136.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Links

Bore Hole ID: 1006712664
Depth M:
Year Completed:
Well Completed Dt:
Audit No: C36226

Tag No: A198420
Contractor: 7543
Path:
Latitude: 45.4044988818001
Longitude: -75.7159838933495

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	1 of 1	SSE/167.8	67.9 / 3.31	975 Gladstone Avenue Ottawa ON K1Y 4W5	EHS

Order No:	20190501135	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	08-MAY-19	**Search Radius (km):**	.3
Date Received:	01-MAY-19	**X:**	-75.716925
Previous Site Name:		**Y:**	45.404122
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	1 of 3	NE/171.3	61.2 / -3.41	1010 Somerset Street West Ottawa ON	EHS

Order No:	21032900261	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	26-APR-21	**Search Radius (km):**	.25
Date Received:	29-MAR-21	**X:**	-75.71628743
Previous Site Name:		**Y:**	45.40693246
Lot/Building Size:	6.3 acres		
Additional Info Ordered:	City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	2 of 3	NE/171.3	61.2 / -3.41	1010 Somerset Street West Ottawa ON	EHS

Order No:	21032900261	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	26-APR-21	**Search Radius (km):**	.25
Date Received:	29-MAR-21	**X:**	-75.71628743
Previous Site Name:		**Y:**	45.40693246
Lot/Building Size:	6.3 acres		
Additional Info Ordered:	City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	3 of 3	NE/171.3	61.2 / -3.41	1010 Somerset Street West Ottawa ON	EHS

Order No:	21032900261	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	26-APR-21	**Search Radius (km):**	.25
Date Received:	29-MAR-21	**X:**	-75.71628743
Previous Site Name:		**Y:**	45.40693246
Lot/Building Size:	6.3 acres		
Additional Info Ordered:	City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	1 of 1	ESE/172.3	64.9 / 0.31	ON	WWIS

Well ID:	7387934	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	31-Mar-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z359395	**Contractor:**	7241

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Tag:	A318162	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008670109	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443987.00
Code OB Desc:		**North83:**	5028143.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	30-Apr-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008670109	**Tag No:**	A318162
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Path:**	
Well Completed Dt:	2021/04/30	**Latitude:**	45.4045634074236
Audit No:	Z359395	**Longitude:**	-75.7157419236745

---

40 **1 of 1** **SE/175.1** **66.0 / 1.39** **ON** **WWIS**

Well ID:	7387898	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	31-May-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z359394	**Contractor:**	7241
Tag:	A318163	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008664429	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443979.00
Code OB Desc:		***North83:***	5028131.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	30-Apr-2021 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008664429	***Tag No:***	A318163
Depth M:		***Contractor:***	7241
Year Completed:	2021	***Path:***	
Well Completed Dt:	2021/04/30	***Latitude:***	45.4044547598388
Audit No:	Z359394	***Longitude:***	-75.715842776616

41 ***1 of 1*** ***SE/175.5*** ***66.7 / 2.15*** ***975 GLADSTON AVE OTTAWA ON*** ***WWIS***

Well ID:	7245909	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	05-Aug-2015 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z199797	***Contractor:***	7238
Tag:	A175220	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2015/07/02
Year Completed:	2015
Depth (m):	5.5373016
Latitude:	45.4041996193699
Longitude:	-75.716337898736
Path:	

Bore Hole Information

Bore Hole ID:	1005538753	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443940.00
Code OB Desc:		***North83:***	5028103.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02-Jul-2015 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005652322
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	8.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005652321
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	8.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005652324
Layer:	4
Color:	
General Color:	
Mat1:	26

Most Common Material: ROCK
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 18.0
Formation End Depth: 18.16699981689453
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005652323
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 10.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005652331
Layer: 1
Plug From: 18.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005652332
Layer: 2
Plug From: 6.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005652330
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005652320
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005652327
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 8.0
Depth To: 0.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005652328
Layer: 1
Slot: 10
Screen Top Depth: 18.0
Screen End Depth: 8.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1005652326
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005652325
Diameter: 8.0
Depth From: 0.0
Depth To: 18.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1005538753
Depth M: 5.5373016
Year Completed: 2015
Well Completed Dt: 2015/07/02
Audit No: Z199797
Tag No: A175220
Contractor: 7238
Path: 724\7245909.pdf
Latitude: 45.4041996193699
Longitude: -75.716337898736

---

42 ***1 of 2*** ***SW/177.1*** ***65.9 / 1.31*** ***The Original Maple Bat Company***
93 Bayswater Ave Unit A
Ottawa ON K1Y 2G2 ***SCT***

Established:
Plant Size (ft²):
Employment: 3

--Details--
Description: Sporting and Athletic Goods Manufacturing
SIC/NAICS Code: 339920

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	2 of 2	SW/177.1	65.9 / 1.31	The Original Maple Bat Company 93 Bayswater Ave Ottawa ON K1Y 2G2	SCT

Established: 1996
Plant Size (ft²):
Employment:

--Details--
Description: Sporting and Athletic Goods Manufacturing
SIC/NAICS Code: 339920

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	1 of 16	SE/177.6	66.2 / 1.61	TerraPro Corporation 145 Loretta Ave. North Ottawa ON K1Y 2J7	GEN

Generator No: ON4523321
SIC Code: 561730
SIC Description: Landscaping Services
Approval Years: 03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	2 of 16	SE/177.6	66.2 / 1.61	TERRA PRO CORPORATION 145 LORETTA AVE N OTTAWA ON K1Y 2J7	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code: 02
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	3 of 16	SE/177.6	66.2 / 1.61	TERRAPRO CORPORATION 145 LORETTA AVENUE NORTH OTTAWA ON K1Y 2J7	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code: 02
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	4 of 16	SE/177.6	66.2 / 1.61	TerraPro Corporation 145 Loretta Ave. North Ottawa ON	GEN

Generator No: ON4523321
SIC Code: 561730
SIC Description: LANDSCAPING SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	5 of 16	SE/177.6	66.2 / 1.61	TerraPro Corporation 145 Loretta Ave. North Ottawa ON	GEN

Generator No: ON4523321
SIC Code: 561730
SIC Description: Landscaping Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

43 | ***6 of 16*** | ***SE/177.6*** | ***66.2 / 1.61*** | ***145 Loretta Avenue North Ottawa ON*** | ***EHS***

Order No: 20120329007
Status: C
Report Type: Custom Report
Report Date: 4/4/2012 9:34:30 AM
Date Received: 3/29/2012 9:32:56 AM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.716187
Y: 45.404308

---

43 | ***7 of 16*** | ***SE/177.6*** | ***66.2 / 1.61*** | ***TerraPro Corporation 145 Loretta Ave. North Ottawa ON*** | ***GEN***

Generator No: ON4523321
SIC Code: 561730
SIC Description: Landscaping Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

43 | ***8 of 16*** | ***SE/177.6*** | ***66.2 / 1.61*** | ***TerraPro Corporation 145 Loretta Ave. North Ottawa ON*** | ***GEN***

Generator No: ON4523321
SIC Code: 561730
SIC Description: Landscaping Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

43 | ***9 of 16*** | ***SE/177.6*** | ***66.2 / 1.61*** | ***TerraPro Corporation***
145 Loretta Ave. North
Ottawa ON K1Y 2J7 | ***GEN***

Generator No: ON4523321
SIC Code: 561730
SIC Description: Landscaping Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

43 | ***10 of 16*** | ***SE/177.6*** | ***66.2 / 1.61*** | ***TerraPro Corporation***
145 Loretta Ave. North
Ottawa ON K1Y 2J7 | ***GEN***

Generator No: ON4523321
SIC Code: 561730
SIC Description: LANDSCAPING SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Hank Mollema
Choice of Contact: CO_ADMIN
Phone No Admin: (613) 248-8383 Ext.221
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	11 of 16	SE/177.6	66.2 / 1.61	DST Group Inc 145 Loretta Ave Ottawa ON K1Y 4W5	GEN

Generator No: ON4749433
SIC Code:
SIC Description:
Approval Years: As of Dec 2017
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	12 of 16	SE/177.6	66.2 / 1.61	TERRA PRO CORPORATION 145 LORETTA AVE N OTTAWA ON K1Y2J7	PES

Detail Licence No:
Licence No: 05112
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Operator
Licence Type Code: 02
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 2488383
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	13 of 16	SE/177.6	66.2 / 1.61	TERRAPRO CORPORATION 145 LORETTA AVENUE NORTH OTTAWA ON K1Y2J7	PES

Detail Licence No:
Licence No: 05875
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Operator
Licence Type Code: 02
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 2488383
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	14 of 16	SE/177.6	66.2 / 1.61	TERRA PRO CORPORATION 145 LORETTA AVE N OTTAWA ON K1Y2J7	PES

Detail Licence No:
Licence No: 05112
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Operator
Licence Type Code: 01
Licence Class: 06
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 2488383
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	15 of 16	SE/177.6	66.2 / 1.61	145 Loretta Ave North Ottawa ON	SPL

Ref No: 6320-BA8RWR
Site No: NA
Incident Dt: 3/13/2019
Year:
Incident Cause:
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/13/2019
Dt Document Closed:
Incident Reason:
Site Name: 145 Loretta Ave North<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: TSSA: sheen on surface water private fuel outlet
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address: 145 Loretta Ave North
Site District Office: Ottawa
Site Postal Code:
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	16 of 16	SE/177.6	66.2 / 1.61	Private Pickup Truck<UNOFFICIAL> 145 Loretta Avenue, North Ottawa ON K1Y 2J7	SPL

Ref No:	6872-BLDNXE	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2020/02/01	**Health/Env Conseq:**	0 - No Impact
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	MOTOR OIL	**Site Address:**	145 Loretta Avenue, North
Contaminant Limit 1:		**Site District Office:**	Ottawa
Contam Limit Freq 1:	n/a	**Site Postal Code:**	K1Y 2J7
Contaminant UN No 1:	1993	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Ottawa
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land; Surface Water	**Northing:**	5028095.09
MOE Response:	No	**Easting:**	443957.07
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2020/02/01	**Site Map Datum:**	
Dt Document Closed:	2020/07/17	**SAC Action Class:**	Watercourse Spills
Incident Reason:	Operator/Human Error	**Source Type:**	Motor Vehicle
Site Name:	Parking Lot<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	City of Ottawa: Unknown Quantity of Motor Fluids to CB		
Contaminant Qty:	0 other - see incident description		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	1 of 3	W/178.4	64.8 / 0.22	57 Bayswater Avenue Ottawa ON K1Y 3C4	EHS

Order No:	20191128034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	ON
Report Date:	29-NOV-19	**Search Radius (km):**	.001
Date Received:	28-NOV-19	**X:**	-75.71966
Previous Site Name:		**Y:**	45.405512
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	2 of 3	W/178.4	64.8 / 0.22	57 Bayswater Avenue Ottawa ON K1Y 3C4	EHS

Order No:	20191128034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	ON
Report Date:	29-NOV-19	**Search Radius (km):**	.001
Date Received:	28-NOV-19	**X:**	-75.71966
Previous Site Name:		**Y:**	45.405512
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	3 of 3	W/178.4	64.8 / 0.22	57 Bayswater Avenue Ottawa ON K1Y 3C4	EHS

Order No:	20191128034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	29-NOV-19	**Search Radius (km):**	.001
Date Received:	28-NOV-19	**X:**	-75.71966
Previous Site Name:		**Y:**	45.405512
Lot/Building Size:			
Additional Info Ordered:			

45 **1 of 11** **E/179.0** **62.9 / -1.69** **SPL**

UNKNOWN
933 GLADSTONE
OTTAWA CITY ON K1A 0T4

Ref No:	231625	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	7/11/2002	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	OTTAWA CITY
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	LAND, WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/11/2002	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Municipality No:	20107		
Site Geo Ref Meth:			
Incident Summary:	TOW TRUCK:8L HYDRAULIC OIL TO GRD AND STORM SEW-ER, CLEANING		
Contaminant Qty:			

45 **2 of 11** **E/179.0** **62.9 / -1.69** **GEN**

GVT. OF CAN.- PUBLIC WORKS CANADA
CHP PLOUFFE PARK 933 GLADSTONE AVE.
C/O PLACE DU PORTAGE PHASE IV LEVEL II
OTTAWA ON K1A 0T4

Generator No:	ON0144774
SIC Code:	8159
SIC Description:	OTHER GEN. ADMIN.
Approval Years:	90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		WASTE OILS & LUBRICANTS			
45	3 of 11	E/179.0	62.9 / -1.69	GVT. OF CAN.- PUBLIC WORKS CANADA 18-375 CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II HULL OTTAWA ON K1A 0T4	GEN

Generator No: ON0144774
SIC Code: 8159
SIC Description: OTHER GEN. ADMIN.
Approval Years: 92,93,94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	4 of 11	E/179.0	62.9 / -1.69	GVT. OF CAN.- PUBLIC WORKS CANADA 18-375 CHP PLOUFFE PARK 933 GLADSTONE AVE. C/O PLACE DU PORTAGE PHASE IV LEVEL II ON K1A 0T4	GEN

Generator No: ON0144774
SIC Code: 8159
SIC Description: OTHER GEN. ADMIN.
Approval Years: 95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	5 of 11	E/179.0	62.9 / -1.69	DSS CAPITAL REGION SUPPLY CENTRE 933 GLADSTONE AVENUE OTTAWA ON K1A 0T4	GEN

Generator No: ON0989500
SIC Code: 8159
SIC Description: OTHER GEN. ADMIN.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

45	6 of 11	E/179.0	62.9 / -1.69	***PUBLIC WORKS AND GOVT SERVICES CANADA*** ***CAPITAL REGION SUPPLY CENTRE (CRSC) 933 GLADSTONE AVENUE*** ***OTTAWA ON K1A 0T4***	GEN

Generator No: ON0989500
SIC Code: 8159
SIC Description: OTHER GEN. ADMIN.
Approval Years: 92,93,95,96,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

45	7 of 11	E/179.0	62.9 / -1.69	***DSS CAPITAL REGION SUPPLY CENTRE 13-297*** ***933 GLADSTONE AVENUE*** ***OTTAWA ON K1A 0T4***	GEN

Generator No: ON0989500
SIC Code: 8159
SIC Description: OTHER GEN. ADMIN.
Approval Years: 94
PO Box No:

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

45 | ***8 of 11*** | ***E/179.0*** | ***62.9 / -1.69*** | ***933 Gladstone Ave Ottawa ON K1A0T4*** | ***EHS***

Order No: 20160822162
Status: C
Report Type: Custom Report
Report Date: 23-SEP-16
Date Received: 22-AUG-16
Previous Site Name:
Lot/Building Size: ~7ha
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality: Ottawa
Client Prov/State: ON
Search Radius (km): .25
X: -75.714916
Y: 45.405543

---

45 | ***9 of 11*** | ***E/179.0*** | ***62.9 / -1.69*** | ***OTTAWA COMMUNITY HOUSING CORPORATION 933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4 Ottawa ON*** | ***RSC***

RSC ID: 226204
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Industrial
Ministry District: Ottawa District Office
Filing Date: 2019/11/29
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Asmt Roll No: 061406350116102-0000
Prop ID No (PIN): 04107-0288 (LT)
Property Municipal Address: 933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119556&fileName=BROWNFIELDS-E.pdf

Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: ERIC WILSON
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:

Document(s) Detail

Document Heading: Supporting Documents
Document Name: 933 Gladstone - Deed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119553&fileName=933+Gladstone+-+Deed.pdf

Document Heading: Supporting Documents
Document Name: 933 Gladstone Lawyer letter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119558&fileName=933+Gladstone+Lawyer+letter.pdf

Document Heading: Supporting Documents
Document Name: 933 Gladstone - Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119561&fileName=933+Gladstone+-+Survey.pdf

Document Heading: Supporting Documents
Document Name: 933 Gladstone - CSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119559&fileName=933+Gladstone+-+CSM.pdf

Document Heading: Supporting Documents
Document Name: 933 Gladstone - Owner Cert Status.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119554&fileName=933+Gladstone+-+Owner+Cert+Status.pdf

Document Heading: Supporting Documents
Document Name: 933 Gladstone-APEC_Table.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119552&fileName=933+Gladstone-APEC_Table.pdf

Document Heading: Supporting Documents
Document Name: 933 Gladstone-Current_and_Past_Use_Table.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=119560&fileName=933+Gladstone-Current_and_Past_Use_Table.pdf

---

45	***10 of 11***	***E/179.0***	***62.9 / -1.69***	***OTTAWA COMMUNITY HOUSING CORPORATION*** ***933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4*** ***Ottawa ON***	***RSC***

RSC ID: 236233
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Industrial
Ministry District: Ottawa District Office
Filing Date: 2022/12/21
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: ERIC WILSON
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:
Asmt Roll No: 0614063501161040000
Prop ID No (PIN): 04107-0299 (LT)
Property Municipal Address: 933 GLADSTONE AVENUE, OTTAWA, ON K1A 0T4
Mailing Address:

Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175478&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-Non Potable notice.pdf
Document Type: A copy of No Objection Statement from municipality
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175477&fileName=NW933+Gladstone-Non+Potable+notice.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-Deed.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175474&fileName=NW933+Gladstone-Deed.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladsteone-Owner cert status.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175481&fileName=NW933+Gladsteone-Owner+cert+status.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175470&fileName=NW933+Gladstone-Survey.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-Lawyer Letter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175475&fileName=NW933+Gladstone-Lawyer+Letter.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-Current_and_Past_Use_Table.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175471&fileName=NW933+Gladstone-Current_and_Past_Use_Table.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-APEC_Table.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175473&fileName=NW933+Gladstone-APEC_Table.pdf

Document Heading: Supporting Documents
Document Name: NW933 Gladstone-CSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=175472&fileName=NW933+Gladstone-CSM.pdf

45	***11 of 11***	***E/179.0***	***62.9 / -1.69***	***933 Gladstone Ave Ottawa ON K1Y 3E5***	***EHS***

Order No: 23011900394
Status: C
Report Type: Standard Report
Nearest Intersection:
Municipality:
Client Prov/State: ON

Report Date:	24-JAN-23	**Search Radius (km):**	.25
Date Received:	19-JAN-23	**X:**	-75.7151321
Previous Site Name:		**Y:**	45.405884
Lot/Building Size:			
Additional Info Ordered:	City Directory		

46 **1 of 1** **SE/180.3** **66.2 / 1.61** **ON** **WWIS**

Well ID:	7391244	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z364088	**Contractor:**	7241
Tag:	A303025	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008704742	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443964.00
Code OB Desc:		**North83:**	5028112.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	25-May-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008704742	**Tag No:**	A303025
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Path:**	
Well Completed Dt:	2021/05/25	**Latitude:**	45.4042825474191
Audit No:	Z364088	**Longitude:**	-75.7160322728215

47 **1 of 1** **SE/180.9** **66.2 / 1.61** **ON** **WWIS**

Well ID:	7391243	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	29-Jun-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z364091	**Contractor:**	7241
Tag:	A303024	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008704739	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443969.00
Code OB Desc:		**North83:**	5028115.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	25-May-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008704739	**Tag No:**	A303024
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Path:**	
Well Completed Dt:	2021/05/25	**Latitude:**	45.4043099496498
Audit No:	Z364091	**Longitude:**	-75.7159687285529

48	*1 of 1*	*ESE/181.5*	*64.3 / -0.24*	*ON*	***BORE***

Borehole ID:	847977	**Inclin FLG:**	No
OGF ID:	215589634	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	05-DEC-1962	**Municipality:**	
Static Water Level:		**Lot:**	LOT 38
Primary Water Use:		**Township:**	NEPEAN
Sec. Water Use:		**Latitude DD:**	45.404899
Total Depth m:	3.2	**Longitude DD:**	-75.715286
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	444023
Drill Method:	Diamond Drill	**Northing:**	5028180
Orig Ground Elev m:	59.9	**Location Accuracy:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Elev Reliabil Note: | **Accuracy:** Within 50 metres
DEM Ground Elev m: 57.3
Concession: CON 1 ON OTTAWA RIVER
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 6559452
Top Depth: 0
Bottom Depth: 1.8
Material Color: Grey-Brown
Material 1: Silt
Material 2: Clay
Material 3: Gravel
Material 4: Fill
Gsc Material Description:
Stratum Description: GREY-BROWN CLAYEY SILT AND GRAVEL FILL **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6559453
Top Depth: 1.8
Bottom Depth: 3.2
Material Color: Grey
Material 1: Till
Material 2: clay silt
Material 3: Fine Sand
Material 4: Gravel
Gsc Material Description:
Stratum Description: GREY, CLAYEY SILT, FINE SAND, GRAVEL (GLACIAL TILL) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

---

49 | ***1 of 2*** | ***W/187.6*** | ***64.8 / 0.22*** | ***57 Bayswater Ave Ottawa ON K1Y 2E8*** | ***EHS***

Order No: 20070322010
Status: C
Report Type: CAN - Custom Report
Report Date: 3/30/2007
Date Received: 3/22/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps And /or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X: -75.719684
Y: 45.405687

---

49 | ***2 of 2*** | ***W/187.6*** | ***64.8 / 0.22*** | ***57 Bayswater Ave Ottawa ON K1Y2E8*** | ***EHS***

Order No: 20130801025
Status: C
Report Type: Custom Report
Report Date: 09-AUG-13
Date Received: 01-AUG-13
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.719598
Y: 45.405522

---

50 | ***1 of 1*** | ***SE/188.1*** | ***66.2 / 1.61*** | ***1010 SOMERSET ET W OTTAWA ON*** | ***WWIS***

Well ID: 1535405
Flowing (Y/N):

Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	22-Mar-2005 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z20840	**Contractor:**	1844
Tag:	A011954	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/153\1535405.pdf

Additional Detail(s) (Map)

Well Completed Date:	2004/08/18
Year Completed:	2004
Depth (m):	
Latitude:	45.4041742200112
Longitude:	-75.7160820165187
Path:	153\1535405.pdf

Bore Hole Information

Bore Hole ID:	11315944	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443960.00
Code OB Desc:		**North83:**	5028100.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	18-Aug-2004 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Method of Construction & Well Use

Method Construction ID:	961535405
Method Construction Code:	5
Method Construction:	Air Percussion
Other Method Construction:	

Pipe Information

Pipe ID:	11330799
Casing No:	1

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	930855169
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933412025
Layer:	1
Slot:	#10
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.5

Links

Bore Hole ID:	11315944	**Tag No:**	A011954
Depth M:		**Contractor:**	1844
Year Completed:	2004	**Path:**	153\1535405.pdf
Well Completed Dt:	2004/08/18	**Latitude:**	45.4041742200112
Audit No:	Z20840	**Longitude:**	-75.7160820165187

---

51 | ***1 of 1*** | ***S/188.5*** | ***68.6 / 4.02*** | ***City of Ottawa***
Breezehill Ave N between Laurel and Gladstone
Ottawa ON | ***SPL***

Ref No:	0381-83NPSF	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge Or Bypass To A Watercourse	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	41	**Nearest Watercourse:**	
Contaminant Name:	PAINT AND PIGMENT WASTES	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	3/18/2010	**Site Map Datum:**	
Dt Document Closed:	4/20/2010	**SAC Action Class:**	Watercourse Spills
Incident Reason:	Negligence (Apparent) - Caused by lack of diligence	**Source Type:**	
Site Name:	Spill site<UNOFFICIAL>		
Site County/District:			

Municipality No:
Site Geo Ref Meth:
Incident Summary: Spill of paint to storm system
Contaminant Qty:

---

52 **1 of 1** **NNW/188.5** **61.9 / -2.69** **ON** **BORE**

Borehole ID:	847981	**Inclin FLG:**	No
OGF ID:	215589638	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	15-DEC-1961	**Municipality:**	
Static Water Level:		**Lot:**	LOT 38
Primary Water Use:		**Township:**	NEPEAN
Sec. Water Use:		**Latitude DD:**	45.407176
Total Depth m:	7.8	**Longitude DD:**	-75.718267
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443792
Drill Method:	Diamond Drill	**Northing:**	5028435
Orig Ground Elev m:	58.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 50 metres
DEM Ground Elev m:	64.5		

Concession: CON 1 ON OTTAWA RIVER
Location D:
Survey D:
Comments: BH 15 IS LACKING A DATE, USED THE SAME DATE FOR 14 AS A MARKER.

Borehole Geology Stratum

Geology Stratum ID:	6559465	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Boulders	**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: BROWN SAND AND GRAVEL WITH BOULDERS (POSSIBLE FILL) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	6559466	**Mat Consistency:**	Soft
Top Depth:	3.2	**Material Moisture:**	
Bottom Depth:	6.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SOFT TO FIRM GREY CLAY, TRACE OF SILT **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	6559467	**Mat Consistency:**	Very Dense
Top Depth:	6.4	**Material Moisture:**	
Bottom Depth:	7.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand - Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: VERY DENSE SILTY TILL, SOME SAND AND GRAVEL **Note: Many records provided by the department have a truncated [Stratum Description] field.

---

53 | **1 of 2** | **W/193.8** | **65.0 / 0.39** | **Broadband Maintenance Inc. <UNOFFICIAL>**
49 Bayswater Ave
Ottawa ON K1Y 2E7 | **SPL**

Ref No:	5553-863QB4	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge or Emission to Air	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	METHANE GAS, COMPRESSED (NATURAL GAS)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	Referral to others	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/3/2010	**Site Map Datum:**	
Dt Document Closed:	6/10/2010	**SAC Action Class:**	TSSA - Fuel Safety Branch
Incident Reason:	Spill	**Source Type:**	
Site Name:	gas service damage<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	TSSA FSB: 1inch plastic made safe		
Contaminant Qty:			

---

53 | **2 of 2** | **W/193.8** | **65.0 / 0.39** | **49 Bayswater Avenue, Ottawa**
ON K1Y 2E7 | **INC**

Incident No:	399906	**Any Health Impact:**	
Incident ID:	2551556	**Any Enviro Impact:**	
Instance No:		**Service Interrupted:**	
Status Code:	Causal Analysis Complete	**Was Prop Damaged:**	
Attribute Category:	FS-Incident	**Reside App. Type:**	
Context:		**Commer App. Type:**	
Date of Occurrence:		**Indus App. Type:**	
Time of Occurrence:		**Institut App. Type:**	
Incident Created On:		**Venting Type:**	
Instance Creation Dt:		**Vent Conn Mater:**	
Instance Install Dt:		**Vent Chimney Mater:**	
Occur Insp Start Date:		**Pipeline Type:**	Service / Riser Distribution Pipeline
Approx Quant Rel:		**Pipeline Involved:**	
Tank Capacity:		**Pipe Material:**	Plastic
Fuels Occur Type:		**Depth Ground Cover:**	0.6
Fuel Type Involved:		**Regulator Location:**	Outside
Enforcement Policy:		**Regulator Type:**	Service Regulator (up to 60 psi intake)
Prc Escalation Req:		**Operation Pressure:**	60
Tank Material Type:		**Liquid Prop Make:**	
Tank Storage Type:		**Liquid Prop Model:**	
Tank Location Type:		**Liquid Prop Serial No:**	
Pump Flow Rate Cap:		**Liquid Prop Notes:**	
Task No:		**Equipment Type:**	
Notes:		**Equipment Model:**	

Drainage System:
Sub Surface Contam.:
Aff Prop Use Water:
Contam. Migrated:
Contact Natural Env:
Incident Location: 49 Bayswater Avenue, Ottawa - 1" Pipeline Hit
Occurence Narrative: contractor hit gas line with mini excavator. Had locates and did not use them.
Operation Type Involved:
Item:
Item Description:
Device Installed Location:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Near Body of Water:

---

54 | ***1 of 1*** | ***SE/194.3*** | ***66.7 / 2.16*** | ***975 GLADSTONE AVE. OTTAWA ON*** | ***WWIS***

Well ID:	7245910	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	0	***Date Received:***	05-Aug-2015 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z199798	***Contractor:***	7238
Tag:	A175219	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	NEPEAN TOWNSHIP		
Site Info:			

PDF URL (Map):

Additional Detail(s) (Map)

Well Completed Date:	2015/07/02
Year Completed:	2015
Depth (m):	5.4864
Latitude:	45.4040472504841
Longitude:	-75.7162337487348
Path:	

Bore Hole Information

Bore Hole ID:	1005538756	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443948.00
Code OB Desc:		***North83:***	5028086.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02-Jul-2015 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1005652455
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 6.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005652457
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3: 91
Mat3 Desc: WATER-BEARING
Formation Top Depth: 10.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005652456
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 84
Mat2 Desc: SILTY
Mat3:
Mat3 Desc:
Formation Top Depth: 6.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005652458
Layer: 4
Color:
General Color:

Mat1: 26
Most Common Material: ROCK
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 18.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005652465
Layer: 1
Plug From: 18.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005652466
Layer: 2
Plug From: 6.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005652464
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005652454
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005652461
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 8.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005652462
Layer: 1
Slot: 10
Screen Top Depth: 8.0

Screen End Depth: 18.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1005652460
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005652459
Diameter: 8.0
Depth From: 0.0
Depth To: 18.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID: 1005538756
Depth M: 5.4864
Year Completed: 2015
Well Completed Dt: 2015/07/02
Audit No: Z199798
Tag No: A175219
Contractor: 7238
Path: 724\7245910.pdf
Latitude: 45.4040472504841
Longitude: -75.7162337487348

---

55 | **1 of 1** | **E/196.8** | **62.9 / -1.69** | **933 Gladstone Ave**
Ottawa ON K1A0T4 | **EHS**

Order No: 20150303037
Status: C
Report Type: Custom Report
Report Date: 06-MAR-15
Date Received: 03-MAR-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Topographic Maps
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.714882
Y: 45.405412

---

56 | **1 of 66** | **SSE/209.3** | **68.2 / 3.61** | **B.A. BANKNOTE INC.**
975 GLADSTONE AVE.
OTTAWA CITY ON K1Y 4W5 | **CA**

Certificate #: 8-4158-92-
Application Year: 92
Issue Date: 12/23/1992
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: INST. MIST ELMIN., (2) GEN. EXH. SYSTEMS
Contaminants:
Emission Control: Packed Tower,

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	2 of 66	SSE/209.3	68.2 / 3.61	B A BANKNOTE 975 GLADSTONE AVE OTTAWA ON K1Y 4W5	SCT

Established: 0000
Plant Size (ft²): 0
Employment: 252

--Details--
Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2759

Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	3 of 66	SSE/209.3	68.2 / 3.61	975 Gladstone Avenue Ottawa ON K1Y 4W5	CA

Certificate #: 6703-4SSRE3
Application Year: 01
Issue Date: 1/8/01
Approval Type: Industrial air
Status: Revoked and/or Replaced
Application Type: Amended CofA
Client Name: BA Banknote Inc.
Client Address: 975 Gladstone Avenue
Client City: Ottawa
Client Postal Code: K1Y 4W5
Project Description: Installation of one Super Simultank-212 printing press used in printring commercial paper.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	4 of 66	SSE/209.3	68.2 / 3.61	975 Gladstone Avenue Ottawa ON K1Y 4W5	CA

Certificate #: 9223-5C6HZK
Application Year: 02
Issue Date: 9/6/02
Approval Type: Industrial air
Status: Approved
Application Type: Amended CofA
Client Name: BA Banknote Inc.
Client Address: 975 Gladstone Avenue
Client City: Ottawa
Client Postal Code: K1Y 4W5
Project Description: The applicant seeks approval for an amendment to the existing Certificate of Approval for the installation of a silk screen press. The addition of this equipment will include construction of three stacks that will ventilate the silk screen area and will exhaust solvent vapours to the atmosphere.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	5 of 66	SSE/209.3	68.2 / 3.61	BA Banknote Inc. 975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA	EBR

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				ON	

EBR Registry No: IA00E0164
Ministry Ref No: 8042-4FUP9P
Notice Type: Instrument Decision
Notice Stage:
Notice Date: January 10, 2001
Proposal Date: January 24, 2000
Year: 2000
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: BA Banknote Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 975 Gladstone Avenue, Ottawa Ontario, K1Y 4W5
Comment Period:
URL:

Site Location Details:

975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA

56	6 of 66	SSE/209.3	68.2 / 3.61	BA Banknote Inc. 975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA ON	EBR

EBR Registry No: IA01E0439
Ministry Ref No: 3825-4VAQMB
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 10, 2002
Proposal Date: March 30, 2001
Year: 2001
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: BA Banknote Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 975 Gladstone Avenue, Ottawa Ontario, K1Y 4W5
Comment Period:
URL:

Site Location Details:

975 Gladstone Avenue Ottawa Ontario CITY OF OTTAWA

56	7 of 66	SSE/209.3	68.2 / 3.61	B.A. Banknote 975 Gladstone Ave Ottawa ON K1Y 4W5	SCT

Established: 1867
Plant Size (ft²):
Employment: 170

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

---

56 | ***8 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BRITISH AMERICAN BANK NOTE INC.***
975 GLADSTONE AVENUE C/O P.O. BOX 399, STATION A
OTTAWA ON K1Y 4W5 | ***GEN***

Generator No: ON0297401
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

---

56 | ***9 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA BANKNOTE***
OTTAWA DIV., DIV OF QUEBECOR PUBLITECH INC./975 GLADSTONE AVENUE
OTTAWA ON K1Y 4W5 | ***GEN***

Generator No: ON0297401
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 89,90,92,93,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

56	***10 of 66***	***SSE/209.3***	***68.2 / 3.61***	***BA BANKNOTE 05-931*** ***OTTAWA DIV., DIV OF QUEBECOR PUBLITECH INC./975 GLADSTONE AVENUE*** ***OTTAWA ON K1Y 4W5***	***GEN***

Generator No: ON0297401
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263

Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

56 | **11 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA BANKNOTE**
975 GLADSTONE AVENUE
OTTAWA ON K1N 8V4 | **GEN**

Generator No: ON0297401
SIC Code: 2819
SIC Description: OTHER COMM. PRINTING
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 146

Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	12 of 66	SSE/209.3	68.2 / 3.61	BA BANKNOTE INC. 975 GLADSTONE AVENUE OTTAWA ON K1N 8V4	GEN

Generator No: ON0297401
SIC Code:
SIC Description:
Approval Years: 02,03
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241

Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

56 | **13 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA BANKNOTE INC.**
975 GLADSTONE AVE. NOT AVAILABLE
OTTAWA ON K1Y 4W5 | **NPRI**

NPRI ID:	7358	**Org ID:**	38275
Other ID:	Y	**Submit Date:**	7/14/2003
No Other ID:	1	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	18366	**Contact ID:**	168490
Report ID:	163453	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	JOHN
Report Year:	2002	**Cont Last Name:**	CODY
Not-Current Rpt?:	No	**Contact Position:**	ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2011	**Contact Fax:**	6137287419
Fac ID:	141158	**Contact Ph.:**	6137285854
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	613
Fac Address1:	975 GLADSTONE AVE.	**Contact Tel.:**	37285854
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	228
Fac Postal Zip:	K1Y 4W5	**Cont Fax Area Cde:**	613
Facility Lat:		**Contact Fax:**	37287419
Facility Long:		**Contact Email:**	JOHN_CODY@GDM.DE
DLS (Last Filed Rpt):		**Latitude:**	45.4038
Facility DLS:		**Longitude:**	-75.7167
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	Fals	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	240	**Waste Streams:**	False
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1
Stacks:	False	**Shutdown:**	False
No of Stacks:		**No of Shutdown:**	0
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	10.1
Unit:	tonnes
Basis of Estimate Cd:	E E2
Basis of Estimate Desc:	E- Emission Factor - In use from 1994 to 2002 ; E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Hexavalent chromium (and its compounds)
Chem (fr):	Chrome hexavalent (et ses composés)
Quantity:	11
Unit:	kg
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

56 ***14 of 66*** ***SSE/209.3*** ***68.2 / 3.61*** ***B.A. Banknote Inc.*** ***975 Gladstone Ave*** ***Ottawa ON K1Y 4W5*** ***SCT***

Established:	1867
Plant Size (ft²):	
Employment:	170

--Details--

Description:	Other Printing
SIC/NAICS Code:	323119

---

56 ***15 of 66*** ***SSE/209.3*** ***68.2 / 3.61*** ***BA BANKNOTE INC.*** ***975 GLADSTONE AVENUE NOT AVAILABLE*** ***OTTAWA ON K1Y4W5*** ***NPRI***

NPRI ID:	7358	***Org ID:***	38275
Other ID:	Y	***Submit Date:***	8/6/2004
No Other ID:	1	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	20585	***Contact ID:***	168490
Report ID:	155066	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	JOHN
Report Year:	2003	***Cont Last Name:***	CODY
Not-Current Rpt?:	No	***Contact Position:***	ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2011	***Contact Fax:***	6137287419
Fac ID:	141159	***Contact Ph.:***	6137285854
Fac Name:	NOT AVAILABLE	***Cont Area Code:***	613
Fac Address1:	975 GLADSTONE AVENUE	***Contact Tel.:***	37285854
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	228
Fac Postal Zip:	K1Y4W5	***Cont Fax Area Cde:***	613
Facility Lat:	45.4038	***Contact Fax:***	37287419
Facility Long:	-75.7167	***Contact Email:***	JOHN_CODY@GDM.DE
DLS (Last Filed Rpt):		***Latitude:***	45.4038
Facility DLS:		***Longitude:***	-75.7167

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	240	**Waste Streams:**	True¿
Parent Co.:	*	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1
Stacks:	True	**Shutdown:**	True
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:

NAICS Code (2 digit):	32
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3231
NAICS 4 Description:	Printing and related support activities
NAICS Code (6 digit):	323119
NAICS 6 Description:	Other printing

Substance Release Report

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	11.1
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Hexavalent chromium (and its compounds)
Chem (fr):	Chrome hexavalent (et ses composés)
Quantity:	11
Unit:	kg
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

---

56 | ***16 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***975 Gladstone Avenue Ottawa ON K1Y 4W5*** | ***EHS***

Order No:	20050520015	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:		**Client Prov/State:**	ON
Report Date:	5/31/2005	**Search Radius (km):**	0.25
Date Received:	5/20/2005	**X:**	-75.716382
Previous Site Name:		**Y:**	45.403273
Lot/Building Size:			
Additional Info Ordered:			

---

56 | ***17 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA INTERNATIONAL INC. 975 GLADSTONE AVENUE OTTAWA ON K1N 8V4*** | ***GEN***

Generator No: ON0297401
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 254
Waste Class Name: TRANSFER STATION OILS WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 998
Waste Class Name: NONHAZARDOUS WASTE

Waste Class: 132
Waste Class Name: NEUTRALIZED WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

---

56 | **18 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA International Inc.**
975 Gladstone Ave
Ottawa ON K1Y 4W5 | **SCT**

Established: 1866
Plant Size (ft²):
Employment: 170

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

---

56 | **19 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA INTERNATIONAL**
975 GLADSTONE AVENUE NOT AVAILABLE
OTTAWA ON K1Y4W5 | **NPRI**

NPRI ID: 7358
Other ID: Y
No Other ID: 1
Track ID: 32859
Report ID: 92759
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2004
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2011
Fac ID: 141167
Fac Name: BA INTERNATIONAL
Fac Address1: 975 GLADSTONE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K1Y4W5
Facility Lat: 45.4038
Facility Long: -75.7167
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: True

Org ID: 38290
Submit Date: 1/22/2006
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 168497
Cont Type: MED
Contact Title:
Cont First Name: JOHN
Cont Last Name: CODY
Contact Position: QUALITY AND ENVIRONMENTAL MANAGER
Contact Fax: 6137287419
Contact Ph.: 6137285854
Cont Area Code: 613
Contact Tel.: 37285854
Contact Ext.:
Cont Fax Area Cde: 613
Contact Fax: 37287419
Contact Email: JOHN_CODY@GDM.DE
Latitude: 45.4038
Longitude: -75.7167
UTM Zone:
UTM Northing:

URL:		**UTM Easting:**	
No of Empl.:	240	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	True	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Carbon black
Chem (fr):	Noir de carbone
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Titanium (and its compounds)
Chem (fr):	Titane (et ses composés)
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	MSG#2 - Hydrotreated light distillate
Chem (fr):	EMG#2 - Distillat léger hydrotraité
Quantity:	8.947
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Light aromatic solvent naphtha
Chem (fr):	Solvant naphta aromatique léger
Quantity:	.213
Unit:	tonnes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: GE - Ethylene glycol propyl ether (EGPE)
Chem (fr): EG - Éther propylique d'éthylèneglycol (EGPE)
Quantity: .317
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: GE - Ethylene glycol butyl ether acetate (EGBEA)
Chem (fr): EG - Acétate d'éther butylique d'éthylèneglycol (EGBEA)
Quantity: .164
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 3
Category Type Desc: Fugitive
Category Type Desc (fr): Émissions fugitives
Grouping: Total Air
Trans Code: VOCs
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 13.851
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Hexavalent chromium (and its compounds)
Chem (fr): Chrome hexavalent (et ses composés)
Quantity: .026
Unit: kg
Basis of Estimate Cd:
Basis of Estimate Desc:

56	20 of 66	SSE/209.3	68.2 / 3.61	**Pinchin Environmental** **975 Gladstone** **Ottawa ON K1Y 4W5**	GEN

Generator No: ON5063272
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

---

56 ***21 of 66*** ***SSE/209.3*** ***68.2 / 3.61*** ***BA INTERNATIONAL***
975 GLADSTONE AVENUE NOT AVAILABLE
OTTAWA ON K1Y4W5 ***NPRI***

NPRI ID:	7358	***Org ID:***	38290
Other ID:	Y	***Submit Date:***	6/1/2006
No Other ID:	1	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	40358	***Contact ID:***	168497
Report ID:	100544	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	JOHN
Report Year:	2005	***Cont Last Name:***	CODY
Not-Current Rpt?:	No	***Contact Position:***	QUALITY AND ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2011	***Contact Fax:***	6137287419
Fac ID:	141167	***Contact Ph.:***	6137285854
Fac Name:	BA INTERNATIONAL	***Cont Area Code:***	613
Fac Address1:	975 GLADSTONE AVENUE	***Contact Tel.:***	37285854
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	K1Y4W5	***Cont Fax Area Cde:***	613
Facility Lat:	45.4038	***Contact Fax:***	37287419
Facility Long:	-75.7167	***Contact Email:***	JOHN_CODY@GDM.DE
DLS (Last Filed Rpt):		***Latitude:***	45.4038
Facility DLS:		***Longitude:***	-75.7167
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	Fals	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	240	***Waste Streams:***	False
Parent Co.:	Y	***No Streams:***	
No Parent Co.:	1	***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	False	***No Off Sites:***	1.00
Stacks:	False	***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	GE - Ethylene glycol butyl ether acetate (EGBEA)
Chem (fr):	EG - Acétate d'éther butylique d'éthylèneglycol (EGBEA)
Quantity:	.593
Unit:	tonnes
Basis of Estimate Cd:	

Basis of Estimate Desc:

Category Type ID: 3
Category Type Desc: Fugitive
Category Type Desc (fr): Émissions fugitives
Grouping: Total Air
Trans Code: VOCs
Chem: MSG#1 - Solvent naphtha medium aliphatic
Chem (fr): EMG#1 - Solvant naphta aliphatique moyen
Quantity: 4.706
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Hexavalent chromium (and its compounds)
Chem (fr): Chrome hexavalent (et ses composés)
Quantity: .017
Unit: kg
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: MSG#1 - Hydrotreated heavy naphtha
Chem (fr): EMG#1 - Naphta lourd hydrotraité
Quantity: .908
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

---

56 | **22 of 66** | **SSE/209.3** | **68.2 / 3.61** | **975 Gladstone Avenue Ottawa ON K1Y 4W5** | **EHS**

Order No: 20071128024
Status: C
Report Type: CAN - Complete Report
Report Date: 11/30/2007
Date Received: 11/28/2007
Previous Site Name:
Lot/Building Size: NA
Additional Info Ordered: Fire Insur. Maps And /or Site Plans

Nearest Intersection: Gladstone Avenue and Loretta Avenue North
Municipality: City of Ottawa
Client Prov/State:
Search Radius (km): 0.25
X: -75.716927
Y: 45.404016

---

56 | **23 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA INTERNATIONAL 975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5** | **NPRI**

NPRI ID: 7358
Other ID: Y
No Other ID: 1
Track ID: 50882
Report ID: 111337
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2006
Not-Current Rpt?: No

Org ID: 38290
Submit Date: 6/2/2007
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 168497
Cont Type: MED
Contact Title:
Cont First Name: JOHN
Cont Last Name: CODY
Contact Position: QUALITY AND ENVIRONMENTAL MANAGER

Yr of Last Filed Rpt:	2011	***Contact Fax:***	6137287419
Fac ID:	141167	***Contact Ph.:***	6137285854
Fac Name:	BA INTERNATIONAL	***Cont Area Code:***	613
Fac Address1:	975 GLADSTONE AVENUE	***Contact Tel.:***	37285854
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	K1Y4W5	***Cont Fax Area Cde:***	613
Facility Lat:	45.4038	***Contact Fax:***	37287419
Facility Long:	-75.7167	***Contact Email:***	JOHN_CODY@GDM.DE
DLS (Last Filed Rpt):		***Latitude:***	45.4038
Facility DLS:		***Longitude:***	-75.7167
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	False	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	240	***Waste Streams:***	True¿
Parent Co.:	Y	***No Streams:***	
No Parent Co.:	1	***Waste Off Sites:***	Fals
Pollut Prev Cmnts:	False	***No Off Sites:***	1.00
Stacks:	True	***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Hexavalent chromium (and its compounds)
Chem (fr):	Chrome hexavalent (et ses composés)
Quantity:	.016
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	MSG#1 - Hydrotreated heavy naphtha
Chem (fr):	EMG#1 - Naphta lourd hydrotraité
Quantity:	.836
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Category Type ID:	3
Category Type Desc:	Fugitive
Category Type Desc (fr):	Émissions fugitives
Grouping:	Total Air
Trans Code:	VOCs
Chem:	MSG#1 - Solvent naphtha medium aliphatic
Chem (fr):	EMG#1 - Solvant naphta aliphatique moyen
Quantity:	2.9
Unit:	tonnes

Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

---

56 **24 of 66** **SSE/209.3** **68.2 / 3.61** **BA Banknote Inc.**
975 Gladstone Avenue Ottawa Ontario Ottawa ON **EBR**

EBR Registry No: IA04E0048
Ministry Ref No: 9227-5V5REP
Notice Type: Instrument Decision
Notice Stage:
Notice Date: June 08, 2004
Proposal Date: January 13, 2004
Year: 2004
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: BA Banknote Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 975 Gladstone Avenue, Ottawa Ontario, K1Y 4W5
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

975 Gladstone Avenue Ottawa Ontario Ottawa

---

56 **25 of 66** **SSE/209.3** **68.2 / 3.61** **BA Banknote Inc.**
975 Gladstone Avenue Ottawa Ontario Ottawa ON **EBR**

EBR Registry No: IA04E0471
Ministry Ref No: 6786-5XFJPS
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 09, 2004
Proposal Date: April 02, 2004
Year: 2004
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: BA Banknote Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 975 Gladstone Avenue, Ottawa Ontario, K1Y 4W5
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

975 Gladstone Avenue Ottawa Ontario Ottawa

---

56 **26 of 66** **SSE/209.3** **68.2 / 3.61** **BA Banknote Inc.**
975 Gladstone Avenue Ottawa Ontario Ottawa ON **EBR**

EBR Registry No: IA06E1098
Decision Posted:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ministry Ref No:	4981-6SKPCP	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	April 16, 2007	**Act 2:**	
Proposal Date:	August 31, 2006	**Site Location Map:**	
Year:	2006		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	BA Banknote Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	975 Gladstone Avenue, Ottawa Ontario, K1Y 4W5		
Comment Period:			
URL:			

Site Location Details:

975 Gladstone Avenue Ottawa Ontario Ottawa

56	27 of 66	SSE/209.3	68.2 / 3.61	**BA International Inc.** **975 Gladstone Ave** **Ottawa ON K1Y 4W5**	SPL

Ref No:	3258-76CGWF	**Discharger Report:**	
Site No:		**Material Group:**	Other
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Discharges	**Sector Type:**	Transport Truck
Incident Event:		**Agency Involved:**	
Contaminant Code:	99	**Nearest Watercourse:**	
Contaminant Name:	CORROSIVE LIQUIDS, N.O.S.	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Brant
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	Planned Field Response	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/23/2007	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	Process upset	**Source Type:**	
Site Name:	122 HWY 53<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	Lacombe: small quantity 121 C liquid to parking lot		
Contaminant Qty:	0 other - see incident description		

56	28 of 66	SSE/209.3	68.2 / 3.61	**BA International Inc.** **975 Gladstone Ave** **Ottawa ON K1Y 4W5**	SPL

Ref No:	0352-789G8L	**Discharger Report:**	
Site No:		**Material Group:**	Oil
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Pipe Or Hose Leak	**Sector Type:**	Other

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Event:		**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	HYDRAULIC OIL	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Ottawa
Nature of Impact:	Other Impact(s)	**Site Lot:**	
Receiving Medium:	Land & Water	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	No Field Response	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/23/2007	**Site Map Datum:**	
Dt Document Closed:	11/15/2007	**SAC Action Class:**	
Incident Reason:	Equipment Failure	**Source Type:**	
Site Name:	BA International Inc.		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	BA International: Hydraulic oil to parking lot and drain		
Contaminant Qty:	10 L		

56	29 of 66	SSE/209.3	68.2 / 3.61	**975 Gladstone Avenue** **n/a ON K1Y 4W5**	EHS

Order No:	20080226024w	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Online Mapless	**Client Prov/State:**	ON
Report Date:	2/26/2008	**Search Radius (km):**	0.25
Date Received:	2/26/2008	**X:**	0
Previous Site Name:		**Y:**	0
Lot/Building Size:			
Additional Info Ordered:			

56	30 of 66	SSE/209.3	68.2 / 3.61	**BA INTERNATIONAL** **975 GLADSTONE AVENUE NOT AVAILABLE** **OTTAWA ON K1Y4W5**	NPRI

NPRI ID:	7358	**Org ID:**	38290
Other ID:	Y	**Submit Date:**	5/31/2008
No Other ID:	1.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	58740	**Contact ID:**	168497
Report ID:	118575	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	JOHN
Report Year:	2007	**Cont Last Name:**	CODY
Not-Current Rpt?:	No	**Contact Position:**	QUALITY AND ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2011	**Contact Fax:**	6137287419
Fac ID:	141167	**Contact Ph.:**	6137285854
Fac Name:	BA INTERNATIONAL	**Cont Area Code:**	613
Fac Address1:	975 GLADSTONE AVENUE	**Contact Tel.:**	37285854
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K1Y4W5	**Cont Fax Area Cde:**	613
Facility Lat:	45.4038	**Contact Fax:**	37287419
Facility Long:	-75.7167	**Contact Email:**	JOHN_CODY@GDM.DE
DLS (Last Filed Rpt):		**Latitude:**	45.4038
Facility DLS:		**Longitude:**	-75.7167
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	240	**Waste Streams:**	True¿
Parent Co.:	Y	**No Streams:**	

No Parent Co.:	1.00	**Waste Off Sites:**	True
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Hexavalent chromium (and its compounds)
Chem (fr):	Chrome hexavalent (et ses composés)
Quantity:	.018
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

---

56 | ***31 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***Drain-All Ltd.***
975 Gladstone Ave
Ottawa ON K1Y 4W5 | ***SPL***

Ref No:	7780-7HAJKY	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	41	**Nearest Watercourse:**	
Contaminant Name:	EFFLUENT (NOT OTHERWISE SPECIFIED)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Ottawa
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Ottawa
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	No Field Response	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/7/2008	**Site Map Datum:**	
Dt Document Closed:	9/9/2008	**SAC Action Class:**	Land Spills
Incident Reason:		**Source Type:**	
Site Name:	BA International Inc.		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	Drain-All: 50 L effluent sol'n to rd. Cleaning.		
Contaminant Qty:			

---

56 | ***32 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA International Inc.***
975 Gladstone Ave | ***SCT***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Ottawa ON K1Y 4W5	

Established: 01-AUG-40
Plant Size (ft²):
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	33 of 66	SSE/209.3	68.2 / 3.61	BA INTERNATIONAL 975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	NPRI

NPRI ID: 7358
Other ID: Y
No Other ID: 1
Track ID: 69223
Report ID: 127541
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2008
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2011
Fac ID: 141167
Fac Name: BA INTERNATIONAL
Fac Address1: 975 GLADSTONE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K1Y4W5
Facility Lat: 45.4038
Facility Long: -75.7167
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: No
URL:
No of Empl.: 240
Parent Co.: Y
No Parent Co.: 1
Pollut Prev Cmnts: No
Stacks: No
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3231
NAICS 4 Description: Printing and related support activities
NAICS Code (6 digit): 323119
NAICS 6 Description: Other printing

Org ID: 38290
Submit Date: 5/31/2009
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 168497
Cont Type: MED
Contact Title:
Cont First Name: JOHN
Cont Last Name: CODY
Contact Position: QUALITY AND ENVIRONMENTAL MANAGER
Contact Fax: 6137287419
Contact Ph.: 6137285854
Cont Area Code: 613
Contact Tel.: 37285854
Contact Ext.:
Cont Fax Area Cde: 613
Contact Fax: 37287419
Contact Email: JOHN_CODY@GDM.DE
Latitude: 45.4038
Longitude: -75.7167
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: No
No Streams:
Waste Off Sites: Yes
No Off Sites: 1
Shutdown: No
No of Shutdown:

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Hexavalent chromium (and its compounds)
Chem (fr): Chrome hexavalent (et ses composés)

Quantity: .012
Unit: kg
Basis of Estimate Cd:
Basis of Estimate Desc:

---

56 | **34 of 66** | **SSE/209.3** | **68.2 / 3.61** | **349977 Ontario Ltd.**
975 Gladstone Ave
Ottawa ON K1Y 4W5 | **SPL**

Ref No: 6348-7Q2JKQ
Site No:
Incident Dt:
Year:
Incident Cause: Unknown
Incident Event:
Contaminant Code:
Contaminant Name: CAUSTIC SOLUTION (< 20%)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact:
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/11/2009
Dt Document Closed:
Incident Reason: Other - Reason not otherwise defined
Site Name: BA International Inc.
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: Lacombe: 20 L caustic sol'n to pavement. Cleaning.
Contaminant Qty: 20 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing: NA
Easting: NA
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

56 | **35 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA International Inc.**
975 Gladstone Avenue
Ottawa ON K1Y 4W5 | **CA**

Certificate #: 1491-63LLHD
Application Year: 2006
Issue Date: 3/23/2006
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

56 | **36 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA International Inc.**
975 Gladstone Avenue
Ottawa ON K1Y 4W5 | **CA**

Certificate #: 1491-63LLHD
Application Year: 2004
Issue Date: 11/9/2004

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

56 | ***37 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA Banknote Inc.***
975 Gladstone Avenue
Ottawa ON K1Y 4W5 | ***CA***

Certificate #: 3844-5SQTGU
Application Year: 2003
Issue Date: 10/29/2003
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

56 | ***38 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA International Inc.***
975 Gladstone Avenue
Ottawa ON K1Y 4W5 | ***CA***

Certificate #: 5712-6XRLU3
Application Year: 2007
Issue Date: 3/19/2007
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

56 | ***39 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA Banknote Inc.***
975 Gladstone Avenue
Ottawa ON K1Y 4W5 | ***CA***

Certificate #: 7660-5Z4PFX
Application Year: 2004
Issue Date: 6/4/2004
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:

Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

56 | ***40 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA INTERNATIONAL***
975 GLADSTONE AVENUE NOT AVAILABLE
OTTAWA ON K1Y4W5 | ***NPRI***

NPRI ID:	7358	***Org ID:***	38290
Other ID:	Y	***Submit Date:***	6/1/2010
No Other ID:	1	***Last Modified:***	5/29/2015 3:28:24 PM
Track ID:	86101	***Contact ID:***	168497
Report ID:	140030	***Cont Type:***	MED
Report Type:	NPRI	***Contact Title:***	
Rpt Type ID:	1	***Cont First Name:***	JOHN
Report Year:	2009	***Cont Last Name:***	CODY
Not-Current Rpt?:	No	***Contact Position:***	QUALITY AND ENVIRONMENTAL MANAGER
Yr of Last Filed Rpt:	2011	***Contact Fax:***	6137287419
Fac ID:	141167	***Contact Ph.:***	6137285854
Fac Name:	BA INTERNATIONAL	***Cont Area Code:***	613
Fac Address1:	975 GLADSTONE AVENUE	***Contact Tel.:***	37285854
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	K1Y4W5	***Cont Fax Area Cde:***	613
Facility Lat:	45.4038	***Contact Fax:***	37287419
Facility Long:	-75.7167	***Contact Email:***	JOHN_CODY@GDM.DE
DLS (Last Filed Rpt):		***Latitude:***	45.4038
Facility DLS:		***Longitude:***	-75.7167
Datum:	1983	***UTM Zone:***	
Facility Cmnts:	Yes	***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	210	***Waste Streams:***	No
Parent Co.:	Y	***No Streams:***	
No Parent Co.:	1	***Waste Off Sites:***	Yes
Pollut Prev Cmnts:	No	***No Off Sites:***	1
Stacks:	No	***Shutdown:***	No
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Hexavalent chromium (and its compounds)
Chem (fr):	Chrome hexavalent (et ses composés)
Quantity:	.003
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	41 of 66	SSE/209.3	68.2 / 3.61	BA INTERNATIONAL INC. 975 GLADSTONE AVENUE NOT AVAILABLE OTTAWA ON K1Y4W5	NPRI

NPRI ID:	7358	**Org ID:**	38292
Other ID:	Y	**Submit Date:**	6/18/2011
No Other ID:	2	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	93289	**Contact ID:**	168491
Report ID:	147340	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	JOHN
Report Year:	2010	**Cont Last Name:**	CODY
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, PROCESSES, TECHNOLOGY AND ENVIRONMENT
Yr of Last Filed Rpt:	2011	**Contact Fax:**	6137286847
Fac ID:	141167	**Contact Ph.:**	6137285854
Fac Name:	BA INTERNATIONAL	**Cont Area Code:**	613
Fac Address1:	975 GLADSTONE AVENUE	**Contact Tel.:**	37285854
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K1Y4W5	**Cont Fax Area Cde:**	613
Facility Lat:	45.4038	**Contact Fax:**	37286847
Facility Long:	-75.7167	**Contact Email:**	JOHN.CODY@GI-DE.COM
DLS (Last Filed Rpt):		**Latitude:**	45.4038
Facility DLS:		**Longitude:**	-75.7167
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	194	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	No
Pollut Prev Cmnts:	Yes	**No Off Sites:**	
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Hexavalent chromium (and its compounds)
Chem (fr):	Chrome hexavalent (et ses composés)
Quantity:	.0003
Unit:	kg
Basis of Estimate Cd:	
Basis of Estimate Desc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	42 of 66	SSE/209.3	68.2 / 3.61	BA INTERNATIONAL INC. 975 GLADSTONE AVENUE OTTAWA ON K1Y 4W5	GEN

Generator No:	ON0297401
SIC Code:	323119

SIC Description: Other Printing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 267

Waste Class Name:	ORGANIC ACIDS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	121
Waste Class Name:	ALKALINE WASTES - HEAVY METALS
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	132
Waste Class Name:	NEUTRALIZED WASTES - OTHER METALS

56 | ***43 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA INTERNATIONAL INC.***
975 GLADSTONE AVENUE NOT AVAILABLE
OTTAWA ON K1Y4W5 | ***NPRI***

NPRI ID:	7358	**Org ID:**	38291
Other ID:		**Submit Date:**	6/29/2012
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	106512	**Contact ID:**	
Report ID:	8148	**Cont Type:**	
Report Type:	DNMC	**Contact Title:**	
Rpt Type ID:	2	**Cont First Name:**	
Report Year:	2011	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2011	**Contact Fax:**	
Fac ID:	141167	**Contact Ph.:**	
Fac Name:	BA INTERNATIONAL	**Cont Area Code:**	
Fac Address1:	975 GLADSTONE AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K1Y4W5	**Cont Fax Area Cde:**	
Facility Lat:	45.4038	**Contact Fax:**	
Facility Long:	-75.7167	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	45.4038
Facility DLS:		**Longitude:**	-75.7167
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3231		
NAICS 4 Description:	Printing and related support activities		
NAICS Code (6 digit):	323119		
NAICS 6 Description:	Other printing		

56 | ***44 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***BA INTERNATIONAL INC.***
975 GLADSTONE AVENUE
OTTAWA ON K1Y 4W5 | ***GEN***

Generator No: ON0297401
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 132
Waste Class Name: NEUTRALIZED WASTES - OTHER METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

56 | **45 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA INTERNATIONAL INC.**
975 GLADSTONE AVENUE
OTTAWA ON K1Y 4W5 | **GEN**

Generator No: ON0297401
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 132
Waste Class Name: NEUTRALIZED WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	46 of 66	SSE/209.3	68.2 / 3.61	CANADIAN BANK NOTE COMPANY, LIMITED 975 GLADSTONE AVE OTTAWA ON K1Y 4W5	EASR

Approval No: R-002-3388172978
Status: REGISTERED
Date: 2013-11-19
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name: Rideau Valley
PDF URL:
PDF Site Location:

MOE District: Ottawa
Municipality: OTTAWA
Latitude: 45.4041
Longitude: -75.71691
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	47 of 66	SSE/209.3	68.2 / 3.61	CANADIAN BANK NOTE COMPANY, LIMITED 975 GLADSTONE AVE OTTAWA ON K1Y 4W5	EASR

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	R-003-9388039268	**MOE District:**	Ottawa
Status:	REGISTERED	**Municipality:**	OTTAWA
Date:	2013-11-19	**Latitude:**	45.4041
Record Type:	EASR	**Longitude:**	-75.71691
Link Source:	MOFA	**Geometry X:**	
Project Type:	Heating System	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Heating System		
SWP Area Name:	Rideau Valley		
PDF URL:			
PDF Site Location:			

56	48 of 66	SSE/209.3	68.2 / 3.61	**BA INTERNATIONAL INC.** **975 GLADSTONE AVENUE** **OTTAWA ON K1Y 4W5**	GEN

Generator No:	ON0297401
SIC Code:	323119
SIC Description:	Other Printing
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	231
Waste Class Name:	LATEX WASTES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 132
Waste Class Name: NEUTRALIZED WASTES - OTHER METALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

56	49 of 66	SSE/209.3	68.2 / 3.61	**Canadian Bank Note Company, Limited** **975 Gladstone Avenue Ottawa K1Y 4W5 CITY OF OTTAWA** **ON**	EBR

EBR Registry No: 012-1359
Ministry Ref No: 7194-9H3LA9
Notice Type: Instrument Decision
Notice Stage:
Notice Date: January 04, 2017
Proposal Date: March 19, 2014
Year: 2014
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Canadian Bank Note Company, Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 975 Gladstone avenue, Ottawa Ontario, Canada K1Y 4W5
Comment Period:
URL:

Site Location Details:

975 Gladstone Avenue Ottawa K1Y 4W5 CITY OF OTTAWA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	50 of 66	SSE/209.3	68.2 / 3.61	BA INTERNATIONAL INC. 975 GLADSTONE AVENUE OTTAWA ON	GEN

Generator No: ON0297401
SIC Code: 323119
SIC Description: OTHER PRINTING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 132
Waste Class Name: NEUTRALIZED WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

56 | **51 of 66** | **SSE/209.3** | **68.2 / 3.61** | **Canadian Bank Note Company, Limited**
975 Gladstone Ave
Ottawa ON K1Y 4W5 | **ECA**

Approval No: 3835-A7QLZW
Approval Date: 2016-12-30
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Canadian Bank Note Company, Limited
Address: 975 Gladstone Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7194-9H3LA9-14.pdf
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

---

56 | **52 of 66** | **SSE/209.3** | **68.2 / 3.61** | **BA International Inc.**
975 Gladstone Avenue
Ottawa ON K1Y 4W5 | **ECA**

Approval No: 1491-63LLHD
Approval Date: 2006-03-23
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: BA International Inc.
Address: 975 Gladstone Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6469-6MXMT6-14.pdf
PDF Site Location:

MOE District: Ottawa
City:
Longitude: -75.71691
Latitude: 45.4041
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	53 of 66	SSE/209.3	68.2 / 3.61	BA International Inc. 975 Gladstone Avenue Ottawa ON K1Y 4W5	ECA

Approval No: 1491-63LLHD
Approval Date: 2004-11-09
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: BA International Inc.
Address: 975 Gladstone Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6786-5XFJPS-14.pdf
PDF Site Location:
MOE District: Ottawa
City:
Longitude: -75.71691
Latitude: 45.4041
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	54 of 66	SSE/209.3	68.2 / 3.61	BA Banknote Inc. 975 Gladstone Avenue Ottawa ON K1Y 4W5	ECA

Approval No: 7660-5Z4PFX
Approval Date: 2004-06-04
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: BA Banknote Inc.
Address: 975 Gladstone Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9227-5V5REP-14.pdf
PDF Site Location:
MOE District: Ottawa
City:
Longitude: -75.71691
Latitude: 45.4041
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	55 of 66	SSE/209.3	68.2 / 3.61	BA Banknote Inc. 975 Gladstone Avenue Ottawa ON K1Y 4W5	ECA

Approval No: 9223-5C6HZK
Approval Date: 2002-09-06
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: BA Banknote Inc.
Address: 975 Gladstone Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3825-4VAQMB-14.pdf
PDF Site Location:
MOE District: Ottawa
City:
Longitude: -75.71691
Latitude: 45.4041
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	56 of 66	SSE/209.3	68.2 / 3.61	BA International Inc. 975 Gladstone Avenue Ottawa ON K1Y 4W5	ECA

Approval No: 5712-6XRLU3
Approval Date: 2007-03-19
Status: Approved
MOE District: Ottawa
City:
Longitude: -75.71691

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Record Type:	ECA	**Latitude:**	45.4041
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	BA International Inc.		
Address:	975 Gladstone Avenue		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4981-6SKPCP-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	57 of 66	SSE/209.3	68.2 / 3.61	**BA Banknote Inc.** **975 Gladstone Avenue** **Ottawa ON K1Y 4W5**	ECA

Approval No:	6703-4SSRE3	**MOE District:**	Ottawa
Approval Date:	2001-01-08	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-75.71691
Record Type:	ECA	**Latitude:**	45.4041
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	BA Banknote Inc.		
Address:	975 Gladstone Avenue		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/8042-4FUP9P-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	58 of 66	SSE/209.3	68.2 / 3.61	**BA Banknote Inc.** **975 Gladstone Avenue** **Ottawa ON K1Y 4W5**	ECA

Approval No:	3844-5SQTGU	**MOE District:**	Ottawa
Approval Date:	2003-10-29	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-75.71691
Record Type:	ECA	**Latitude:**	45.4041
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Rideau Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	BA Banknote Inc.		
Address:	975 Gladstone Avenue		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1525-5RURU7-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	59 of 66	SSE/209.3	68.2 / 3.61	**Canadian Bank Note Company, limited** **975 Gladstone avenue** **Ottawa ON K1Y 4W5**	GEN

Generator No:	ON8483802
SIC Code:	323113, 323119
SIC Description:	COMMERCIAL SCREEN PRINTING, OTHER PRINTING
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL

Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	60 of 66	SSE/209.3	68.2 / 3.61	Canadian Bank Note Company, limited 975 Gladstone avenue Ottawa ON K1Y 4W5	GEN

Generator No: ON8483802
SIC Code: 323113, 323119
SIC Description: COMMERCIAL SCREEN PRINTING, OTHER PRINTING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 262

Waste Class Name: DETERGENTS/SOAPS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

56 | ***61 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***Canadian Bank Note Company, limited***
975 Gladstone avenue
Ottawa ON K1Y 4W5 | ***GEN***

Generator No: ON8483802
SIC Code: 323113, 323119
SIC Description: COMMERCIAL SCREEN PRINTING, OTHER PRINTING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

---

56 | ***62 of 66*** | ***SSE/209.3*** | ***68.2 / 3.61*** | ***Canadian Bank Note Company, limited***
Gladstone
975 Gladstone avenue
Ottawa ON K1Y 4W5 | ***GEN***

Generator No: ON8483802

SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 131 L
Waste Class Name: Neutralized solutions - containing heavy metals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 232 B
Waste Class Name: Polymeric resins

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

Waste Class: 243 D
Waste Class Name: PCB

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 269 B
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	63 of 66	SSE/209.3	68.2 / 3.61	**Canadian Bank Note Company, limited** **Gladstone** **975 Gladstone avenue** **Ottawa ON K1Y 4W5**	GEN

Generator No: ON8483802
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 269 B
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Class: 243 D
Waste Class Name: PCB

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Class: 267 C
Waste Class Name: Organic acids

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 232 B
Waste Class Name: Polymeric resins

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Class: 131 L
Waste Class Name: Neutralized solutions - containing heavy metals

Waste Class: 150 L
Waste Class Name: Inert organic wastes

---

56 | **64 of 66** | **SSE/209.3** | **68.2 / 3.61** | **Canadian Bank Note Company, Limited**
975 Gladstone Road
Ottawa ON | **SPL**

Ref No: 8041-BJCR6G
Site No: NA
Incident Dt: 2019/11/25
Year:
Incident Cause:
Incident Event: Leak/Break
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1078
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Air
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2019/11/28
Dt Document Closed:
Incident Reason: Equipment Failure
Site Name: Canadian Bank Note Company<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: Canadian Bank Note Company: 320 lbs R134 to atm.
Contaminant Qty: 320 lb

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type: Corporation
Sector Type: Miscellaneous Communal
Agency Involved:
Nearest Watercourse:
Site Address: 975 Gladstone Road
Site District Office: Ottawa
Site Postal Code:
Site Region: Eastern
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type: Valve/Fitting/Piping

---

56 | **65 of 66** | **SSE/209.3** | **68.2 / 3.61** | **Canadian Bank Note Company, limited**
Gladstone
975 Gladstone avenue
Ottawa ON K1Y 4W5 | **GEN**

Generator No: ON8483802
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class:	241 H
Waste Class Name:	Halogenated solvents and residues
Waste Class:	232 L
Waste Class Name:	Polymeric resins
Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	264 L
Waste Class Name:	Photoprocessing wastes
Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues
Waste Class:	243 D
Waste Class Name:	PCB
Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	263 H
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	113 C
Waste Class Name:	Acid solutions - containing other metals and non-metals
Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders
Waste Class:	232 B
Waste Class Name:	Polymeric resins
Waste Class:	263 B
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	331 L
Waste Class Name:	Waste compressed gases including cylinders
Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)
Waste Class:	213 I
Waste Class Name:	Petroleum distillates
Waste Class:	253 L
Waste Class Name:	Emulsified oils
Waste Class:	265 L
Waste Class Name:	Graphic arts wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	66 of 66	SSE/209.3	68.2 / 3.61	**Canadian Bank Note Company, limited** **Gladstone** **975 Gladstone avenue** **Ottawa ON K1Y 4W5**	GEN

Generator No:	ON8483802
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2022
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 232 B
Waste Class Name: POLYMERIC RESINS

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 268 C
Waste Class Name: AMINES

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 265 L
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 253 L
Waste Class Name: EMULSIFIED OILS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 113 C
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241 H
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 263 B
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 243 D
Waste Class Name: PCBS

Waste Class: 263 H
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 232 L
Waste Class Name: POLYMERIC RESINS

---

57 *1 of 3* | *WNW/213.1* | *63.6 / -0.98* | ***ACKLANDS LIMITED*** ***1050 SOMERSET ST. WEST*** ***OTTAWA ON K1Y 3C5*** | ***GEN***

Generator No: ON0021803
SIC Code: 6359
SIC Description: OTHER VEH. REPAIR
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

57 *2 of 3* | *WNW/213.1* | *63.6 / -0.98* | ***ACKLANDS LIMITED 02-414*** ***1050 SOMERSET ST. WEST*** ***OTTAWA ON K1Y 3C5*** | ***GEN***

Generator No: ON0021803
SIC Code: 6359
SIC Description: OTHER VEH. REPAIR
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

57 *3 of 3* | *WNW/213.1* | *63.6 / -0.98* | ***ACKLANDS LIMITED*** ***1050 SOMERSET STREET WEST*** ***OTTAWA ON K1Y 3C5*** | ***GEN***

Generator No: ON0021803
SIC Code: 6359
SIC Description: OTHER VEH. REPAIR
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

58 | ***1 of 3*** | ***NW/214.1*** | ***61.8 / -2.73*** | ***OLRT Constructors 1035 somerset street Ottawa ON*** | ***SPL***

Ref No: 4784-A7ANLR
Site No: NA
Incident Dt: 2016/02/19
Year:
Incident Cause:
Incident Event: Operator/Human error
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/02/19
Dt Document Closed:
Incident Reason: Operator/Human Error
Site Name: Bayview overpass demolition<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: OLRT- 550L diesel to ground *MOL holding site*
Contaminant Qty: 550 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Miscellaneous Communal
Agency Involved:
Nearest Watercourse:
Site Address: 1035 somerset street
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

58 | ***2 of 3*** | ***NW/214.1*** | ***61.8 / -2.73*** | ***SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc. and EllisDon Corporation Bayview (1035 Somerset Street W, 801 Albert Street) Ottawa ON K1Z 1G3*** | ***ECA***

Approval No: 0736-AGCLQM
Approval Date: 2016-12-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc. and EllisDon Corporation
Address: Bayview (1035 Somerset Street W, 801 Albert Street)
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1033-AFTP6U-14.pdf
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

---

58 | ***3 of 3*** | ***NW/214.1*** | ***61.8 / -2.73*** | ***CITY OF OTTAWA CITY OF OTTAWA*** | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				1035 Somerset Street West Ottawa ON K2P 0H9	

Generator No: ON4459511
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

59	1 of 1	S/216.0	68.9 / 4.31	150 BREEZEHILL AVENUE NORTH OTTAWA ON K1Y 2H8	HINC

External File Num: FS INC 0905-02838
Fuel Occurrence Type:
Date of Occurrence:
Fuel Type Involved:
Status Desc: Pending Level 1 Occurrence Investigation
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:
Service Interruptions:
Property Damage:
Fuel Life Cycle Stage:
Root Cause:
Reported Details:
Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Ottawa
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

60	1 of 1	ESE/216.2	65.7 / 1.13	ON	WWIS

Well ID: 7387933
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z359396
Tag: A318161
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 31-Mar-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1008670106	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	444020.00
Code OB Desc:		**North83:**	5028114.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	30-Apr-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008670106	**Tag No:**	A318161
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Path:**	
Well Completed Dt:	2021/04/30	**Latitude:**	45.4043050319339
Audit No:	Z359396	**Longitude:**	-75.7153169838665

---

61 | ***1 of 1*** | ***WSW/217.2*** | ***66.9 / 2.31*** | ***86 Bayswater Ave Ottawa ON K1Y 2E9*** | ***EHS***

Order No:	20021204006	**Nearest Intersection:**	Laurel St
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	ON
Report Date:	12/6/02	**Search Radius (km):**	0.25
Date Received:	12/5/02	**X:**	-75.719583
Previous Site Name:		**Y:**	45.404672
Lot/Building Size:			
Additional Info Ordered:			

---

62 | ***1 of 1*** | ***SE/217.6*** | ***66.3 / 1.77*** | ***951 Gladestone Avenue & 145 Loretta Avenue North Ottawa ON*** | ***EHS***

Order No:	20170605066	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	09-JUN-17	**Search Radius (km):**	.25
Date Received:	05-JUN-17	**X:**	-75.715549
Previous Site Name:		**Y:**	45.404125
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	1 of 3	WNW/220.6	63.9 / -0.69	ESPRIT DE CORPS 1066 SOMERSET ST W SUITE 204 OTTAWA ON K1Y 4T3	SCT

Established: 1991
Plant Size (ft²): 1096
Employment: 4

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	2 of 3	WNW/220.6	63.9 / -0.69	Esprit de Corps Inc. 1066 Somerset St W Unit 204 Ottawa ON K1Y 4T3	SCT

Established: 01-AUG-91
Plant Size (ft²): 1100
Employment:

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Description: Periodical Publishers
SIC/NAICS Code: 511120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	3 of 3	WNW/220.6	63.9 / -0.69	Grafik Visuals A-1066 Somerset St W Ottawa ON K1Y 4T3	SCT

Established: 01-JAN-86
Plant Size (ft²): 1150
Employment:

--Details--
Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	1 of 3	SE/221.4	66.3 / 1.77	155 Loretta Ave N Ottawa ON K1Y 3E5	EHS

Order No: 21072000119
Status: C
Report Type: Custom Report
Report Date: 23-JUL-21
Date Received: 20-JUL-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.71549537
Y: 45.40411365

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	2 of 3	SE/221.4	66.3 / 1.77	155 Loretta Ave N Ottawa ON K1Y 3E5	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No: 21072000119
Status: C
Report Type: Custom Report
Report Date: 23-JUL-21
Date Received: 20-JUL-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.71549537
Y: 45.40411365

---

64 | **3 of 3** | **SE/221.4** | **66.3 / 1.77** | **155 Loretta Ave N**
Ottawa ON K1Y 3E5 | **EHS**

Order No: 21072000119
Status: C
Report Type: Custom Report
Report Date: 23-JUL-21
Date Received: 20-JUL-21
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.71549537
Y: 45.40411365

---

65 | **1 of 3** | **SE/222.1** | **66.6 / 2.00** | **SPORTIVE SPORTSWEAR MFG INC.**
155A LORETTA AVE N
OTTAWA ON K1Y 2J7 | **SCT**

Established: 1984
Plant Size (ft²): 3200
Employment: 14

--Details--

Description: All Other Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315299

Description: MEN'S AND BOYS' CLOTHING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2329

Description: WOMEN'S, MISSES', AND JUNIORS' OUTERWEAR, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2339

Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Men's and Boys' Cut and Sew Shirt Manufacturing
SIC/NAICS Code: 315226

Description: Men's and Boys' Cut and Sew Trouser, Slack and Jean Manufacturing
SIC/NAICS Code: 315227

Description: Other Men's and Boys' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315229

Description: Women's and Girls' Cut and Sew Blouse and Shirt Manufacturing
SIC/NAICS Code: 315232

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

---

65 | **2 of 3** | **SE/222.1** | **66.6 / 2.00** | **SPORTIVE SPORTSWEAR MFG INC.**
155 A LORETTA AVE N | **SCT**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				OTTAWA ON K1Y 2J7	

Established: 1984
Plant Size (ft²): 3200
Employment: 14

--Details--
Description: MEN'S & BOYS' CLOTHING, N.E.C.
SIC/NAICS Code: 2329

Description: WOMEN'S, MISSES', & JUNIORS' OUTERWEAR, N.E.C.
SIC/NAICS Code: 2339

65	3 of 3	SE/222.1	66.6 / 2.00	**Sportive Sportswear Manufacturers Inc.** **155A Loretta Ave N** **Ottawa ON K1Y 2J7**	SCT

Established: 1984
Plant Size (ft²): 3200
Employment: 20

66	1 of 1	SE/223.0	65.7 / 1.13	ON	WWIS

Well ID: 7388045
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z359465
Tag: A318243
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: OTTAWA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 31-Mar-2021 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: OTTAWA-CARLETON
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008670442
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 29-Apr-2021 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:

Elevation:
Elevrc:
Zone: 18
East83: 444017.00
North83: 5028101.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Links

Bore Hole ID:	1008670442	***Tag No:***	A318243
Depth M:		***Contractor:***	7241
Year Completed:	2021	***Path:***	
Well Completed Dt:	2021/04/29	***Latitude:***	45.4041877842693
Audit No:	Z359465	***Longitude:***	-75.7153538382987

---

67 ***1 of 1*** ***SE/223.5*** ***66.3 / 1.77*** ***ON*** ***WWIS***

Well ID:	7388050	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	31-Mar-2021 00:00:00
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z359466	***Contractor:***	7241
Tag:	A318241	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	OTTAWA-CARLETON
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008670457	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	444007.00
Code OB Desc:		***North83:***	5028091.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	27-Apr-2021 00:00:00	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008670457	***Tag No:***	A318241
Depth M:		***Contractor:***	7241
Year Completed:	2021	***Path:***	
Well Completed Dt:	2021/04/27	***Latitude:***	45.4040969781161
Audit No:	Z359466	***Longitude:***	-75.7154804726249

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	1 of 3	W/228.9	65.6 / 1.00	PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	EHS

Order No:	20321400013	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	17-DEC-20	**Search Radius (km):**	.25
Date Received:	14-DEC-20	**X:**	-75.7203084
Previous Site Name:		**Y:**	45.4056164
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	2 of 3	W/228.9	65.6 / 1.00	PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	EHS

Order No:	20321400013	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	17-DEC-20	**Search Radius (km):**	.25
Date Received:	14-DEC-20	**X:**	-75.7203084
Previous Site Name:		**Y:**	45.4056164
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	3 of 3	W/228.9	65.6 / 1.00	PE5130 - 54-60 Bayswater Ave Ottawa ON K1Y 2E9	EHS

Order No:	20321400013	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	17-DEC-20	**Search Radius (km):**	.25
Date Received:	14-DEC-20	**X:**	-75.7203084
Previous Site Name:		**Y:**	45.4056164
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
69	1 of 1	SSE/231.5	67.9 / 3.34	ON	BORE

Borehole ID:	613116	**Inclin FLG:**	No
OGF ID:	215514420	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.403652
Total Depth m:	-999	**Longitude DD:**	-75.716322
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443941
Drill Method:		**Northing:**	5028042
Orig Ground Elev m:	61.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	68.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218393779	***Mat Consistency:***	Hard
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	3.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	CLAY. HARD.		

Geology Stratum ID:	218393780	***Mat Consistency:***	
Top Depth:	3.4	***Material Moisture:***	
Bottom Depth:	3.8	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Pebbles	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	PEBBLES.		

Geology Stratum ID:	218393781	***Mat Consistency:***	
Top Depth:	3.8	***Material Moisture:***	
Bottom Depth:	4.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Gravel	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	CLAY.		

Geology Stratum ID:	218393782	***Mat Consistency:***	Compact
Top Depth:	4.3	***Material Moisture:***	
Bottom Depth:		***Material Texture:***	Fibrous
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BEDROCK. FEET.SAND. GRAVEL. COMPACT. GRAVEL. COMPACT. FIBROUS. SAND. GREY,COMPACT.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 056240 NTS_Sheet: 31G05G		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

70 **1 of 1** **W/231.9** **66.7 / 2.15** **ON** **BORE**

Borehole ID:	613139	**Inclin FLG:**	No
OGF ID:	215514443	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	AUG-1970	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	45.405248
Total Depth m:	9.7	**Longitude DD:**	-75.720304
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443631
Drill Method:		**Northing:**	5028222
Orig Ground Elev m:	63	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	65.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218393856	**Mat Consistency:**	Dense
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	2.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND. DENSE.		

Geology Stratum ID:	218393858	**Mat Consistency:**	Dense
Top Depth:	3.8	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Unknown	**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	UNSPECIFIED. LOOSE,DENSE.		

Geology Stratum ID:	218393855	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:		**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Bedrock	**Geologic Period:**	
Material 4:	Wood Fragments	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	ARTIFICIAL.		

Geology Stratum ID:	218393857	**Mat Consistency:**	Stiff
Top Depth:	2.6	**Material Moisture:**	

Bottom Depth:	3.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	CLAY. BROWN,GREY,STIFF,FISSURED.		

Geology Stratum ID:	218393859	**Mat Consistency:**	Dense
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	6.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Unknown	**Geologic Formation:**	
Material 2:	Till	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	UNSPECIFIED. DENSE.		

Geology Stratum ID:	218393861	**Mat Consistency:**	
Top Depth:	8.1	**Material Moisture:**	
Bottom Depth:	9.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Limestone	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK. 00000 009 00025 010 00085 032 00126 012 00150 010 000000370002503900 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218393860	**Mat Consistency:**	
Top Depth:	6.6	**Material Moisture:**	
Bottom Depth:	8.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Limestone	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: OTTAWA2.txt RecordID: 056470 NTS_Sheet: 31G05G		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
71	1 of 1	ESE/233.0	65.2 / 0.62	ON	WWIS

Well ID:	7388044	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	31-Mar-2021 00:00:00
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z359467	**Contractor:**	7241
Tag:	A318227	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	OTTAWA-CARLETON
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	OTTAWA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008670439	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	444029.00
Code OB Desc:		**North83:**	5028099.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	29-Apr-2021 00:00:00	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Links

Bore Hole ID:	1008670439	**Tag No:**	A318227
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Path:**	
Well Completed Dt:	2021/04/29	**Latitude:**	45.4041707432815
Audit No:	Z359467	**Longitude:**	-75.7152002865069

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
72	1 of 1	N/233.2	60.2 / -4.39	ON	BORE

Borehole ID:	847975	**Inclin FLG:**	No
OGF ID:	215589632	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	01-DEC-1961	**Municipality:**	
Static Water Level:		**Lot:**	LOT 38
Primary Water Use:		**Township:**	NEPEAN
Sec. Water Use:		**Latitude DD:**	45.407695

Total Depth m:	5.5	**Longitude DD:**	-75.717264
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	443871
Drill Method:	Diamond Drill	**Northing:**	5028492
Orig Ground Elev m:	58.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 50 metres
DEM Ground Elev m:	58.8		
Concession:	CON 1 ON OTTAWA RIVER		
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6559445	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand - Gravel	**Geologic Group:**	
Material 3:	Boulders	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	FILL (SAND, GRAVEL AND SMALL BOULDERS) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6559446	**Mat Consistency:**	
Top Depth:	1.9	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Boulders	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND, GRAVEL AND BOULDERS **Note: Many records provided by the department have a truncated [Stratum Description] field.		

73	*1 of 2*	***WSW/235.8***	***66.9 / 2.31***	***Hydro OTTAWA LIMITED 59 LAUREL AVE OTTAWA ON K2C3G2***	***GEN***

Generator No:	ON8833481
SIC Code:	221122
SIC Description:	Electric Power Distribution
Approval Years:	05
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	243
Waste Class Name:	PCB'S

73	*2 of 2*	***WSW/235.8***	***66.9 / 2.31***	***Hydro Ottawa Limited 59 Laurel St***	***ECA***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Ottawa ON K1G 3S4	

Approval No: 8609-C4JQWS
Approval Date: 2021-07-29
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Hydro Ottawa Limited
Address: 59 Laurel St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8873-BSLJAT-14.pdf
PDF Site Location:

MOE District: Ottawa
City:
Longitude:
Latitude:
Geometry X: -8429107.3901
Geometry Y: 5685430.653300004

74	1 of 8	SE/237.7	66.9 / 2.31	MR GAS LIMITED ATTN LILIANNE LEVAC 971 GLADSTONE AV OTTAWA ON K1Y 3E5	PRT

Location ID: 10944
Type: retail
Expiry Date: 1994-06-30
Capacity (L): 45400
Licence #: 0010002008

74	2 of 8	SE/237.7	66.9 / 2.31	MR GAS LIMITED ** 971 GLADSTONE AV OTTAWA ON K1Y 3E5	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9453941
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:

Expired Date: 6/17/1993
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Original Source:		EXP			
Record Date:		Up to May 2013			

74	3 of 8	SE/237.7	66.9 / 2.31	MR GAS LIMITED ** 971 GLADSTONE AV OTTAWA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10902905	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	51114	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

74	4 of 8	SE/237.7	66.9 / 2.31	MR GAS LIMITED ** 971 GLADSTONE AV OTTAWA ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10902920	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	51537	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

74	***5 of 8***	***SE/237.7***	***66.9 / 2.31***	***MR GAS LIMITED***** ***971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA*** ***ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10902896	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	NULL
Instance ID:		***Facility Location:***	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA
Instance Type:		***Facility Type:***	FS LIQUID FUEL TANK
Instance Creation Dt:	10/2/1989	***Fuel Type 2:***	NULL
Instance Install Dt:	10/2/1989	***Fuel Type 3:***	NULL
Item Description:	FS Liquid Fuel Tank	***Panam Related:***	NULL
Manufacturer:	NULL	***Panam Venue Nm:***	NULL
Model:	NULL	***External Identifier:***	NULL
Serial No:	NULL	***Item:***	
ULC Standard:	NULL	***Piping Steel:***	
Quantity:	1	***Piping Galvanized:***	
Unit of Measure:	EA	***Tank Single Wall St:***	
Overfill Prot Type:	NULL	***Piping Underground:***	
Creation Date:	7/5/2009 1:22:05 AM	***Tank Underground:***	
Next Periodic Str DT:	NULL	***Source:***	FS Liquid Fuel Tank
TSSA Base Sched Cycle 2:	NULL		
TSSAMax Hazard Rank 1:	NULL		
TSSA Risk Based Periodic Yn:	NULL		
TSSA Volume of Directives:	NULL		
TSSA Periodic Exempt:	NULL		
TSSA Statutory Interval:	NULL		
TSSA Recd Insp Interva:	NULL		
TSSA Recd Tolerance:	NULL		
TSSA Program Area:	NULL		
TSSA Program Area 2:	NULL		
Description:	UNDERGROUND TANK		
Original Source:	EXP		
Record Date:	31-JUL-2020		

74	***6 of 8***	***SE/237.7***	***66.9 / 2.31***	***MR GAS LIMITED***** ***971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA*** ***ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No:	10902914	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	NULL
Instance ID:		**Facility Location:**	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA
Instance Type:		**Facility Type:**	FS LIQUID FUEL TANK
Instance Creation Dt:	10/2/1989	**Fuel Type 2:**	NULL
Instance Install Dt:	10/2/1989	**Fuel Type 3:**	NULL
Item Description:	FS Liquid Fuel Tank	**Panam Related:**	NULL
Manufacturer:	NULL	**Panam Venue Nm:**	NULL
Model:	NULL	**External Identifier:**	NULL
Serial No:	NULL	**Item:**	
ULC Standard:	NULL	**Piping Steel:**	
Quantity:	1	**Piping Galvanized:**	
Unit of Measure:	EA	**Tank Single Wall St:**	
Overfill Prot Type:	NULL	**Piping Underground:**	
Creation Date:	7/5/2009 1:22:06 AM	**Tank Underground:**	
Next Periodic Str DT:	NULL	**Source:**	FS Liquid Fuel Tank

TSSA Base Sched Cycle 2:	NULL
TSSAMax Hazard Rank 1:	NULL
TSSA Risk Based Periodic Yn:	NULL
TSSA Volume of Directives:	NULL
TSSA Periodic Exempt:	NULL
TSSA Statutory Interval:	NULL
TSSA Recd Insp Interva:	NULL
TSSA Recd Tolerance:	NULL
TSSA Program Area:	NULL
TSSA Program Area 2:	NULL
Description:	UNDERGROUND TANK
Original Source:	EXP
Record Date:	31-JUL-2020

---

74 | ***7 of 8*** | ***SE/237.7*** | ***66.9 / 2.31*** | ***MGL PROPERTIES LTD.***
971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA
ON | ***FST***

Instance No:	10902914	**Manufacturer:**	
Status:		**Serial No:**	
Cont Name:		**Ulc Standard:**	
Instance Type:		**Quantity:**	
Item:		**Unit of Measure:**	
Item Description:	FS Liquid Fuel Tank	**Fuel Type:**	Gasoline
Tank Type:	Liquid Fuel Single Wall UST	**Fuel Type2:**	NULL
Install Date:	10/2/1989	**Fuel Type3:**	NULL
Install Year:	1979	**Piping Steel:**	
Years in Service:		**Piping Galvanized:**	
Model:	NULL	**Tanks Single Wall St:**	
Description:		**Piping Underground:**	
Capacity:	22700	**No Underground:**	
Tank Material:	Steel	**Panam Related:**	
Corrosion Protect:	Sacrificial anode	**Panam Venue:**	
Overfill Protect:			

Facility Type:	FS Liquid Fuel Tank
Parent Facility Type:	
Facility Location:	
Device Installed Location:	971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA

Liquid Fuel Tank Details

Overfill Protection:	
Owner Account Name:	MGL PROPERTIES LTD.
Item:	FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	8 of 8	SE/237.7	66.9 / 2.31	MGL PROPERTIES LTD. 971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA ON	FST

Instance No: 10902896
Status:
Cont Name:
Instance Type:
Item:
Item Description: FS Liquid Fuel Tank
Tank Type: Liquid Fuel Single Wall UST
Install Date: 10/2/1989
Install Year: 1979
Years in Service:
Model: NULL
Description:
Capacity: 22700
Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protect:
Facility Type: FS Liquid Fuel Tank
Parent Facility Type:
Facility Location:
Device Installed Location: 971 GLADSTONE AV OTTAWA K1Y 3E5 ON CA

Manufacturer:
Serial No:
Ulc Standard:
Quantity:
Unit of Measure:
Fuel Type: Gasoline
Fuel Type2: NULL
Fuel Type3: NULL
Piping Steel:
Piping Galvanized:
Tanks Single Wall St:
Piping Underground:
No Underground:
Panam Related:
Panam Venue:

Liquid Fuel Tank Details

Overfill Protection:
Owner Account Name: MGL PROPERTIES LTD.
Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	1 of 33	NNW/239.4	60.4 / -4.15	Primrose Printing Inc 250 City Centre Avenue, BAY 142 Ottawa ON K1R 6K7	GEN

Generator No: ON2422403
SIC Code: 323113
SIC Description: Commercial Screen Printing
Approval Years: 04,05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	2 of 33	NNW/239.4	60.4 / -4.15	Display Laminating 250 City Centre Ave Suite 128 Ottawa ON K1R 6K7	SCT

Established: 01-JUL-87
Plant Size (ft²): 6000
Employment:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: Support Activities for Printing
SIC/NAICS Code: 323120

75	3 of 33	NNW/239.4	60.4 / -4.15	***Artext Electronic Publishing*** ***250 City Centre Ave Suite 140*** ***Ottawa ON K1R 6K7***	SCT

Established: 01-AUG-87
Plant Size (ft²):
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: Manufacturing and Reproducing Magnetic and Optical Media
SIC/NAICS Code: 334610

75	4 of 33	NNW/239.4	60.4 / -4.15	***Ottawa Print Finishing*** ***250 City Centre Ave Suite 226*** ***Ottawa ON K1R 6K7***	SCT

Established: 01-AUG-86
Plant Size (ft²): 6500
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: Support Activities for Printing
SIC/NAICS Code: 323120

75	5 of 33	NNW/239.4	60.4 / -4.15	***Marquardt Printing Ltd.*** ***250 City Centre Ave Bay 240*** ***Ottawa ON K1R 6K7***	SCT

Established: 01-JAN-48
Plant Size (ft²): 10200
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Support Activities for Printing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 323120

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Other Printing
SIC/NAICS Code: 323119

---

75 | **6 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Quality Signs Ltd.**
250 City Centre Ave Suite 128
Ottawa ON K1R 6K7 | **SCT**

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Sign Manufacturing
SIC/NAICS Code: 339950

---

75 | **7 of 33** | **NNW/239.4** | **60.4 / -4.15** | **C.N. Embroidery Inc.**
250 City Centre Ave Unit 100
Ottawa ON K1R 6K7 | **SCT**

Established: 01-AUG-94
Plant Size (ft²):
Employment:

--Details--
Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

---

75 | **8 of 33** | **NNW/239.4** | **60.4 / -4.15** | **250 City Centre Avenue (formerly Champagne Avenue N)**
Ottawa ON | **EHS**

Order No: 20081114004
Status: C
Report Type: Custom Report
Report Date: 11/24/2008
Date Received: 11/14/2008
Previous Site Name: formerly known as 250, 270 and 290 City Centre Avenue
Lot/Building Size: lot: 8.07 acres
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory

Nearest Intersection: City Centre Ave. and Elm Street
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.718294
Y: 45.409166

---

75 | **9 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Cielo Print Inc.**
250 City Centre Avenue, BAY 136
Ottawa ON | **GEN**

Generator No: ON2422403
SIC Code: 323113
SIC Description: Commercial Screen Printing
Approval Years: 06,07,08
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

75 | ***10 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***Equity Management International Limited*** ***250 City Centre Avenue*** ***Ottawa ON*** | ***GEN***

Generator No: ON4569420
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

75 | ***11 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***Cdn Parks & Wilderness Society*** ***250 City Centre Ave Suite 506*** ***Ottawa ON K1R 6K7*** | ***SCT***

Established: 01-DEC-64
Plant Size (ft²):
Employment:

--Details--
Description: Social Advocacy Organizations
SIC/NAICS Code: 813310

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	12 of 33	NNW/239.4	60.4 / -4.15	Christie Lites Ltd. - Ottawa 250 City Centre Ave Suite 102-104 Ottawa ON K1R 6K7	SCT

Established: 01-SEP-01
Plant Size (ft²):
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Electrical Contractors and Other Wiring Installation Contractors
SIC/NAICS Code: 238210

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Other Commercial and Industrial Machinery and Equipment Rental and Leasing
SIC/NAICS Code: 532490

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	13 of 33	NNW/239.4	60.4 / -4.15	Cielo Print Inc. 250 City Centre Ave Unit 136 Ottawa ON K1R 6K7	SCT

Established: 01-OCT-88
Plant Size (ft²):
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Support Activities for Printing
SIC/NAICS Code: 323120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	14 of 33	NNW/239.4	60.4 / -4.15	MARQUARDT PRINTING LTD. 250 CITY CENTRE AVENUE, UNIT 236 OTTAWA ON K1R 6K7	GEN

Generator No: ON5555800
SIC Code: 323119
SIC Description: Other Printing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

75 | ***15 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***PUBLIC WORKS AND GOVERNMENT SERVICES CANADA***
250 City Centre Av
Ottawa ON K1R 6K7 | ***GEN***

Generator No: ON6026658
SIC Code: 911910
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

75 | ***16 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***City of Ottawa***
250 City Centre Avenue
Ottawa ON | ***GEN***

Generator No: ON9363398
SIC Code: 913910
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

75 | ***17 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***VISION FORM***
BAY 244-250 CITY CENTRE AVE
OTTAWA ON | ***GEN***

Generator No: ON5433512
SIC Code: 323115
SIC Description: DIGITAL PRINTING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

75 | **18 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Cascades Recovery Inc.**
250 City Centre Ave.
Ottawa ON | **SPL**

Ref No: 0423-8Y8TGA
Site No:
Incident Dt: 17-SEP-12
Year:
Incident Cause:
Incident Event:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact:
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 17-SEP-12
Dt Document Closed:
Incident Reason:
Site Name: Road and curb area<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: Cascades Recovery: 218 L hydrlc oil to road, cleaned
Contaminant Qty: 218 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address: 250 City Centre Ave.
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

75 | **19 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Equity Realty Group Inc.**
250, 270, 290 City Centre Avenue
Ottawa ON | **GEN**

Generator No: ON8497519
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2013
PO Box No:
Country:

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

75 | ***20 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***FURNITURE AFFAIRS***
250 CITY CENTRE.UNIT 222
OTTAWA ON | ***GEN***

Generator No: ON8702314
SIC Code: 337121, 337126
SIC Description: UPHOLSTERED HOUSEHOLD FURNITURE MANUFACTURING, HOUSEHOLD FURNITURE (EXCEPT WOOD AND UPHOLSTERED) MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

75 | ***21 of 33*** | ***NNW/239.4*** | ***60.4 / -4.15*** | ***FURNITURE AFFAIRS***
250 CITY CENTRE.UNIT 222
OTTAWA ON K1R6K7 | ***GEN***

Generator No: ON8702314
SIC Code: 337121, 337126
SIC Description: UPHOLSTERED HOUSEHOLD FURNITURE MANUFACTURING, HOUSEHOLD FURNITURE (EXCEPT WOOD AND UPHOLSTERED) MANUFACTURING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	22 of 33	NNW/239.4	60.4 / -4.15	VISION FORM BAY 244-250 CITY CENTRE AVE OTTAWA ON K1R 6K7	GEN

Generator No: ON5433512
SIC Code: 323115
SIC Description: DIGITAL PRINTING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Carol Menard
Choice of Contact: CO_OFFICIAL
Phone No Admin: 61356996258 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	23 of 33	NNW/239.4	60.4 / -4.15	FURNITURE AFFAIRS 250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	GEN

Generator No: ON8702314
SIC Code: 337121, 337126
SIC Description: UPHOLSTERED HOUSEHOLD FURNITURE MANUFACTURING, HOUSEHOLD FURNITURE (EXCEPT WOOD AND UPHOLSTERED) MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	24 of 33	NNW/239.4	60.4 / -4.15	FURNITURE AFFAIRS 250 CITY CENTRE.UNIT 222 OTTAWA ON K1R6K7	GEN

Generator No: ON8702314
SIC Code: 337121, 337126
SIC Description: UPHOLSTERED HOUSEHOLD FURNITURE MANUFACTURING, HOUSEHOLD FURNITURE (EXCEPT WOOD AND UPHOLSTERED) MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

75 | **25 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Visionform Inc**
BAY 244-250 City Centre Avenue
Ottawa ON K1R 6K7 | **GEN**

Generator No: ON5433512
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

75 | **26 of 33** | **NNW/239.4** | **60.4 / -4.15** | **VISION FORM**
BAY 244-250 CITY CENTRE AVE
OTTAWA ON K1R 6K7 | **GEN**

Generator No: ON5433512
SIC Code: 323115
SIC Description: DIGITAL PRINTING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Carol Menard
Choice of Contact: CO_OFFICIAL
Phone No Admin: 6132312246 Ext.235
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 232

Waste Class Name: POLYMERIC RESINS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

75 | **27 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Public Services & Procurement Canada**
ESD/Trades
250 City Centre Av
Ottawa ON K1R 6K7 | **GEN**

Generator No: ON6026658
SIC Code:
SIC Description:
Approval Years: As of Jun 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

---

75 | **28 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Public Services and Procurement Canada**
250 City Centre Avenue
Ottawa ON K1R 6K7 | **GEN**

Generator No: ON3185623
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	29 of 33	NNW/239.4	60.4 / -4.15	Visionform Inc BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	GEN

Generator No: ON5433512
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	30 of 33	NNW/239.4	60.4 / -4.15	Visionform Inc BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	GEN

Generator No: ON5433512
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 252 L

Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

75 | **31 of 33** | **NNW/239.4** | **60.4 / -4.15** | **District Realty <UNOFFICIAL>**
250 City Centre Ave
Ottawa ON | **SPL**

Ref No:	0520-BTGHGT	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2020/09/11	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	38	**Nearest Watercourse:**	
Contaminant Name:	REFRIGERANT GAS, N.O.S.	**Site Address:**	250 City Centre Ave
Contaminant Limit 1:		**Site District Office:**	Ottawa
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1078	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Ottawa
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	5028689.02
MOE Response:	No	**Easting:**	443796.01
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2020/09/15	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Air Spills - Gases and Vapours
Incident Reason:	Equipment Failure	**Source Type:**	Valve/Fitting/Piping
Site Name:	District Realty<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	122.7 kg of 134A refrigerant to atm		
Contaminant Qty:	122.7 kg		

---

75 | **32 of 33** | **NNW/239.4** | **60.4 / -4.15** | **Marquardt Printing Ltd.**
208-250 City Centre Avenue
Ottawa ON K1R6K7 | **GEN**

Generator No:	ON8990194
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	33 of 33	NNW/239.4	60.4 / -4.15	Visionform Inc BAY 244-250 City Centre Avenue Ottawa ON K1R 6K7	GEN

Generator No: ON5433512
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 145 H
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	1 of 3	SE/241.8	66.3 / 1.77	LOVE PRINTING SERVICE LTD. 951 GLADSTONE AVENUE OTTAWA ON K1Y 3E5	GEN

Generator No: ON0607900
SIC Code: 0007
SIC Description: LETTER ACKNOWLEDG.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	2 of 3	SE/241.8	66.3 / 1.77	LOVE PRINTING (OUT OF BUS) 24-265 951 GLADSTONE AVENUE OTTAWA ON K1Y 3E5	GEN

Generator No: ON0607900
SIC Code: 2841
SIC Description: NEWSPAPER, ETC. IND.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

76 | **3 of 3** | **SE/241.8** | **66.3 / 1.77** | **DST Group Inc**
951 Gladstone Ave
Ottawa ON K1Y 3E5 | **GEN**

Generator No: ON8186657
SIC Code:
SIC Description:
Approval Years: As of Dec 2017
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

77 | **1 of 5** | **ESE/246.3** | **65.8 / 1.25** | **VESUVIO IRON LOGIC CUSTOM**
949 GLADSTONE AVE
OTTAWA ON K1Y 3E5 | **SCT**

Established: 1972
Plant Size (ft²): 1500
Employment: 3

--Details--
Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

---

77 | **2 of 5** | **ESE/246.3** | **65.8 / 1.25** | **VESUVIO IRON WORKS**
949 GLADSTONE AVE
OTTAWA ON K1Y 3E5 | **SCT**

Established: 1972
Plant Size (ft²): 1500
Employment: 3

--Details--
Description: ARCHITECTURAL AND ORNAMENTAL METAL WORK
SIC/NAICS Code: 3446

---

77 | **3 of 5** | **ESE/246.3** | **65.8 / 1.25** | **SNC-Lavalin Inc.**
949 B Gladstone Ave,
Ottawa ON | **SPL**

Ref No: 0700-BSLS56 **Discharger Report:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site No:	NA	**Material Group:**	
Incident Dt:	2020/08/18	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Corporation
Incident Cause:		**Sector Type:**	Other
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	HYDRAULIC OIL	**Site Address:**	949 B Gladstone Ave,
Contaminant Limit 1:		**Site District Office:**	Ottawa
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	n/a	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Ottawa
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land; Source Water Zone	**Northing:**	5028066.47
MOE Response:	No	**Easting:**	444018.62
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2020/08/18	**Site Map Datum:**	
Dt Document Closed:	2020/08/31	**SAC Action Class:**	TSSA - Fuel Safety Program Notifications
Incident Reason:	Equipment Failure	**Source Type:**	Other
Site Name:	Work site<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	SNC-Lavalin 2L hydraulic oil to gravel, contained		
Contaminant Qty:	2 L		

77	4 of 5	ESE/246.3	65.8 / 1.25	**SNC- Lavalin Trillium Partner 1 Inc. and SNC-Lavalin Trillium Partner 2 Inc.** **949-B Gladstone Avenue** **Ottawa ON**	SPL

Ref No:	0070-BRKQS2	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2020/07/16	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Partnership
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	HYDRAULIC OIL	**Site Address:**	949-B Gladstone Avenue
Contaminant Limit 1:		**Site District Office:**	Ottawa
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	n/a	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Ottawa
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	5028083.08
MOE Response:	No	**Easting:**	444126.44
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2020/07/16	**Site Map Datum:**	
Dt Document Closed:	2020/09/21	**SAC Action Class:**	
Incident Reason:	Equipment Failure	**Source Type:**	Valve/Fitting/Piping
Site Name:	Construction Project - OLRT phase 2<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	SNC Lavalin: 0.5L of hydraulic oil to gravel; cleaned		
Contaminant Qty:	0.5 L		

77	5 of 5	ESE/246.3	65.8 / 1.25	**SNC- Lavalin Trillium Partner 1 Inc. and SNC-Lavalin Trillium Partner 2 Inc., as general partners for and on behalf of Transitnext General Partnership 949 Gladstone**	ECA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ave
Ottawa ON M5H 3T9

Approval No: 9377-C4EMBA
Approval Date: 2021-07-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Rideau Valley
MOE District: Ottawa
City:
Longitude:
Latitude:
Geometry X: -8428590.8676
Geometry Y: 5685327.911600001
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: SNC- Lavalin Trillium Partner 1 Inc. and SNC- Lavalin Trillium Partner 2 Inc., as general partners for and on behalf of Transitnext General Partnership
Address: 949 Gladstone Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5379-C3MK7F-14.pdf
PDF Site Location:

---

78 **1 of 5** **N/247.1** **59.9 / -4.69** **ROBERT TAPE LIMITED**
989 SOMERSET ST W
OTTAWA ON K1R 6R8 **SCT**

Established: 1945
Plant Size (ft²): 8000
Employment: 10

--Details--
Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

Description: Machine Shops
SIC/NAICS Code: 332710

---

78 **2 of 5** **N/247.1** **59.9 / -4.69** **ROBT TAPE LIMITED**
989 SOMERSET ST. W.
OTTAWA ON K1R 6R8 **GEN**

Generator No: ON0194400
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

78 **3 of 5** **N/247.1** **59.9 / -4.69** **ROBT TAPE LIMITED 33-483**
989 SOMERSET ST. W.
OTTAWA ON K1R 6R8 **GEN**

Generator No: ON0194400

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 3081
SIC Description: MACHINE SHOP IND.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

78	4 of 5	N/247.1	59.9 / -4.69	ROBT TAPE LIMITED 989 SOMERSET STREET WEST OTTAWA ON K1R 6R8	GEN

Generator No: ON0194400
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

78	5 of 5	N/247.1	59.9 / -4.69	ROBT. TAPE LTD. 989 Somerset St. West Ottawa ON K1R 6R8	GEN

Generator No: ON0194400
SIC Code:
SIC Description:
Approval Years: 02,03,04,05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	1 of 1	SW/247.3	67.9 / 3.31	ST LAWRENCE PLACE C/O HARBOUR PLANT RETIREMENT LODGES 114 BAYSWATER AVE,,OTTAWA,ON,K1Y 2G1, CA ON	PINC

Incident Id:
Incident No: 1494406
Incident Reported Dt: 10/8/2014
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: ST LAWRENCE PLACE C/O HARBOUR PLANT RETIREMENT LODGES
Incident Address: 114 BAYSWATER AVE,,OTTAWA,ON,K1Y 2G1,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	1 of 7	N/247.6	59.9 / -4.69	Equity Realty Group Inc. 250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	GEN

Generator No: ON8497519
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	2 of 7	N/247.6	59.9 / -4.69	Equity Realty Group Inc. 250, 270, 290 City Centre Avenue Ottawa ON K1R 6K7	GEN

Generator No: ON8497519
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS

Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS

---

80 | ***3 of 7*** | ***N/247.6*** | ***59.9 / -4.69*** | ***Equity Realty Group Inc.***
250, 270, 290 City Centre Avenue
Ottawa ON K1R 6K7 | ***GEN***

Generator No:	ON8497519
SIC Code:	531310
SIC Description:	REAL ESTATE PROPERTY MANAGERS
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS

---

80 | ***4 of 7*** | ***N/247.6*** | ***59.9 / -4.69*** | ***Equity Realty Group Inc.***
250, 270, 290 City Centre Avenue
Ottawa ON K1R 6K7 | ***GEN***

Generator No:	ON8497519
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

---

80 ***5 of 7*** ***N/247.6*** ***59.9 / -4.69*** ***Equity Realty Group Inc.***
250, 270, 290 City Centre Avenue
Ottawa ON K1R 6K7 ***GEN***

Generator No: ON8497519
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 221 L
Waste Class Name: Light fuels

---

80 ***6 of 7*** ***N/247.6*** ***59.9 / -4.69*** ***Equity Realty Group Inc.***
250, 270, 290 City Centre Avenue
Ottawa ON K1R 6K7 ***GEN***

Generator No: ON8497519
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 L

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 241 L
Waste Class Name: Halogenated solvents and residues

Waste Class: 221 L
Waste Class Name: Light fuels

80	7 of 7	N/247.6	59.9 / -4.69	**Equity Realty Group Inc.** **250, 270, 290 City Centre Avenue** **Ottawa ON K1R 6K7**	GEN

Generator No: ON8497519
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 241 L
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 146 L
Waste Class Name: OTHER SPECIFIED INORGANICS

81	1 of 9	WNW/247.7	62.9 / -1.70	**HARAMBEE CENTRES CANADA** **29 BAYWATER AVE. (SWM)** **OTTAWA CITY ON**	CA

Certificate #: 3-0329-95-
Application Year: 95
Issue Date: 5/31/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

81	2 of 9	WNW/247.7	62.9 / -1.70	**Institute of Naturopathic Education and**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Research ***29 Bayswater Ave.*** ***Ottawa ON K1Y 2E5***	

Generator No: ON4138655
SIC Code: 621499
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

81	***3 of 9***	***WNW/247.7***	***62.9 / -1.70***	***Institute of Naturopathic Education and Research*** ***29 Bayswater Ave.*** ***Ottawa ON K1Y 2E5***	***GEN***

Generator No: ON4138655
SIC Code: 621499
SIC Description: All Other Out-Patient Care Centres
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

81	***4 of 9***	***WNW/247.7***	***62.9 / -1.70***	***Institute of Naturopathic Education and Research*** ***29 Bayswater Ave.*** ***Ottawa ON***	***GEN***

Generator No: ON4138655
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

81	***5 of 9***	***WNW/247.7***	***62.9 / -1.70***	***Ottawa Integrative Cancer Centre*** ***29 Bayswater Ave.*** ***Ottawa ON K1Y 2E5***	***GEN***

Generator No: ON4138655

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

81	6 of 9	WNW/247.7	62.9 / -1.70	**Institute of Naturopathic Education and Research** **29 Bayswater Ave.** **Ottawa ON K1Y 2E5**	GEN

Generator No: ON4138655
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Sean Fisher
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-475-7755 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

81	7 of 9	WNW/247.7	62.9 / -1.70	**Institute of Naturopathic Education and Research** **29 Bayswater Ave.** **Ottawa ON K1Y 2E5**	GEN

Generator No: ON4138655
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Sean Fisher
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-475-7755 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	8 of 9	WNW/247.7	62.9 / -1.70	Ottawa Integrative Cancer Centre 29 Bayswater Ave. Ottawa ON K1Y 2E5	GEN

Generator No: ON4138655
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	9 of 9	WNW/247.7	62.9 / -1.70	Ottawa Integrative Cancer Centre 29 Bayswater Ave. Ottawa ON K1Y 2E5	GEN

Generator No: ON4138655
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	1 of 1	NNW/248.3	59.9 / -4.69	250 CITY CENTRE AVE. Ottawa ON	WWIS

Well ID: 7121083
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: M04546
Tag: A074574
Constructn Method:
Elevation (m):
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 30-Mar-2009 00:00:00
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1844
Form Version: 5
Owner:
County: OTTAWA-CARLETON

Elevatn Reliabilty: ***Lot:***
Depth to Bedrock: ***Concession:***
Well Depth: ***Concession Name:***
Overburden/Bedrock: ***Easting NAD83:***
Pump Rate: ***Northing NAD83:***
Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: OTTAWA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/01/19
Year Completed: 2009
Depth (m):
Latitude: 45.4078893067677
Longitude: -75.7193364618343
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/02/02
Year Completed: 2009
Depth (m):
Latitude: 45.4080393474841
Longitude: -75.7183799464828
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/01/16
Year Completed: 2009
Depth (m):
Latitude: 45.4080220695882
Longitude: -75.7182647171092
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/01/20
Year Completed: 2009
Depth (m):
Latitude: 45.4077179781824
Longitude: -75.7179541703183
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/02/02
Year Completed: 2009
Depth (m):
Latitude: 45.4078087067401

Longitude: -75.7178403098324
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/01/16
Year Completed: 2009
Depth (m):
Latitude: 45.40877072393
Longitude: -75.7180186241709
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/02/02
Year Completed: 2009
Depth (m):
Latitude: 45.4077428911134
Longitude: -75.7182867364221
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/01/19
Year Completed: 2009
Depth (m): 5.18
Latitude: 45.4093961828194
Longitude: -75.7187549657085
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/01/16
Year Completed: 2009
Depth (m):
Latitude: 45.4081409248189
Longitude: -75.7179723075875
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/02/02
Year Completed: 2009
Depth (m):
Latitude: 45.4083924589007
Longitude: -75.718052168456
Path: 712\7121083.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7121083.pdf

Additional Detail(s) (Map)

Well Completed Date: 2009/02/02
Year Completed: 2009
Depth (m):
Latitude: 45.4081336909844
Longitude: -75.7176910789749
Path: 712\7121083.pdf

Bore Hole Information

Bore Hole ID: 1002751309
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 02-Feb-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443791.00
North83: 5028498.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002751313
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751312
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751314
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751316
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1002751315
Layer:	
Slot:	
Screen Top Depth:	3.0
Screen End Depth:	4.5
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002751317
Pump Set At:	
Static Level:	3.299999952316284
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002751311
Diameter:	20.0
Depth From:	
Depth To:	4.570000171661377
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002751300	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443784.00
Code OB Desc:		***North83:***	5028531.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	02-Feb-2009 00:00:00	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment

Sealing Record

Plug ID:	1002751304
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002751303
Method Construction Code:	
Method Construction:	
Other Method Construction:	HSA

Pipe Information

Pipe ID:	1002751305
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002751307
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.5
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002751306
Layer:	
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.5
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002751308
Pump Set At:	
Static Level:	2.700000047683716
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	
Water State After Test:	

Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751302
Diameter: 20.0
Depth From:
Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002751246
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 16-Jan-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443816.00
North83: 5028542.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002751250
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751249
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751251
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751253
Layer:

Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.5
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002751252
Layer:	
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.599999904632568
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002751254
Pump Set At:	
Static Level:	2.5
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002751248
Diameter:	20.0
Depth From:	
Depth To:	4.619999885559082
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002751255	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	443793.00
Code OB Desc:		**North83:**	5028529.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	16-Jan-2009 00:00:00	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002751259
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751258
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751260
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751262
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.0999999046325684
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002751261
Layer:
Slot:
Screen Top Depth: 2.0999999046325684
Screen End Depth: 5.099999904632568
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002751263
Pump Set At:
Static Level: 3.5
Final Level After Pumping:

Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751257
Diameter: 20.0
Depth From:
Depth To: 5.110000133514404
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002036074
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole: No
Cluster Kind:
Date Completed: 19-Jan-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443756.00
North83: 5028682.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1002751329
Layer: 1
Color: 2
General Color: GREY
Mat1: 12
Most Common Material: STONES
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.20000000298023224
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002751332

Layer: 4
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 2.2899999618530273
Formation End Depth: 3.200000047683716
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002751330
Layer: 2
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2: 28
Mat2 Desc: SAND
Mat3: 11
Mat3 Desc: GRAVEL
Formation Top Depth: 0.20000000298023224
Formation End Depth: 1.6699999570846558
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002751333
Layer: 5
Color: 2
General Color: GREY
Mat1: 34
Most Common Material: TILL
Mat2: 28
Mat2 Desc: SAND
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 3.200000047683716
Formation End Depth: 5.179999828338623
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002751331
Layer: 3
Color: 6
General Color: BROWN
Mat1: 04
Most Common Material: PEAT
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.6699999570846558
Formation End Depth: 2.2899999618530273
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1002751335
Layer:	1
Plug From:	1.2999999523162842
Plug To:	1.7999999523162842
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1002751338
Method Construction Code:	F
Method Construction:	H.S.A.
Other Method Construction:	

Pipe Information

Pipe ID:	1002751327
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Screen

Screen ID:	1002751336
Layer:	1
Slot:	10
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	5.800000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002751328
Pump Set At:	
Static Level:	2.5
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	0
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002751334
Diameter:	20.0

Depth From: 0.0
Depth To: 5.179999828338623
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002751264
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 19-Jan-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443709.00
North83: 5028515.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002751268
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751267
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751269
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751271
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002751270
Layer:
Slot:
Screen Top Depth: 2.0
Screen End Depth: 3.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002751272
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751266
Diameter: 20.0
Depth From:
Depth To: 3.5799999237060547
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002751282
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 02-Feb-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443810.00
North83: 5028570.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002751286
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751285
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751287
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751289
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.5
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002751288
Layer:
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002751290
Pump Set At:
Static Level: 2.0999999046325684
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:

Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751284
Diameter: 20.0
Depth From:
Depth To: 4.949999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002751291
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 02-Feb-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443838.00
North83: 5028541.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002751295
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751294
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751296
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751298
Layer:
Material: 5
Open Hole or Material: PLASTIC

Depth From:
Depth To: 1.5
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002751297
Layer:
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002751299
Pump Set At:
Static Level: 3.0
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751293
Diameter: 20.0
Depth From:
Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002751318
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 02-Feb-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:

Elevation:
Elevrc:
Zone: 18
East83: 443826.00
North83: 5028505.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002751322
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751321
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751323
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002751325
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002751324
Layer:
Slot:
Screen Top Depth: 3.0
Screen End Depth: 4.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002751326
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:

Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751320
Diameter: 20.0
Depth From:
Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002751237
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 16-Jan-2009 00:00:00
Remarks:
Loc Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 443813.00
North83: 5028612.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002751241
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002751240
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002751242
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1002751244
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.5
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002751243
Layer:	
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.5
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002751245
Pump Set At:	
Static Level:	2.299999952316284
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002751239
Diameter:	20.0
Depth From:	
Depth To:	4.570000171661377
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002751273	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	443817.00
Code OB Desc:		***North83:***	5028495.00
Open Hole:		***Org CS:***	UTM83

Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	20-Jan-2009 00:00:00	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002751277
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002751276
Method Construction Code:	
Method Construction:	
Other Method Construction:	HSA

Pipe Information

Pipe ID:	1002751278
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002751280
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.7999999523162842
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002751279
Layer:	
Slot:	
Screen Top Depth:	1.7999999523162842
Screen End Depth:	4.800000190734863
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002751281
Pump Set At:
Static Level: 3.5999999046325684
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002751275
Diameter: 20.0
Depth From:
Depth To: 4.800000190734863
Hole Depth UOM: m
Hole Diameter UOM: cm

Links

Bore Hole ID: 1002751273 ***Tag No:*** A074574
Depth M: ***Contractor:*** 1844
Year Completed: 2009 ***Path:*** 712\7121083.pdf
Well Completed Dt: 2009/01/20 ***Latitude:*** 45.4077179781824
Audit No: M04546 ***Longitude:*** -75.7179541703183

Links

Bore Hole ID: 1002036074 ***Tag No:*** A074574
Depth M: 5.18 ***Contractor:*** 1844
Year Completed: 2009 ***Path:*** 712\7121083.pdf
Well Completed Dt: 2009/01/19 ***Latitude:*** 45.4093961828194
Audit No: M04546 ***Longitude:*** -75.7187549657085

Links

Bore Hole ID: 1002751264 ***Tag No:*** A074574
Depth M: ***Contractor:*** 1844
Year Completed: 2009 ***Path:*** 712\7121083.pdf
Well Completed Dt: 2009/01/19 ***Latitude:*** 45.4078893067677
Audit No: M04546 ***Longitude:*** -75.7193364618343

Links

Bore Hole ID: 1002751318 ***Tag No:*** A074574
Depth M: ***Contractor:*** 1844
Year Completed: 2009 ***Path:*** 712\7121083.pdf
Well Completed Dt: 2009/02/02 ***Latitude:*** 45.4078087067401
Audit No: M04546 ***Longitude:*** -75.7178403098324

Links

Bore Hole ID:	1002751300	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/02/02	**Latitude:**	45.4080393474841
Audit No:	M04546	**Longitude:**	-75.7183799464828

Links

Bore Hole ID:	1002751246	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/01/16	**Latitude:**	45.4081409248189
Audit No:	M04546	**Longitude:**	-75.7179723075875

Links

Bore Hole ID:	1002751237	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/01/16	**Latitude:**	45.40877072393
Audit No:	M04546	**Longitude:**	-75.7180186241709

Links

Bore Hole ID:	1002751309	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/02/02	**Latitude:**	45.4077428911134
Audit No:	M04546	**Longitude:**	-75.7182867364221

Links

Bore Hole ID:	1002751291	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/02/02	**Latitude:**	45.4081336909844
Audit No:	M04546	**Longitude:**	-75.7176910789749

Links

Bore Hole ID:	1002751282	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/02/02	**Latitude:**	45.4083924589007
Audit No:	M04546	**Longitude:**	-75.718052168456

Links

Bore Hole ID:	1002751255	**Tag No:**	A074574
Depth M:		**Contractor:**	1844
Year Completed:	2009	**Path:**	712\7121083.pdf
Well Completed Dt:	2009/01/16	**Latitude:**	45.4080220695882
Audit No:	M04546	**Longitude:**	-75.7182647171092

Unplottable Summary

Total: 47 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	City of Ottawa	Somerset St W	Ottawa ON	
CA	City of Ottawa	Somerset St W	Ottawa ON	
CA	Drain-All Ltd.	Mobile System	Ottawa ON	
CA	CITY	BREEZEHILL AVE.	OTTAWA CITY ON	
CA		Gladstone Avenue	Ottawa ON	
CA		Breezehill Ave N, George St, Louisa St	Ottawa ON	
CA		Breezehill Ave N, George St, Louisa St	Ottawa ON	
CA		Gladstone Avenue	Ottawa ON	
CA	349977 Ontario Ltd.		Ottawa ON	
CA	City of Ottawa	Larch Street and Laurel Street	Ottawa ON	
CA	OTTAWA CITY	BAYSWATER AVE.	OTTAWA CITY ON	
CA	City of Ottawa	Gladstone Avenue	Ottawa ON	
CA	R.M. OF OTTAWA-CARLETON	SOMERSET STREET	OTTAWA CITY ON	
CA	OTTAWA CITY	BAYSWATER AVE.	OTTAWA CITY ON	
CA	City of Ottawa	Gladstone Avenue	Ottawa ON	
CA	City of Ottawa	Gladstone Avenue	Ottawa ON	
CONV	349977 Ontario Ltd.		Ottawa ON	
CONV	349977 ONTARIO LTD		ON	
CONV	DRAIN-ALL LTD.		ON	

CONV	SHELL CANADA PRODUCTS LIMITED		DON MILLS ON	
ECA	City of Ottawa	Somerset St W	Ottawa ON	K1P 1J1
ECA	SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc., and EllisDon	Corporation	Ottawa ON	K1Z 1G3
ECA	City of Ottawa	Gladstone Ave	Ottawa ON	K2G 6J8
ECA	City of Ottawa	Breezehill Ave N, George St, Louisa St	Ottawa ON	K1V 6A6
ECA	City of Ottawa	Larch Street and Laurel Street	Ottawa ON	K1P 1J1
ECA	Drain-All Ltd.	Mobile System	Ottawa ON	K1G 3N2
ECA	City of Ottawa	Breezehill Ave N, George St, Louisa St	Ottawa ON	K1V 6A6
EHS		0 Breezehill Avenue	n/a ON	
EHS		0 Loretta Avenue	n/a ON	
GEN	City of Ottawa	City Centre Avenue	Ottawa ON	K1R 6K7
SPL	DRAIN-ALL LTD	TRANSPORT TRUCK (CARGO)	OTTAWA CITY ON	
SPL	Shell Canada Products Limited	Shell Canada	Ottawa ON	
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON	
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON	
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON	
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON	
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON	
SPL	OLRT Constructors		Ottawa ON	NA
SPL	OLRT Constructors		Ottawa ON	
SPL	OLRT Constructors; City of Ottawa		Ottawa ON	
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON	

SPL	SHELL CANADA PRODUCTS LTD.	SERVICE STATION	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SNC-Lavalin Operations & Maintenance Inc.		Ottawa ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	SHELL CANADA PRODUCTS LTD.	TANK TRUCK (CARGO)	OTTAWA CITY ON
SPL	City of Ottawa; Drain-All Ltd.		Ottawa ON

Unplottable Report

Site: ***City of Ottawa***
Somerset St W Ottawa ON

Database: ***CA***

Certificate #: 0195-8HMLH2
Application Year: 2011
Issue Date: 6/15/2011
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***City of Ottawa***
Somerset St W Ottawa ON

Database: ***CA***

Certificate #: 6180-8JKNNV
Application Year: 2011
Issue Date: 7/22/2011
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Drain-All Ltd.***
Mobile System Ottawa ON

Database: ***CA***

Certificate #: A860302
Application Year: 2006
Issue Date: 8/4/2006
Approval Type: Waste Management Systems
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY***
BREEZEHILL AVE. OTTAWA CITY ON

Database: ***CA***

Certificate #: 3-1423-85-006
Application Year: 85

Issue Date: 11/22/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Gladstone Avenue Ottawa ON

Certificate #: 2461-4LXMEM
Application Year: 00
Issue Date: 7/5/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the City of Ottawa
Client Address: 111 Sussex Drive, 7th Floor
Client City: Ottawa
Client Postal Code: K1N 5A1
Project Description: Construction of Storm and Sanitary sewers on Gladstone Avenue from Bronson Avenue to Bay Street
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Breezehill Ave N, George St, Louisa St Ottawa ON

Certificate #: 2984-5AVRLF
Application Year: 02
Issue Date: 6/7/02
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: City of Ottawa
Client Address: 1495 Heron Road
Client City: Ottawa
Client Postal Code: K1V 6A6
Project Description: Replacement of existing combined sewers on George Street and Louisa Street with new PVC SDR35 combined sewers, and the separation of the combined sewer on Breezehil Avenue North into separate storm and sanitary sewers
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Breezehill Ave N, George St, Louisa St Ottawa ON

Certificate #: 1592-5AVRXD
Application Year: 02
Issue Date: 6/7/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: City of Ottawa
Client Address: 1495 Heron Road
Client City: Ottawa
Client Postal Code: K1V 6A6
Project Description: Replacement of existing 150 mm CI watermains on Breezehill Avenue North, George Street, and Louisa Street with 150 mm PVC DR18 watermain, with the terminal portion being 50 mm type K copper
Contaminants:
Emission Control:

Site:
Gladstone Avenue Ottawa ON

Database:
CA

Certificate #:	4558-4LXLWW
Application Year:	00
Issue Date:	7/5/00
Approval Type:	Municipal & Private water
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Corporation of the Regional Municipality of Ottawa-Carleton
Client Address:	111 Lisgar Street
Client City:	Ottawa
Client Postal Code:	K2P 2L7
Project Description:	Watermains to be constructed on Gladstone Ave. and Percy St. in the City of Ottawa
Contaminants:	
Emission Control:	

Site: ***349977 Ontario Ltd.***
Ottawa ON

Database:
CA

Certificate #:	A860156
Application Year:	2010
Issue Date:	4/15/2010
Approval Type:	Waste Management Systems
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***City of Ottawa***
Larch Street and Laurel Street Ottawa ON

Database:
CA

Certificate #:	9051-7BLLPL
Application Year:	2008
Issue Date:	3/25/2008
Approval Type:	Municipal and Private Sewage Works
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***OTTAWA CITY***
BAYSWATER AVE. OTTAWA CITY ON

Database:
CA

Certificate #:	3-1076-89-
Application Year:	89
Issue Date:	6/15/1989
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***City of Ottawa***
Gladstone Avenue Ottawa ON

Database: ***CA***

Certificate #: 3692-6PGP9X
Application Year: 2006
Issue Date: 5/6/2006
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF OTTAWA-CARLETON***
SOMERSET STREET OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0096-88-
Application Year: 88
Issue Date: 2/10/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***OTTAWA CITY***
BAYSWATER AVE. OTTAWA CITY ON

Database: ***CA***

Certificate #: 7-0907-89-
Application Year: 89
Issue Date: 6/15/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***City of Ottawa***
Gladstone Avenue Ottawa ON

Database: ***CA***

Certificate #: 6651-73WP47
Application Year: 2007
Issue Date: 6/6/2007

Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***City of Ottawa***
Gladstone Avenue Ottawa ON

Database: ***CA***

Certificate #: 7239-738KJA
Application Year: 2007
Issue Date: 6/18/2007
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***349977 Ontario Ltd.***
Ottawa ON

Database: ***CONV***

File No: 109022
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Location:
Region:
Ministry District:

Description: An Ottawa waste services company was fined $100,000 for depositing waste on an unapproved site and failing to decontaminate a tanker contrary to a ministry approval and the Environmental Protection Act. "Polluters should be aware that the ministry"s Investigations and Enforcement Branch will vigorously pursue charges when our environmental laws are broken," said Environment Minister Jim Bradley. 349977 Ontario Ltd., operating as Lacombe Waste Services operates a waste transportation services under a ministry approval for a waste management system. The facility is located on Power Road in the City of Ottawa. The company was contracted to provide roll-off containers for a retrofit project to remove toilets and transport them for disposal. An investigation found the toilets were taken to the company"s transfer facility located on Power Road in Ottawa and later transferred to a former quarry on Bank Street. Lacombe deposited two loads of approximately 500 toilets wrapped in garbage bags, including materials that were not inert fill on Bank Street, a property that was not an approved waste disposal site. A separate investigation also found Lacombe failed to properly decontaminate tankers used to transport various liquid wastes. Ministry approval requires the tankers to be cleaned when different types of waste are to be hauled. The company failed to do so leaving a load of wastewater contaminated with industrial fuels and oils. In a global resolution, Lacombe was fined a total of $100,000 plus victim fine surcharges of $25,000. All fines were paid immediately after the conviction.

Background:
URL:

Additional Details

Publication Date:
Count:
Act: EPA

Regulation:
Section:
Act/Regulation/Section: EPA
Date of Offence:
Date of Conviction:
Date Charged: July 23, 2013
Charge Disposition: fine, victim fine surcharge
Fine: $100,000
Synopsis:

Additional Details

Publication Date:
Count:
Act:
Regulation:
Section:
Act/Regulation/Section:
Date of Offence:
Date of Conviction:
Date Charged: January 9, 2014
Charge Disposition: fine, victim fine surcharge
Fine: $3,500
Synopsis:

Site: ***349977 ONTARIO LTD***
ON

Database: ***CONV***

File No:
Location:
Crown Brief No: 01-0136-0330
Region: EASTERN REGION
Court Location:
Ministry District: OTTAWA
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: FAIL TO CLEARLY MARK VEHICLE USED TO HAUL SEWAGE WITH "SEWAGE WASTE" ACCORDING TO THE STANDARDS.
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 16 (1) (12)
Act/Regulation/Section: EPA- -16 (1) (12)
Date of Offence:
Date of Conviction:
Date Charged: 9/6/01
Charge Disposition: SUSPENDED SENTENCE
Fine: $305.00
Synopsis:

Site: ***DRAIN-ALL LTD.***
ON

Database: ***CONV***

File No:
Location:
Crown Brief No: 98-0000-9004
Region: EASTERN REGION
Court Location:
Ministry District:
Publication City:

Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: THIS IS THE EASTERN BRIEF FOR ALL P.O.A. TICKETS
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 186(3)
Act/Regulation/Section: EPA- -186(3)
Date of Offence:
Date of Conviction:
Date Charged: 4/14/99
Charge Disposition: SUSPENDED SENTENCE
Fine: $305.00
Synopsis:

Site: ***SHELL CANADA PRODUCTS LIMITED***
DON MILLS ON

Database: ***CONV***

File No:
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: DISCHARGING A CONTAMINANT - ADVERSE EFFECT
Background:
URL:

Location:
Region: SOUTH EAST REGION
Ministry District:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 13(1)
Act/Regulation/Section: EPA- -13(1)
Date of Offence:
Date of Conviction:
Date Charged: 92/05/12
Charge Disposition:
Fine: 90000
Synopsis:

Site: ***City of Ottawa***
Somerset St W Ottawa ON K1P 1J1

Database: ***ECA***

Approval No: 0195-8HMLH2
Approval Date: 2011-06-15
Status: Approved

MOE District:
City:
Longitude:

Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: City of Ottawa
Address: Somerset St W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3106-8HFGKN-14.pdf
PDF Site Location:
Latitude:
Geometry X:
Geometry Y:

Site: ***SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc., and EllisDon Corporation Ottawa ON K1Z 1G3***

Database: ***ECA***

Approval No: 3474-99NHUQ
Approval Date: 2013-08-07
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: SNC-Lavalin Constructors (Pacific) Inc., Dragados Canada, Inc., and EllisDon Corporation
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2982-99JLHL-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***City of Ottawa Gladstone Ave Ottawa ON K2G 6J8***

Database: ***ECA***

Approval No: 3935-98BQWQ
Approval Date: 2013-08-01
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: City of Ottawa
Address: Gladstone Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1525-95PLKG-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***City of Ottawa Breezehill Ave N, George St, Louisa St Ottawa ON K1V 6A6***

Database: ***ECA***

Approval No: 2984-5AVRLF
Approval Date: 2002-06-07
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: City of Ottawa
Address: Breezehill Ave N, George St, Louisa St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1419-5ATHRG-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***City of Ottawa***

Database: ***ECA***

Larch Street and Laurel Street Ottawa ON K1P 1J1

Approval No:	9051-7BLLPL	***MOE District:***	Ottawa
Approval Date:	2008-03-25	***City:***	
Status:	Approved	***Longitude:***	-75.7108
Record Type:	ECA	***Latitude:***	45.405
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Rideau Valley	***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	City of Ottawa		
Address:	Larch Street and Laurel Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1567-74CM38-14.pdf		
PDF Site Location:			

Site: ***Drain-All Ltd.***
Mobile System Ottawa ON K1G 3N2

Database: ***ECA***

Approval No:	A860302	***MOE District:***	Ottawa
Approval Date:	2006-08-04	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Rideau Valley	***Geometry Y:***	
Approval Type:	ECA-WASTE MANAGEMENT SYSTEMS		
Project Type:	WASTE MANAGEMENT SYSTEMS		
Business Name:	Drain-All Ltd.		
Address:	Mobile System		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/8652-6HXRNS-14.pdf		
PDF Site Location:			

Site: ***City of Ottawa***
Breezehill Ave N, George St, Louisa St Ottawa ON K1V 6A6

Database: ***ECA***

Approval No:	1592-5AVRXD	***MOE District:***	
Approval Date:	2002-06-07	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-Municipal and Private Water Works		
Project Type:	Municipal and Private Water Works		
Business Name:	City of Ottawa		
Address:	Breezehill Ave N, George St, Louisa St		
Full Address:			
Full PDF Link:			
PDF Site Location:			

Site:

Database: ***EHS***

0 Breezehill Avenue n/a ON

Order No:	20080226017w	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Online Mapless	***Client Prov/State:***	ON
Report Date:	2/26/2008	***Search Radius (km):***	0.25
Date Received:	2/26/2008	***X:***	0
Previous Site Name:		***Y:***	0
Lot/Building Size:			
Additional Info Ordered:			

Site:

Database: ***EHS***

0 Loretta Avenue n/a ON

Order No:	20080226021w	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Online Mapless	***Client Prov/State:***	ON
Report Date:	2/26/2008	***Search Radius (km):***	0.25
Date Received:	2/26/2008	***X:***	0
Previous Site Name:		***Y:***	0
Lot/Building Size:			
Additional Info Ordered:			

Site: ***City of Ottawa***
City Centre Avenue Ottawa ON K1R 6K7

Database: ***GEN***

Generator No:	ON5650646
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2019
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	150 L
Waste Class Name:	Inert organic wastes

Site: ***DRAIN-ALL LTD***
TRANSPORT TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	145961	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	9/2/1997	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	OPP
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	9/2/1997	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	NEGLIGENCE (APPARENT)	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	DRAIN-ALL: UNSECURED BARRELS LEAKED OIL DURING TRANSPORT: OPP		
Contaminant Qty:			

Site: ***Shell Canada Products Limited***
Shell Canada Ottawa ON

Database: ***SPL***

Ref No:	6267-5M2K7H	***Discharger Report:***	
Site No:		***Material Group:***	Oil
Incident Dt:	4/28/2003	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:		***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:	12	***Nearest Watercourse:***	
Contaminant Name:	GASOLINE	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Ottawa
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	Eastern
Environment Impact:	Possible	***Site Municipality:***	Ottawa
Nature of Impact:	Other Impact(s)	***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/28/2003	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Spills
Incident Reason:		***Source Type:***	
Site Name:	LOADING RACK 1<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	Shell - 1L gasoline		
Contaminant Qty:	1 L		

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	8471	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/22/1988	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	ABOVE-GROUND TANK LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	8/22/1988	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	UPLANDS AIRPORT - 50 L OF JET FUEL TO PAVEMENT FROM TANK TRUCK.		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	16382	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	3/27/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	

Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	3/27/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	UPLANDS AIRPORT - 20 L OF JET FUEL TO GROUND.		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	21872	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/11/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/11/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL REFUELING VEHICLE- 70 L AVIATION FUEL TO GROUND.		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	23253	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	//	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	

Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	8/7/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL- 4.5 LTR SPILL OF JET FUEL AT UPLANDS AIRPORT		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	26231	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/5/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	DEPT OF TRANSPORT
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/5/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL CANADA - 120L JET FUEL TO TERMINAL RAMP		
Contaminant Qty:			

Site: ***OLRT Constructors***
Ottawa ON NA

Database: ***SPL***

Ref No:	2136-A6TPRD	***Discharger Report:***	
Site No:	0500-9VRLCQ	***Material Group:***	
Incident Dt:	2016/02/04	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:		***Sector Type:***	Miscellaneous Industrial
Incident Event:	Leak/Break	***Agency Involved:***	
Contaminant Code:	13	***Nearest Watercourse:***	
Contaminant Name:	DIESEL FUEL	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	NA
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	Ottawa
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Land	***Northing:***	5031025
MOE Response:	No	***Easting:***	452415
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	NA
MOE Reported Dt:	2016/02/04	***Site Map Datum:***	NA
Dt Document Closed:		***SAC Action Class:***	Land Spills
Incident Reason:	Unknown / N/A	***Source Type:***	
Site Name:	OLRT Blair Station		

Site County/District:
Municipality No:
Site Geo Ref Meth: NA
Incident Summary: OLRT- 2L Diesel to Asphalt
Contaminant Qty: 2 L

Site: ***OLRT Constructors***
Ottawa ON

Database: ***SPL***

Ref No: 5368-A5EMJN
Site No: NA
Incident Dt: 12/21/2015
Year:
Incident Cause:
Incident Event:
Contaminant Code: 28
Contaminant Name: CONCRETE ADMIXTURE (DE-WATERING)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env:
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/21/2015
Dt Document Closed:
Incident Reason: Operator/Human Error
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:
Site Name: OLRT construction site - located by Belfast Rd. overpass<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth:
Incident Summary: OLRT: 3 L of concrete washout to soil, cleaned
Contaminant Qty: 3 L

Site: ***OLRT Constructors; City of Ottawa***
Ottawa ON

Database: ***SPL***

Ref No: 7521-9URNRM
Site No: NA
Incident Dt: 3/4/2015
Year:
Incident Cause: Leak/Break
Incident Event:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact: Land
Receiving Medium:
Receiving Env:
MOE Response: N
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/19/2015
Dt Document Closed: 4/2/2015
Incident Reason: Equipment Failure
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Ottawa
Site Lot:
Site Conc:
Northing: 5029087
Easting: 444249
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:
Site Name: grassy area between Albert Street and the pedestrian multi-use pathway, immediately east of Booth Street<UNOFFICIAL>
Site County/District:
Municipality No:
Site Geo Ref Meth: 10 -100 metres eg. Topographic Map
Incident Summary: OLRT - 15L diesel to grass March 4th, cleaning
Contaminant Qty: 15 L

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	30521	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/2/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND / AIR	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/2/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL TANK TRUCK-50 L AVIATION FUEL TO ASPHALT		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
SERVICE STATION OTTAWA CITY ON

Database: ***SPL***

Ref No:	60160	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/24/1991	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	SHELL, FIRE DEPT. TRIANGLE PUMP
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	11/25/1991	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	CORROSION	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL SERVICE STATION - 25 L. OF GASOLINE TO GROUND FROM LEAKY CAR		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	81836	***Discharger Report:***	
Site No:		***Material Group:***	

Incident Dt:	2/14/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/14/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL-25L OF JET A-1 FUELTO GROUND DURING FUELLINGCONTAINED, CLEANED UP.		
Contaminant Qty:			

Site: ***SNC-Lavalin Operations & Maintenance Inc.***
Ottawa ON

Database: ***SPL***

Ref No:	4475-8DGQA2	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/17/2011	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Unknown	***Sector Type:***	Other
Incident Event:		***Agency Involved:***	
Contaminant Code:	n/a	***Nearest Watercourse:***	
Contaminant Name:	Propylene glycol	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Ottawa
Nature of Impact:	Soil Contamination; Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	No Field Response	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	1/26/2011	***Site Map Datum:***	
Dt Document Closed:	2/16/2011	***SAC Action Class:***	Land Spills
Incident Reason:	Equipment Failure - Malfunction of system components	***Source Type:***	
Site Name:	SNC Lavalin 150 Tunney's Pasture Driveway<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	113L propylene glycol to roof, storm sewer.		
Contaminant Qty:	113 L		

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	81843	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/14/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	

Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/14/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL CANADA - 20 L OF AVIATION FUEL TO RAMP DUE TO TRUCK LEAK		
Contaminant Qty:			

Site: ***SHELL CANADA PRODUCTS LTD.***
TANK TRUCK (CARGO) OTTAWA CITY ON

Database: ***SPL***

Ref No:	84404	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/21/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	OTTAWA CITY
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/22/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Municipality No:	20101		
Site Geo Ref Meth:			
Incident Summary:	SHELL CANADA - 40 L OF AVIATION FUEL AT GATE A DUE TO TRUCK LEAK		
Contaminant Qty:			

Site: ***City of Ottawa; Drain-All Ltd.***
Ottawa ON

Database: ***SPL***

Ref No:	2725-BCFDLJ	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	5/22/2019	***Health/Env Conseq:***	
Year:		***Client Type:***	Municipal Government; Corporation
Incident Cause:		***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Ottawa
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	Eastern
Environment Impact:		***Site Municipality:***	Ottawa
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	

MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/22/2019	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:		***Source Type:***	
Site Name:	To be determined<UNOFFICIAL>		
Site County/District:			
Municipality No:			
Site Geo Ref Meth:			
Incident Summary:	EGN for (3) zones - Ottawa Flooding (2019)		
Contaminant Qty:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Northern Development, Mines, Natural Resources and Forestry (ONDMNRF) maintains this database of pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Oct 2022

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Mar 2022

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-May 31, 2022

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2020

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-May 31, 2022

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Sep 2022

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Nov 2022

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Jan 31, 2023

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2022

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Feb 28, 2022

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011- Jan 31, 2023

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Jan 31, 2023

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- Jan 31, 2023

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Dec 31, 2022

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2021

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Dec 2022

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: May 31, 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2019

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 21, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2023

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2021

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Nov 30, 2022

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2021

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Jan 31, 2023

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011- Jan 31, 2023

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Jan 31, 2023

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2019

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Jan 2023

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-May 31, 2022

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: 1988-Sep 2020; Dec 2020-Mar 2021

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2020

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2020

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011- Jan 31, 2023

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Jun 30 2022

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX 3

QUALIFICATIONS OF ASSESSORS

PATERSON GROUP

solution oriented engineering



Mark St Pierre, P.Eng.
Intermediate Environmental Engineer – Level II

Mark joined Paterson Group in July 2018 as part of the Environmental Department. Mark received his Bachelor of Engineering from Carleton University in 2015, specializing in Environmental Engineering. Since joining Paterson Group in 2018, Mark has worked on numerous residential and commercial development projects, predominantly within the National Capital Region as well as various locations within Southeastern Ontario. His scope of work consists of conducting Phase I & II environmental site assessments, field inspections, contaminated soil and groundwater field sampling, supervising the remediation of contaminated sites, as well as performing designated substance surveys and indoor air quality assessments.

EDUCATION
Bachelor of Environmental Engineering, B.Eng., 2015
Carleton University
Ottawa, Ontario

ASSOCIATIONS/ AFFILIATIONS
Professional Engineers of Ontario (P.Eng.)

YEARS OF EXPERIENCE
With Paterson: 4

With other firms: 3

OFFICE LOCATION
9 Auriga Drive, Ottawa, Ontario, K2E 7T9

SELECT LIST OF PROJECTS

- Designated Substance Surveys – Residential and Commercial Sites – Southeastern Ontario
- Asbestos Air Testing – Residential and Commercial Sites – Ottawa
- Mould Testing – Residential and Commercial Sites
- Indoor Air Quality Surveys – Commercial and Residential Sites
- Phase I Environmental Site Assessments – Residential and Commercial Sites – Ottawa (CSA Z768-01 & MECP)
- Phase II Environmental Site Assessments – Commercial and Industrial Sites - Ottawa (CSA Z768-01 & MECP)
- Contaminated Soil and Groundwater Sampling – Various Sites – Ottawa
- Remediation Programs – Various Sites - Ottawa

PROFESSIONAL EXPERIENCE

2018 to present, **Intermediate Environmental Engineer, Paterson Group**, Ottawa, Ontario

- Conducting Phase I and Phase II Environmental Site Assessments in accordance with CSA standards and O.Reg. 153/04.
- Responsible for the application of environmental, hydrogeological, and/or geotechnical principles and practices in the identification and delineation of soil and groundwater contamination plumes while ensuring compliance with federal, provincial, and/or municipal legal and regulatory requirements.
- Completing Designated Substance Surveys (including Air Quality Testing)
- Presenting analytical test results, interpretations, assessments, recommendations and/or conclusions in a final technical report.
- Field experience in the supervision of drilling and excavation contractors, inspection of aboveground and underground fuel storage tanks, soil and rock classification, soil and groundwater field sampling, as well as the collection of hazardous building materials and designated substances.
- Coordination and on-site supervision of soil and groundwater remediation activities for contaminated sites.
- Liaising with clients, contractors, consultants, and government officials.
- Coordination of contractors and field staff while directly reporting to senior management and client to ensure completion of project on schedule and within budget.
- Provide cost estimates for environment field programs

2015 to 2018**, Environmental Consultant and Project Manager**, InAIR Environmental Limited

- Conduct Designated Substance Survey's in accordance with the O.Reg. 278/05.
- Conduct Indoor Air Quality testing on residential and commercial sites.
- Present and produce methodologies, analytical results, assessments and/or results, and recommendations in the form of technical reports.
- Report project status and/or issues that may affect project budgets and/or scheduled completion dates.
- Provide cost estimates for environment field programs
- Liaise with clients, contractors, consultants, and stakeholders.

PATERSON GROUP
solution oriented engineering



Michael Beaudoin, P.Eng., QP$_{ESA}$
Senior Project Manager

Michael received his Bachelor of Engineering from Carleton University in 2010 in Environmental Engineering. Michael joined the Paterson Group in the Environmental Division. Michael has worked for Paterson for approximately 12 years and has accrued extensive field and office experience. Michael's experience working in the field ranges from Phase I site reviews, Phase II investigations, remediation site inspections and designated substance surveys. Through his years of field experience, Michael has obtained invaluable knowledge on contractor relationships, budgets, time management, consultant/owner relation, quality data and information, and working with a variety of different personnel and situations. Michael has moved into a more senior role by becoming a qualified person for environmental assessments, overseeing small to large scale environmental projects, which include, Phase I and II reports, Record of Site Conditions and Brownfield Applications. Michael has assisted with Mark D'Arcy in the development of young staff and continuous improvement of Paterson internal systems.

EDUCATION
B.Eng. 2010, Environmental Engineering
Carleton University
Ottawa, ON

LICENCE/ PROFESSIONAL AFFILIATIONS
Professional Engineers of Ontario

Ottawa Geotechnical Group

YEARS OF EXPERIENCE
With Paterson: 12

OFFICE LOCATION
9 Auriga Drive, Ottawa, Ontario, K2E 7T9

SELECT LIST OF PROJECTS
- Rideau Street Reconstruction, Ottawa, ON Phase I ESA, Phase II ESA, (Field Manager)
- Main Street Reconstruction, Ottawa, ON Phase I ESA, Phase II ESA, (Field Manager)
- Woodroffe Avenue Reconstruction, Ottawa, ON Phase I ESA, Phase II ESA, (Field Manager)
- Westboro Connection Development, Ottawa ON, Phase II ESA, Remediation Supervision (Field Manager)
- Riverview Development – Kingston, ON, Phase I ESA, Phase II ESA, and filing of multiple RSCs in the MECP Environmental Site Registry (Project Manager)
- West Village Development – Kingston, ON, Phase I ESA, Phase II ESA, and filing of multiple RSCS in the MECP Environmental Site Registry (Project Manager)
- Moon Development – 245 Rideau Street, Ottawa, ON, Phase I ESA, Phase II ESA, and RSC Filing (Project Manager)
- ESAP Project, Ottawa, ON
- Record of Site Condition Filings – Residential and Commercial Development Properties, Various Sites, Ottawa, Kingston ON.
- Designated Substance Surveys, Ottawa, ON
- Phase I and Phase II Investigations in accordance with CSA standards and O.Reg 153/04

PROFESSIONAL EXPERIENCE

November 2010 to present**, Environmental Engineer, Paterson Group**, Ottawa, Ontario

- Provide on-site environmental expertise for various soil and groundwater remediation projects including but not limited to the following: Riverview Development, West Village, Westboro Connection, ESAP Project, and 405 Terminal Avenue.
- Oversee Phase I and Phase II Investigations in accordance with CSA standards and O.Reg 153/04 on a variety of residential and commercial developments.
- Responsible for filing Records of Site Condition with the MECP Environmental Site Registry.
- Completing Designated Substance Surveys (including Air Quality Testing)
- Problem solving to help advance or maintain project schedules.
- Complete environmental reports with recommendations for environmental concerns.
- Liaising with contractors, consultants and government officials.
- Provide cost estimates for environment field programs and construction costs.
- Review RFI's, submittals, monthly progress reports and other various construction related work.