


The North West  
half of Lot 20  
Block 32

Fd. I. Plan 390LK  
C.S. 0.70

# ALBERTA LAND SURVEYOR'S REAL PROPERTY REPORT

## THIRD ROCK GEOMATICS

PO Box 216, Suite 104 1240 Kensington Road NW  
Calgary, Alberta T2N 3P7 Phone 587-333-4413



### Description of Property:

Civic Address: 5417 Dalrymple Crescent NW, Calgary, Alberta  
Legal Address: The North West half of Lot 5, Block 34, Plan 390LK

Certificate of Title: 031 264 074

Owner(s):

Registered instrument affecting the extent of property:

7535LA Utility Right Of Way,

031 264 076 Caveat, 101 297 573 Release of Dower Rights

Date of Title Search: April 21, 2026

Date of Survey: April 21 and 24, 2026

I, Mark A. Sutter, Alberta Land Surveyor, hereby certify that this Report, which includes the attached plan and related survey, was prepared and performed under my supervision, direction, and control and in accordance with standards and rules for the practice of surveying prescribed by the Alberta Land Surveyors' Association. Accordingly, within those standards and as of the date of this Report, I am of the opinion that:

1. the plan illustrates the boundaries of the subject Property, the improvements as defined in Part C, Section 6.5 of the Alberta Land Surveyors' Association's Manual of Standard Practice, and the defined limits of registered interests affecting the extent of the title to the subject Property;
2. the improvements are entirely within the boundaries of the subject Property except: NONE IDENTIFIED
3. no visible improvements situated on an adjoining property cross the boundaries of the subject Property except: NONE IDENTIFIED
4. no visible improvements exist within the defined limits of any registered interests affecting the extent of the subject Property except: NONE IDENTIFIED

**Notes:** Distances are in metres and decimals thereof. Bearings are assumed from plan 390LK.

All ties are perpendicular to property line. Side yard and setback distances are measured to concrete walls, except otherwise shown. All fences are within 0.20m of the property line unless otherwise noted. Eaves are measured to the foundation, unless otherwise noted.

Fd. - Found, Mk. - Mark, C.S. - Countersunk, AGL - Above ground level, Conc. - Concrete

Δ - Central angle of curve, R - Radius, A - Arc Length, Ck.m. - Check measured, (R) - Radial Bearing

Calculated Position shown thus . . . . . X

Statutory Iron Post found shown thus . . . . . ● Fd. I.


Title boundary shown thus . . . . . ————

Fence shown thus . . . . . —□—□—□—□—

Dated at the City of Calgary, Alberta, April 27, 2026

**Mark A. Sutter, ALS, P. Surv.** (Copyright reserved)

This document is not valid unless it bears the original or digital signature of an Alberta Land Surveyor and a Third Rock Geomatics Ltd. permit stamp.



**Purpose:** This Report and attached plan have been prepared for the benefit of the subject Property owner, subsequent owners, and any of their agents for the purposes of a land conveyance, support of a subdivision application, a mortgage application, or a submittal to the municipality for a compliance certificate. Copying is permitted only for the benefit of these parties, and only if the plan remains attached.

The owner is responsible for the review of this Real Property Report and to report any discrepancies or omissions within 3 months of the issuance of this report to the surveyor. Failure to report the discrepancies relieves Third Rock Geomatics Ltd. of any future liabilities or claims. Some improvements may not be shown if they are, in the opinion of the surveyor, considered to be temporary or do not substantially affect the value of the property.

Where applicable, registered interests affecting the extent of the Property have been shown on the attached plan. Unless shown otherwise, property corner markers have not been placed during the survey for this Report. The attached plan should not be used to establish boundaries (e.g., for fencing) because of the risk of misinterpretation or measurement error by the user. The information shown on this Report reflects the status of this subject Property as of the date of survey only. Users are encouraged to have the Real Property Report updated for future requirements because subsequent development changes will not be reflected on the existing Real Property Report.

